

G360 SUPER FAST SYSTEM.

! For optimum results use correct machine speeds, minimal product, apply minimal pressure and clean the pads regularly, especially the G Mop Super High Cut Pad, with a G Plus Spurring Brush.
* P2000 is suggested for low energy clear coats (air dry).

HIGH CUT

To remove P1500 or finer* sanding marks

~~P3000~~ **NO P3000 SANDING REQUIRED!**




G360 SUPER FAST COMPOUND
1 kg **SFC101**
(78072700162)

G MOP SUPER HIGH CUT PAD
6" / 150 mm
GMC650
(78072700153)

ON ALL COLOURS

- Eliminates P1500 sanding marks from all conventional clear coats (low bake)
- Prepares for **MEDIUM CUT** polishing



Apply product, using a **small amount**

Using minimal pressure, start polishing at **1500rpm** at a slight angle, ending at **900rpm** keeping the pad flat

MEDIUM CUT

To remove process marks and medium defects (such as swirls and light scuffs)



G360 SUPER FAST COMPOUND
1 kg **SFC101**
(78072700162)

G MOP ANGLED YELLOW FOAM
6" / 150 mm
GMC622
(78072769182)

ON LIGHT COLOURS

- Rapidly eliminates visible swirls and holograms
- Leaves an excellent gloss finish

ON DARK COLOURS

- Rapidly eliminates heavy swirls and holograms
- Prepares for **FINE CUT** polishing



Apply product, using a **small amount**

Polish at **900 - 1300rpm**, keeping the pad flat

Wipe clean with a G Plus Finishing Cloth

FINE CUT

To remove fine defects (such as holograms and light swirls) and enhance gloss levels



G360 SUPER FAST FINISH
1 L **SFF101**
(78072700138)

G MOP ANGLED BLACK FOAM
6" / 150 mm
GMF622
(78072769185)

ON LIGHT COLOURS

- Further enhances gloss levels if desired

ON DARK COLOURS

- Rapidly eliminates light swirls and holograms
- Leaves an enhanced deep gloss finish



Apply product, using a **small amount**

Polish at **800 - 1100rpm**, keeping the pad flat

Wipe clean with a G Plus Finishing Cloth

FINAL CLEANING AND PROTECTION

To remove residue and contaminants while adding shine and protection



CLEAN AND PROTECT
1 L **CAP101**
(78072766935)

G PLUS FINISHING CLOTH
400 mm x 400 mm
3 cloths **FC-3**
(78072700136)

NO SILICONES, NO VOC

- Cleans away residue, dust, fingerprints and other contaminants
- Use on paint, glass, trims, rubber and many other surfaces
- Leaves a friction-free, high gloss finish
- Leaves a breathable, water-resistant film



Spray a light mist onto the surface

Wipe clean with a G Plus Finishing Cloth

Use a clean, dry G Plus Finishing Cloth to buff to a shine



Write on and wipe off surfaces including paint work and glass

G PLUS AUTOPEN
AP-5YW (78072709135)



For best results and longer pad life:

G MOP FLEXIBLE BACK PLATE
14 mm thread **GMB146** (78072700148)
5/8" thread **GMB586** (78072715924)
16 mm thread **GMB166** (78072715925)



Microfibre, low-lint wiping:

G PLUS FINISHING CLOTH
(400 x 400 mm and edgeless)
3 cloths **FC-3** (78072700136)
100 cloths **FC-100** (78072709136)



Keep pads clean using a:

G PLUS SPURRING BRUSH
GPS001 (78072773569)



#FARECLAG360

+44 (0) 1920 465 041 | enquiries@farecla.com | www.farecla.com

SEE THE
G360 SYSTEM
IN ACTION



Farécla | SURFACE FINISHING SPECIALISTS