



IATF16949:2016



KAITUO
CORPORATION



- Auto Blower
- Auto Fan Assy
- Auto Wiper Assy
- Auto Electrical Running Board System
- High Power High Speed Motor
- High Torque Gear Reduction Motor

Add: No. 66, Weiye RD, Gexiang Zone, Southern Zhejiang Industrial Cluster District, Ruian, Zhejiang, China

地址:浙江省瑞安市浙南产业聚集区阁巷分区围一路66号

Sale Tel: 86-577-65351188 65373898 65352521

传真(Fax): 86-577-65377770

E-mail: kaikaichina@kaikaichina.com

Https://www.kaikaichina.com



Automotive Motor Expert!



企业简介 Enterprise Introduction

Kaituo Factory



浙江开拓汽车电器有限公司创建于1992年,是一家专业生产汽车电机的企业,公司位于中国汽配之都瑞安市浙南产业聚集区阁巷分区,公司紧邻火车站东路与甬台温高速复线,距离温州机场36公里,瑞安火车站15公里。经过30多年的不断发展,使公司逐渐发展成为国内汽车电机制造行业中规模最大的企业之一。

公司已形成研发、生产和销售为一体的汽配生产型企业。公司主要产品有汽车雨刮器总成、散热器风扇、冷凝器风扇、鼓风机、电动踏板系统、大功率大转速电机、大扭矩减速电机等系列产品。公司占地面积13333平方米,建筑面积36325平方米,现有230多名员工,其中各类专业技术人才50多名,9个发明专利。

公司于1999年开始不断获取ISO9000、CE、EMC、TUV、ISO/TS16949、ISO14001、ISO45001、IAF16949等认证;并于2013年开始被评为“国家级高新技术企业”,进一步强化公司的质量管理,增强顾客满意度,提高公司的核心竞争力。公司产品远销欧洲,北美,拉丁美洲,东南亚,俄罗斯,中东,南非等国家和地区,并与印度TATA公司、俄罗斯LADA公司、墨西哥FORD公司进行配套;以及在国内各主要城市都建立了经销网点和国内配套公司等。产品深受国内外客户的好评。


公司以“创新电机应用,开拓美好生活”为使命,以“做电机生产行业新标杆,打造企业与员工共同发展的平台”为愿景,以“勤奋、务实、诚信、正直”为价值观来打造企业,竭诚为国内外顾客提供优质的产品与服务。真诚希望与国内外汽车制造商、汽车零部件集团采购商建立长期稳固的合作伙伴关系,共同发展,共创辉煌!

Zhejiang Kaituo Automobile Electrical Appliance Co., Ltd founded in 1992, specializing in producing auto motors. The company is located in Gexiang Industrial Zone, Ruian City which is the capital of Automobile & Motorcycle Spare Parts in China. It is close to railway station east road and Yongtaiwen highway, 30 kilometers from Wenzhou Airport and 15 kilometers from Ruian Railway Station. After 30 years of continuous development, the company has now become one of the leading manufacturers in the auto motor line.

The company has become an auto parts manufacturing enterprise integrating R&D, production and sales. The main products include wiper assy, radiator fan, cooling fan, blower, running board system, high Power high Speed Motor, high torque reduction Motor etc. . The company covers an area of 13,333 square meters, and the construction area is 36,325 square meters, currently has more than 230 employees, over 50 Technical Talents, and already got 9 invention patents.

Since 1999, our company has constantly got ISO9000、CE、EMC、TUV、ISO/TS16949、ISO14001、ISO45001、IAF16949 certificates etc. The company has been rated as “National High-Technology Enterprise” in 2013, which has further strengthened the company's quality management, enhanced customer satisfaction and company's core competitiveness. Our products export to Europe, North America, Latin America, Southeast Asia, Russia, the Middle East, South Africa and other countries and regions, cooperating with companies like TATA in India, LADA in Russia, and FORD in Mexico etc in OEM and OES business. Through setting up sales and supplying networks in major cities, our company has received good reputation home and abroad.

“Developing motors new future application, striving to innovation for clients” as our mission, “become the motor industry new standard, built the common development platform for enterprise and employees” as the vision, “diligent, pragmatic, sincerity, integrity” as the values, wholeheartedly providing quality products and services for the customers. We sincerely hope to establish long-term and stable cooperative partnership with domestic and foreign customers for common development and brilliant future.





企业荣誉
Enterprise Honor



IATF 16949



ISO 14001



ISO 45001




FAN ASSY CE



Patent of invention



High and New Technology Enterprises



Export Level 1 enterprise



Afforestation Donation



Wenzhou Famous Brand Products



Wenzhou Famous Trademark



AA Level Shou Contract Re Credit Enterprise



生产现场
Production Site



冲制车间

Stamping Workshop




模具仓库

Moulds Warehouse



注塑车间

Injection Workshop 1



减速箱加工线

Gearbox processing line




压铸车间

Extrusion Aluminum die-casting machine



线束装配线

Wire harness assembly line



风扇动平衡

Fan dynamic balance



电枢绕组线

Armature winding wire



连杆产线

Linkage production line



装配生产线

Motor assembly line



零配件仓库

Semi finished warehouse



外检计量中心

Metrology Center



研发中心
R&D CENTER



淋雨&泥浆综合耐久试验箱

Rain&Slurry Comprehensive Durable Test Box



步入式高低温交变湿热试验箱

Programmable Temperature & Humidity Chamber



盐水喷雾试验箱

Salt Spray Test Chamber



静音试验箱

Silence Test Box



三综合振动试验台

Comprehensive Vibration Test Bench



风机性能测试台

Fan Performance Test Bench



风扇数据采集中心

Fan Assembly Balancing Machines



金相显微分析仪

Metallographic Analyzer



直流电机数据采集中心

Motor Automatic Testing System




万能拉压力试验机

Universal Tension and Pressure Testing Machine



三坐标测量仪

Trilinear Coordinates Measuring Instrument




高精度三维数据采集

High-precision 3D data acquisition



营销网络
Marketing network





Wiper Motor

10-1005		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	TIY223	Wuling(柳州五菱) MITSUBISHI L100 84~89
10-1006		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	5205010C01	CHANA Benni(长安奔奔)
10-1006A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		CHANA Benni MINI(长安奔奔迷你)
10-1008		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		CHANA 462Q(松花江,长安462) SUZUKI ST90
10-1009		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8512087Z07000;8512097207;0590506789;TG059050838A	CHANA SC6350(长安之星) DAIHATSU Move 1999 GF-L900S PERODUA Kenari
10-1011		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511087702;TIY226	FAW XIALI(一汽夏利) DAIHATSU G100 Parts
10-1012		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		SUZUKI CHANGHE 1018(昌河1018)
10-1014		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		KAMA Aofeng(凯马奥峰)
10-1014A		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		KAMA Aofeng(凯马奥峰)
10-1015		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		FOTON Forland(福田时代)

10-1015A		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		FOTON Forland(福田时代)
10-1016		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	3810160E00	CHANA Lingyang(长安羚羊)
10-1017		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		JINBEI Hiace(金杯海狮)
10-1018		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		BRILLIANCE Jinbei(华晨金杯)
10-1018A		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		BRILLIANCE Jinbei(华晨金杯)
10-1020A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	6262000;6262002	东风风神 H30 S30
10-1038		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	S215205510	CHERY QQ(奇瑞QQ); QQ6(奇瑞QQ6)
10-1038B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	S225205111	CHERY QQ(奇瑞QQ); QQ6(奇瑞QQ6); Youya(奇瑞优雅)
10-1038C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		WULING Hongguang S(五菱宏光S)
10-1038D		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		WULING Hongguang S(五菱宏光S)

10-1038E		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		BAIC(北汽) 威旺 M20,M30, Hyosow(幻速) S2,S3
10-1038F		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	5205110D0010A000000	SWM斯威X7
10-1039		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	AAC52050001060618Z	HAFEI Miyi(哈飞民意)
10-1039A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		HAFEI Lobo HFJ6352(哈飞路宝)
10-1042		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		Wulingzhiguang(柳州五菱之光)
10-1044		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		WulingXingwang(柳州五菱兴旺)
10-1047		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		Special Vehicle(挂重汽车)
10-1051		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		JINBEI Hiace(RHD) SOUTH AFRICA
10-1052		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		DAIHATSU M80,S80(一汽森雅)
10-1053A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	S125205010	CHERY A1(奇瑞A1)

10-1043		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	5496062;23856275;24528393;24544014	CHEVROLET N200 09~11; N300 09~11 WULING N300(柳州五菱荣光,鸿途) 航天汽车成功一号
10-1052A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	BJ0E67340;BJ0E67340B; BJ0E67340C;BJ0E67340D ;BJ0E67340DL1;BJ0E67340E;434406	HAIMA Family(海马福美来,海福星) MAZDA(马自达) 323; Protege 99~03; Protege5 02~03
10-1056		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		FAW weizhi V5(一汽威志)
10-1057A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	Q225205010;Q225205111	KARRY Q22(开瑞Q22); Yoyo(开瑞优优); Null(开瑞优劲)
10-1059		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	SA0067340F	HAIMA(海马) S3,S7
10-1060		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		东南 菱悦V3,菱帅,蓝瑟,富利卡
10-1062		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		Wuling(柳州景逸BE1)
10-1065		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		中兴威虎(ZXAUTO)
10-1066		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		篷车三轮车

10-1073C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		JAC J3(江淮同悦)
10-1074		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		JAC J6(江淮和悦)
10-1074A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		HAWTAI Baolige(华泰宝利格)
10-1098A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GEELY Meiri(吉利美日)
10-1115A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	6262001	东风风神A60 E70
10-1119A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		HAIMA(海马) Qiubite(丘比特);M3
10-1121		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GEELY Vision,(远景) BYD F3(比亚迪)
10-1121C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	3741100001	GEELY GX7, Jingang, Panda (吉利全球鹰,金刚,熊猫)
10-1122		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GEELY Ziyoujian(吉利自由舰)
10-1123		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		JINBEI Grace(金杯阁瑞斯)

10-1124		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	LK3741120;FA146737X;FA146737XA;FA146737XB	BYD(比亚迪) F0 HAIMA(海马) M5
10-1128		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		BRILLIANCE Grandeur(华晨中华尊驰骏捷)
10-1129		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		BRILLIANCE Junjie FRV、CROSS、FSV(华晨中华FRV、CROSS、FSV)
10-1130		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		LIFAN 520(力帆520)
10-1138		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		FOTON MP-X(福田蒙派克)
10-1201		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GREAT WALL Wingle3(长城风骏3)
10-1202		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GREAT WALL Hover H3;Hover H5(长城哈弗H3;哈弗H5)
10-1203		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GREAT WALL V80(长城嘉誉V80;腾翼V80)
10-1204		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GREAT WALL Havel M1(长城精灵;哈弗M1)
10-1205		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GREAT WALL Coolbear(长城酷熊;哈弗M2)

10-1206		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GREAT WALL Wingle5(长城风骏5)
10-1207		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GREAT WALL(长城赛铃, 福田皮卡)
10-1208		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GREAT WALL C30(长城腾翼C30; 长城凌傲)
10-1209		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		GREAT WALL Xuanli(长城炫丽)
10-1221		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		CHERY Eastar(奇瑞东方之子)
10-1222		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	A215205110	CHERY(奇瑞) Fulwin; Cowin; Cowin2; Cowin3; G3; A5; E5(风云; 旗云; 旗云2; 旗云3; G3; A5; E5)
10-1223		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	J725205110	CHERY EQ1(奇瑞小蚂蚁) 18~
10-1223A		V 12V W RPM.L RPM.R N.m	5479001	BRILLIANCE(华晨中华 V3, F10)
10-1251		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	6020000200; W000032001	GEELY EC718 EC715-RV(吉利帝豪) 14~16
10-1252		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	5205110AKZ16A; W000049173	GREAT WALL Hover H6(长城哈弗H6运动版)

10-1261		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		CHANA CS35(长安CS35)
10-1261A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	B2110630800	CHANA(长安) Alsvin V7(悦翔V7) 14~; Eado(逸动); Eado DT(逸动DT) 18~
10-1263		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	24545318	BAOJUN(宝骏) 630 14~16
10-1265		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	B3110430100	CHANA(长安) CS15 16~
10-1266		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	C3010530100	CHANA Raeton CC(长安睿骋cc) 17~
10-1267		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	5205010BS01	CHANA Alsvin(长安悦翔) 18~
10-1267A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	5205010BQ01	CHANA(长安) CS35 Plus 19~
10-1268		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	5205010BN01	CHANA Eado(长安逸动) 18~
10-1356		V 12V W 50 RPM.L 45? RPM.R 65?	7520006AAF0000;23936071;7520005ARD0000	Trumpchi(传祺) GA3,GA3S,GS4 宝骏560 15~18 广汽埃安S
10-1356A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	S185205010AB;S18520511AB	奇瑞 瑞麒X1;瑞麟M1

10-1370		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		ZOTYE(众泰) 2008
10-1371		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		ZOTYE(众泰) Z100
10-1372		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		ZOTYE(众泰) Z200
10-1373		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30		ZOTYE(众泰) Z300
10-1374		W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	6020016300;SA1267340Y	GEELY EMGRAND(吉利帝豪) EV350; EV450 HAIMA(海马) SC00;S5
10-1374B		W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	6600041925	GEELY(吉利) 博越 18~ PROTON X70
10-1375		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		ZOTYE Domy(众泰大迈) X5
10-1375A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		ZOTYE(众泰) E200
10-1376		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	EG3741100;EG3741100A C1;T215205111;03902430 20;0390243054;	BYD(比亚迪) F6;G5;G6;S6;秦;唐;速锐;思锐 CHERY Tiggo5 14~(奇瑞瑞虎 5,凯翼X5)
10-1376A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	HAD3741100;0390243630; 0390243670	BYD(比亚迪) 秦Pro 燃油;秦Pro DM,秦Pro EV,秦PLUS DM-I; 汉 EV;汉 DM;E9;汉 DM-I;汉 EV创世版;汉 EV千山翠


10-1377		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25		ZOTYE(众泰) T700
10-1377A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25		ZOTYE(众泰) T300
10-1393		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	T115205011	CHERY Tiggo3(奇瑞瑞虎3)
10-1456A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	3810052S10;7520006BAC0000;7520006BAD0000	Trumpchi(传祺) GS5 12~15 SUZUKI New Carry
10-1636B		W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	288102FK0A;288102FK0B	VENUCIA(启辰) R30 14~16
10-1641A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	CB076737XGL2;CB076737XGL2A;CB0767340BL1;CB0767340Y	HAIMA Premacy(海马普力马) 08~15
10-1702		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	M125205111BA	CHERY A3(奇瑞A3两厢)
10-1725		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	6020003500;W000068527	GEELY(吉利博越) 16~17
10-1725A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	5205110XSZ08A;W000055119	GREAT WALL HAVAL(长城哈弗) H2 14~18
10-1752		V 12 W 40V RPM.L 40±7 RPM.R 60±7 N.m ≥25	5205080MH	红旗H7

10-1752B		V 12 W 40V RPM.L 40±7 RPM.R 60±7 N.m ≥25	SA3F3741100;039024366 1	BYD(比亚迪) 宋PLUS; 宋PLUS EV; 宋PLUS DM-I
10-1756		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	M115205111BA;SA374110 0A;0390241582	BYD(比亚迪) 宋 CHERY A3(奇瑞A3三厢) ZOTYE(众泰) T600
10-1756A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	0390243642	理想ONE 2020~
10-1781B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30		GEELY(吉利帝豪) FE-7 GS 16~
10-3245		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	C5ZD020DQ0;E5ZD020D Q0;0390243245;03902432 54;0390243264	CHANA CS55;CS75(长安 CS55;CS75) GEELY(吉利) FE-5 GL 16~
12-1002		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	KKY0167350;KKY0167350 A;PW537049;1592005380	KIA Pride(起亚普莱特) PROTON Perdana
12-1012A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	94961186;96960684;56961 186;66961186	DAEWOO Damas 04~19; Labo 04~19; KA21
12-1038A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	96569642;96314772	DAEWOO Matiz 98~ CHEVROLET Sprak(雪佛兰 乐驰) 05~
12-1073		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		INDIA
12-1073A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	PW850686;PW854157;F0 0S2A2285	PROTON Waja MMC; Waja Campr

12-1073B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9810022120;9810022100;9810029000;9810025000;9810022000;F00S2A2378;F00S2A2092;434403;854403	HYUNDAI Accent 97~05; Elantra 96~00; Tiburon 97~01 DODGE(Mexico) 2004 KAI(起亚) 千里马
12-1080		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	96303118	DAEWOO Lanos 97~19
12-1081		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	0K2AA67350;0K2AA67350A;0K2AA67350B;0K2AA67350C;434452	KIA RIO 01~05; Sephia 00~01; Spectra 00~04
12-1100		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	HYS100	HYUNDAI SANTRO
12-1106		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	96100626;96175535	DAEWOO Cielo; Espero 91~99
12-1107		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	96540501;96415083;401056	CHEVROLET Aveo 05~08 DAEWOO Kalos 05~08
12-1258		V 12V W 50 RPM.L 455±7 RPM.R 65±7 N.m ≥30	981102K000;4345009;8545009	KIA Soul 10~13
12-1260B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981101J000	HYUNDAI i20 08~
12-1261B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	981101J900	HYUNDAI i20 08~15(RHD)

12-1262		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	981004N900	HYUNDAI i10 15~(RHD) EON
12-1264		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	981004N000;981104N000	HYUNDAI i10 15~
12-1352		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	K71067345B	KIA Besta 92~95 KAMCO
12-1438C		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981100C000;981100W000 ;1593002270	KIA Cerato(起亚赛拉图)
12-1468		V 12V W 30 RPM.L 42±7 RPM.R 65±7 N.m ≥20	98110F0000;1593007820	HYUNDAI Elantra(现代领动) 16~19
12-1616		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9811002000;9811002100;9 810002100;9811002900	HYUNDAI Atos 00~09
12-1623		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	98110B5000	KIA(起亚) K3 12~17
12-1626		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981104D000;F00S2A2518; 434526;854526	HYUNDAI Entourage 07~08 KIA Sedona 06~14; (起亚)QV 11~13
12-1631		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	981100Q100	HYUNDAI(现代) Elantra(悦动) 10~16; 伊兰特EV 17~
12-1632		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	981100U000	KIA(起亚) K2; 瑞纳 10~16; 瑞奕 14~16

12-1633		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30		HYUNDAI(现代) IX25 15~19; Sorento(索纳塔8) 11~15 KIA Forte(起亚福瑞迪) 09~16; Sorento 11~15
12-1633A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	98110A1000;1593003781	HYUNDAI(现代胜达) IX45 13~17
12-1634		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	98100D0000;98100F9000; 98100H2000;98110H6000; 98100J4000;98100Q2000; 98100S3000;98100S4000; 98100S6000	HYUNDA(现代) Elantra(悦动) 17~23; Verna(悦纳) 17~23; IX35 18~ KIA(起亚) Forte(福瑞迪) 18~22; K2 18~; Sportage(起亚智跑) 18~21 瑞纳 18~
12-1635		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981102E000;981101F000; 981001F000;9811007000; 981101H900;981101Y000; F00S2A2515;434516;8545 16	HYUNDAI(现代) Azera(雅尊) 06~11; Veloster(飞思) 12~14; Tucson(途胜) 05~09 KIA(起亚) K5; Optima 11~13; Picanto 04~20; Sportage(狮跑) 05~10
12-1636		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981100X910;981102S000; 981000X912;4345013	HYUNDAI(现代) i10(RHD) 07~13; IX35 10~15; Tucson(途胜) 10~17
12-1637		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981100X000;981500X000	HYUNDAI i10 07~13
12-1637A		V 12V W 30 RPM.L 42? RPM.R 62?	981101V900	HYUNDAI(RHD) Verna Fluidic
12-1638		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981001M000;981101M000 ;981102H001;981103S000 ;98110B2000;4345008;854 5008;	HYUNDAI(现代) Azera 12~17; Elantra 2008; Sonata(索纳塔) 13~15 雅尊 11~15 KIA (起亚) Forte 10~13; Forte5 12~13; Soul 14~18; Soul EV 15~18 速迈 10~13

12-1639		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981101G000;981102B000; 981102G000;981102M000; 434465;854465;	DODEG Attitude 06~11 HYUNDAI(现代) Accent(雅绅特) 05~10; Genesis Coupe(劳恩斯-酷派) 11~16; SantaFe 07~09 KIA(起亚) Magentis 07~10; Optima 07~10; Rio(锐欧) 06~11; Rio5 06~11
12-1639A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981102F000;981103K000; 434462	HYUNDAI(现代) Sonata(御翔) 05~10 领翔 09~ KIA(起亚) Cerato(赛拉图) 05~08; Spectra 05~09; Spectra5 05~09
12-1641		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	981102D101;981102D200; 434409	HYUNDAI Elantra(伊兰特) 00~06
12-1642		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	98100A2000;981001H000; 981001Z000;98110A2000; 981101H000;981102W000 ;981103W000;4345026;85 45026;	HYUNDAI(现代) Elantra 09~13; I30 07~12; SantaFe(胜达) 13~18 格越 13~17 KAI Ceed 06~12; Sportage(起亚智跑) 11~15
12-1643		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	9811038100;9811038200;9 81103C100;F00S2A2142;4 34510	HYUNDAI(现代) SonataIV(索纳塔) 98~04; SG300 2001; SG350 02~04
12-1644		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	981104F000	HYUNDAI H100 93~00; Porter 94~04
12-1645		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	981003X000;981103X000; 98110A7000;981101D000; 434537;854537;4345031;8 545031;	HYUNDAI Elantra 11~16 KIA Forte 14~18; Rondo(起亚佳乐) 07~11
12-1646		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	981003E000;981003E100; 981103E000;035247410;0 35247430;434464;854464;	KIA Sorento(起亚索兰托) 03~09

12-1647		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	981003E900;035247420	KIA Sorento 02~13(RHD)
12-1647A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	9811038500;9811038501;981103A000;981103C200;035417390;434457;434515;854515	HYUNDAI(现代) 名驭 09~ Sonata(索纳塔) 05~08; Trajet 01~08; XG350 2005 KIA(起亚) Magentis 01~06; Optima(远舰) 01~06
12-1647B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	PW897217	PROTON Exora
12-1648		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	981001W000;981101R000;981101W000;4345041;8545041;	DODGE Attitude 12~14 HYUNDAI Accent 12~17 KIA RIO 12~17
12-1648A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981004H000;981104H000	HYUNDAI H-1(现代H-1辉翼) 08~
12-1649		V 24V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20		Poong Sung
12-1649A		V 24V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20		Poong Sung
12-1754A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	98110B4000;98100B9000;F00S282807	HYUNDAI i10 13~17
12-1758A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	98110C5500	HYUNDAI(现代) Encino(昂希诺) 18~; Lafesta(菲斯塔) 19~ KIA 索兰托 18~ KX3傲跑 20~21 焕驰 19~


12-1943E		V 12V RPM 30? Angle 135?	9870026000;434514;854514;	HUATAI(华泰圣达菲) HYUNDAI Santafe 01~06
12-1943F		V 12V RPM 30? Angle 135?	987003E000; 434522;854522;	KIA Sorento 03~09
12-1943G		V 12V RPM 35? Angle 165?	987102B000;987102B500; 434597;854597	HYUNDAI Santafe 07~12
12-1958C		V 12V RPM 30? Angle 169?	987102L100;4345007;8545007	HYUNDAI Elantra 09~13
12-1974		V 12V RPM 25? Angle 162?	987003J000;F00S2B4050; 434574;854574	HYUNDAI Veracruz 07~12
13-1008A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	SR0590504771;38101M79110;38100M79130	SUZUKI 800 Van
13-1008B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		SUZUKI 465 齿轮轴比KK-1008A长5mm
13-1008C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		SUZUKI
13-1010		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	3810179050;TIY275;HC111825	SUZUKI ST100 90~1.3,1.5(RHD)
13-1013		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	BL5767350A	FORD Lanse 88~ MAZDA 323 FWD P3 86~

13-1013A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	TG1592003131;HC111853 ;	MAN PICK-UP 3.0 99~(RHD) MAZDA B-Ser 2.0 99~(RHD)
13-1013B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MB06007A;HC111314;	MITSUBISHI Delica 2.0 90~95
13-1013C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MR109451	MITSUBISHI L200 98~06 K74(RHD)
13-1022		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		SUZUKI Alto(铃木奥拓)
13-1022A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	38100M84030;TIY278	SUZUKI 800 Car; Escudo
13-1024		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9397041061	NISSAN Pick-Up D21
13-1028		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MBE41843;MBE41135	MITSUBISHI Delica L300B,L300D 1.5 82~86
13-1028A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MB543839;MBC1508;HC1 11902	MITSUBISHI Delica L300 1.5 84~86 (RHD)
13-1028B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MBE41136;MB543840	MITSUBISHI Delica L300 85~
13-1030		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	28810HG032DY;TIY280	NISSAN BE40 Parts; 1400 Late

13-1031		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MBE88107	mitsubishi L111 PS-100(OLD)
13-1031B		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	HC222802;MBE88929	MITSUBISHI FE111,FE119 6.8T 92~(RHD) PS-100
13-1034		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	38410SB2732;MS10246304	HONDA Civic V2000 1.5 84~88 HONDA 87-Flip Up
13-1035		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		NISSAN Skyline Early Sentra
13-1035A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	2881060A00;TIY205	NISSAN Blue Bird 2.0 85~; V30 3.0 98~(RHD); Datsun Sentar 86~90; Sentra 1.6 92~(LHD)
13-1037A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	HC111932	MITSUBISHI Colt 3.0 87~95 (RHD)
13-1037B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MR192056;MR221974;434201;854201	MITSUBISHI Mirage 97~02; Montero sport 97~04
13-1037C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MB623285;431119	MITSUBISHI Montero(三菱帕杰罗V31,V32,V36,V46) 92~00
13-1040		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	28810BP640Y;TIY279;NSJ1514	NISSAN E20 1800 L18 81~
13-1052B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	85110BZ040;1592008401	VAUXHALL Vivi

13-1037		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MR155342;3810172A00;1592000960	TOYOTA Pick-Up 3.5 86~94; Bu9.5 3.5T 90~(LHD) MITSUBISHI Mirage 1.5,1.6 97~; Colt Ldv L300; Pajero Mini 660 H56A
13-1041		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	TYH3518;HC1107	TOYOTA Hiace Y-SER 84~; YH50 3.5T 90~
13-1041A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	HC122842	SOUTH AFRICA
13-1052C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511026080;ASMO.8492000881	TOYOTA Hiace(丰田海狮) 05~14
13-1058		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	2881003W00;TIY204;NSH2508	NISSAN Datsun 720 80~85
13-1067		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	3810177500	SUZUKI T120SS MITSUBISHI Futura
13-1078		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	2881002A00;TIY202	NISSAN Datsun BE1
13-1078A		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	894166957;894110123A;8941218100;HC213801;HC213803;HC223812B	ISUZU Npr 8.8T 84~

13-1070		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	3810160A20	SUZUKI Escudo; Maruti 800; Vitara
13-1071		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	851100B010;8511087604; 851208712001	DAIHATSU Taft Gt(F70) 85~95 TOYOTA Kijang 7K 96~07; Zace 1.5,1.8 1988
13-1072		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MR221315	mitsubishi Kuda Tahun 00~05 TOYOTA Tercel 1.3,1.5 95~; Camry 88~91 (RHD)
13-1073D		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	PW851711;3113503201	PROTON Gen2
13-1077		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511095187	TOYOTA Kijang 4K KF20
13-1083		V 24V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	MC853952;1591005790	mitsubishi FUSO FU,FV;20T,35T(LHD) 84~
13-1088		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8978550114;8973613731	ISUZU NHR55; NHR69
13-1088A		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8978550120;8978550122;8 973613740;8973613741	ISUZU NKR58; NKR66; NKR71
13-1089		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	851201510B;851201540B; 8490509821;HC2228101	HINO 500(RHD) 15T-17T 03~
13-1091		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511090P00;8511090100; TIY284	TOYOTA Kejan(RHD) KF 40 / 50 5K

13-1092		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	851100B040;SR15920040 21	TOYOTA
13-1093		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511090951;TIY245	TOYOTA Kejan;Zace
13-1098		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	85110BZ010	TOYOTA Avanza 06~
13-1098B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	85110BZ150;85110BZ151; 1592009470	DAIHATSU Xenia TOYOTA Avanza 11~14
13-1098C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	85110BZ060	TOYOTA Rush 06~17; Terios 06~17
13-1099		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MK461340;0590508304	MITSUBISHI Canter PS 110T,125T
13-1101		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9397041062;F006B20011	NISSAN Tsuru 93~04
13-1102		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9390041102;F006B20000	NISSAN Pick-Up 79~84
13-1103		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9390041107;F006B20001	NISSAN Datsun 79~84; Tsuru 84~86
13-1105		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	BL6767350	MAZDA 323 86~87 ISUZU Panther 2.0 / 2.2 96~ FORD Lanser 1.3 / 1.5 88~89 MAN Pick-Up 3.0 99~(RHD)

13-1105A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8943682300	ISUZU Panther 2.3 / 2.5 00~21
13-1112		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		ISUZU 81~88
13-1115		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	F004039001;SDK18619	TOYOTA Hilux 04~12 SUZUKI CHANGHE Iiana A6(利亚纳A6)
13-1118		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511010210;HC111819	TOYOTA Surf 1.8,2.4 99~ KF60 (RHD)
13-1118A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		897505 TBWIPER 3#
13-1118B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	851100B050A;9390692115	TOYOTA Hilux RN-SER
13-1119		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	3811062L00	SUZUKI Alto(长安铃木奥拓)
13-1120		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	85110BZ090001;85110BZ 091;85110BZ180;AE15093 001700;1593001730;15930 03571	DAIHATSU Grandmax 07~; Luxio 09~ HONDA type 2 SUZUKI Swift TOYOTA Corolla EX 02~05; Innova 04~16; Rush 07~16; Terios 07~16
13-1120A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	FC016737X	MAZDA M6(马自达6) 奔腾 B50,B70

13-1126		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥20	WM3	SOUTH AFRICA
13-1132A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		ISUZU Pick-Up 3.5T 87~90
13-1132B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		ISUZU Tfr 8.8T 91~98(RHD)
13-1132C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		CHEVROLET LUV 91~98 ISUZU Late 98~
13-1136		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		SUZUKI Wagan r(RHD)
13-1137		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		SUZUKI Alto W/R
13-1150		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TOYOTA Venture
13-1151		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TOYOTA Venture
13-1212		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		ISUZU WFR
13-1237		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	2881501G00;2881503G00; 2881557G00;28815S3800; 28815S3801;28815S3802; 431237	INFINITI M30 90~92 NISSAN D21 86~02; Pathfinder 87~95; Pickup 85~04

13-1242		V 12V W 40 RPM.L 42±7 RPM.R 68±7 N.m ≥25	2881013E10;288103S500; 2881040F00;2881061E00; 2881085E11;2881086E00; 2881086E11;28810D4710; 431242	NISSAN 240SX 89~94; Frontier 98~04; Maxima 89~94; Stanza 89~92; Xterra 2000
13-1251A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	3810062J0000;3810063J0 000;3811077J00000;53562 502	SUZUKI Swift(铃木雨燕) 05~13
13-1312		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8512090306;8512090800;8 512090806;8512090812;85 125D0800;ASMO.8590502 650	TOYOTA FJ Cruiser 80~84 (RHD)
13-1313		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8512090802;B590502630	TOYOTA Land Cruiser 81~82
13-1313A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511090303	TOYOTA FJ40 75~84
13-1317		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	288102W600;288107J101; 288109Z400;434363;4343 17854317	INFINITI G20 2002; QX4 01~03 NISSAN Frontier 01~04; Pathfinder 01~04; Xterra 01~04
13-1317A		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	288104B000;434305	NISSAN 200SX 95~98; Lucino 96~98; Sentra 95~99
13-1318		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	2881065Y00;TIY247	NISSAN Sentra(NEW)
13-1318A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	0155627B;8155634B;8980 576220;89736436900	ISUZU D-Max 06~16(RHD)

13-1253		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		NISSAN Sentra MK 1 &2
13-1253A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		NISSAN Big-M
13-1255		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	GA2976345	MAZDA 323 FWD 81~85
13-1307		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	28805J1705	NISSAN
13-1307A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		NISSAN
13-1307B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	28810J1700	NISSAN Z24
13-1320		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8507037220;0590508510	TOYOTA Dyna 125 6.5T 01~
13-1320A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	850700W030;0590509051	TOYOTA Dyna 130
13-1346		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	288009N00A;28800JA000; 28800JBE00;434346;8543 46;	NISSAN Altima 07~13; Maxima 09~15
13-1350		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511087Z03000; TG0590508190	PERODUA Kembara

13-1350A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8512087Z10000;TG059050849A	PERODUA Kelisa
13-1350B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	3810161J00;0590508791	SUZUKI APV 04~
13-1350C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8512087618	DAIHATSU Taruna 99~07
13-1353		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	PW500030;TG0590508470	PROTON Saga
13-1354		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	HC111818	NISSAN Sunny 720 1.6 84~88(RHD)
13-1366		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		HONDA(RHD) City 03~07; Fit
13-1366A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	3810058J00	SUZUKI Wagon R K 2003(RHD)
13-1366B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		HONDA type 3(RHD)
13-1366C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	PW865761	LOTUS Savvy PROTON Saga
13-1366D		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	76505SELT02	HONDA(RHD) City 03~07; Fit

13-1405A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	8511006030;8511033160;8511033220;8511033270;8511042120;8511042130;8511052240;8511053030;85110AA030;85110AA050;85110AE010;432015;852015	LEXUS(雷克萨斯) ES300 97~03; ES330 04~06; IS300 99~05; SCION XB 04~06 TOYOTA(丰田) Camry 01~06; RAV4 00~06; Sienna 04~10; Solara 99~08
13-1405B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	76505SZTG01;76505TE0A01;76505TE0A02;76505TK6A01;76505TM8A01;434081;854081	HONDA(本田) Accord 08~12; CR-Z 11~16; FIT(飞度) 09~14; INSIGHT 10~14 SUZUKI Kizashi(铃木凯泽西)
13-1405C		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	3810065J00;8250A057;851100E020;8511047240;8511050140;8511058090;TD1167340; TD1267340;434105;434053;854053;98110C3000;AC1593004790	HYUNDAI Elantra(索纳塔) 15~18 LEXUS HS250H 10~12; LS460 07~14; LS600H 08~14; RX350 10~14; RX450H 10~14; MAZDA(马自达) CX-9 07~14; MITSUBISHI Eclipse(三菱 伊柯丽斯) 06~12; SUZUKI Grand Vitara 07~13 TOYOTA Corolla 07~13(RHD) Prius 10~13
13-1405E		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	85110BZ131;1593004741	PERODUA Alza
13-1406		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	8511002570;8511012C30;8511002440;39204667;HX1590608642	BUICK Regal(别克君威) 18~; Toyota Corolla 19~22; Levin 19~23
13-1410		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	76500TG2K010;76500TG2K111;76505TG4K01	HONDA Brio 12~17; Mobilio 12~; BRV 16~; HRV
13-1411		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	76505SAP004	HONDA Life Dunk 2000(RHD)

13-1412		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TOYOTA Condor AE80(4XHOLE); Hilux Cmry ~94
13-1412A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511005800;TYE8509;939 0692112;9390690262	TOYOTA
13-1412B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9390692113	MITSUBISHI Col 3.0 96~
13-1413		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	38101775500	SUZUKI SL413
13-1415		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TOYOTA Corolla EE 90~92(3 HOLE MTG)
13-1417		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511052060;1592003981	TOYOTA Yaris 99~05
13-1418		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	MR388037;8511016650;A SMO.8492007341;159200 2301;432053;852053;4342 17	MITSUBISHI Montero(三菱帕 杰罗) 01~06 TOYOTA Tevcel 97~99; Paseo 98~98
13-1418A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511004010;8511004020;8 51100C010;851100C020;8 511016660;8511016670;M R192794;432026;852026	MITSUBISHI Galant 99~03 TOYOTA(丰田) Hilux 2004; Sequoia(红杉) 01~07; Tacoma 98~04; Tundra 00~06
13-1418B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511060290;8511060300; 432035	LEXUS(雷克萨斯) LX470 98~07 TOYOTA Land Cruiser(丰田 兰德酷路泽) 98~07

13-1419		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511090K08;8491003892	TOYOTA Land Cruiser 84~90
13-1419A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	UH7167340A	FORD Ranger 06~11
13-1421		V 12V W 60 RPM.L 42±7 RPM.R 62±7 N.m ≥35	85110AA010;432012	TOYOTA Camry 97~01
13-1423		V 12V W 30 RPM.L 42±7 RPM.R 65±7 N.m ≥20	851100E060;851100E080; 1595006182	TOYOTA Highlander(丰田汉兰达) 14~16
13-1423A		V 12V W 30 RPM.L 42±7 RPM.R 65±7 N.m ≥20	851100D190;851100K201; 8511052620;1593004114;1 593004134	TOYOTA 4Runner 15~; Fortuner 15~(RHD); Hilux 15~(RHD); Yaris 12~17
13-1423B		V 12V W 30 RPM.L 42±7 RPM.R 65±7 N.m ≥20	85110BZ230	TOYOTA Avanza 15~; Xenia 15~
13-1425		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511060180;8511060181	TOYOTA Land cruiser 93~ 06(RHD)
13-1425A		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TOYOTA(RHD)
13-1426		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511060201;8511060202	TOYOTA Land Cruiser 93~ 06(LHD)
13-1427		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	76505TK8A01;76505TK8A 02;434078	HONDA Odysser 11~17

13-1428		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	76505SR1A05;76574S01A 07;431428;851428;	HONDA Civic 92~95; Civic 97~00
13-1429		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511012810;8511002040; HC122819;432027	TOYOTA Corolla 1.6,1.8 93~02
13-1429A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	8511012820;8511012830;4 31742	TOYOTA Corolla 93~97
13-1430		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	76505SFJW01	HONDA Odyssey(本田奥德赛 RBE) 05~08
13-1431		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	28810JN00A;28810JN00A BE21	NISSAN Teana 09~(尼桑天 籁)
13-1432		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	28815ED500;28800ED500 BE21;4343114	NISSAN Tiida 05~10(尼桑骐 达;颐达)
13-1433		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	6E5Z17508AA;851100K01 0;851100K011;851101A03 0;8511047100;851104719; 85110BZ031;8511060370; GJ6A67340;GJ6A67340A; GK2C67340;434417;85441 7	FORD Fusion 06~12 LINCOLN MKZ 07~12; Zephyr 06 MAZDA(马自达) 6 02~05 TOYOTA(丰田) Corolla 02~07(RHD); Prius(普拉多) 08~20(RHD); Hiace 05~14; Hilux 09~15 MERCURY Milan 06~11 PERODUA Axia
13-1433A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	8511006120;8511006150;8 51100D150;851100N020;8 51100T010;GP7A67340;G P7A67340A;PW951372;43 4481;854481;	MAZDA 6 06~08 TOYOTA Avalon 13~14; Camry(凯美瑞) 12~16; Crown(皇冠) 10~12; Venza(锐志) 09~15; Vios(威驰,威驰FS) 14~21; Yaris(致炫) 12~16; Yaris L(致炫,致享) 17~18 Venza(威飒) 13~ PROTON Suprima

13-1434		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76505SNAA000M1;76505SNAA01;76505SNAA02;76505TM0T01;8250A156;28800EW700BE21;434034;854034;	HONDA Civic(思域FA1,C14) 06~11 NISSAN Sylphy(尼桑轩逸) 06~12 MITSUBISHI L200 05~15
13-1434A		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	28810EQ300;28810EQ31A;4343116	NISSAN X-Trail(尼桑奇骏) 05~07
13-1434B		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	8250A170;434231	MITSUBISHI Lancer(三菱蓝瑟) 08~17
13-1435		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511014230;8511014232;8511016262;8511016370;8511016371;8511016420;8511016430;8511016460;8511032241;8511032242;8511032270;8511032271;8511035090;8511035100;8511035130;8511035280;8511089143;8511089144;431735;851735;	LEXUS ES250 90~91 TOYOTA 4Runner 89~02; Camry 87~91; Celica 1986; Paseo 1992; Pickup 89~95 Supra 86~93; Tercel 89~92;
13-1440		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76500S01999;76505S00A01;76505S00C01;76505S04G01;76505S04Y01;76505S5AA01;76505S5AA02;76505S5D999;76505S5DA01;434000;434026	HONDA(本田) CRV 97~01; Civic(思域里程) 96~05
13-1440A		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76505SR3A01;431423;HC1619A051	ACURA Integra 94~01 HONDA Civic 92~95; Civic Del Sol 93~97
13-1440B		V 12V W 40 RPM.L 44±7 RPM.R 68±7 N.m ≥25	76505SV4A01;76505SW5A01;WM72282S;53546602;431427;851427;HC1619A041	ACURA CL 97~99; TL 95~98 HONDA Accord 94~97
13-1436		V 12V W 60 RPM.L 42±7 RPM.R 62±7 N.m ≥35	8511007030;24011962;432036	TOYOTA Avalon 00~05

13-1437		V 12V W 30 RPM.L 42±7 RPM.R 65±7 N.m ≥20	3811078M00;1593006570	SUZUKI Alivio(铃木启悦) 15~
13-1438		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	5CA067340;5EA067340;851100K030;851100K060;851100K061;8511060430;8511035310;CC2967340A;C2967340B;GS3L67340	BESTURN(奔腾) B70; X80 LEXUS(雷克萨斯) GX460 10~18 MAZDA(马自达) 5 06~12; 6(睿翼) 07~13 TOYOTA(丰田) 4Runner 10~16; Hiace(海狮) 05~14 Hilux 05~12; Prado(普拉多) 10~18
13-1438A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	8511004040;8511008020;8511026210;8511053040;8511060390;8511060400;86510SC010;86510SC011CC3867340A;432054;852054	HYUNDAI SantaFe 10~12 LEXUS(雷克萨斯) IS F 08~14; IS250 06~15; IS350 06~15; LX570 08~16 SCION XB 08~15 SUBARU Forester(斯巴鲁森林人) 09~13 TOYOTA(丰田) FJ Cruiser(酷路泽) 07~14; Land Cruiser(兰德酷路泽) 08~16; Sienna 11~15; Tacoma 05~16
13-1438B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	8511002110;8511005060;851100D030;851100K020;851100K021;8511002260;851101A040;8511035290;8511035300;8511048070;8511060360;88969918;432050;852050	LEXUS(雷克萨斯) GX470 03~09 PONTIAC Vibe 03~08 SCION XA 04~06 TOYOTA(丰田) 4Runner 03~09; Avenis 03~08; Corolla(花冠) 03~08; Corolla(花冠) 14~19; Fortuner 2015; Hilux 05~15; Highlander(汉兰达) 01~08; Matrix 03~08
13-1440C		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76505S0XA02;76505S3VA01;76505S4KA01;76505S84A01;404013;854013;434025;854025	ACURA CL 01~03; MDX 01~04; TL 99~03 HONDA(本田) Accord 2.3(雅阁) 98~02; Civic 2001; Odyssey 02~04; Pilot 03~04

13-1440E		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	86511AE04A;86511SA010; 86511SA030;434506	SUBARU Baja 03~;
 Forester 03~04;
 Legacy 00~04;
 Outback 00~04
13-1441		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	28815EB400;28815EA000; 434338	NISSAN Frontier 05~08; Pathfinder 05~08; Xterra 05~08
13-1441A		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	28815ZL00A;28815ZL90B; 434396	NISSAN Frontier 09~22; Pathfinder 09~12; Xterra 09~15
13-1442		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	28800JD900;579751	NISSAN Qashqai(尼桑逍客) 07~
13-1442A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	288103DN01	NISSAN Tiida(尼桑骐达) 11~15
13-1442B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	28800CJ00AB064;545264 11;54526611;	NISSAN Livana(尼桑骊威) VENUCIA(启辰) D50,R50
13-1443		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	288101E300B064;M12551 53	NISSAN Altima(尼桑蓝鸟)
13-1444		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	2881057G00F301;520500 0	NISSAN D22;Paladin(尼桑帕 拉丁)
13-1445		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	288101H010	NISSAN(尼桑) March(玛驰)11~15; Almera(阳光)11~14
13-1446		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	288109W60A;28810CA00 0;434341;854341;	NISSAN(尼桑) Murano(楼兰) 03~07; Teana 05~07(天籁)


13-1447		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76505SMGE11;76505SMGE12;76505SHJA01;76505SWAA01;76505SWAA02;76505TA0A01;76505TA0A02;76505TM0Y01;76505TK4A01;80211B078;8250A125;8250A146;8250A206;434042;854042;434047;854047;34068;854068;434076;854076;	ACURA(讴歌) TL 09~14; TSX 09~14 HONDA Accord(雅阁) 08~12; Accord Crosstour 10~11; City(锋范) 09~13; Civic(思域) 06~11; CRV 07~11; CR-Z 14~15; Crider(凌派) 14~18; Crosstour(歌诗图) 12~15; Odyssey(奥德赛) 05~14; Pilot 09~15 Spirior(思铂睿)09~ MITSUBISHI(三菱) L200 06~ Lancer 07~17; 翼神 2014
13-1447A		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76505S9VA01;76505S9VA02;76505SDAA01;76505SDAA11;76505SJDG01;434028;854028;434032	ACURA MDX 05~06; RL 05~10; TL 04~08; TSX 04~08 HONDA(本田) Accord(雅阁) 03~07; Pilot 05~08
13-1447B		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76505SDNA01;1155665A;434027;854027	HONDA Accord 03~07
13-1447C		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76505S6MA01;76505S9AA01;7655S9AA01;434017;854017;	ACURA RSX 02~06 HONDA(本田) CRV 02~06
13-1447D		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	86511FE010;MR957879;434524;434229	MITSUBISHI(三菱) Lancer 03~07 SUBARU Impreza 02~03
13-1447E		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	28815AC500;32008786;76505STKA01;76505STKA02;86511AE074;86511AE07A;86511FE030;86511SA050;434054;434518;854518;	ACURA RDX 07~12 NISSAN 350Z 06-09 SAAB 9-2X 05-06 SUBARU(斯巴鲁) Baja 04-06; Forester(森林人) 05-08; Impreza(翼豹) 04-07; Legacy 2004; Outback 2004
13-1448		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	288005M000;288105M000;434316;854316;	NISSAN Sentra 00~07(尼桑阳光N16)

13-1449		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	288107Y000;288107Y005; 434331;854331;	NISSAN Altima 02~07; Maxima 04~08
13-1449A		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	28810AU310	NISSAN Primera 02~08
13-1451		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	28810AX700;4343112	NISSAN Micra 03~10
13-1452		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76505SAA011;76505SLNA 01;434058	HONDA Fit(本田飞度) 07~08
13-1453		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76505S04E01;76505S04Q 01;434015	HONDA(本田) Prelude 97~01; S2000(雅阁96款) 00~09
13-1453A		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76505SP0A01;76505SZ3A 01;431424	ACURA Legend 91~95; RL 96~04 HONDA Accord(本田雅阁2.2 CD420,CD520) 91~98
13-1454		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	288001AA0A;434393	NISSAN Murano(尼桑楼兰) 08~15
13-1462		V 12V W 30 RPM.L 40±7 RPM.R 60±7 N.m ≥20	MB249196;431162	DODGE Raider 87~89 MITSUBISHI Montero 83~91
13-1466		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	76505SENH01	HONDA Fit 03~08(本田飞度 思迪)
13-1466A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	PW867677;3114303200	PROTON Satria Neo

13-1456		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	288003TA0A;288003TA2A ;288004BA0A;288004CC0 A;288004CC1A;28800BM9 0A;288103TS0A;288104B A0A;288104CC0A;288104 CL0A;28810BM90A;43431 21	NISSAN(尼桑) Altima 13~15; Livana(骊威); Maxima(西玛)16~ Rogue 14~16; Qashqai(逍客) 15~; Teana(天籁) 13~15; X-TRAIL(奇骏) 14~
13-1458		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	76505T0AA01;434082	HONDA(本田) CRV(RM) 12~16
13-1458A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	76505T5AJ01;76505TG1T 01	HONDA(本田) Brio 13~17(RHD); Gienia(竞瑞) 17~; Vezel(缤智) 14~15; XR-V(XRV,RU1,RU5,RU6) 14~15
13-1458B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	MT11449001	HONDA
13-1459		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	288003SC0B;288003SG1 A;288103SG0A;4343122;8 543122;	NISSAN(尼桑) Bluebird(蓝鸟) 18~19; Sentra 13~19; Sylphy(轩逸) 12~17
13-1459A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	288004AA0A;288104AA0A	NISSAN Almera(G15) 12~18
13-1460		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	76505T2FA01;76505T3VA 01;434084	HONDA(本田) Accord(雅阁) 13~17 Spirio(思铂睿) 15~17
13-1461		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	288003JA0A;288003JA2A; 288105BC0A;288106CT0A ;4343123	INFINITI JX35 2013~; QX60 14~16 NISSAN Murano(尼桑楼兰) 15~19; Pathfinder 13~15; Teana 18~(尼桑天籁)
13-1455		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	765055SMA01;76505SZW A01;76505SZWJ01;76505 TR0A01;76505T0AJ01;434 080	HONDA(本田) Civic(思域FB2,FB3) 12~15; Fit(飞度FR1) 15~16; Elysion(艾力绅) 16~17; Jade(杰德) 13~17; Odyssey(奥德赛RC3)

13-1455A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	288152GE0A;76505T9AY01	HONDA(本田) CITY(思迪,锋范GM6) 15~19; Fit(飞度GK5) 14~20; Gienia(竞瑞GJ8) 17~ Greiz(哥瑞GJ6) 16~ NISSAN Sylphy(经典轩逸) 17~
13-1467		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	3810080J00;3810080J01;3811079J00;3811081K00;8250A178;8250A809;8250B137;8511002250;8511002270;8511002271;8511006060;8511006110;851100D080;851100E050;851100R010;851100R030;8511012A20;8511012B30;8511030590;8511033050;8511033330;8511042150;8511042190;8511050160;8511052310;8511052440;8511052510;86510FG010;86510FG011;86510FJ010;86510FJ011;86511FG010;86511FJ010;981004V000;98110B3000;EG2167340;EH1067340;432067;852067;	HYUNDAI(现代) Avante(朗动); Mistra(名图) 14~19 LEXUS ES350 07~12; GS350 08~11; GS450H 08~11; GS460 08~11 MAZDA(马自达) CX-7 07~12 MITSUBISHI(三菱) Outlander(欧蓝德) 07~22; ASX(劲炫) 11~12 SUBARU(斯巴鲁) Impreza(翼豹) 08~13; WRX 12~14; XV 2013 SUZUKI SX4(铃木天语) 06~12 TOYOTA(丰田) Camry(凯美瑞) 07~11; Corolla(花冠) 08~13; Crown(皇冠) 05~09; Matrix 09~13; Highlander(汉兰达) 11~13; RAV4 06~12; Yaris 06~11
13-1467A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	3811054G00;85110AA020;MR971835;432004;852004	MITSUBISHI Outlander 01~07 SUZUKI Aerio 02~07 TOYOTA Camry 97~00
13-1467B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	851102B040;851102B060;432038	TOYOTA Celica 00~05
13-1467C		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	76505TF0004;851100D130;851100D140;8511002240;8511002450;8511012A50;AC1593000255;AC1593001230	HONDA(RHD) FIT;Jazz 08~13 TOYOTA(丰田) Corolla 08~17(卡罗拉); Vios 08~13(威驰); Camry 06~11(凯美瑞)
13-1467D		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	3811056K00;1593001220	SUZUKI SX4(铃木天语)

13-1468		V 12V W 30 RPM.L 42±7 RPM.R 65±7 N.m ≥20	3811061M00;8511002350; 8511042190;851100K110; 86510SG010;86510VA010 ;86511AL02A;4320046	LEXUS NX200T 07~14; NX300 07~13; NX300H 07~13 SUBARU(斯巴鲁) Crosstrek 07~14; Forester(森林人) 08~14; Impreza 14; Legacy 07~14; Outback 07~13; XV Crosstrek 07~14 SUZUKI SX4 S-Cross(铃木锋 驭) 13~21 TOYOTA Corolla 07~13; Innova Reborn 15~; Rav4 14~18
13-1469		V 12V W RPM.L RPM.R N.m ≥	8511048120;1592007290; 4320020;8520020;	TOYOTA Highlander(丰田汉 兰达) 07~13
13-1507		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	HC1073	MAZDA Mrth Spec 91~
13-1509		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	TIY281	MAZDA G2 FORD Cour Maz B-Ser MAZDA B Series
13-1515		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		NISSAN 1400 Early
13-1516A		V 24V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	MB302224; 1591001182	MITSUBISHI PS120;PS135
13-1517		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	HC2028	MITSUBISHI Canter FE 6.8T 90~
13-1517A		V 24V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	183311053A	ISUZU Rocky


13-1551		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8512087532;ASMO.84905 05551;TIY276	DAIHATSU S65,S88,S89
13-1612		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TOYOTA Cress 86~
13-1612A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511087333	CHRYSLER delta
13-1620		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	76505SX8F	HONDA INDONESIA
13-1622		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	SR0590506621	HONDA
13-1723D		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	28800JD000;579754;5357 0202;54592597	NISSAN Dualis I J10, JJ10 07~13; Qashqai(RHD) 07~13
13-1724		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	TG1592001724;851100A0 10	TOYOTA Soluna
13-1756		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	288005JG0A ;0390243262	NISSAN(尼桑途达18~;纳瓦拉 17~)
13-1760		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511095A00;16600760;TI Y282;HC111817	TOYOTA Hiace RH20 2.5 90~
13-1857		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	TYE8507	TOYOTA Hilux 1-Tonn 98~

13-1859		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8511095427;K710673458	TOYOTA
13-1943		V 12V RPM 36? Angle 84?	8513020780;1592004272;432043;852043;	TOYOTA Celica 00~05
13-1943A		V 12V RPM 35? Angle 135?	8513048020;1592005572;432063;852063;	TOYOTA Highlander(丰田汉兰达) 01~07
13-1943B		V 12V RPM 35? Angle 163?	8513012840;1592006080;432049;852049	PONTIAC Vibe 03~08 TOYOTA Matrix 03~08
13-1943D		V 12V RPM 35? Angle 163?	85130AE010;432060	TOYOTA(丰田) Sienna 04~10
13-1945		V 12V RPM 36? Angle 173?	76710SWA003;434045	HONDA(本田) CRV 07~11
13-1945A		V 12V RPM 36? Angle 107?	76710TF0003;854067;434067	HONDA Fit(本田飞度) 09~14
13-1945B		V 12V RPM 35? Angle 163?	76700STXA01;434065;854065	ACURA(讴歌) MDX 07~13
13-1945D		V 12V RPM 35? Angle 165	76700TK8A01;434079;854079;	HONDA Odysser 11~17
13-1951		V 12V RPM 25? Angle 125?	8513035080;2596000183;432051;852051;	TOYOTA 4Runner 03~09

13-1951A		V 12V RPM 25? Angle 125?	8513034010;1592004661;432062	TOYOTA Sequoia(丰田红杉) 01~07
13-4360		V 12V RPM 30? Angle 172?	28710ED500;28710EL000;434360;53027012;434385	NISSAN(骐达, 骊威, 俊逸, 逍客) Rogue 07~13; Tiida 08~11; Versa 07~13; Livana; Geniss; Qashqai
13-4363		V 12V RPM 35? Angle 160?	287104BA0A;287104BA0C;287105483R;582602;431237	Nissan Qashqai(逍客) 13~20; X-Trail(奇骏) 13~20 RENAULT Captur 13~21
13-453A		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	288001LA0A;28810JH10A	INFINITI QX56 11~13 NISSAN X-Trail(RHD)
15-1019		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	171955113AX;191955113;191955113A;191955113AX;251955113;251955113A;251955113C;251955119;251955119C;252955113A;252955113C;281955113;281955113C;282955113;282955113C;321955113;321955113F;321955113G;321955119A;443955113C;533955113A;533955113AV;533955113AX;533955113C;533955113X;867955113;867955113A;868955113;868955113A;96462812000;0390241094;431834;851834;	VW(大众) Derby 77~84; Fox 87~93; Golf II 83~92; Jetta II (捷达) 84~12; LT 28-35 75~96; LT 40-55 75~96; Passat 80~88; Polo 75~99; Quantum 82~88; Santana(桑塔纳) 81~04; Scirocco 80~92; T3 79~92; Vanagon 80~91
15-1019B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	1C0955119;1C1955113B;1C2955113B;1H0955119;1H1955113;1H1955113B;1H1955119;1J0955119;1J1955113;1J1955119;1J2955113;1L0955023;1L0955023A;1L0955119;357955113;357955113A;357955113B;358955113A;3A1955113;535955119;535955119A;535955119C;6K0955119;6N1955113;6X0955119;701955113;701955113A;701955113B;702955113;702955113A;702955113B;404242;064052203010;TGE522CM;431835;851835	AUDI A3 96~03 SEAT Leon 99~06; Toledo II 99~06 SKODA Octavia 97~10 VW Beetle 98~10; Bora 98~05; Cabrio 95~02; Corrado 88~95; Eurovan 93~03; Golf III 91~99; Golf IV 97~06; Jetta 93~01; New Beetle 98~10; Passat 88~97; T4 90~03; Vento 91~98

15-1003		V 12V W 40 RPM.L 42±7 RPM.R 60±7 N.m ≥20	6202001	AGIR HiZMET FORD Cargo Tractor
15-1003A		V 24V W 40 RPM.L 42±7 RPM.R 60±7 N.m ≥20	6202003	AGIR HiZMET IVECO FORD Cargo Tractor
15-1004		V 12V W 40 RPM.L 42±7 RPM.R 60±7 N.m ≥20	6201006	MAN Magirus
15-1004A		V 24V W 40 RPM.L 42±7 RPM.R 60±7 N.m ≥20	6201008	MAN Otoyol
15-1007		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		OPEL Monza Kdtt
15-1019A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	BCA955113;9390692050	VW Golf 1.6 86~92(RHD)
15-1020		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	C95656573	CITROEN Fukang(东风富康)
15-1023		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	BASKURT.50032610	BMC Leyland Tm 30 1.8,3.0
15-1026		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	811955113F;9390041114	VW Combi 1800 87~98
15-1026A		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	BASKURT.50032515	BMC FATIH PROFESYONEL

15-1027		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	BASKURT.50032510	FATİH YENİ MODEL
15-1032		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	RSM845	FIAT Dogan Slx
15-1032A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	64342394;TGE423MK4	FIAT Slx(NEW); Dogan Kartal-Sahin 1600 YM
15-1032D		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	64357031	RENAULT R12 94~
15-1032E		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	7984515;0390246314;0643 42801010;TGE428A	IVECO Daily I 78~89; Daily II 89~99
15-1032F		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	0038208142;A0038208142 ;403411	MB Trac Unimog U405,U425,U436,U437
15-1032I		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8961573;064355701010;T GE557A	IVECO 625N,645,650,662,682,693 65~75
15-1032I- 1		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	2103037300000;210303730 00000	LADA 2104,2105,2106,2107
15-1032J		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		ALFA ROMEO Giulia Saloon 105-Series 64~74
15-1032L		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9937361;64300106	FIAT 131 T.T. 85~ LADA

15-1032M		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	64342392;TGE423MK2	RENAULT R19
15-1032ML		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		(2号铝头)ALGERIA
15-1032MR		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		(3号铝头)ALGERIA
15-1032N		V 24V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	ITG31	
15-1032P		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	64357002	PEUGEOT J9
15-1032R		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	64357001;TGE570A	RENAULT R12
15-1033		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		OPEL Kdtt TT 84-D
15-1045		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	640522	PEUGEOT 405 Parts IRAN
15-1054		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	640513	PEUGEOT 504 EGYPT
15-1055		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		PEUGEOT 504

15-1079		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	851100F900;9390692092	TOYOTA Corolla AE110,AE111 80~95
15-1086B		V 24V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	ML35113;2R2955113A;	VW 13180 15180 17250 19370 24250 25320 25370 26260 31260 19320 31320 31370
15-1032C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	5103561AA;5103561AB;5103870AA;0048206542;A0048206542;2D1955119;0390241345;403044	DODGE Sprinter 2500,3500 03~06 FREIGHTLINER Sprinter 2500,3500 03~06 MB Sprinter 95~06 VW LT 96~06
15-1116		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9397041092;F600FA4004;F006B20019	MB LL W; S163 MOD97 VW Golf 93~98; Jetta A3 93~98; Jetta A4
15-1116A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	1J1955023A;1HM955113;1HM955113A;1HM955113C;1638201042;A1638201042;9397041101;431836;851836;	MB ML320 1998 VW Cabrio 98~99; Golf 94~99; Jetta 94~99
15-1117		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	17S955113 ;HC122832;9390692103	VW Golf 1.6 87~(RHD)
15-1125		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	HC122924;9390692109	OPEL Astra,Corsa 1.4 94~00(RHD)
15-1125A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	90341903;SWF.403865	OPEL Astra 1.6
15-1125B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	1270013;1270027;22115459;22115488;22117108;22084020;220884020	OPEL Vectra A 88~95; Omega A 91~93

15-1125C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		OPERL Corsa Gamma
15-1125D		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	1273027;1273061;2300082 6;90512668;9117536;9117 722;9149882;0390241141; 0390241142;0390241182;0 390241512	OPEL&VAUXHALL Astra G 98~09; Vectra B 96~01
15-1125E		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	1270000;23001269;230017 43;23001902;23002736;23 002751;24441422;9149823 2	OPEL&VAUXHALL Combo 01~; Corsa C 00~09; Corsavan 04~; Tigra 04~
15-1125G		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	1270039;1270041;1270232 ;22084745;22085493;4010 037;8510037	CHEVROLET Chevy 96~12 OPEL Astra F 98~01; Corsa B 93~00
15-1125H		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	09003138	BUICK Sail(赛欧) 01~08
15-1131		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	8D2955113;8D2955113A;8 D2955113B;0390241131	AUDI A4 94~01 VW Passat Estate 97~01
15-1133		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	1BM955113B;9397014106 5;F006B200012	VW Sedan 1600 93~; Beetle(NEW)
15-1301		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	6405F8;6405J0;579224;03 90241360	PEUGEOT 206 93~97
15-1301A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		Peugeot 306 93~02

15-1302		V 24V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥20	6202004	ISUZU
15-1311		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	7701030692;7701349770;0390246310	RENAULT R9 81~88; R11 83~88; Rapid 85~98; Super 5 84~96
15-1311A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	6405J5;9642127580;64343297	PEUGEOT Partner 98~02
15-1315		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	64342391	RENAULT R9;R11
15-1316		V 24V W 30 RPM.L 16? RPM.R 22? ANGLE 93?	50032309	Bi?er D?ver - ?? Mak. Silgi
15-1316A		V 12V W 30 RPM.L 16? RPM.R 22? ANGLE 93?	50032308	Trakt?r Kabin Silgi MOTORU
15-1390		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	10099111	ROEWE (荣威) RX5 16~20 MG(名爵) 锐腾 15~17
15-1391B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	DLB90157B	ROEWE (荣威)750 06~11
15-1395		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	28800JY40A	RENAULT Koleos(科雷傲) 17~
15-1433		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	LR033035;CPLA17500AC;1590604644	LAND ROVER Range Rover(路虎揽胜,揽胜运动版) 13~17

15-1467E		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	05182430AA;68093039AA; 1590603900	FIAT 500 12~17
15-1392		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	1270343;10374584;132273 92;13277078;25790521;25 892085;401072;851072;	BUICK(别克) Allure 2010; Lacrosse 10~16; Regal(君威) 11~17 CADILLAC DTS 06~11 OPEL Insignia 08~12
15-1518		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	F006WM0308;9390082053 ;9390453024	MB LS1935 1924 1932 1933 1934 LS1932 1929 1930 SCANIA Onibus K113
15-1518A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	3458247201;A3458247201 ;9390453023;9390082052	MB 912 1113 2213
15-1518C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9390082070;9390453019;9 390453050;TAC955113	VW Delivery 7100 8100 8120 8140 8150 12140 12170 12180 13150 13170 13180 14150 14170 14180 14200 14220 15190 16170 16200 16220 16300 17210 17220 17300 17310 24220 24250 26300 26310 35300 40300
15-1521		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	03903260025	ALFA ROMEO GT Spider
15-1522		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	605201470;115607703600; 0390246145	ALFA ROMEO Spider 86~93
15-1523		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	7701021818;60703408;105 966506104;105246505204; 0390346086	ALFA ROMEO Duetto 78~86
15-1525		V 12V W RPM.L RPM.R N.m	6405G8;6405N8;F006B20 050;064053021010;TGE53 0VM	CITROEN Xsara Picasso 99 ~ 12

15-1527		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	6001547913;6001550803;8 200619512;64343295;TGE 432MK5	DACIA Duster 10~; Logan 04~; Sandero 08~
15-1527B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	6405N5;0390241523	CITROEN (雪铁龙C2) PEUGEOT(标致) 206 98~09
15-1600		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9397041021;9390041133; F006B20006;2870800	CHRYSLER Truck VW Camion P-100
15-1613		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	113955113G;113955113E	VW Beetle Bug 70~71; Super Beetle 71~; Sedan 73~92
15-1613A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	BAA955113B;9390041108; F006B20002	VW Beetle(OLD)
15-1625		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	22107720	OPEL Corsa B 93~00(RHD)
15-1636A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	1395107265;288001940R; 3397021823	DACIA Duster 10~19(RHD)
15-1680		V 24V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	0058209642;0058209842; A0058209642;A005820984 2;404398;404399	MB Atego 98~04
15-1689		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	2558026;2039222	SCANIA P45;G410
15-1681		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	6968247001;A6968247001 ;9390453084;	MB 1215 1318 2324

15-1681A		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	1958047;XC4517504BA;9390082057;9390082076;9390453030	FORD Cargo C1217 C1417 C1722E C2422E C2428E E2622E C2628E 2831 C4331S C5031 C712 C915 C915 MASFERSA M-210 M-240 SCANIA F 112/203 F 112/305 P 93 R 112/310 R 112/316 R 112/360 R 142/394 R 142/405 R 142/406 S 113/203 S 113/303 T 112/310 T 112/316 T
15-1682		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9390453033	MB 1630 1935 1941
15-1682A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	6888247301;A6888247301;9390453032;	MB 709 710 912 1614 1618 1630 1714 1718 1721 1825 1941 2314 2418
15-1690		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	1704355;180424;31917242000;10684795	DOGA MPN30R23AA1,WH501-MFG
15-1691		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40		INDIA
15-1692		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	81264016118;404027	MAN L2000 93~04; M2000L 95~05
15-1693		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	1250326;403863	DAF 65 92~98; 75 92~98; 85 92~98
15-1694		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	1063838;8143408S;403961	VOLVO FH12 93~
15-1696		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	1392755;1858661;2348384;0390242409;0986337209	SCANIA 4 95~; G 04~; P 04~

15-1697		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	99439631;99439637;403945;404056	IVECO EuroCargo 91~; EuroStar 93~; EuroTech MH 98~; EuroTech MP 92~; EuroTech MT 92~; EuroTrakker 93~; Stralis 02~;
15-1697A		V 24V W RPM.L RPM.R N.m	ITG42	
15-1698		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	0097938;0386253;1209106;1254891;150720200;36264016004;A0058202142;403924;404233	DAF 95 87~90; 95XF 97~02; XF95 02~06; XF105 05~ NEOPLAN Spaceliner 90~ MB Actros 96~02
15-1698A		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	1522016;910423;2388883050;2388883726;5001826864;A0018201501;A0018241501;A0018243001;A0028203042;A0038202742;A0038204842;A0038205042;A0048201301;A0048206742;0390242400;0390242404;403873	DAF F1600 73~91; F1700 86~95; F1800 70~91; F1900 86~93; F2000 70~79; F2100 78~91; F2200 71~80; F2200 78~91; F2300 78~93; F2800 74~91; F3300 81~91; F3600 85~91 IVECO P&PA 79~93 MB LK@LN2 84~98; NG 73~96; O 301 86~87; O 302 64~75; O 303 74~92; O 307 73~87; SK 87~; T2&LN1 86~94; VARIO 96~ NEOPLAN Cityliner 90~; Skyliner 90~; Spaceliner 90~
15-1698B		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	11026847;150703026;5010441051;7731143000B;81264016056;81264016112;81264016127;404067;404580	RENAULT Magnum 00~05 SETRA 200 79~

15-1699		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	20442878;404767	VOLVO FM10 99~01; FM12 98~05; FH12 98~05; FH16 05~
15-1699A		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	1442100;1620100;404832	DAF CF65 01~13; CF75 06~13; CF85 05~13
15-1699B		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	5010623023;579416	RENAULT Magnum DXi12,DXi13 04~
15-1700A		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	1264016088;81264016094; 81264016115;8126401611 9;81264016126;812640161 34;403947;0390442405;03 90242407	MAN E2000 00~; F2000 94~; F90 86~; N90 88~; M2000 95~; M90 88~
15-1701G		V 24V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	81264016132;8126401613 3;81264016135;812640161 38;81264016139;81264016 140;81264016141;8126401 6142;81264016143	MAN TGA 02~; TGL 05~; TGM 05~; TGS 07~; TGX 07~
15-1702		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	1J0955113C;1J0955119A; 1J0955119B;1J1955113C; 064052110010;TGE521LM M;433511;853511	AUDI A3 96~03 SEAT Leon 99~06; Toledo II 99~06 SKODA Octavia 96~10 VW(大众) BORA(宝来) 98~19; C-TREK(蔚领) 17~20 GOLF(高尔夫) 97~06; Jetta 02~10
15-1703		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	18D955113	VW(大众) Lavida(朗逸) 08~19; Gran Lavida(朗行) 13~17; Cross Lavida(朗境) 14~17
15-1703B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	4B29550236;4B2955113A; 8D2955113C;404586	AUDI(RHD) A4 94~01; A6 97~05

15-1704		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	10004346	ROEWE(荣威) 550 08~14 E550 14~16 MG(名爵) 6 10~15
15-1705		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	8D1955113;8D1955113A;8D1955113B;0390241132;433503;853503;	AUDI A4,S4 94~99 VW Passat B5 97~00
15-1705A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	3BE955119A;3B1955113B;4B1955113;0390241175	VW Passat B5(大众帕萨特) 96~00 AUDI A6 95~01
15-1706		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	9949505;6051106;60511009;064079600147;14003010;TGE511CM	FIAT Stilo 01~08
15-1706A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	3BE955113A	VW Passat B5(大众帕萨特)
15-1706B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	4BE955113A;8D1955113C;404587;433501;853501;	AUDI(奥迪) A4 94~01; A6 97~05
15-1708		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	2208200742;A2208200742;0390241435;433408;853408	MB(奔驰 W220) CL500 00~06; CL55 AMG 01~06; CL600 01~06; CL65 AMG 05~06; S350 2006; S430 00~06; S500 00~06; S55 AMG 01~06; S600 01~06; S65 AMG 2006
15-1710		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	1648201742;1648202442;1668200642;A1648201742;A1648202442;A1668200642;404930;433426;853426;	MB(奔驰) ML-CLASS(W164) 06~11; GL-CLASS(W164) 07~12
15-1710A		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	2518201442;2518202542;A2518201442;A2518202542;404929;433427;853427;	MB(奔驰) R-CLASS(W251) 05~13

15-1711		V 12V	8J1955119;8T1955119;8T1955119B;8T1955119C;8T1955119D;8K1955119A;405116;	AUDI(奥迪) A4 09~15, S4 13~15
15-1713		V 12V	4L1910113;4L1955119A;4L1955119C;405174;433547	AUDI(奥迪) Q7 07~12
15-1715		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	6161111535;61616913006;61617111535;432106;852106;	BMW(宝马) X5(E53) 00~06
15-1716A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	1273062;1274140;24450195;90587507;404496	OPEL Zafira A 99~05
15-1718		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	6401G9;6401H0;71792681;98846221;98846359;98846360;98846589;064300015010;064300023010;TGECSM15A;TGECSM23A	CITROEN Nemo 08~ FIAT Fiorino 07~; Linea 07~; Punto 05~ PEUGEOT Bipper 08~
15-1719		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	064300019;TGECSM19A	RENAULT Clio 09~
15-1719A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	288001683R;7701057358;064300021010;TGECSM21A	RENAULT Megane II (雷诺梅甘娜) 02~
15-1720		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	288000001R;288100941R;582618	RENAULT MeganeIII 09~15
15-1722		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	6401F5;7701054828;8200036921;53556602;53557102;53569202;579711;579740	CITROEN(RHD) C2 03~08; C3 02~10 RENAULT Megane II 03~08
15-1722C		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	7701066449;582605;54526811;54001902	RENAULT Kangoo II 08~19

15-1722B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	288009U100;288009U10A; 288009U10B;7701061590; 8200268931;53567502;535 68902;53630147;54523631 ;54525311;579738;579748	NISSAN Note 06~ RENAULT Clio III 06~12
15-1722F		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	6401F4	CITROEN C2 03~09; C3 02~05
15-1723		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	7701206549;579223	RENAULT Megane I 99~03
15-1723A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	61617138789;6161822912 8;53555304;432124;85212 4	BMW MINI Cooper 02~13
15-1723B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	7701046305;7701049802;7 701052152;7701054172;77 01207956;53562802;53555 102;579234	RENAULT Clio II 01~08; Thalia 01~
15-1723C		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	53550102;53550112;77010 43984;7701207957;770105 6060;579206;53563102	RENAULT Kangoo 97~ 08
15-1723E		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	0390241544	FORD Roxanne
15-1723F		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	288006475R;W000033365	DACIA Logan Sondero 06~20
15-1723G		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	7701208533;8200000526;8 200317212;8200317213;06 4300403010;TGE403M	RENAULT Laguna II 02~12
15-1723H		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	53565602;6405L1;6405TH; 9644210780;96442107800 1;470146	CITROEN Berlingo 02~12 PEUGEOT Partner 96~16

15-1725B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	288005974R	RENAULT MeganeIV 16~20
15-1725C		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	288008961R;288004542R; 288A53268R	RENAULT ClioIV 12~20
15-1725D		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	288004574R;A4538200140 ;A4538202000;W0000481 81;W000050447	MERCEDES SMART Forfour 453 15~21 RENAULT Twingo 14~19
15-1725E		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	280004410R;288004410R; W000052634	RENAULT Logan 15~;Sandero 15~
15-1728		V 12V	1K1955119A;1K1955119B; 1K1955119C;1K1955119E; 1Q1955119A;1Q1955119B ;1Q1955119C;1Z1955119 A;1Z1955119C;1Z1955119 D;1ZD955119;3C1955119; 3C1955119B;3TD955119;5 K1955119;8P1955119B;8P 1955119E;8P1955119F;03 90241783;4335001;433552	SKODA(斯柯达) Octavia(明锐) 04~15; Superb(昊锐) 09~13 VW(大众) Eos 06~16; Golf(高尔夫) 10~15; GTI 06~14; Jetta 05~14; Passat 3C(迈腾) 05~10; R32 2008; Rabbit 06~09; Scirocco(速腾) 08~13
15-1728B		V 12V	5ND955119A;5TC955119A ; 1397220648;1397229662	VW Touran 5T(大众途观) 15 ~
15-1728C		V 12V	4G1955199;4GD955119;1 397220616;1397220664	AUDI(奥迪) A6,C7 12~18
15-1728H		V 12V		
15-1730		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	7701034656;579127	RENAULT Clio I 90~98

15-1731		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	640589;640592;53545802; 53565704;579151;0390241 366;0390246338	Peugeot 306 93~02
15-1731A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	0058207842;A0058207842 ;53547902	MB(W638) V-Class 97~03; Vito 97~03; Viano 97~03
15-1732		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	640573;640581;579089;57 9139;53540402;53545402; 53545412;	CITROEN Saxo 96~04 PEUGEOT 106 91~03; PEUGEOT 405 87~96
15-1740		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥27		
15-1741		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	DLB101530;DLB101531;D LB101532	LAND ROVER Freelander 98~06(RHD)
15-1741A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	DKD100630; 434550	LAND ROVER Discovery 98- 04
15-1741B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	22115702;AMR1515;PRC7 096;434554	LAND ROVER Discovery 94~99; Range Rover 87~91
15-1741C		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	22147499;9169736;DLBE0 1390;DLB000510	MG(名爵) 3 01~05; ZR 01~05 ROVER 25 99~05; 200 95~00
15-1742		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	2108201742;A2108201742 ;0390241420;433400;8534 00	MB(奔驰) CLK-CLASS 97~02; E-CLASS 95~03
15-1746		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	61611373385;6161138615 5;61611386156;431057;85 1057	BMW 3(E30) 84~91; 5(E28) 84~88; M3 88~91; M5 1988

15-1744		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	95012138;DLB500030;DLB500031;LR020112;LR075581;434561;4345017	LAND ROVER(路虎) LR3,4(发现3,4) 05~16; Range Rover Sport(揽胜运动1,2) 06~13
15-1745		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	DLB101540;DLB101541;DLB101542;064300422010;TGE422M;434568	LAND ROVER Freelander(路虎神行者1) 02~05
15-1745A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	DKD100620	LAND ROVER Discovery 98~04
15-1745B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	91498335	MG(名爵) 7
15-1747		V 12 W 40V RPM.L 40±7 RPM.R 60±7 N.m ≥25	8Z0955113;579709	AUDI A2 00~05
15-1747A		V 12 W 40V RPM.L 40±7 RPM.R 60±7 N.m ≥25	5U0955119;1VW0ML306	VW GOL Voyage
15-1753		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	10100752;6405LK;0390241621	CITROEN Berlingo 08~18 PEUGEOT Partner 08~18
15-1759		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	8E1955113;8E1955119;0390241509;433515;853515;	AUDI(奥迪) A4 00~10 SEAT Exeo 08~; Exeo ST 09~
15-1762A		V 12V W 40 RPM.L 40? RPM.R 60? ANGLE 140?	TGE64342640;775391000	FIAT Uno(RHD) 83~95
15-1762B		V 12V W 40 RPM.L 40? RPM.R 60? ANGLE 140?	7791870;7799817;77998170;064342640010;TGE426BA	FIAT Uno 83~95

15-1754		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	6405CH;9650380780;9806 872780;8200364766;03902 41540;0390241541;039024 1583;0390241586	PEUGEOT(标志) 207CC 06~09; 2008; 308 14~19; 408 14~19 RENAULT Twingo II 07~16
15-1755		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	1273083;51810592;521517 75;52059679;93179149;6Q 2955119A;61617350657;0 390243525;0390241539;03 90241538;0390241564;F0 06B20409;F006B20436	BMW(宝马) X1(F48) 16~20 FIAT Doblo II 10~19 GM Prisma Onix 15~19 OPEL Astra H 04~14; Combo D 12~19 SEAT Ibiza 02~09 Cordoba 02~09; SKODA Fabia 99~08 VW Pol 01~10(RHD)
15-1755A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	61617380486;0390243617	BMW(宝马) 1-Series(F52) 16~20
15-1755B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	31G955119;34D955119;5 C6955113A;5C7955113A; 5C7955113D;6R1955119A ;6RD955119;90803209;03 90241566;0390241573;433 5002;8535002;	CHEVROLET Sail(雪佛兰赛 欧3) 15~18 SKODA Rapid(斯柯达昕锐) 13~19 VW(大众) Polo(波罗) 01~; Passat(帕沙特) 11~17; JettaIV(捷达) 08~14; Sagitar(速腾) 12~18; Santana(桑塔纳) 13~19
15-1756		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	55263842;77363822;60195 5119A;6Q1955119C;6Q19 55119A;6Q1955119;6Q19 55113;6R2955119A;03902 41514;0390243533;039024 1534	ALFA ROMEO 147 FIAT 500X 14~19 LANCIA Ypsilon 03~11 SKODA Fabia 99~08 VW Polo(大众波罗) 02~12
15-1757		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	5JB955113;5JB955113PL9	SEAT ToledoIV 12~ SKODA Rapid 12~
15-1758		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	98100B9900;98110F2000; F00S2S2885	HYUNDAI Grand I10 13~19(RHD) KIA (LHD)

15-1764		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	9945855;9948873;9948873 0;064342210010;TGE422L	FIAT Ducato 94~01 CITROEN Jumper 94~01 PEUGEOT Boxer 94~01
15-1764A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	6401E8;9949394;0643422 14010;TGE422P	FIAT Ducato 02~06 CITROEN Jumper 02~06 PEUGEOT Boxer 02~06
15-1765		V 12V W 30 RPM 64±7 N.m ≥15	9942152;064342101010;T GE421A	ALFA ROMEO 145 94~01; 146 94~01; 155 92~97 FIAT Tempra 90~96; Tipo 87~95 LANCIA Dedra 89~99; Delta II 93~99
15-1765A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	9948301;9948305;9945984 ;064343207010;TGE432G	FIAT Punto MK1 93~99 FIAT Punto 93~99 Punto Cabriolet 94~00 Punto Van 96~00
15-1766		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	9947349;9948307;0643423 14010;TGE423P	FIAT Croma 85~96; Punto 94~00 LANCIA Y 95~03
15-1766A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	9949162;9948494;9948303 ;9945841;8001063103624; MSY6434240404E;064342 404010;TGE424D;	FIAT Seicento 98~10 FIAT Punto 93~99 Punto Cabriolet 94~00 Punto Van 94~00 LANCIA(蓝旗亚)Y 95~03
15-1766B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	9941983;9944295;9942456 ;064342402010;064342403 010;TGE424B;TGE424C	FIAT Cinquecento 91~98; Panda 80~04, Seicento 97~10
15-1766D		V 12V W RPM.L RPM.R N.m	9949126;064343506010;T GE435F	ALFA ROMEO 145 94~99; 146 94~01
15-1769		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	1X4317508AA;C2S36555; C2S36556;C2S8855;C2S8 856;432910	JAGUAR(捷豹) X-Type 01~10

15-1770		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	50509396;77363796;67633405319;0390241915;0390243019	ALFA ROMEO 159 09~11; Brera 09~; Giulietta 10~19; Spider 09~ BMW X3(E83 RHD) 03~11
15-1771		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	561955023B;561955119A;0390243078;0390243090	VW(大众) Beetle(甲壳虫) 12~18; Passat 12~15
15-1773		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	67636914577;0390241712;432104;852104	BMW(宝马) 3-SERIES(E46) 98~05; X3(E83) 03~
15-1774		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	13145558;404977	OPEL Zafira B 05~14(RHD)
15-1774A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	1273398;13145557;404976	OPEL Zafira B 08~14(LHD)
15-1775		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	61617200510;405154;432121;852121	BMW(宝马) X5(E70) 07~13
15-1775A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	6935781;61614848602;61617161710;404960	BMW 3(E90 RHD) 05~11
15-1775B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	6978263;61617161711;432122;852122	BMW(宝马) 3(E90 LHD) 05~11
15-1775C		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	61612990025	BMW(宝马) X1 (E84) 10~15
15-1776		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	53102455;AJ1590604840	FIAT Viaggio(菲亚特菲翔) 12~

15-1777		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	51787566;51793272;77364424;064014011010;TGE511MOM;MS15920086504E	FIAT 500 07~; 500C 09~; Bravo II 07~ LANCIA DeltaIII 08~
15-1777A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	77362587;064014007010;TGE511GM;MS15901079434E	FIAT Panda 03~
15-1777C		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	51833650;52025797;64351117	FIAT LANCIA Ypsilon 11~19
15-1778		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	67638360603;8360603;DKD000010;DKD000020;LR035806;LR035813;404202;432103	BMW(宝马) 5(E39) 95~04 LAND ROVER Range Rover(路虎揽胜) 03~12
15-1779		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	1270815;1272045;1272128;13182342;13372899;13432686;405068	OPEL&VAUXHALL Corsa D 06~14(RHD)
15-1779A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	1270814;1272127;13182340;13432685;367546129;405067	OPEL&VAUXHALL Corsa D 06~14(LHD); Corsa E 15~
15-1780		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	77362588;064014009010;TGE511IM	FIAT Idea 03~20 LANCIA Musa 04~12
15-1781		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	61614848613;61617239510;61617239527;61617260488;726750302	BMW(宝马) 1(F20,F21) 10~16; 3(F30,F31,F35,F80) 11~16
15-1781A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	61617260489;61614848621;7267504	BMW 1(F20,F21 RHD) 10~16; 3(F30,F31,F35,F80 RHD) 11~16

15-1782		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	288100236R;4419283;820 0734788;93197310	OPEL Movano B 10~ 19 RENAULT MasterIII 10~ 19
15-1784		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	51843622;064351116010; TGE511R	FIAT Panda 12~20
15-1785		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	61617131164;6161717637 7;61617179433;616171940 29;404822;432109;852109 ;	BMW(宝马) 5- SERIES(E60,E61,E63,E64) 02~10
15-1785B		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	9068200040;A9068200040 ;2E0955023;68017435AA; 405146;403041	DODGE Sprinter 2500 07~09; Sprinter 3500 07~09 MB Sprinter(W906) 10~16 VW Crafter 06~
15-1785C		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	9068200140;A9068200140 ;405147	MB Sprinter(W906 RHD) 06~12 VW Crafter 06~12
15-1785D		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	6368200040;6398200140; A6368200040;A639820014 0	MB(奔驰) Viano(唯雅诺) 03~19; Vito(威霆) 03~19
15-1786		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	61617200513;6161715373 4;61614848604;7200536;7 200513;7153734;4848604; 405155	BMW X5(E70 RHD) 07~13
15-1788		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	61617292653;1593003940	BMW(宝马) X5(F15) 14~18
15-1789		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	1698200300;A1698200300	MB(奔驰) A-CLASS(W169) 04~08

15-1791		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	GX7317500AC;T2H1168;T2H1169;T2H23527;T2H23528;W000060842	JAGUAR(捷豹) XJ 15~; XF 16~18; XFL 17~20; XE 17~18; XEL 18~21
15-1796		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	Q0001754V009000000;404389	MB SMART MMC City
15-1799		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	46748140;46804975;51793158;51839941;64343498;64343418;064343499010;TGE434T	FIAT Doblo(菲亚特派力奥,西耶那,周末风) 01~10; Strada
15-1891C		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	8693848;86938480;86938487;404766;434817	VOLVO(沃尔沃) XC90 03~14
15-1892		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	8648343;86483430;86483435;9171901;91719010;91719013;404775;434803	VOLVO(沃尔沃) S60 01~09; S80 99~06; V70 01~07; XC70 03~08; XC90 2003
15-1901		V 12V W 20 RPM 40? Angle 98?	64399938	Kartal Vidali
15-1903		V 12V W 20 RPM 40? Angle 98?	7702247339;7702254878;64399935;64399937	RENAULT R12 SW Vidali
15-1906		V 12V RPM 45? Angle 130?	1273006;90341911;90421858;403780	OPEL Astra F 91~98
15-1906A		V 12V RPM 45? Angle 130?	1273007;90421859;403781	OPEL Astra F 91~98

15-1906B		V 12V RPM 45? Angle 115?	1273013;90386268;403980; 401104	CHEVROLET Chevy 06~11 Corsa 06~08 OPEL Combo 94~01 Corsa B 93~00 VAUXHALL Corsa 93~00
15-1910		V 12V RPM 43? Angle 135?	46426581;064343010010; TGE430L	FIAT Palio 97~02
15-1910A		V 12V RPM 43? Angle 85?	46752717;46816698;06434 3019010;TGE430U	FIAT Doblo 01~
15-1910B		V 12V RPM 43? Angle 112?	51757281;064343021010; TGE430Z	FIAT Doblo 01~10
15-1911		V 12V RPM 40? Angle 172?	4F9955711C;4F9955711E; 8E9955711;8E9955711A;8 E9955711B;8E9955711C;8 E9955711D;8E9955711E;8 E9955711G;8R0955711A; 8R0955711B;8R0955711C ;579603;579705;579706;4 33533;853533	AUDI(奥迪) A3 03~12; A4 01~15; A6 04~11; Q5 08~17; Q7 06~12
15-1911A		V 12V RPM 40? Angle 172?	5J7955711;5J7955711A;5J 7955711B;5J7955711C;5J 9955711;5J9955711A;5J9 955711B;6Q6955711;6Q6 955711B;404726;5303121 2;064038006010;06403800 5010;TGL380E;TGL380F	SEAT Arosa 97~04 SKODA(斯柯达) Fabia 06~14; Roomster 06~15; Yeti(野帝) 09~17; Superb(速派) 13~; Superb Derivative(速尊) 14~ VW(大众) Lupo 98~05; Polo(波罗) 01~09
15-1911B		V 12V RPM 40? Angle 172?	1J0955711C;1J9955711;1 J6955711A;1J6955711B;1 J6955711C;1J6955711F;1 J6955711G;1J9955711F;3 B9955711E;7E0955711B;7 M3955711;7M3955711A;7 M3955711C;4248079M91; 0390201592;404425;40483 4;404886;404849B;433506 ;853506	FORD Galaxy 95~06(RHD) SEAT Alhambra 96~10(RHD); Leon 99~06; Toledo 91~99 SKODA Fabia 99~08; Octavia 98~10 VW(大众) Bora(宝来) 99~06; Camper V 05~15; Golf(高尔夫) 99~06; Jetta(捷达) 01~05; Passat 03~05; Sharan 95~10(RHD); Transporter V 06~15

15-1911C		V 12V RPM 40? Angle 172?	1U9955711;1Z9955711;1Z9955711A;1Z9955711B;1Z9955711C;404683;064038004010;TGL380D	SKODA Octavia(斯柯达明锐) 98~10 Octavia 04~13 RHD
15-1911D		V 12V RPM 40? Angle 172?	3B9955711C;6X0955711A;6X0955711B;6X0955711C;8D9955711;8L0955711;8L0955711A;8L0955711B;404219;404430;433528;853528	AUDI(奥迪) A3 96~06; A4 94~01; A6 97~11 SEAT Arosa 97~04 VW Passat(大众帕萨特) 96~05
15-1911E		V 12V RPM 40? Angle 172?	6Q6955711A;6Q6955711C;0390201596	VW Polo 01~09
15-1911F		V 12V RPM 40? Angle 172?	4F9955711;4F9955711A;4F9955711B;579602	Audi(奥迪) A4 08~15; A6(旅行版) 05~11 VW Touran 04~10
15-1911K		V 12V RPM 40? Angle 172?	7H0955711;404808	VW(大众) TransporterV 03~15; Caravelle(凯路威) 03~15; Multivan(迈特威) 03~15
15-1911L		V 12V RPM 40? Angle 172?	5Z6955711;5Z6955711A;F006B20058	VW Fox 04~14; Gol 08~14
15-1912		V 12V RPM 40? Angle 172?	1K6955711B;1K6955711C;1K9955711A;1K9955711B;5N0955711A;5N0955711B;0390201800;F006B20113;579746;433530;853530;433578;853578	VW(大众) Bora 07~09; Golf(高尔夫) 13~14; Golf Sportwagen 2013; GTI 06~09; Jetta 07~14; Passat 07~10; R32 2008; Rabbit 06~09 Tiguan(途观) 07~11

15-1912B		V 12V RPM 40? Angle 172?	1S6955711A;1S6955711B; 5G0955711;5G0955711A; 5G0955711C;582624	SEAT Arona 17~; Ateca 16~; Mii 11~12 SKODA Citigo 11~ VW Atlas 18~22; E-Golf(高尔夫新能源) 15~20; Golf(高尔夫) 15~21; Polo 12~17; GTI 15~20; Tiguan(途观) 18~22; Touran(途锐) 15~; UP 11~15; Variant(蔚揽,蔚揽新能源) 16~
15-1912C		V 12V RPM 40? Angle 172?	5K6955711;5K6955711A;5 K6955711B; 0390201222;582621;43359 0	VW(大众) Golf(高尔夫) 10~14; Golf Sportwagen 2011; Gran Lavida(朗行) 13~17; Cross Lavida(朗境) 14~17; GTI 10~14; Namo(夏朗) 12~18; Polo(波罗) 11~18
15-1919		V 12V RPM 35? Angle 172?	LR002243;LR033226;4345 77	LAND ROVER LR2(路虎神行者2) 08~13
15-1919B		V 12V RPM 35? Angle 172?	1141045;1422314;2S61A1 7K441AB;2S61A17K441A C;404736	FORD FiestaV 01~08 Fusion 04~12
15-4082		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	7E1955113;7E1955113A;7 E1955113B;7H1955603A;7 H1955023B;443122351017 ;064052111010;TGE521N OM	VW T5 04~14
15-2904		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	12755304;12805859;43290 4;852904;	SAAB 9-3 03~05
15-2904A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	1273071;1273086;1275715 3;93171543;93185526;432 931;852931;	OPEL(欧宝) Signum 03~; Vectra(威达) C 02~ SAAB 9-3 02~15(RHD)

15-4080		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	6405ER;6405PP;77364080 ;064052101010;TGE521A M	CITROEN Jumper 06~ FIAT Ducato 06~ PEUGEOT Boxer 06~
15-4080A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	77364111;1363339080	CITROEN Relay 06~19(RHD) FIAT Ducato 01~19(RHD) PEUGEOT Boxer 06~19(RHD)
15-4081		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	6405GE;6405GF;0640521 03010;064052104010;TGE 521CM;TGE521DM	CITROEN Dispatch 07~; Jumpy 07~ FIAT Scudo 07~ PEUGEOT Expert 07~
15-4082A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	7E2955113;064052113010 ;TGE521OM	VW T5 04~14 (RHD)
15-4525		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	2881000QAB;2881000QA C;4408625;4414681;77010 55893;7701473363;931607 91;91160081;579732	RENAULT Trafic II 01 NISSAN Primastar 01~ OPEL Vivaro 01~
15-4526		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	42535383;42535712;42536 088;53556502;504033863; 504084722;9900333;77010 44526;7701050898;770105 8169;579220;579710	IVECO DAILYIII 99~07 RENAULT Master II 98~
15-4526A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	53565202;7701056003;579 735	RENAULT(雷诺) Scenic II (风景) 03~; Grand Scenic II 04~
15-4526B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	2881000QAD;4404165;441 1919;7701055895;7701473 364;9112165;93160794;57 9733;53554102;53554122; 53554142	NISSAN Primastar 02~16 OPEL Movano 98~04; Vivaro 03~06 RENAULT Trafic 01~10

15-4526C		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	6405G1;579230;53553202	PEUGEOT 406 96~04; 607 00~11
15-4526D		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	6405A8; 579169;53551502	PEUGEOT 406 96~04
15-4545		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	F004R00010	OPEL Corsa 02~06(RHD)
15-4809		V 12V	8667188;277715;P700040 6681CAR;434809	VOLVO V70 05~07;XC70 05~08
15-4810		V 12V	8638163;268408;434810	VOLVO XC90 03~12
15-5039		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	LR072416;LR055421;LR00 2253;405039;434578	LAND ROVER LR2(路虎神行 者2) 08~13
15-5039A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	W0027101;LR078300;LR0 75361;LR024224;LR00225 4;405040	LAND ROVER Evoque(极光) 12~17(LHR); Freelander2 06~14(RHD)
15-5039B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	51701421;51881061;77363 952;404978	FIAT Grande Punto 05~12; Linea 08~12; Punto 07~12; Punto EVO 09~14
15-5039C		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	404979	FIAT Linea Pinto(RHD)
15-5039D			5J1955113;5J1955113A;5J 1955113B;5JD955113;405 119	SKODA(斯柯达) FABIA I 05~08; ABIA II 07~14; ROOMSTER 06~15

15-5342		V 12V RPM 40? Angle 172?	2038200542;2038204642;2038205342;A2038200542;A2038204642;A2038205342;579600;53030412	MB C-CLASS 01~07
15-5938		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	2028200408;A2028200408;433401;853401	MB C-CLASS(W202) 93~01
15-5938A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	2028201108;2028202308;A2028201108;A2028202308;404437; 433403	MB C-CLASS(W202) 96~01
15-5939		V 12V	2028200308;A2028200308;404423	MB C-CLASS(W202 RHD) 96~01
15-5939A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	2028202408;A2028202408	MB C-CLASS(W202 RHD) 93~01
15-5940		V 24V W 150 RPM.L 30±3 RPM.R 45±3 N.m ≥70		沃尔沃客车大巴
15-5940A		V 24V W 180 RPM.L 30±3 RPM.R 45±3 N.m ≥85		沃尔沃客车大巴
17-1021		V 12V W 20 RPM.L 50±7 RPM.R 75±7 N.m ≥15	5453956;8491000462;40437;85437	JEEP Cj5 81~82; Cj7 81~82
17-1021A		V 12V W 20 RPM.L 50±7 RPM.R 75±7 N.m ≥15		JEEP Cj7
17-1025		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	6203014	FORD Transit T 12-15

17-1032B		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	64342395;TGE423MK5	DODGE 26.200
17-1036		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		FORD Xr3 Bntm
17-1048		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	56030005;8491002178;40432;85432	JEEP Tj(CANADA) 1996; Wrangler 87~96; Yj 91~95
17-1049		V 12V W 20 RPM.L 50±7 RPM.R 75±7 N.m ≥15		JEEP Cherokee S-715
17-1050A		V 12V W 20 RPM.L 50±7 RPM.R 75±7 N.m ≥15	5763696;8491000160;RAY LOC.49433;40433;85433	JEEP Cj5 1983; Cj7 83~86
17-1104		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9390041124;F006B20005	GM CHEVROLET Camioned / 10 / 15 Pick-Up M041124 82~84
17-1125I		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	21019036;21019798;22688179;22699805;401035;851035	SATURN L sedan 01~05; L300 2004; Ls sedan 2000; Lw wagon 00~03
17-1180		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	20910180;20910181	CADILLAC(凯迪拉克) XTS 13~17
17-1301C		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	YC1517504CD;YC1517504CB;4637734;64342298	FORD TRANSIT V 184
17-1326A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	55076549AH;55076549AG;49412;403024;853024	DODGE Ram 1500 Pickup 00~02; Ram 2500 Pickup 00~02; Ram 3500 Pickup 00~02

17-1326C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	4389131;4584260;55155043;40387;85387;	CHRYSLER Dynasty(CANADA) 89~93; Imperial 90~93; LeBaron 89~94; New Yorker 89~93 DODGE Dynasty 89~93; Lancer 1989; Monaco 91~92; Shadow 89~94; Spirit 89~95; Dakota 89~96; Dynasty 89~93; Lancer 1989; Monaco 91~92; Ram 1500 Pickup 94~96; Ram 2500 Pickup 94~96; Ram 3500 Pickup 94~96 EAGLE Premier 91~92 PLYMOUTH Acclaim 89~95; Sundance 89~94
17-1326D		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	4389132;40388;85388;	CHRYSLER Dynasty 89~93; Fifth Avenue 1989; LeBaron 89~95; TC Maserati 89~91; Town&Country 90~95 DODGE Aries 1989; Daytona 89~93; Diplomat 1989; Omni 89~90; BE50 Van 89~94; BE500 Van 95~97; B250 Van 89~94; B2500 Van 95~97; B350 Van 89~94; B3500 Van 95~97; Caravan 89~95; D100 Pickup 1989; D150 Pickup 89~93; D250 Pickup 89~93; D150 Pickup 89~93; Grand Caravan 89~95; Ram 1500 Van 95~97;
17-1326E		V 12V W 30 RPM.L 42±7 RPM.R 58±7 N.m ≥20	55076549;55076549AC;403000;853000;	DODGE Ram 1500 Pickup 97~99; Ram 2500 Pickup 97~99; Ram 3500 Pickup 97~99
17-1326P		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	85387P	AMERICA

17-1326F		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	55155046AD;55155046AE; 403009;853009;	DODGE BE500 Van 1998; B2500 Van 1998; B3500 Van 1998; Ram 1500 Van 98~03; Ram 2500 Van 98~03; Ram 3500 Van 98~03
17-1327		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	24015340	T600,T800 MEXICO
17-1327A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	A186256;0390241318;F00 6B20047	CASE 570LXT 95~99; 580K 86~94; 580L 95~06; 580SK; 580SL; 590 Turbo; 590L 92~01; 590SL; 90XT 97~06; 95XT 97~06
17-1334		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	21302905;401034	SATURN SC Series 00~02; SL Series 00~02; SW Series 00~01
17-1362		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	1064811;1211262;XS4117 508BA;XS4117508BB;XS4 117B571AA;0390241362;0 390241363;064053006010; TGE530GM	FORD Focus 98~04
17-1362A		V 12V W RPM.L RPM.R N.m	2R0955113A;F006B20022	VW 15190 17180 23210 24220 26260 31260 00~11; Delivery 7110 8120 00~11
17-1363		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	1008772;96FB17B571DA; 9390453088;404240;40209 6	FORD FiestaIV(福特嘉年华 03~07) 95~06; Puma 97~02
17-1367		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	19120347;19120349;19120 736;19120738;19120740;2 5791962;401067;851067;	BUICK Allure 06~09; LaCrosse 06~09 For CHEVROLET Impala 06~12; Impala Limited 14~15; Monte Carlo 06~07 PONTIAC Grand Prix 06~08

17-1391		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25		FORD Fucus(福特福克斯 05~14)
17-1391A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	9009598	BUICK(别克) GL8 11~18
17-1391C		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	1807192;90733177;92164383;92273050;92293743;4010020;8510020	BUICK Boulevard(别克林荫大道) CHEVROLET Caprice 13~17; SS 14~17 PONTIAC G8 08~09
17-1405		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	15940208;20837131;25801063;25801064;25875313;25877338;4010005;8510005	CADILLAC(凯迪拉克) CTS 08~13 CHEVROLET Silverado 1500 08~10; Silverado 2500 HD 08~10; Silverado 3500 HD 08~10 GMC Sierra 1500 08~10; Sierra 2500 HD 08~10; Sierra 3500 HD 08~10
17-1423		V 12V W 30 RPM.L 42±7 RPM.R 65±7 N.m ≥20	23340478;23368170;1590607870	CADILLAC(凯迪拉克) CT6 16~
17-1433		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	10389558;04805711AB;05152034AB;5175910AA;68044164AA;68065563AA;68082552AA;403033;853033;403051;853051	CHRYSLER(克莱斯勒) 300C 10~19; PT Cruiser(PT漫步者) 06~10 DODGE Challenger 08~18; Charger 10~18; HUMMER(悍马) H3 06~10; H3T 09~10
17-1437		V 12V W 30 RPM.L 42±7 RPM.R 65±7 N.m ≥20	23372081;23372086;1590608032	BUICK ENCLAVE(别克昂科旗) 20~ CADILLAC(凯迪拉克) XT5 17~20; XT6 20~ CHEVROLET Blazer 19~20 GMC Acadia 17~
17-1438E		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	22905713;20908672;84230547;1590605950	CADILLAC(凯迪拉克) ATS 13~19

17-1438		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	4879432AG;4879432AH;5183273AA;5183273AB;5303780AB;5303780AE;5303827AC;5303827AD;5303827AE;5503827AC;55079158AD;55079158AF;68002320AA;68003729AA;68079854AA;68156259AA;68190045AA;68197132AA;68197132AD;68301826AA;76505TZ5A01;KD5367340;KD5367340B;403038;853038	ACURA MDX 14~18 CADILLAC ATS 13~18 DODGE(道奇) Caliber(酷搏) 07~12; Dart 13~16; Durango 11~12 JEEP(吉普) Cherokee(自由光) 14~18; Compass(指南者) 07~17; Grand Cherokee 11~13; Patriot(自由客) 07~17 MAZDA CX-5 13~15
17-1447		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	6L8Z17508B;6L8Z17566BA	FORD Escape(福特翼虎) 05~07) 01~07 MERCURY Mariner 05~07
17-1467		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	13240560;19184572;20980563;23389493;23389495;92212322;92231678;55158313AB;68040580AA;401114;851114;	CHEVROLET(雪佛兰) Camaro 10~12; Impala 14~17; Malibu(迈锐宝) 13~15 JEEP Grand Cherokee(吉普大切诺基) 05~10 PONTIAC Vibe 09~10 SCION XD 08~09
17-1467A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	5183007AA;55156313AB;55156851AB;55156851AC;55156851AE;40457	JEEP Commander(吉普指挥官) 06~07; Grand Cherokee(吉普大切诺基) 05~07
17-1468		V 12V W 30 RPM.L 42±7 RPM.R 65±7 N.m ≥20	23278042;23353578;1590607861	CADILLAC Malibu(凯迪拉克迈锐宝XL) 16~21
17-1519		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9390082049	CHEVROLET Monza
17-1520		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9390082037	CHEVROLET Chevette
17-1520A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9390453045;9390453070	CHEVROLET D20,D11000,D12000,D13000,D14000,D19000,D21000,D22000;BONANZA;VERANEIO

17-1614		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	9397041010;F006B20007	FORD Camion 87~ DCAMIONY Camionetas 87~91
17-1650		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	00076044;AM2302005	Special Vehicle
17-1651		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	00076586;AM2301002	Special Vehicle
17-1652		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	AX9112;10102238	Blue Bird Bus (post 2006)
17-1652A		V 24V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	MPL-003	Special Vehicle
17-1653		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	AX9111;85650481;430444 0	Thomas Bus (1973-present) Blue Bird (pre 2006)
17-1653A			9397236032;433854001;42 4119001	International And RE Series Model
17-1654		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	WM612	Special Vehicle
17-1655		V 12V W 30 RPM.L 42±7 RPM.R 58±7 N.m ≥20	437192010;2511785C91;N IDEC.403878	International 3000 Bus, Amtran, CE200, CE300 Series, And RE300 Bus
17-1656		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	AM230J652;85697028	GRUMMAN LLV

17-1683		V 12V W RPM.L RPM.R N.m	100490112;9390453021	FORD Cargo Todos
17-1703A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	9028850;9062432	CHEVROLET Sail(雪佛兰新赛欧) 10~12
17-1717		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	1534235;5081623;8T1617508AA;8T1617508AB;8T1Z17508A;064300022010;TGECSM22A;402089;852089	FORD Transit 02~13
17-1722D		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	26689065	BUICK (别克) Excelle(英朗) 15~17; 阅朗 18~19 CHEVROLET(雪佛兰) 科沃兹 16~19; 科鲁泽 19~21
17-1722E		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	1270060;1270062;1272158;42333713;42333715;42401250;95323223;95323224;95323225;95915118;573117;401120;851120;	BUICK Encore(别克昂科拉) 12~15 CHEVROLET Trax 14~15 OPEL Mokka 12~15
17-1722H		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	94525906;95168357;95917201;401118	CHEVROLET Aveo(雪佛兰爱唯欧) 11~14; Sonic 12~17
17-1722I		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	52071121;W000022512	CHEVROLET Cobalt 13~19
17-1755		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	1514060;1698869;8A6117B571AA;8A6117B571AB;0390241569;064350005010;TGE500GM	FORD Fiesta(福特嘉年华) 08~13

17-1756		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	22664679;AB3917504AD; AB3917504BD;AB3917504 BE;EB3BE7504FA;EB3Z1 7508J;401059;401059	CHEVROLET Cobalt 05~10 FORD Ranger 12~15(LHD,RHD) PONTIAC G4 05~06; G5 07~10; Pursuit 05~06 SATURN Ion 03~07
17-1768		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	95VB17508BA	FORD Transit(江铃全顺)
17-1770		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	1255958;12335832;152547 96;15942928;1694757;258 21246;20785187;68030272 AA;68044087AA;7S71175 08AA;7S7117508AB;0390 243069;0390241619;03902 41633;0390241653;039024 1770;0390241729;F00HV2 0023;401070;851070;	BUICK(别克) Enclave(昂科雷) 08~12; Terraza 05~07; GL8FristLand(陆尊) CHEVROLET Traverse 09~12; Uplander 05~09 CHRYSLER 200 11~14; Sebring 2010 DODGE(道奇) Avenger 10~14; Journey(酷威) 09~15 FORD(福特) C-Max 05~07; Focus C-Max 05~07; Mondeo(蒙迪欧致胜) 08~12 GMC Acadia 07~12 PONTIAC Montana SV6 05~09 SATURN Outlook 07~10; Relay 05~07
17-1771		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	1329835;1704578;1709010 ;4M5117508AA;4M511750 8AB;8V4117508AB;BE8Z1 7508A;BN8V67340;BN8V6 7340A;BP4K67340;039024 1697;0390241731;434418; 854418;434419;854419	FORD(福特) Fiesta 11~19 Fucos(福克斯) II 04~12; Kuga 08~12 MAZDA(马自达) 3 04~09
17-1772		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	1S7117508AA;1S7117508 AB;1S7117508AD;1S7117 508BA;1116759;1116760;1 229139;0390241702;03902 41715;402109	FORD MondeoIII(福特蒙迪 欧) 00~07

17-1776A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	22888505;1590606540	BUICK Envision(别克昂科威)
17-1797		V 12V W 50 RPM.L RPM.R N.m ≥30	1FD0ML0300;1FD0ML301; 2S6517504;MNG2PTH	FORD Ecosport 02~12 Fiesta 02~12
17-1800		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40	4673013;4673013AA;4708 171;403001;853001;	CHRYSLER Grand Voyager 2000; Town&Country 96~00; voyager 97~00 DODGE Caravan 96~00; Grand Caravan 96~00 PLYMOUTH Grand Voyager 96~00; Voyager 96~00
17-1801		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	9032072;96850001;861013 4000;8610134001	CHEVROLET Lova(雪佛兰乐风) 09~; AVEO 07~11; AVEO5 09~11 PONTIAC G3 09~10; G3 WAVE 2009; WAVE 07~08 SANGYONG Korando 10~19
17-1802		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	96893302;401110;851110;	CHEVROLET Cruze(雪佛兰科鲁兹) 09~
17-1803		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	20829042;20829043;20829 044;25918738;25919459;9 6673024;96673047;401001 3;8510013	CHEVROLET Captiva Sport(雪佛兰科帕奇) 08~11 OPEL Antara(欧宝安德拉) 07~17 SATURN Vue 08~10
17-1803B		V 1V2 W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	93734763	CHEVROLET Epica(雪佛兰景程) 07~13
17-1804		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	F4ZZ17508A;402004;8520 04	FORD Mustang 94~98; Windstar 1995

17-1804A		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	F5RZ17508E;402009;852009	FORD Contour 95~97; Mystique 95~97 MERCURY Mystique 95~97
17-1804B		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	F58Z17508C;402011;852011;	FORD Windstar 95~96
17-1804C		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	F4SZ17508A;F4SZ17508B;F5CZ17508A;F5TZ17508A;F5ZZ17508A;ZMZ067350;402003	FORD Cougar 96~00; Escort 91~96; Thunderbird 89~97; E Super Duty 1996; E-150 Econoline 95~96; E-250 Econoline 95~96; E-350 Econoline 95~96; Explorer 95~97; Ranger 95~97 MAZDA B2300 95~97; B3000 95~97; B4000 95~97 MERCURY Cougar 89~97; Tracer 91~96; Mountaineer 1997
17-1804D		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	F5HZ17508A;402002	FORD Bronco 87~96; F Super Duty 88~97; F-150 87~96; F-250 87~97; F-350 87~97; F-600 90~94; F-700 90~98; F-800 90~99; F53 88~97; F59 88~97
17-1805		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	EW7Z17V508A;F5AZ17508A;F7AU17504AA;F7AZ17508AA;6U2Z17V508ABRM;6W7Z17508BB;WM512;WM658;WM736RM;WM837;402005;852005	FORD Crown Victoria 95~02; Grnd Marguis(Mexico)95~02 LINCOLN Town Car 95~97 MERCURY Grand Marguis 95~02
17-1805A		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	F4DZ17508B;F4DZ17580B;F50Y17508A;402001;852001;	FORD Sable 87~95; Taurus 87~95 LINCOLN Continental 88~97 MERCURY Sable 87~95

17-1805B		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	F5AZ17508B;402012	FORD Country Squire 87~91; Grand Marquis 87~91; LTD Crown Victoria 87~91 MERCURY Colony Park 87~91; Grand Marquis 87~91
17-1805C		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	F5VY17508A;402007	LINCOLN Town Car 87~89
17-1805D		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	F4LY17508A;F7LZ17508A; A;402008;852008	LINCOLN MarkⅧ 94~98
17-1806		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	96396525	BUICK Excelle(别克凯越7P) 04~15
17-1806A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25		BUICK Excelle(别克凯越8P)
17-1807		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	E63Z17508A;E7ZZ17508A ;E8ZZ17508A;E93Z17505 A;E93Z17508A;F0CZ1750 8A;F2UZ17508A;F43Z175 08A;F5UZ17508A;40297;8 5297;	FORD E-150 92~94; E-250 92~94; E-350 92~94; Escort 91~94; Mustang 87~93; Tempo 86~94; Topaz 86~94 MERCURY Topaz 86~94; Tracer 91~94
17-1807A		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	E7TZ17508A;40299;85299	FORD bronco 87~96; F super duty 88~94; F-150 87~96; F-250 87~96; F-350 87~96; F53 88~96; F59 88~96; F600 90~94; F700 87~96; F800 87~96; FT900 90~94

17-1808		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	3810085Z10;3810185Z00; 3881085Z10;96434730;96 442580; 434103	CHEVROLET Lacetti 05; Optra 04~10 SUZUKI Forenza 04~08; Reno 05~08
17-1812		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	10440412;12367316;12487 575;12494761;22144097;8 8958109;401012;851012	BUICK Century 97~05; Regal 97~04 CHEVROLET Impala 00~05; Monte Carlo 00~05 OLDSMOBILE Intrigue 98~02 PONTIAC Firebird 98~02; Grand Prix 97~03
17-1812A		V 12V W 40 RPM.L 45±7 RPM.R 65±7 N.m ≥30	12363317;401010;851010	CHEVROLET Cavalier 95~97 PONTIAC Sunfire 95~97
17-1812B		V 12V W 40 RPM.L 45±7 RPM.R 65±7 N.m ≥30	12363316;401011	CHEVROLET Camaro 99~02 PONTIAC Firebird 99~02
17-1812C		V 12V W 40 RPM.L 45±7 RPM.R 65±7 N.m ≥30	12363318;12494759;40101 9;851019	CHEVROLET Corvette(别克 君威) 97~04
17-1813		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	12487586;22144497;81248 75860;401013;851013	CHEVROLET Express 1500 96~02; Express 2500 96~02; Express 3500 96~02; C4 Series 03~09; C5 Series 03~09; C6 Series 03~09; C7 Series 03~09; C8 Series 03~09 GMC Savana 1500 96~02; Savana 2500 96~02; Savana 3500 96~02; C4 Series 03~09; C5 Series 03~09; C6 Series 03~09; C7 Series 03~09; C8 Series ISUZU HTR 2009; HVR 2009; HXR 05~09

17-1813A		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	88958135;401047;851047	CHEVROLET Express 1500 03~07; Express 2500 03~07; Express 3500 03~07 GMC Savana 1500 03~07; Savana 2500 03~07; Savana 3500 03~07
17-1813B		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	15874973;19169125;401096;851096	CHEVROLET Express 1500 08~14; Express 2500 08~14; Express 3500 08~14; Express 4500 09~14 GMC Savana 1500 08~14; Savana 2500 08~14; Savana 3500 08~14
17-1814		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥25	12463095;22154405;401014;851014	CHEVROLET Malibu 97~03; Malibu Classic 04~05 OLDSMOBILE Cutlass 97~99
17-1815		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	12365366;401015;851015	CHEVROLET Cavalier 98~03 OLDSMOBILE Alero 99~03 PONTIAC Grand Am 99~03; Sunfire 98~03
17-1816		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	88958371;88958406;88959371;401054;4010016;8510016	CADILLAC Escalade 04~07 CHEVROLET Avalanche 2007; Avalanche 1500 04~06; Avalanche 2500 04~06; Silverado 1500 04~06; Silverado 1500 Classic 2007; Silverado 2500 04~06; Silverado 2500 Classic 2007; Silverado 3500 04~06; Silverado 3500 Classic 2007; Suburban 1500 04~07 Suburban 2500 04~07; Tahoe 05~07 GMC Sierra 1500 04~07; Sierra Classic 1500 2007; Sierra 2500 04~07; Sierra Classic 2500 2007;
17-1821		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	96648776;4010021	CHEVROLET Aveo 07~18 PONTIAC G3 07~08; Wave 07~08 SUZUKI Swift+(Canada) 07~08

17-1822		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	25895883;4010022	CHEVROLET Malibu 09~12 PONTIAC G6 09~10 SATURN Aura 2009
17-1822A		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	25979382;4010034	CADILLAC(凯迪拉克) SRX 10~16
17-1822B		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	15929735;22675750;401061	CHEVROLET Malibu 04~08
17-1822C		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	15813769;22665038;401057	CHEVROLET Equinox 05~06 PONTIAC Torrent 2006 SATURN VUE 02~07
17-1822D		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	15849819;25828080;3810178J00;3810178J01;434112;401087;851087	CHEVROLET Equinox 07~08 PONTIAC Torrent 07~08 SUZUKI XL~7 07~08
17-1822E		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	25942547;401107;851107	CHEVROLET Equinox 10~17 GMC Terrain 10~17
17-1822F		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	25907424	CHEVROLET Equinox 08~09 PONTIAC Torrent 08~09 SUZUKI XL-7 08~09
17-1822G		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	22711010;401071;851071	CHEVROLET Malibu 2008; Vectra 07~08 PONTIAC G6 05~08 SATURN Aura 07~08
17-1825		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	55077098AA;55077098AC; 55077098AF;55077098AG; 55077098AH;55077098AJ; 55077098AK;55077098AL; 68043386AC;403025;853025	DODGE Ram1500 Pickup 03~09; Ram2500 Pickup 03~10; Ram3500 Pickup 03~10; Ram4500HD Pickup 08~10; Ram5500HD Pickup 08~10

17-1827		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	12365360;12463052;12494772;401027;851027	CADILLAC Escalade 2002; Escalade EXT 2002 CHEVROLET Avalanche 1500 2002; Avalanche 2500 2002; Silverado 1500 99~02; Silverado 1500 HD 01~02; Silverado 2500 99~02; Silverado 2500 HD 01~02; Silverado 3500 01~02; Suburban 1500 00~02; Suburban 2500 00~02; Tahoe 01~02; Tahoe 2000 GMC Sierra 1500 99~02; Sierra 1500 HD 01~02; Sierra 2500 99~02; Sierra 2500 HD 01~02; Sierra 3500 01~02; Yukon 00~02; Yukon XL 1500 00~02; Yukon XL 2500 00~02
17-1827A		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	88958144;401046;851046	CADILLAC Escalade 2003 CHEVROLET Avalanche 1500 2003; Avalanche 2500 2003; Silverado 1500 2003; Silverado 2500 2003; Silverado 3500 2003; Suburban 1500 2003; Suburban 2500 2003; Tahoe 2003 GMC Sierra 1500 2003; Sierra 2500 2003; Sierra 3500 2003; Yukon 2003; Yukon xl 1500 2003; Yukon xl 2500 2003
17-1829		V 12V W 40 RPM.L 45±7 RPM.R 60±7 N.m ≥30	12463070;12487617;12487618;12487679;12487681;12494827;88958170;88958171;401029;851029	BUICK LeSabre 00~05 CADILLAC DeVille 00~05 OLDSMOBILE Aurora 01~03 PONTIAC Bonneville 00~05
17-1829B		V 12V W 40 RPM.L 45±7 RPM.R 60±7 N.m ≥30	12368685	BUICK GL8(别克GL8)

17-1829C		V 12V W 40 RPM.L 45±7 RPM.R 60±7 N.m ≥30	12365393;401025;851025	CHEVROLET Venture 97~05 OLDSMOBILE Silhouette 97~04 PONTIAC Montana 99~05; Trans Sport 97~98
17-1830		V 12V W 40 RPM.L 45±7 RPM.R 60±7 N.m ≥30	12365319;12368703;8123653190;8150360080;401030;851030	CHEVROLET S10 Blazer 98~04; S10 Pickup 98~04 GMC S15 Jimmy 98~04; S15 Somoma 98~04 ISUZU Hombre 98~00 OLDSMOBILE Bravada 98~01
17-1830A		V 12V W 40 RPM.L 45±7 RPM.R 60±7 N.m ≥30	12368695;22121967;8221219670;15740474;401004;851004;	CHEVROLET S10 Blazer 95~97; S10 Pickup 94~97 GMC S15 Jimmy 95~97; S15 Somoma 94~97 ISUZU Hombre 96~97 OLDSMOBILE Bravada 96~97
17-1830B		V 12V W 40 RPM.L 45±7 RPM.R 60±7 N.m ≥30	12368702;15036007;15746785;15740719;40158;85158	CADILLAC Escalade 99~00 CHEVROLET Blazer 92~94; C1500 Pickup 91~99; C1500 Suburban 92~99; C2500 Pickup 91~99; C2500 Suburban 92~99; C3500 Pickup 91~02; K1500 Pickup 91~99; K1500 Suburban 92~99; K2500 Pickup 91~00; K2500 Suburban 92~99; K3500 Pickup 91~00; P30 Van 91~93; Tahoe 95~00; GMC C1500 Pickup 91~99; C1500 Suburban 92~99; C2500 Pickup 91~99; C3500 Pickup 91~02; K1500 Pickup 91~99; K1500 Suburban 92~99; K2500 Pickup 91~99; K2500 Suburban 92~99; K3500 Pickup 91~00; P35/P3500 Van 91~93; Yukon 92~98
17-1838		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	2M5Z17508AA;2M5Z17508AB;6S4Z17508AA;YS4Z17508BB;YS4Z17508CA;0390351364;402038;852038;	FORD Focus 00~07
17-1842		V 12V W 50 RPM.L 40±7 RPM.R 60±7 N.m ≥25	4864892;40442;85442	JEEP TJ 98~02; Wrangler 97~02

17-1830C		V 12V W 40 RPM.L 45±7 RPM.R 60±7 N.m ≥30	22100736;22071770;22100490;22101097;40169;851690;40186	CADILLAC Escalade 99~00 CHEVROLET Blazer 92~94; C1500 Pickup 88~99; C1500 Suburban 92~99; C2500 Pickup 88~99; C2500 Suburban 92~99; C3500 Pickup 88~00; K1500 Pickup 88~99; K1500 Suburban 92~99; K2500 Pickup 88~00; K2500 Suburban 92~99; K3500 Pickup 88~00; P20 1989; P30 Van 89~93; Tahoe 95~00; GMC C1500 Pickup 88~99; C1500 Suburban 92~99; C2500 Pickup 88~99; C2500 Suburban 92~99; C3500 Pickup 88~02;
17-1831		V 12V W 40 RPM.L 45±7 RPM.R 60±7 N.m ≥30	22101637;40192;85192;	CHEVROLET Lumina apv 90~96 OLDSMOBILE Silhouette 90~96 PONTIAC Trans sport 90~96
17-1831A		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	12368704;12494840;15746784;22121186;401003;851003	CHEVROLET Astro 94~05 GMC Safari 94~05
17-1831B		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	22110519;22137782;40159	CHEVROLET G10 92~95; G20 92~95; G30 92~96; P30 93~99; GMC G1500 92~95; G2500 92~95; G3500 92~96; P3500 93~99;
17-1834		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	1F2Z17508AA;F78Z17508AA;402034	FORD Windstar 97~03
17-1834E		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	XR3Z17508AB;XR8Z17508AB;402035;852035;	FORD Mustang 99~04

17-1834A		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	1C3Z17508AA;1L2Z17508AB;2C3Z17508BA;4F1Z17508AB;6C3417500X;F4PU17504CA;F6DU17B571AB;F7DU17B571AA;YL8X17508AA;XR813450;XR816610;XR826762;XR829229;XR836708;XR83678;XR845459;XR852087;XR856070;XR88135;XW4X17B571AA;EC0167340;EC0167340A;6L8Z17508AA;6W1317508CA;6W1Z17508CA;F8VU17B271AA;F8VU17B571AA;F65Z17508AB;F6DZ17508AA;F7RZ17508AA;F80Z17508BA;F81Z17508AA;F8RZ17508AA;F8RZ17508DA;F8RZ17508GA;F8VZ17508BA;XW4Z17508AA;XW4Z17508CA;YL3Z17508AB;YL8Z17508AA;ZZC067350;ZZC067350R00;402010;852010	FORD Cougar 95~00; Mystique 95~00; Sable 96~00; Taurus 96~07; Thunderbird 2000; Escape 01~07; Excursion 00~01; Expedition 97~02; Explorer 2002; F-150 Pickup 97~04; F-250 Pickup 97~99; F-250 Super Duty Pickup 99~01; F-350 Super Duty Pickup 99~01; F-450 Super Duty Pickup 99~01; F-550 Super Duty Pickup 99~01; F53 Stripped Chassis 99~03; F-4000 98~08; F-12000 99~05; F-16000 99~05; F-14000 99~05;
17-1834B		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	F9PZ17508AA;402037	FORD F Super Duty 95~97; F700 95~98; F800 95~99
17-1834C		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	1F8067350;1F8067350A;1F8067350R00;1F8067350R0A;6L5Z17508AA;F7CZ17508AA;F7SZ17508AA;F7UZ17508AA;F87Z17508AB;F8SZ17508AA;ZZP067350;402013;852013	FORD Cougar 96~00; Escort 91~03; Thunderbird 97~00; E Super Duty 96~01; E-150 Econoline 95~04; E-250 Econoline 95~04; E-250 Super Duty 03~04; E-350 Econoline 95~04; E-350 Super Duty 03~04; E-450 Super Duty 03~04; E-550 Super Duty 02~03; Explorer 95~01; Explorer Sport 01~03; Explorer Sport Trac 01~02; Ranger 95~07 MAZDA B2300 01~07; B2500 98~01; B3000 98~07; B4000 98~07 MERCURY Cougar 90~97;

17-1843		V 12V W 50 RPM.L 40±7 RPM.R 60±7 N.m ≥25	5056028AG;55154863;55154863AB;55154863AC;55154863AE;55154863AG;55154863AH;55154863AI;55155092;55155092AD;55155092AE;55155895AA;55155895AB;55155895AD;55155895AE;5515895AD;40443;85443	DODGE Dakota 97~10; Durango 98~03 JEEP Grand Cherokee 99~04; liberty 02~07 MITSUBISHI Raider 06~09 RAM Dakota 2011
17-1843A		V 12V W 50 RPM.L 40±7 RPM.R 60±7 N.m ≥25	55155297AB;55155300AB;40447;854470	JEEP Cherokee 00~01
17-1843B		V 12V W 50 RPM.L 40±7 RPM.R 60±7 N.m ≥25	4723419;4756018;4769121;40440;85440	CHRYSLER Concorde 93~97; Intrepid 93~97; LHS 94~97; New yorker 94~96 DODGE Intrepid 93~97 EAGLE Vision 93~97
17-1843C		V 12V W 50 RPM.L 40±7 RPM.R 60±7 N.m ≥25	4723460;4856478;55154611;55155297;40438;85438	JEEP Cherokee 91~99; Comanche 91~92
17-1848		V 12V W 40 RPM.L 45±7 RPM.R 60±7 N.m ≥30	68383593AA;404005;854005	JEEP Wrangler(吉普牧马人) 18~21
17-1856		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	3F2Z17508AA;6F2Z17508CA;402056;852056	FORD Freestar 04~07 MERCURY Monterey 04~07
17-1856A		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	3W4Z17508AA;6W1Z17508BA;402063	LINCOLN LS 03~06; Town Car 04~07
17-1856B		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	3L5Z17508AA;3W7Z17508AA;5C2Z17508AA;5L2Z17508AB;8C2Z17508B;9C2417504AB;402048;852048	FORD(福特) Crown Victoria 03~06; E-150 05~14; E-250 05~14; E-350 05~19; E-450 05~18; Econoline(依克诺莱恩) 05~14; Explorer Sport Trac 04~05; Grand Marquis 03~04 MERCURY Grand Marquis 03~06; Marauder 03~04

17-1856C		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30	2C3Z17508AA;2L1Z17508AA;2L1Z17508AB;2L2Z17508AB;3L2Z17508AA;3W1Z17508AA;4C3Z17508AA;4L3Z17508AA;6L1Z17508AB;6L1Z17508BA;6L2Z17508AA;6L3Z17508AC;6W1Z17508AA;8C3Z17508A;8C3Z17508D;402036;852036	FORD Excursion 02~05; Expedition 02~06; Exlrler 02~07; Explorer Sport Trac 2007; F-150 04~07; F-150 Heritage 2004; F-250 Super Duty 02~07; F-350 Super Duty 02~07; F-450 Super Duty 02~07; F-550 Super Duty 02~07; Five Hundred 05~07; Freestyle 05~07; Lobo 04~07; Mustang 05~07; Thunderbird 03~05 LINCOLN Aviator 03~05; LS 03~06; Mark LT 06~07; MKX 07~09; Navigator 02~07; Town Car 03~07 MERCUR
17-1862		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	10379535;25809218;8889582230;88958223;401062;851062	CHEVROLET Colorado 04~12 GMC Canyon 04~12 ISUZU i-280 2006; i-290 07~08; i-350 2006; i-370 07~08
17-1867		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	8A8Z17508B;8F9Z17508B;8G1Z17508A;8L1Z17508D;8L2Z17508A;8L3Z17508A;8L3Z17508B;8L8Z17508A;8L8Z17508C;8R3Z17508A;8S4Z17508A;8W1Z17508A;9L3Z17508A;402067;8520670	FORD Focus 08~12; Mustang 08~14; Taurus 09~12; Escape 08~12; Expedition 09~14; Explorer 08~10; Explorer Sport Trac 08~10; F-150 Pickup 08~10; Flex 09~13; Lobo 08~10; Taurus X 08~09 LINCOLN MKS 09~12; Town Car 08~11; Mark LT 2008 MERCURY Sable 2009; Mariner 08~11; Mountaineer 08~10
17-1868A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	8W7Z17508A;WM734	FORD Crown Victoria 03~06 MERCURY Grand Marquis 03~06

17-1868		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	8C3Z17508BA;8C3Z17508C;8L1Z17508A;8L1Z17508C;402068;852068;	FORD Expedition 07~08; F-250 Super Duty Pickup 08~10; F-350 Super Duty Pickup 08~10; F-450 Super Duty Pickup 08~10; F-550 Super Duty Pickup 08~10; F650 08~11; F750 08~11 LINCOLN Navigator 2008
17-1868B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	6W7Z17508AC;8L5Z17508A;91498438;9C2417508AB;9L5417504AB;402074;852074	FORD Crown Victoria 03~06; Ranger 08~11 MERCURY Grand Marquis 03~06
17-1883		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥30	4339449;40383;85383	CHRYSLER Daytona (CANADA) 85~87; Executive Limousine 1985; Fifth Avenue 84~87; Laser 85~86; LeBaron 85~87; New Yorker 85~87; Town & Country 85~87 DODGE 600 85~87; Aries 85~87; Charger 85~87; Daytona 85~87; Diplomat 85~87; Omni 85~87; BE50 Van 85~87; B250 Van 85~87; B350 Van 85~87; Caravan 85~87; D100 Pickup 86~87; D150 Pickup 85~87; D250 Pickup 85~87; D350 Pickup 85~87; Mini Ram 85~8
17-1891		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	7C1917504AB;W503924S427;5810360B01S0000	FORD Transit(福特世代,江铃全顺V348) 06~13 TRUMPCHI(传祺) GA5
17-1891A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	1079510;1097546;1666654;6818241;6922648;93BBE7B571AA;93BBE7B571AB;93BBE7B571AC;93BBE7B571AD;XS7117B571AA;404520	FORD Mondeo 93~00; Transit 00~14

17-1883A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥30	4467258;40385;85385	CHRYSLER Fifth Avenue 88~89; LeBaron 88~89; New Yorker 1988; Maserati 1989; Town & Country 1988 DODGE 600 1988; Aries 88~89; BE50 88~89; B250 88~89; B350 88~89; Caravan 88~89; D100 Pickup 88~89; D150 Pickup 88~89; D250 Pickup 88~89; D350 Pickup 88~89; Daytona 88~89; Diplomat 88~89; Mini Ram 1988; Omni 88~89; Ramcharger 88~89; W100 Pickup 88~89; W150 Pickup 88~89; W250 Pickup 88~89
17-1890		V 12V W 30 RPM.L 40±7 RPM.R 60±7 N.m ≥20	22049815;22062915;88961296;40190;85190	BUICK Skyhawk 82~89 CADILLAC Cimarron 82~88 CHEVROLET Cavalier 82~94; Astro 85~90; S10 Blazer 83~94; S10 Pickup 82~93 GMC S15 Jimmy 83~94; S15 Pickup 82~90; S15 Sonoma 91~93; S15 Syclone 1991; S15 Typhoon 92~93; Safari 85~90 OLDSMOBILE Firenza 82~88; Bravada 91~93 PONTIAC Fiero 84~88; J2000 82~84; Sunbird 85~94; Tempest 87~91
17-1895		V 12V	E3SZ17508A;E6DZ17508B;E6SZ17508A;E7SZ17508A; 40295	FORD Cougar 85~87; Taurus 1986; Thunderbird 83~88 LINCOLN Mark 84~92 MERCURY Cougar 83~88 Sable 1986
17-1904		V 12V W 5 RPM 30? Angle 124?	55154944;55154944AB;40444;85444	JEEP Cherokee 97~01


17-1890A		V 12V W 30 RPM.L 40±7 RPM.R 60±7 N.m ≥20	22062913;88961173;40191	BUICK Skyhawk 84~89 CADILLAC Cimarron 84~88 CHEVROLET Cavalier 84~94; Astro 85~93; S10 Blazer 85~94; S10 Pickup 85~93 GMC S15 Jimmy 85~94; S15 Pickup 85~90; S15 Sonoma 91~93; S15 Syclone 1991; S15 Typhoon 92~93; Safari 85~93 OLDSMOBILE Firenza 84~88; Bravada 91~94 PONTIAC Fiero 85~88; J2000 82~84; Sunbird 85~94; Tempest 87~91
17-1890B		V 12V W 30 RPM.L 40±7 RPM.R 60±7 N.m ≥20	22049813;22049816;401911;851911	BUICK Skyhawk 84~89 CADILLAC Cimarron 84~88 CHEVROLET Cavalier 84~94; Astro 85~93; S10 Blazer 85~94; S10 Pickup 85~93 GMC S15 Jimmy 85~94; S15 Pickup 85~90; S15 Sonoma 91~93; S15 Syclone 1991; S15 Typhoon 92~93; Safari 85~93 OLDSMOBILE Firenza 84~88; Bravada 91~94 PONTIAC Fiero 85~88; J2000 82~84; Sunbird 85~94; Tempest 87~91
17-1895A		V 12V	E0TZ17508B;E2TZ17508A ;E69Z17508B;E79Z17508A; 40290	FORD Aerostar 86~97; Bronco 80~86; F-100 80~83; F-150 80~86; F-250 80~86; F-350 80~86; F700 80~86; F800 80~86
17-1904A		V 12V W 5 RPM 30? Angle 124?	55155317;56006336;40436	JEEP Cherokee(吉普切诺基2500) 91~96

17-1894		V 12V	4205956;40394;85394	CHRYSLER Cordoba 79~83; Imperial 81~83; LeBaron 1979; New Yorker 79~81; Newport 79~81; Town&Country 1979 DODGE Aspen 1979; Diplomat 1979; Magnum 1979; Mirada 80~83; St.Regis79~81; BE00 Van 79~80; BE50 Van 81~84; B200 Van 79~80; B250 Van 81~84; B300 Van 79~80; B350 Van 81~84; D100 Pickup 1979; D150 Pickup 79~84; D200 Pickup 79~80; D250 Pickup 81~84; D300 Pickup 79~80; D350 Pickup
17-1894A		V 12VV	4205951;4205958;4205998; ;4270452;40380;85380	CHRYSLER Daytona(CANADA) 1984; E-Class 83~84; Executive Sedan 1984; Fifth Avenue 83~84; Laser 1984; LeBaron 79~84; New Yorker 82~84; Town&Country 79~94 DODGE 400 82~83; 600 83~84; Aries 81~84; Aspen 76~80; Charger 83~84; Dart 72~76; Daytona 1984; Diplomat 79~84; Omni 78~84; BE00 Van 72~80; BE50 Van 81~84; B200 Van 72~77; B250 Van 81~84; B300 Van 72~80; B350 Van 81~84; Carav
17-1921		V W RPM Angle	12V 5 34? 172?	BT4317404AB;BT4Z17508 A;WM789;402121;852121 0 FORD Edge(福特锐界) 11~14 LINCOLN MKX 11~15

17-1894B		V 12V	2770090;2822252;40350	CHRYSLER New Yorker 1968; Newport 1968 DODGE Charger 68~70; Coronet 68~70; Dart 68~71; Monaco 1968; Polara 1968; A100 69~70; A108 Van 69~70; BE00 Van 1971; B200 Van 1971; B300 Van 1971; D100 Pickup 69~71; D200 Pickup 69~71; D300 Pickup 69~71; W100 Pickup 69~71; W200 Pickup 69~71; W300 Pickup 69~71 PLYMOUTH Barracuda 68~69; Belvedere 68~70; Duster 70~71; Fury 1968; Roadrunner 68
17-1894C		V 12V	3431533;3431606;3431608; 3431718;3431790;40382	CHRYSLER Cordoba 75~79; LeBaron 77~78; New Yorker 72~79; Newport 72~79; Town&Country 77~78 DODGE Challenger 72~74; Charger 72~78; Coronet 72~76; Diplomat 77~78; Magnum 78~79; Monaco 72~78; Polara 72~73; Royal Monaco 75~77; St. Regis 1979 PLYMOUTH Barracuda 72~74; Caravelle 1978; Fury 72~78; Fury I 72~74; Fury II 72~74; FuryIII 72~74; Gran Fury 72~77; Roadrunner 72~75; Satellite 72
17-1907C		V 12V W 5 RPM 39? Angle 171?	12365368;12494790;15053 983;22154965;401005;851 005	CHEVROLET Blazer 95~05 GMC Jimmy 95~05 OLDSMOBILE Bravada 96~01

17-1907B		V 12V W 5 RPM 39? Angle 171?	22154964;401016	CADILLAC Escalade 99~00 CHEVROLET Blazer 92~94; C1500 Suburban 92~99; C2500 Suburban 92~99; K1500 Suburban 92~99; K2500 Suburban 92~99; Tahoe 95~00 GMC C1500 Suburban 92~99; C2500 Suburban 92~99; K1500 Suburban 92~99; K2500 Suburban 92~99; Yukon 92~00
17-1918		V 12V W 5 RPM 30? Angle 172?	4717710AA;4717710AD;5018406AA;403018;853018;	CHRYSLER PT Cruiser 01~03; Town&Country 01~03; Voyager 01~03 DODGE Caravan 01~03; Grand Caravan 01~03
17-1918A		V 12V W 5 RPM 30? Angle 172?	4673010;403004;853004	CHRYSLER Grand Voyager 98 ~00; Town & Country 96 ~00; Voyager 97 ~00 DODGE Caravan 96 ~00; Grand Caravan 96 ~00 PLYMOUTH Grand Voyager 96 ~00; Voyager 96 ~00
17-1919A		V 12V RPM 35? Angle 172?	1466253;1520306;4374755;4419556;6T1617404BB;404739E;064342008010;TGL420H	FORD Tourneo Connect 02~13; Transit Connect 02~13
17-1926		V 12V W 5 RPM 39? Angle 168?	12362550;12363350;12494791;15099936;401026	BUICK(别克) GL8 05~07 CHEVROLET Venture 97~05 OLDSMOBILE Silhouette 97~04 PONTIAC Montana 99~05; Trans Sport 97~98
17-1926A		V 12V W 5 RPM 39? Angle 168?	12365396;401042	CADILLAC Escalade 99~00 CHEVROLET C1500 Suburban 92~99; C2500 Suburban 92~99; K1500 Suburban 92~99; K2500 Suburban 92~99; Tahoe 95~00 GMC C1500 Suburban 92~99; C2500 Suburban 92~99; K1500 Suburban 92~99; K2500 Suburban 92~99; Yukon 92~00

17-1926B		V 12V W 5 RPM 39? Angle 168?	15192152;851058	BUICK GL8(别克) 01~10; Terraza 05~07 CHEVROLET Uplander 05~09 PONTIAC Montana SV6 05~09
17-1928		V 12V W 5 RPM 30? Angle 172?	4857931AA;4857931AB;4857931AC;4857931AD;2518200042;A2518200042;403028;853028	CHRYSLER(克莱斯勒) PT Cruiser(PT 漫步者) 04~10; Town&Country 04~07; Voyager(大捷龙) 06~07 DODGE Caravan 04~07; Grand Caravan 04~07 MB(奔驰) GL320 07~09; GL350 10~14; GL450 07~14; GL550 08~14; GL63 AMG 07~09; ML320 07~09; ML350 06~14; ML450 10~11; ML500 06~07; ML550 08~14; ML63 AMG 07~14; R320 07~09; R350 06~12; R500 06~07; R63 AMG 2007
17-1928A		V 12V W 5 RPM 30? Angle 172?	5113411AA;5113411AB;5113411AC;403045;853045	CHRYSLER Town&Country 08~16; Voyager(克莱斯勒大捷龙) 13~14 DODGE Grand Caravan 08~18 RAM C / V 12~15
17-1928B		V 12V W 5 RPM 30? Angle 140?	55077451AB;55077451AC;55077451AD;55077451AE;55077823AA;55077823AC;55077823AF;55157447AA;403036;853036	CHRYSLER Aspen 07~09 DODGE Durango 04~09; Magnum 05~08; Nitro 07~11
17-1928C		V 12V W 5 RPM 30? Angle 160?	9040307	CHEVROLET Sail(雪佛兰赛欧3) 10~13
17-1928D		V 12V W 5 RPM 30? Angle 172?	96955193	BUICK Encore(别克昂科拉) 12~15 CHEVROLET Trax 14~15 OPEL Mokka 12~15

17-1930		V 12V W 5 RPM 31? Angle 125?	F75Z17508AA;F87Z17508AA;F87Z17508AD;XL1Z17508AA;54902212;402030	FORD Expedition 97~02; Explorer 98~02; Explorer Sport 01~02 LINCOLN Navigator 98~02 MERCURY Mountaineer 98~01
17-1933		V 12V W 5 RPM 30? Angle 162?	2F2217404AA;2F2Z17508AA;402039;852039	FORD Windstar 02~03
17-1939		V 12V W 5 RPM 33? Angle 172?	XF2Z17508AA;XF2217404AC;24010051;402033;852033	FORD Windstar 99~01
17-1943C		V 12V W 5 RPM 34? Angle 165?	4894283AA;4894283AB;403047;403035;	CHRYSLER Pacifica 04~08
17-1944		V 12V W 5 RPM 35? Angle 174?	4L8Z17508AB;EC0167450A;ECY1674L0G;ECY1677L0A;YL8Z17508AB;F006WM0605;402044;852044	FORD Escape 01~07 MERCURY Mariner 05~07 MAZDA Tribute 01~05
17-1949		V 12V W 5 RPM 38? Angle 140?	12487646;15173034;401049;8510490	CADILLAC Escalade 02~06; Escalade ESV 03~06 CHEVROLET Suburban 1500 03~06; Suburban 2500 03~06; Tahoe 03~06 GMC Yukon 03~06; Yukon XL 1500 03~06; Yukon XL 2500 03~06
17-1949A		V 12V W 5 RPM 33? Angle 140?	12487592;15198956;15229806;25805561;8151989560;8152298060;8258055610;401045;851045	BUICK Rainier 04~07 CHEVROLET S10 Trailblazer 04~09 GMC S15 Envoy 04~09 ISUZU Ascender 03~08 OLDSMOBILE Bravada 2004 SAAB 9-7X 05~09
17-1955		V 12V W 5 RPM 22? Angle 174?	15821045;19257184;22695045;25788591;401055;851055	SATURN Trucks Vue 02~06

17-1950		V 12V W 5 RPM 30? Angle 150?	55155122AC;55155122AD ;55155122AF;55155122AG ;55155884AA;55155884AB ;55155884AC;40450;8545 0	JEEP Liberty(吉普自由人) 02~07; Grand Cherokee 99~04
17-1956		V 12V W 5 RPM 32? Angle 164?	5116146AA;5116146AC;51 16146AE;5516146AD;4045 6;85456	DODGE Caliber(道奇酷搏) 07~12 JEEP Compass 07~13; Patriot 07~14
17-1956A		V 12V W 5 RPM 32? Angle 174?	25788749;401108;851108	CHEVROLET Equinox 10~ 17 GMC Terrain 10~17
17-1958		V 12V W 5 RPM 30? Angle 172?	20815337;0390201808;	BUICK(别克) GL8 11~14; GL8FristLand(陆尊) 05~06; Terraza 05~07 CHEVROLET Uplander 05~09 PONTIAC Montana SV6 05~09
17-1958B		V 12V RPM 35? Angle 175?	5F9317404AA;5F9Z17508 AA;0390201804;402061	FORD Freestyle 05~07
17-1962		V 12V W 5 RPM 35? Angle 174?	6L2Z17508AB;7L2Z17508 AA;9L1417508AA;9L2417 W400AA;402062;852062	MERCURY Mountaineer 06~10 FORD Explorer 06~10
17-1975		V 12V W 5 RPM 30? Angle 172?	434478;8L8Z17508D;ZZC 067450;ZZC067450R00;W M693;402075;852075;	FORD Escape 08~12 MAZDA Tribute 08~11 MERCURY Mariner 08~11
17-1976		V 12V W 5 RPM 32? Angle 168?	BB5Z17508B;CJ5Z17508B ;402105	FORD(福特) Escape(翼虎) 13~19; Explorer(探险者) 11~19; Police Interceptor Utility 13~19 LINCOLN MKC 15~18; MKT 13~18
17-1988A		V 12V W 5 RPM 35? Angle 174?	9L1Z17508B;WM773;4020 88;852088	FORD Expedition 10~14 LINCOLN Navigator 10~14

17-1984		V 12V W 5 RPM 38? Angle 135?	15282187;25799536;25923437;401084;851084	CADILLAC Escalade 07~14 CHEVROLE Silverado 1500 07~14; Silverado 2500 07~13; Tahoe 07~14 GMC Yukon 07~14; Yukon XL 1500 07~14; Yukon XL 2500 07~13
17-2388		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	55077859AB;55077859AC; 55077859AD;68002388AA; 40458;85458	JEEP Wrangler(吉普牧马人) 07~16
17-3015		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	4778375;5012170AA;403002;853002;403015	CHRYSLER Cirrus 95~00; Sebring 96~00; Voyager 1996 DODGE Stratus 95~00 PLYMOUTH Breeze 96~00
17-3026		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	5101863AA;68003829AA;0390241963;403026;853026	CHRYSLER Cirrus 04~09; Sebring(克莱斯勒铂锐) 04~09 DODGE Avenger 08~09; Stratus 04~06
17-3027		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	10388353;10388433;15812615;19121120;19177837; MR971984;MR987767;401080;851080;403027	BUICK Lucerne 06~11 CADILLAC SRX 07~09 CHRYSLER Cirrus 03~05; Sebring 03~05; Stratus 03~05 MITSUBISHI Eclipse 03~05; Galant 04~11 PONTIAC Solstice 06~09 SATURN SKY 07~10
17-3030			5135058AA;5135058AC;403030	CHRYSLER Aspen 07~09 DODGE Durango 04~09
17-3043		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	403055;68020720AA;68020720AB;68020720AD;403043	DODGE Nitro 07~11 JEEP Liberty 08~12
17-453		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	91496120;91498221;1155520C;55156374AC;40453;85453	JEEP Wrangler(吉普牧马人) 03~06

17-3049		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	5113043AA;68028446AA;68028446AB;7B0955119;431209;403049;853049	CHRYSLER Town&Country 08~16; Voyager(克莱斯勒大捷龙) 13~14 DODGE Grand Caravan 08~16 RAM C / V 14~15 VW Routan 09~14
17-3050		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	55372141AB;55372141AE;55372141AH;68050422AA;68050422AC;403050;853050	DODGE RAM1500 Pickup 09~10 RAM 1500 11~17; 2500 11~17; 3500 11~17; 4500 11~17; 5500 11~17
17-3089		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	15779727;15846942;23167072;25923882;23328193;851100C030;85110AA040;85110AC010;401089;851089;432059	CADILLAC Escalade(凯迪拉克) 07~17 CHEVROLET Avalanche 07~13; Cheyenne 14~18 Silverado 1500 07~18; Silverado 2500 07~18; Silverado 3500 07~18; Suburban 1500 07~14; Suburban 2500 07~13; Tahoe 07~14 GMC Sierra 1500 07~18; Sierra 2500 08~18; Sierra 3500 08~18; Yukon 07~14; Yukon XL 1500 07~14; Yukon XL 2500 07~14 TOYOTA(丰田) Avalon 06~12; Camry 02~06; Sequoia(红杉) 08~18; Tundra(坦途) 07~18
17-3113		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	22820106;W261624;W302256;4011113;8511113	BUICK Enclave(别克昂科雷) 13~17 CHEVROLET Traverse 13~17 GMC Acadia 13~16 Freightliner Cascadia
17-454		V 12V W 5 RPM 35? ANGLE 174?	55156278AA;F006B20026;40454;85454;	JEEP Wrangler(吉普牧马人) 03~06
17-455		V 12V W 5 RPM 35? ANGLE 160?	55156325AB;55156325AC;55156325AD;40455;85455;	JEEP(吉普) Commander(指挥官) 06~10; Grand Cherokee(大切诺基) 05~10

17-7915		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	12335727;19120756;19178992;4010004;401053;851053	BUICK Allure 2005; Lacrosse 2005 HUMMER H2 08~09 PONTIAC Grand prix 04~05
17-8010		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	47004125	Morgan Olsen / Grumman work horse 1991 & up
17-8016		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	10037748;10003907;16M103	Bluebird Dynamic Wiper Motor, 38Nh;New Blue Bird D3 (2013-10) Wiki
17-8016A		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	6URW1;AX9109;V3DC1;25171502	1987 to 2006 Kenworth C500, 1987 to 2006 Kenworth T300, 1987 to 2006 Kenworth T400, 1987 to 2006 Kenworth T450, 1987 to 2006 Kenworth T600, 1987 to 2006 Kenworth T800, 1987 to 2006 Kenworth W900
17-8016B		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	AX9207; E005554	Kenworth T2000, W900, T800
17-8017		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	AX9208;A2268176000;628163404;61250342;61250343;F006B20150;SPRE008161;16M401	Wester Star 2000
17-8017B		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	TRIF989999229; AX9113	Freightliner Cascadia,Columbia,Coronado(2000+),IHC DuraStar,LoneStar,ProStar,TerraStar,WorkStar
17-8019		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	2208008C91;2511779C91;2204855C1;E008159	International FE300 Bus Series
17-8020		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	E108008;E008224	International Mid 2007- Current 9200/9400/9900/5500/5900 - PayStar (3 bolt), 2005-2007 9200/9400/9900/5500/5900 - PayStar (4 bolt), Pre-2005 9200/9400/9900/5500/5900 requires connector gender kit, Peterbuilt All 387/587, Kenworth 2010-Current C500/T300/T400/T450/T600/ T800/W900 (3 bolt), All

17-8020A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	R231040	KENWORTH T600; T660
17-8020B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	600594600E	TESLA(特斯拉) Model S 12~21
17-8020C		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	E008058	Freightliner FL70,FL80
17-8020D		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	E008109;E008205	Peterbilt 335, 377, 379, 387, 587 And Kenworth T2000
17-8021		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	E108024;E008221	International 1999-Current 4000/8000/7000 series (TerraStar, DuraStar,Work Star), 2007-Current ProStar, LoneStar, TranStar, Freightliner 2000-Current Columbia, Century, Coronado, Cascadia, 2001- Current M2 w/ adapter
17-8021A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	2594086C91;91498288	FREIGHTLINER Cascadia 2010
17-8022		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	25133997;63QT310;85130 425	KENWORTH C500 88~06; T300 95~06; T400 89~98; T800 88~01 MACK LE600 95~07; RB; RD; STRAIGHT TRUCK
17-8023		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	E008172;E006185;E00822 2;1803676	Peterbilt 1985- Current 379 / 330 / 389 / 337 / 348 / 340 / 335 / 386



17-8024		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	E006226;E006158;258974 1C91;57775992;404995	Kenworth 2006-2009;2010 C500;T300;T400;T450;T600; T800;W900(4 bolt)
17-8025		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	85150366;85139507;85122 759;20724391;21000862;8 5122415;20707508;161903 4;20707506;1619049;3980 826;E008225;E008236;E1 08009;E108036	Volvo All VN series
17-8027		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	47004124;47004132;23010 02;49004	Morgan Olsen / Grumman 1991 & up
17-8029		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	E007100	Peterbuilt 387 / 587,Kenworth T2000 / T700
17-8030		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	E008161;E006191;16M401 L	Thomas EF / ER WM Asy W / Dual Plug,Ds,
17-8031		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	170897;E008162;E006192; 16M401R	Thomas EF / ER WM Asy W / Dual Plug,Ds,
17-8032		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	E108011;E008230;251278 14;63QT416A;25099382;6 3QT47;63QT416;63QT46; 63QT520;82149188;63QT 311;62QT311;82716004	Mack MRU612 And MRU613 1988-Present C and CH series - Fusion, Vision, Granite, Pinnacle, Titan

17-8033		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	09801571;28071447A;403878	FORD FFV 00~01
17-8034		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	57759964	CHRYSLER
17-8035		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥25	2504129C91;E108106;E106118	Freightliner
17-8036		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	2586921C9;3586801C9;91498196;91498392	NAVISTAR International
17-8037		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	8169B28	USPS LLV
17-8038		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25		Special Vehicle
17-8039		V 12V W RPM.L RPM.R N.m		Special Vehicle
19-1085		V 24V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	F8038600	LEYLAND INDIA
19-1086		V 24V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30		Left INDIA
19-1086A		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	8498001370	Left INDIA

19-1087		V 24V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30		Left INDIA
19-1087A		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30		Left INDIA
19-1095		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20	3810170A00	SUZUKI KATANA FR
19-1095A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TATA Leyland 709
19-1095B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		XVV INDIA
19-1135		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TATA INDICA
19-1326		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TATA ACE CUB RHD CRS 420 CRS 1341
19-1326H		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TATA ACE CUB RHD CRS 420 CRS 1341 配套专用
19-9001		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TATA INDICA VISTA
19-9001A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		Truck

19-9002		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		MAHINDRA Scorpio INDIA
19-9003		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TATA Nano INDIA
19-9003A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		TOYOTA Innova Reborn 15~
19-9004		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		MAHINDRA Maxximo INDIA
19-9007		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		INDIA
19-9009		V 12V		MAHINDRA XUV500
19-9653		V 24V		



20-1005-L				Wuling(柳州五菱)
20-1006A-L			5205010K01	CHANA Benni MINI(长安奔奔迷你)
20-1008-L				CHANA 462Q(松花江,长安462) SUZUKI ST90
20-1009-L				CHANA SC6350(长安之星)
20-1011-L				FAW XIALI(一汽夏利)
20-1012-L				SUZUKI CHANGHE 1018(昌河1018)
20-1016-L				CHANA Lingyang(长安羚羊)
20-1042-L				Wulingzhiguang(柳州五菱之光)

20-1043		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±		航天汽车成功一号
20-1066		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20		篷车三轮车
20-1121A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±		BYD F3(比亚迪F3) GEELY Vision(吉利远景)
20-1121B		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	5205010H01	CHANA Alsvin V101(长安悦翔)
20-1121C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±		GEELY GX7(吉利全球鹰)
20-1121C-1		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±		GEELY Jingang I (吉利金刚一代)
20-1124		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±		BYD(比亚迪) F0 HAIMA(海马) M5
20-1208		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±		GREAT WALL C30(长城腾翼C30;凌傲)

20-1251		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥25 Angle1 ± Angle2 ±	6020001400	GEELY EC718 EC715-RV(吉利帝豪)
20-1261		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	5205010W01	CHANA CS35 12~16(长安CS35)
20-1261A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	5205010U01	CHANA Eado(长安逸动)
20-1375		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±		ZOTYE Domy(众泰大迈) X5
20-1725		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	6020003600	GEELY(博越) 16~17
20-1781B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	6020003700;W000070430	GEELY FE-7(吉利GS) 16~
20-3245		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	5205010M01;3397021744	CHANA CS75(长安CS75)
20-3245-1		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	5205010AW01;3397022052	CHANA CS55(长安CS55)

20-3245-2		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	6020004800;3397021882	GEELY FE-5 GL(吉利GL) 16~
22-1001			9820022000;9820025000;9820025001	HYUNDAI Santa Fe II 05~12 Accent I 94~00 Accent II 99~06
22-1002			9821043001	HYUNDAI H100 Minib(驤) 97~08
22-1002A-L				KIA Pride IRAN
22-1002-L			8908160066;KKY0167360	KIA Pride(起亚普莱特 中国)
22-1038A-L			96314776;96314777	DAEWOO 大宇 MATIZ 98~15 CHEVROLET 雪佛兰 MATIZ 98~13
22-1073B-L			9820025000;602701	HYUNDAI Accent 97~05 KIA(起亚千里马)
22-1106		V 12V W RPM.L RPM.R N.m	96175535	Daewoo Nexia 95~16
22-1106-L			96175535	Daewoo Nexia 95~16


22-1107-L			96450750;96415083;602248	CHEVROLET AVEO 04~06 AVEO5 06~08 PONTIAC WAVE 06~08 WAVE5 05~07 SUZUKI SWIFT+ 07~08
22-1357-L			96602101	CHEVROLET 雪佛兰 MATIZ 05~13
22-1468		V 12V W 30 RPM.L 42±7 RPM.R 65±7 N.m ≥20	98120F0000	HYUNDAI Elantra(现代领动)
22-1468-L			98120F0000	HYUNDAI Elantra(现代领动)
22-1616-L			9820002000	HYUNDAI 现代 ATOS 98~03
22-1633A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	98120A1000	HYUNDAI(现代胜达) IX45 13~17
22-1633A-L			98120A1000	HYUNDAI(现代胜达) IX45 13~17
22-1635-1			981502E010;981502E000	HYUNDAI Tucson(现代途胜) 05~09
22-1635-1L			981502E010;981502E000; 602740	HYUNDAI Tucson(现代途胜) 05~09
22-1635-4L			981201F000;DORMAN.60 2722	KIA SPORTAGE 05~10

22-1636		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981202S000	HYUNDAI Tucson(现代途胜) 10~15; IX35 10~15
22-1636-L			981202S000;602727	HYUNDAI Tucson(现代途胜) 10~15; IX35 10~15
22-1638		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	981203S000;	HYUNDAI Azera(雅尊) 11~17; Sonata(索纳塔8) 11~19
22-1638-L			981203S000;602049	HYUNDAI Azera(雅尊) 11~17; Sonata(索纳塔8) 11~19
22-1639-L			981201G000	HYUNDAI (现代) 雅绅特 05~10
22-1642		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	981202L000	HYUNDAI I30 07~12
22-1642-1		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30	98120A2000	KIA CEED 12~19
22-1642-1L			98120A2000	KIA CEED 12~19
22-1642-L			981202L000;981201H000	HYUNDAI I30 07~12
22-1648			981201R000	Hyundai Solaris 11~17

22-1648A-L			981204H000	HYUNDAI 现代 Starex H1 07~15
22-1648-L			981201R000	HYUNDAI Solaris 10~17 Accent 10~17 KIA RIO 10~17
23-1001			MB415264	mitsubishi DELICA L200 87~95
23-1002			MR109453	Mitsubishi L200 Triton 96~05
23-1022-L				SUZUKI Alto(铃木奥拓)
23-1242-L			288419Z400;28842S3801; 288509Z400;288609Z400; 602016	NISSAN Frontier 01~04; NP300 09~15; Xterra 00~04
23-1251A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±		SUZUKI Swift(铃木雨燕) 05~13
23-1345-L			28840JG40A;28820JG40A ;28841JG40A;28841JG40 A;288001DA0A	NISSAN X-Trail T31(尼桑奇 峻) 07~14
23-1346		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	28800ZX01A;28800ZY80A ;	NISSAN Altima 07~13; Maxima 09~15


23-1346-L			28800ZX01A;28800ZY80A; 602025	NISSAN Altima 07~13; Maxima 09~15
23-1405B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	76530TK6A01;	HONDA Fit,Jazz(本田飞度) 08~14
23-1405B-L			76530TK6A01;602529	HONDA Fit,Jazz(本田飞度) 08~14
23-1407-L			8515008010;852028LK;60 2414	TOYOTA Sienna 98~03
23-1433		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30		FORD Fusion 06~11 LINCOLN Zephyr 06~ MAZDA(马自达) 6 03~08 MERCURY Milan 06~11
23-1433-2		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	8515047110;8515047111;8 515047120;8515047121	TOYOTA Prius 09~15(RHD)
23-1433-2L			8515047110;8515047111;8 515047120;8515047121	TOYOTA Prius 09~15(RHD)
23-1433B-L			851500D200	TOYOTA Vios 14~18
23-1433-L			GP7B67360;GK2C67360B ;6E5Z17566A;602313;602 611;602612	FORD Fusion 06~11 LINCOLN Zephyr 06~ MAZDA(马自达) 6 03~08 MERCURY Milan 06~11

23-1436		V 12V W 60 RPM.L 42±7 RPM.R 62±7 N.m ≥35 Angle1 ± Angle2 ±	8515007030;602417AS	TOYOTA Avalon 00~05
23-1436-L			8515007030;852036LK;602417	TOYOTA Avalon 00~05
23-1437		V 12V W 30 RPM.L 42±7 RPM.R 65±7 N.m ≥20	3810078M00;	SUZUKI Alivio(铃木启悦) 15~
23-1438		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	8515005060;851501A030	TOYOTA Avensis 03~08; Corolla E12(丰田花冠) 03~07
23-1438A-L			8515026160	TOYOTA(丰田) Hiace 05~
23-1438B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	851500D030;851500D040	TOYOTA Vios(丰田威驰) 04~06
23-1438B-1		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	8515001020;851500F020; 8515002090;88969919;	PONTIAC Vibe 03~08 TOYOTA Corolla(丰田花冠) 03~08; Matrix 03~08
23-1438B-1L			8515001020;851500F020; 8515002090;88969919;602402	PONTIAC Vibe 03~08 TOYOTA Corolla(丰田花冠) 03~08; Matrix 03~08
23-1438B-2		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30		TOYOTA Land Cruiser(丰田 兰德酷路泽) 02~15 LEXUS GX470 03~09

23-1438B-2L			8515060250;8515060270;602472	TOYOTA Land Cruiser(丰田兰德酷路泽) 02~15 LEXUS GX470 03~09
23-1438B-3		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30	8515048060;	TOYOTA Highlander(丰田汉兰达) 01~07
23-1438B-3L			8515048060;602410	TOYOTA Highlander(丰田汉兰达) 01~07
23-1438B-4L			851500K081	TOYOTA INNOVA 04~14
23-1438B-L			851500D030;851500D040	TOYOTA Vios(丰田威驰) 04~06
23-1438-L			8515005060;851501A030	TOYOTA Avensis 03~08; Corolla E12(丰田花冠) 03~07
23-1440-1		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25	76530S10A01;602502AS	HONDA CRV 97~01
23-1440-1L			76530S10A01;602502	HONDA CRV 97~01
23-1440-L			76500S5AA00;76530S5AA01;602521	HONDA CIVIC 01~02
23-1442		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±		NISSAN Qashqai(尼桑逍客) 07~

23-1442-L			28800JD900PART	NISSAN Qashqai(尼桑逍客) 07~
23-1446-L			288409W100	NISSAN Tenan(尼桑天籁) 06~08
23-1447		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25 Angle1 ± Angle2 ±	76530SWAA01;76530SWAG01;	HONDA(本田) CRV 07~12
23-1447-1		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25 Angle1 ± Angle2 ±	76530TA0A01;602524AS	HONDA(本田) Accord(雅阁) 08~12; Accord Crosstour 10~11; Crosstour(歌诗图) 12~13
23-1447-1L			76530TA0A01;602524	HONDA(本田) Accord(雅阁) 08~12; Accord Crosstour 10~11; Crosstour(歌诗图) 12~13
23-1447A		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25 Angle1 ± Angle2 ±	76530SDAA01;602508AS	HONDA Accord(本田雅阁) 03~07
23-1447A-L			76530SDAA01;858528LK;602508	HONDA Accord(本田雅阁) 03~07
23-1447C		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25 Angle1 ± Angle2 ±	76530S9AA01;	HONDA CRV 02~06
23-1447C-L			76530S9AA01;858517LK;602510	HONDA CRV 02~06


23-1447E		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25 Angle1 ± Angle2 ±	86521AE05A;86521AE06A ;	SUBARU Baja 03~06; Legacy 00~04; Outback 00~04
23-1447E-L			86511AE04A;86521AE05A ;86521AE06A;602817	SUBARU Baja 03~06; Legacy 00~04; Outback 00~04
23-1447-L			76530SWAA01;76530SW AG01;858568LK;602527	HONDA(本田) CRV 07~12
23-1448-L			28800PA001BE55	NISSAN Sunny 2003~05(尼 桑阳光)
23-1451		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25 Angle1 ± Angle2 ±	28840AX70A;28840AX700	NISSAN Micra 03~10
23-1451-L			28840AX70A;28840AX700 ;1155646B	NISSAN Micra 03~10
23-1452-1L			76530SAAG01;7653SLNA 01	HONDA Jazz 02~08; Fit(本田飞度) 07~08
23-1459A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	288004AA0A	NISSAN Almera(G15) 12~18
23-1459A-L			288004AA0A	NISSAN Almera(G15) 12~18

23-1461			288003JA1A;288003JA3A; 288003JA5D;	INFINITI JX35 2013; QX60 14~19 NISSAN Pathfinder 13~19
23-1461-L			288003JA1A;288003JA3A; 288003JA5D;602042	INFINITI JX35 2013; QX60 14~19 NISSAN Pathfinder 13~19
23-1466-L			76530SENH01	HONDA Fit(本田飞度三厢)
23-1467		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	851500R010;8515042150; 602431AS	TOYOTA RAV4 06~14
23-1467C		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	8515012A70;602445AS	TOYOTA Corolla(丰田卡罗拉) 09~13
23-1467C-1		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	851500D130;851500D140	TOYOTA Vios(丰田威驰) 08~12
23-1467C-1L			851500D130;851500D140	TOYOTA Vios(丰田威驰) 08~12
23-1467C-L			8515012A70;852067LK;602445	TOYOTA Corolla(丰田卡罗拉) 09~13
23-1467-L			851500R010;8515042150; 602431	TOYOTA RAV4 06~14


23-1723D		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	28800JD000	NISSAN Qashqai 07~13 (RHD)
23-1723D-L			28800JD000	NISSAN Qashqai 07~13 (RHD)
23-3323-L			86521FC010;86521FC020;602803	SUBARU Forester 98~01
23-3350-L			MB952178	MITSUBISHI Carisma 99~
23-3351-L			MB821114	MITSUBISHI Mirage 93~96
23-3413-L				SF13
23-3918-L			86521FA010;86521FA020;86521FA060;86521FA090;602815	SUBARU Impreza 98~01
23-3919A-L			851500C010;851500C030;602441	TOYOTA Tacoma 00~03
23-3919B-L			8515004020;8515035200;602407	TOYOTA 4Runner 96~02; Tacoma 96~04



23-3923-L			8515038010	TOYOTA T.U.V KF80
23-3939A-L			BP4K67360E;BP4K67360A;BP4K67360B;BP4K67360C;BP4K67360D;602614	MAZDA 3 04~09
25-1019B-1		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	1C1955603;1C1955603A;	VW Beetle 98~10; Golf 99~10; GTI 2006; Jetta 99~09
25-1019B-1L			1C1955603;1C1955603A;602602	VW Beetle 98~10; Golf 99~10; GTI 2006; Jetta 99~09
25-1019B-2		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	1H0955325;1H1955603;	VW Cabrio 95~02; Golf 93~99; Jetta 93~99; Vento 91~98
25-1019B-2L			1H0955325;1H1955603;602601	VW Cabrio 95~02; Golf 93~99; Jetta 93~99; Vento 91~98
25-1019B-3L			6X1955603A;3397020436;	SEAT Arosa 97~04 VW Lupo 98~05
25-1019-L			321955605;321955605A;3390792122	VW Passat 81~85; Santana(大众桑塔纳2000) 81~85
25-1032C		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	0028202741;9018200081;A0028202741;A9018200081;2D1955603;5124570AA;	DODGE Sprinter 2500,3500 03~06; FREIGHTLINER Sprinter ;2500,3500 03~06; MB Sprinter 95~06 ; VW LT 96~06


25-1032C-L			0028202741;9018200081; A0028202741;A9018200081; 2D1955603;5124570AA; 853044LK;602109	DODGE Sprinter 2500,3500 03~06; FREIGHTLINER Sprinter 2500,3500 03~06; MB Sprinter 95~06; VW LT 96~06
25-1124-L				CITROEN C1 05~ ; PEUGEOT 107 05~ ; TOYOTA Aygo 05~10
25-1125E		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	1274137;6772571;23001901; 93196317	OPEL&VAUXHALL ; Corsa C 00~09; Tigra 04~
25-1125E-1L			6272567;23002667;93196313; 1274053	OPEL Combo 01~
25-1125E-1LL			1274137;6772571;23001901; 93196317	OPEL&VAUXHALL ; Corsa C 00~09; Tigra 04~
25-1125E-2LL			1274137;6772571;23001901; 93196317	OPEL&VAUXHALL ; Corsa C 00~09; Tigra 04~
25-1125E-L			1274137;6772571;23001901; 93196317	OPEL&VAUXHALL ; Corsa C 00~09; Tigra 04~
25-1392-L			1272347;13277077;602097	BUICK Regal(别克君威) 11~17; OPEL Insignia 08~
25-1392		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	1272347;13277077;	BUICK Regal(别克君威) 11~17; OPEL Insignia 08~

25-1395		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	54528411;28800JY40A	RENAULT Koleos(科雷傲) 17 ~
25-1395-L			54528411;28800JY40A	RENAULT Koleos(科雷傲) 17 ~
25-1433		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	LR033035	LAND ROVER Range Rover(路虎揽胜,揽胜运动版) 13~17
25-1433-L			LR033035	LAND ROVER Range Rover(路虎揽胜,揽胜运动版) 13~17
25-1528			6405.J6;9675777180;ZQ9 2244780;ZQ92244880	PEUGEOT(标致) 307 09~ 14; CITROEN(雪铁龙); Quatre(世嘉) 09~14; Triomphe(凯旋) 09~14
25-1528-L			6405.J6;9675777180;ZQ9 2244780;ZQ92244880	PEUGEOT(标致) 307 09~ 14; CITROEN(雪铁龙); Quatre(世嘉) 09~14; Triomphe(凯旋) 09~14
25-1702		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	1J1955113C;1J1955603B; 602650AS	SKODA Octavia 97~10 VW(大众) BORA(宝来) 06~08; Golf(高尔夫) 02~06; Golf City 07~10; Jetta 02~05; Jetta City 07~09
25-1702-L			1J1955603;1J1955603A;1J 1955603B;1U1955603;1U1 955603A;1U1955603B;1U 1955603C;1U1955023E;1 U1955023F;602650	SKODA Octavia 97~10; VW(大众) BORA(宝来) 06~08; Golf(高尔夫) 02~06; Golf City 07~10; Jetta 02~05; Jetta City 07~09



25-1705		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	8D1955603A;	AUDI A4,S4 94~00; VW Passat B5 96~00
25-1705-L			8D1955603A;602605	AUDI A4,S4 94~00; VW Passat B5 96~00
25-1706		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	46784604;51705235;06401 2003010;TGE511C	FIAT Stilo 01~08
25-1706B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	4BE955603B;4BE955325A ;8D1955326B;	AUDI A6 02~05
25-1706B-L			4BE955603B;4BE955325A ;8D1955326B;602637	AUDI A6 02~05
25-1706B-L1			8D1955326B	AUDI A6 97~05
25-1706-L			46784604;51705235;06401 2003010;TGE511C	FIAT Stilo 01~08
25-1710A		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40 Angle1 ± Angle2 ±	2518201542;A2518201542 ;404929	MB(奔驰) R-CLASS(W251) 06~07
25-1710A-L			2518200041A2518200041	MB(奔驰) R-CLASS(W251) 05~13

25-1711-L			8K1955023B;8K1955023C	AUDI(奧迪) A4,S4 08~15
25-1712-L			7L0955601C	VW Touareg 06~10
25-1713		V 12V N.m ≥40 Angle1 ± Angle2 ±	4L1955023C;4L1955023D; 4L1955023F;	AUDI(奧迪) Q7 07~13
25-1713-L			4L1955023C;4L1955023D; 4L1955023F;602635	AUDI(奧迪) Q7 07~13
25-1718		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	1356133080;1356163080;0 64300336	FIAT(RHD) Fiorino 07~15; Qubo 08~15
25-1718-1		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	51753759;64300335;TGE CS05B	FIAT Grande Punto 05~17; Linea 07~17
25-1718-1L			51753759;64300335;TGE CS05B	FIAT Grande Punto 05~17; Linea 07~17
25-1718-2		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	1354851080;1371045080;1 608189580;6401.G6;06430 0334010;TGECS05A	CITROEN Nemo Kasten 08~10; FIAT Fiorino Kasten 07~20; Kombi 07~20; PEUGEOT Bipper 08~20
25-1718-2L			1354851080;1371045080;1 608189580;6401.G6;06430 0334010;TGECS05A	CITROEN Nemo Kasten 08~10; FIAT Fiorino Kasten 07~20; Kombi 07~20; PEUGEOT Bipper 08~20

25-1718-L			1356133080;1356163080;064300336	FIAT(RHD) Fiorino 07~15; Qubo 08~15
25-1719A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	288001683R;7701057358; 064300021010;TGECSM2 1A	RENAULT Megane II (雷诺梅甘娜) 02~
25-1719A-L			288001683R;7701057358; 064300021010;TGECSM2 1A	RENAULT Megane II (雷诺梅甘娜) 02~
25-1722B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	28800CJ00AB064	NISSAN Livana(尼桑骊威); Note 06~
25-1722B-1		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	7701061590;8200268931	RENAULT Clio III 06~12
25-1722B-1L			7701061590;8200268931	RENAULT Clio III 06~12
25-1722B-L			288009U10B;	NISSAN Livana(尼桑骊威); Note 06~
25-1722C			8200409692;54526811;540 01902	RENAULT Kangoo II 08~19
25-1722C-L			8200409692;54526811;540 01902	RENAULT Kangoo II 08~19


25-1723C			7701043887;7701046179	RENAULT Kangoo I 97~
25-1723C-L			7701043887;7701046179	RENAULT Kangoo I 97~
25-1723F			6001547913;6001550803;8200209866;8200619512;3397020879	DACIA Logan 06~10 Sandero 08~11
25-1723F-1			288006475R;288003099R;288002117R;W000037253	DACIA Sandero 13~20 (RHD)
25-1723F-1L			288006475R;288003099R;288002117R;W000037253	DACIA Sandero 13~20 (RHD)
25-1723F-L			6001547913;6001550803;8200209866;8200619512;	DACIA Logan 06~10 Sandero 08~11
25-1723H-L			6401G0;6401A5	CITROEN Berlingo 02~12; PEUGEOT Partner 96~16
25-1725C		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	288008961R;288004542R;288A53268R	RENAULT ClioIV 12~20
25-1725C-L			288008961R;288004542R;288A53268R	RENAULT ClioIV 12~20



25-1728		V 12V	1K1955601;1K1955601A;5K1955601	VW(大众) Eos 06~; Golf V 03~09; Golf VI(高尔夫) 08~13; Jetta III 05~10; Scirocco(速腾) 08~11
25-1728-1			3T1955023;3T1955023A;3T1955601;3TD955023;3397021210	SKODA Superb(斯柯达昊锐) 08~15
25-1728-1L			3T1955023;3T1955023A;3T1955601;3TD955023;3397021210	SKODA Superb(斯柯达昊锐) 08~15
25-1728-3L			8P1955601A;602125	Audi A3 06~08
25-1728-4			5L1955601;5LD955023;5L1955023;5L1955023A	SKODA Yeti(斯柯达野帝) 14~17
25-1728-4L			5L1955601;5LD955023;5L1955023;5L1955023A	SKODA Yeti(斯柯达野帝) 14~17
25-1728-L			1K1955601;1K1955601A;5K1955601	VW(大众) Eos 06~; Golf V 03~09; Golf VI(高尔夫) 08~13; Jetta III 05~10; Scirocco(速腾) 08~11
25-1731A-L			0008201340;A0008201340;5574381	MB(W638) V-Class 97~03; Vito 97~03; Viano 97~03
25-1741		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	2300064;DLS100100	LAND ROVER Freelander 96~06(RHD)



25-1741-L			DLS100100	LAND ROVER Freelander 96~06(RHD)
25-1741A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	23000339;22116543;22116541	LAND ROVER Discovery 98-04(RHD)
25-1741A-L			23000339;22116543;22116541	LAND ROVER Discovery 98-04(RHD)
25-1741B			22115702;AMR1515;PRC7096	LAND ROVER Discovery 94~99; Range Rover 87~91
25-1744		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	DLS500020;DLS500040;LR038348;	LAND ROVER(路虎) LR3,4(发现3,4) 05~16; Range Rover Sport(揽胜运动1,2) 06~13
25-1744-L			DLS500020;DLS500040;LR038348;602136	LAND ROVER(路虎) LR3,4(发现3,4) 05~16; Range Rover Sport(揽胜运动1,2) 06~13
25-1745-L			DLS100110; 602028	LAND ROVER Freelander(路虎神行者1) 02~05
25-1745		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	DLS100110;	LAND ROVER Freelander(路虎神行者1) 02~05
25-1745A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	DKD100620	LAND ROVER Discovery 98~04

25-1745A-L			DKD100620	LAND ROVER Discovery 98~04
25-1751		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	46524670;46834851;51704325;064012005010;TGE511E;MS15901076204E	FIAT Punto 99~09
25-1751A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	1270001;1274142;2190397;24450202;064352403010;TGE524C	OPEL Astra G 98~09; VAUXHALL Astra 98~09
25-1751B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	46524671;51704326;517043260	FIAT(RHD) Punto 99~09
25-1753		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	6405LK;9680694380;9682861480	CITROEN Berlingo 08~18; PEUGEOT Partner 08~18
25-1753-L			6405LK;9680694380;9682861480	CITROEN Berlingo 08~18; PEUGEOT Partner 08~18
25-1754		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	9806872780;3397021736	PEUGEOT(标志) 2008
25-1754-1			9650380780;0390241540	PEUGEOT 207CC 06~09

25-1754-1L			9650380780;0390241540	PEUGEOT 207CC 06~09
25-1754-L			9806872780;3397021736	PEUGEOT(标志) 2008
25-1755		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	6Q2955601B;3398009601	VW Polo(RHD) 02~09
25-1755-1		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	1273421;93179150;13111211;3397020632	OPEL Astra H 04~14
25-1755-1L			1273421;93179150;13111211;3397020632	OPEL Astra H 04~14
25-1755-3		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	51810592;0390241564	FIAT Doblo II 10~19; OPEL Combo D 12~19
25-1755-3L			51810592;0390241564	FIAT Doblo II 10~19; OPEL Combo D 12~19
25-1755B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	6R1955023A;6R1955023B;6R1955023C	SEAT Ibiza 08~10; VW Polo 09~12
25-1755B-1L			56D955023A;573304	VW Passat(大众帕萨特) 11~17

25-1755B-2L			34D955023A; 34D955023B;573305	VW Santana(大众桑塔纳) 13~19
25-1755B-3			56D955023;56D955023A;	VW Passat(大众帕萨特) 11~17
25-1755B-3L			56D955023;56D955023A;	VW Passat(大众帕萨特) 11~17
25-1755B-L			6R1955023A;6R1955023B; 6R1955023C	SEAT Ibiza 08~10; VW Polo 09~12
25-1755-L			6Q2955601B;3398009601	VW Polo(RHD) 02~09
25-1756		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	46826562;51727384;BOS HC.3397020595	LANCIA Ypsilon 03~11
25-1756-1		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	46556570;50501305;50502 816	ALFA ROMEO 147 03~11; GT937 03~11
25-1756-1L			46556570;50501305;50502 816	ALFA ROMEO 147 03~11; GT937 03~11
25-1756-3		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	6Q1955601;6Q1955601B; 6Q1955603A;3397020625	VW Polo(大众波罗) 01~09

25-1756-3L			6Q1955601;6Q1955601B; 6Q1955603A;3397020625	VW Polo(大众波罗) 01~09
25-1756-L			46826562;51727384;BOS HC.3397020595	LANCIA Ypsilon 03~11
25-1759		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	8E1955023E	AUDI A4 00~10
25-1759-L			8E1955023E	AUDI A4 00~10
25-1764A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	1334799080;6405L7;06432 0607010;TGE206G	FIAT Ducato 02~06; CITROEN Jumper 02~06; PEUGEOT Boxer 02~06
25-1764A-L			99493930; 1304086080;08557016801 0	FIAT Ducato 02~06; CITROEN Jumper 02~06; PEUGEOT Boxer 02~06
25-1766		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	46408351;064320901010; TGE209A	LANCIA Y 95~03
25-1766-L			46408351;064320901010; TGE209A	LANCIA Y 95~03
25-1770		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	60694874;3397020724	ALFA ROMEO 159 09~11; Brera 09~; Spider 09~

25-1770-1		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	61617051670;3397020616;	BMW X3(E83 RHD) 03~11
25-1770-1L			61617051670;3397020616;	BMW X3(E83 RHD) 03~11
25-1770-2		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	50509396;3397021178	ALFA ROMEO Giulietta 10~19
25-1770-2L			50509396;3397021178	ALFA ROMEO Giulietta 10~19
25-1770-L			60694874;3397020724	ALFA ROMEO 159 09~11; Brera 09~; Spider 09~
25-1771		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	561955023B;561955023C; 602162	VW Passat 12~19
25-1771-L			56D955023;56D955023A;	VW Passat 12~19
25-1773		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	61617051669;	BMW(宝马) X3(E83) 03~10


25-1773A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	61617071693;602902AS	BMW(宝马) 3(E46) 98~06; M3 01~05
25-1773A-L			61617071693;602902	BMW(宝马) 3(E46) 98~06; M3 01~05
25-1773-L			61617051669;602904	BMW(宝马) X3(E83) 03~10
25-1775		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	61614418698;6161484860 3;61617153733;616172005 10;	BMW(宝马) X5(E70) 07~13; X6(E71) 08~14
25-1775B		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	61617161711;	BMW(宝马) 3-Series(E90 LHD) 05~11
25-1775B-L			61617161711;602000	BMW(宝马) 3-Series(E90 LHD) 05~11
25-1775C			61612990025;7324853	BMW X1 (宝马E84) 10~15
25-1775C-L			61612990025;7324853	BMW X1 (宝马E84) 10~15
25-1775D		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	61617192963	BMW 1-Series (宝马 E81,E82,E88,E87) 04~13

25-1775D-L			61614877149;61614877155;61617061846;61617157789;	BMW 1-Series (宝马 E81,E82,E88,E87) 04~13
25-1775-L			61614418698;61614848603;61617153733;61617200510;602906	BMW(宝马) X5(E70) 07~13; X6(E71) 08~14
25-1777A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	46804522;064351107010; TGE511G	FIAT Panda 03~
25-1777A-L			46804522;064351107010; TGE511G	FIAT Panda 03~
25-1777C-1		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	1747197;1580507;51787565;51793271;52032581;BS5117K484AB;064351113000;TGE5110	ABARTH 500 08~ FIAT 500C 09~22; 500 07~22; FORD KA 08~
25-1777C-1L			1747197;51787565;51793271;52032581;BS5117K484AB;064351113000;TGE5110	FIAT 500(312) 07~22
25-1777C-2		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	51833650;52025797;64351117; 064351117010;TGE511S	LANCIA Ypsilon 11~19
25-1777C-2L			51833650;52025797;64351117;064351117010;TGE511S	LANCIA Ypsilon 11~19
25-1778		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40 Angle1 ± Angle2 ±	DKD000010U;LR035806U	LAND ROVER Range Rover(路虎揽胜) 03~12

25-1778-L			DKD000010U;LR035806U	LAND ROVER Range Rover(路虎揽胜) 03~12
25-1779A			1270814;1272127;13182340;13432685;13432686;36754612;367546129	OPEL CORSA D 06~14
25-1779A-L			1270814;1272127;13182340;13432685;13432686;36754612;367546129	OPEL CORSA D 06~14
25-1780		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	46830275;51829704;51876187;MAKO.064351109000;TGE511I	FIAT Idea 03~ LANCIA Musa 04~12
25-1781		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	61614848613;61617239510;61617260488	BMW(宝马) 1(F20,F21) 10~16; 3(F30,F31,F35,F80) 11~16
25-1781-L			61614848613;61617239510;61617260488	BMW(宝马) 1(F20,F21) 10~16; 3(F30,F31,F35,F80) 11~16
25-1782		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	288815246R;8200734788;93197308	OPEL Movano B 10~ 19; RENAULT MasterIII 10~ 19
25-1782-L			288815246R;8200734788;93197308	OPEL Movano B 10~ 19; RENAULT MasterIII 10~ 19

25-1784		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	51843622;52024852;064351116010;TGE511R	FIAT Panda 12~20
25-1784-L			51843622;064351116010;TGE511R	FIAT Panda 12~20
25-1785		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40 Angle1 ± Angle2 ±	61617114460;61617131164;61617176377;61617179433;61617194029	BMW(宝马) 5-SERIES(E60,E61,E63,E64) 02~10
25-1785B		V 12V W 50 RPM.L 40±7 RPM.R 68±7 N.m ≥40 Angle1 ± Angle2 ±	68017435AA;9068200040;2E0955023;A9068200040;	DODGE Sprinter 2500 07~09; Sprinter 3500 07~09; MB Sprinter(W906) 10~16; VW Crafter 06~
25-1785B-L			68017435AA;9068200040;2E0955023;A9068200040;	DODGE Sprinter 2500 07~09; Sprinter 3500 07~09; MB Sprinter(W906) 10~16; VW Crafter 06~
25-1785-L			61617114460;61617131164;61617176377;61617179433;61617194029	BMW(宝马) 5-SERIES(E60,E61,E63,E64) 02~10
25-1788		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	61617292653;61617350336	BMW(宝马) X5(F15) 14~18; X6(F16) 14~19
25-1788-L			61617292653;61617350336	BMW(宝马) X5(F15) 14~18; X6(F16) 14~19

25-1799		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	46804975;060500101010; TGE223A	FIAT Doblo 01~10
25-1799-L			46804975;060500101010; TGE223A	FIAT Doblo 01~10
25-1891C		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±		VOLVO(沃尔沃) XC90 03~14
25-1891C-L			8693848;86938480;86938487	VOLVO(沃尔沃) XC90 03~14
25-1892		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	86483435	VOLVO(沃尔沃) S60 01~09; S80 99~06; V70 01~07
25-1892-L			86483435	VOLVO(沃尔沃) S60 01~09; S80 99~06; V70 01~07
25-2904		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	12757154;602364AS	SAAB 9-3 05~11
25-2904A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	12757155	SAAB 9-3 02~15(RHD)

25-2904A-L			12757155	SAAB 9-3 02~15(RHD)
25-2904-L			12757154;602364	SAAB 9-3 05~11
25-4080		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	1340683080;1363338080;064352101010;TGE521A	CITROEN Jumper 06~; FIAT Ducato 06~; PEUGEOT Boxer 06~
25-4080A			1363399080;1343896080;064352102010;TGE521B;	FIAT Ducato 06~11 PEUGEOT Boxer 06~10 CITROEN Jumper 06~10
25-4080A-L			1363399080;1343896080;064352102010;TGE521B;	FIAT Ducato 06~11 PEUGEOT Boxer 06~10 CITROEN Jumper 06~10
25-4080-L			1340683080;1363338080;064352101010;TGE521A	CITROEN Jumper 06~; FIAT Ducato 06~; PEUGEOT Boxer 06~
25-4081		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	1400456480;064352103010;TGE521C	CITROEN Dispatch 07~; Jumpy 07~; FIAT Scudo 07~ For ; PEUGEOT Expert 07~
25-4081-L			6405GE;064052103010;TGE521CM	CITROEN Dispatch 07~; Jumpy 07~; FIAT Scudo 07~ For; PEUGEOT Expert 07~
25-4082		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	7E1955113;7E1955113A;7E1955113B;7H1955603A;7H1955023B;443122351017;064052111010	VW T5 04~14

25-4082-L			7H1955603;7H1955603A	VW Multivan T5 03~
25-4526		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	500362502;500395028;504019897;504033863;504084722	IVECO DAILY III 99~07
25-4526-L			42535712;42536088;9900333	IVECO DAILY III 99~07
25-4545		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	6272569;93196316;93604545	OPEL Corsa 02-06(RHD)
25-4545-L			6272569;93196316;93604545	OPEL Corsa 02-06(RHD)
25-5039		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	LR002253;LR055421;LR072416	LAND ROVER LR2(路虎神行者2) 08~13
25-5039A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	LR002254;405040	LAND ROVER Freelander2 06~14 (RHD)
25-5039A-1		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	W0027101;LR078300;LR075361;LR024224	LAND ROVER Evoque(路虎极光) 12~17

25-5039A-1L			W0027101;LR078300;LR075361;LR024224	LAND ROVER Evoque(路虎极光) 12~17
25-5039A-L			LR002254;405040	LAND ROVER Freelander2 06~14 (RHD)
25-5039D		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	5J1955023A;5J1955023B; 5J1955023C;5J1955023D;	SKODA Fabia 00~;
 Roomster 06~10
25-5039D-L			5J0955326;5J1955601;5J1955605B	SKODA Fabia 00~; Roomster 06~10
25-5039-L			LR002253;LR055421;LR072416	LAND ROVER LR2(路虎神行者2) 08~13
25-5923B-L			2028200341A2028200341	MB C-CLASS 93~01
25-5923-L			2108200041;A2108200041;3398009399	MB E-CLASS 95~03
25-5924A-L			61618215988	BMW 3-SERIES 95~99
25-5924B-L			61611387398;61611387403;61611387404;602901	BMW 3-SERIES 91~99; M3 96~98

25-5926-L			6Y1955603;6Y1988023	SKODA Fabia 99~08
25-5930-L			8E1955603B;8E1955603C; 8E1955603D	AUDI A4,S4 00~08
25-5931-L			6X1955603A;3397020436;	SEAT Arosa 97~04 VW Lupo 98~05
25-5931-LL			6X1955325	long
25-5931-LS			6X1955326A	short
25-5934		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	1273401;1273403;1273420 ;93171541;93185524;9318 5528	OPEL Signum 03~; Vectra C 02~ 15-2904A WIPER MOTOR
25-5934-L			1273401;1273403;1273420 ;93171541;93185524;9318 5528	OPEL Signum 03~; Vectra C 02~
25-5935-L			1274058;23003808;230039 05	OPEL Meriva 03~10
25-5936-L			1121117;7M1955603A;95V W17B572AA;3397020479; 3398009476	FORD Galaxy 95~06 SEAT Alhambra 96~10 VW Sharan 95~10


25-5937-L			1384215;7M3955603D;7M3955603E;3398009859;3397020775	FORD Galaxy 95~06 SEAT Alhambra 96~10 VW Sharan 95~10
25-5938-L			2028200307;2028200707;2028200342;A2028200307;A2028200707;A2028200342	MB C-CLASS 93~01
25-5945A-L				FIAT
25-5945B-L				FIAT
25-5945C-L				FIAT
25-5947-L			1T1955601;1T1955601A;2K1955601A;3397021281	VW CaddyIII 04~; Touran 03~10
25-5948-L			6K1955313A;6K1955313C	SEAT CORDOBA 93~02; Ibiza II 93~99; IbizaIII 99~02; INCA 93~03 VW Caddy II 95~04; Polo 95~01
25-5949-L			8H1955603A	AUDI A4 02~08
25-5950-L			3C1955601;3C1955601A;602608	VW Passat 05~10

25-5951-L			5Z0955603B	VW Fox 05~
25-5953-L			1274072;22031055	OPEL Corsa A 82~93
25-5961-L			4F1955023A;4F1955023B; 4F1955023H;4F1955023J; 4F1955023K;4F1955601;4 F1955601A;4F1955601B	AUDI A6,S6 04~11
25-5963-L			8R1955119A;8R1955023D	AUDI(奥迪) Q5 09~16
25-5977-L			53538702	RENAULT R5 73~90
27-1180		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	84572802;20910182	CADILLAC(凯迪拉克) XTS 13~19
27-1180-L			84572802;20910182	CADILLAC(凯迪拉克) XTS 13~19
27-1326A		V 12V W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥20 Angle1 ± Angle2 ±	55076549AH;602117AS	DODGE Ram 1500 Pickup 94~01; Ram 2500 Pickup 94~02; Ram 3500 Pickup 94~02
27-1326A-L			55076549AH;602117	DODGE Ram 1500 Pickup 94~01; Ram 2500 Pickup 94~02; Ram 3500 Pickup 94~02

27-1362		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	1124045;1317135;XS4117504AA;XS4117504AD;XS4117504AE;XS4117504AG;XS4117504AH;XS4117K484AE	FORD Focus 98~04
27-1362-L			1124045;1317135;XS4117504AA;XS4117504AD;XS4117504AE;XS4117504AG;XS4117504AH;XS4117K484AE	FORD Focus 98~04
27-1367		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	19120737;19120741;602225AS	BUICK Allure 06~09; LaCrosse 06~09 For CHEVROLET Impala 06~12; Impala Limited 14~15; PONTIAC Grand Prix 06~08
27-1367-1		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	15793206;602212	CHEVROLET HHR 06~11
27-1367-1L			15793206;602212	CHEVROLET HHR 06~11
27-1367-L			19120737;19120741;602225	BUICK Allure 06~09; LaCrosse 06~09 CHEVROLET Impala 06~12; Impala Limited 14~15; PONTIAC Grand Prix 06~08
27-1391A		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	9009386	BUICK(别克) GL8 11~18

27-1405			20837131;	CHEVROLET Silverado 1500 08~10; Silverado 2500 08~10; Silverado 3500 08~10 GMC Sierra 1500 08~10; Sierra 2500 08~10; Sierra 3500 08~10
27-1405-L			20837131;602079	CHEVROLET Silverado 1500 08~10; Silverado 2500 08~10; Silverado 3500 08~10 GMC Sierra 1500 08~10; Sierra 2500 08~10; Sierra 3500 08~10
27-1433		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20 Angle1 ± Angle2 ±	10389559;602276	HUMMER(悍马) H3 06~10 H3T 09~10
27-1433-L			10389559;602276	HUMMER(悍马) H3 06~10 H3T 09~10
27-1703A		V 12V W RPM.L RPM.R N.m	9062374	CHEVROLET New Sail
27-1703A-L			9028849	CHEVROLET SAIL 10~14
27-1721A-L			107672500D;107672599F; 107672500G	TESLA Model 3 19~
27-1721B-L			149024200A;165893600A	TESLA Model Y 21~


27-1722E		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	95915120;	BUICK Encore(别克昂科拉) 12~15 CHEVROLET Trax 14~15 OPEL Mokka 12~15
27-1722E-L			95915120;602168	BUICK Encore(别克昂科拉) 12~15 CHEVROLET Trax 14~15 OPEL Mokka 12~15
27-1722H			95168355;	CHEVROLET Aveo(雪佛兰爱唯欧) 11~14; Sonic 12~17
27-1722H-L			95168355;602187	CHEVROLET Aveo(雪佛兰爱唯欧) 11~14; Sonic 12~17
27-1770		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	15192145;26265219;602267AS	BUICK(别克) GL8 11~14; GL8FristLand(陆尊) 05~06; Terraza 05~07 CHEVROLET Uplander 05~09 PONTIAC Montana SV6 05~09
27-1770-L			15192145;26265219;602267	BUICK(别克) GL8 11~14; GL8FristLand(陆尊) 05~06; Terraza 05~07 CHEVROLET Uplander 05~09 PONTIAC Montana SV6 05~09
27-1771		V 12V W 50 RPM.L 45±7 RPM.R 65±7 N.m ≥30 Angle1 ± Angle2 ±	1704580;4M5117504AC;4M5117K484AD;3397020850	FORD Focus C-Max 03~07; Fucos(福特福克斯) II 04~12
27-1771-L			1704580;4M5117504AC;4M5117K484AD;3397020850	FORD Focus C-Max 03~07; Fucos(福特福克斯) II 04~12
27-1801		V 12V W RPM.L RPM.R N.m	96988330;96988332	Volvo V70 I 95~00 CHEVROLET Aveo/Kalos Schr鋐heck 08~

27-1801-L			96988327	CHEVROLET AVEO 09~ PONTIAC G3 09~
27-1802		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	95971326;96893302;602231AS	CHEVROLET Cruze(雪佛兰科鲁兹) 09~
27-1802-L			95971326;96893302;602231	CHEVROLET Cruze(雪佛兰科鲁兹) 09~
27-1803		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	20913315;602272AS	CHEVROLET Captiva Sport(雪佛兰科帕奇) 08~11 OPEL Antara(欧宝安德拉) 07~17 SATURN Vue 08~10
27-1803-L			20913315;602272	CHEVROLET Captiva Sport(雪佛兰科帕奇) 08~11 OPEL Antara(欧宝安德拉) 07~17 SATURN Vue 08~10
27-1805-D			F5AZ17508A;F7AZ17508A; 852005CA	FORD Crown Victoria 95~02
27-1806		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	5485174	BUICK Excelle(别克凯越) 04~15
27-1806-L			5485174	BUICK Excelle(别克凯越) 04~15
27-1808		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	3810085Z01;3810185Z00; 3810285Z01;96474947;	CHEVROLET Lacetti 05; Optra 04~10 SUZUKI Forenza 04~08; Reno 05~08

27-1808-L			3810085Z01;3810185Z00; 3810285Z01;96474947; 602881	CHEVROLET Lacetti 05; Optra 04~10 SUZUKI Forenza 04~08; Reno 05~08
27-1812-D			12494832;602209	BUICK Century 97~05; Regal(别克君威) 97~04 CHEVROLET Monte Carlo 00~05 OLDSMOBILE Intrigue 98~02 PONTIAC Grand Prix 97~03
27-1822		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25 Angle1 ± Angle2 ±	22711011;602221AS	CHEVROLET Malibu 09~12 PONTIAC G6 09~10 SATURN Aura 2009
27-1822A		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25 Angle1 ± Angle2 ±	25979384;602138AS	CADILLAC(凯迪拉克) SRX 10~16
27-1822A-L			25979384;602138	CADILLAC(凯迪拉克) SRX 10~16
27-1822B		V 12V W 40 RPM.L RPM.R N.m ≥25 Angle1 ± Angle2 ±	10381692;22675467;	CHEVROLET Malibu 04~08
27-1822B-L			10381692;22675467;602207	CHEVROLET Malibu 04~08
27-1822C		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25 Angle1 ± Angle2 ±	19120343;602238AS	CHEVROLET Equinox 05~06 PONTIAC Torrent 2006 SATURN VUE 02~07

27-1822C-L			19120343;602238	CHEVROLET Equinox 05~06 PONTIAC Torrent 2006 SATURN VUE 02~07
27-1822E		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25 Angle1 ± Angle2 ±	12365395;84126961;84241847	CHEVROLET Equinox 10~17 GMC Terrain 10~17
27-1822E-L			12365395;84126961;84241847;602211	CHEVROLET Equinox 10~17 GMC Terrain 10~17
27-1822F		V 12V W 40 RPM.L 45±7 RPM.R 68±7 N.m ≥25 Angle1 ± Angle2 ±	19179941; 602250AS	CHEVROLET Equinox 08~09 PONTIAC Torrent 08~09
27-1822F-L			19179941; 602250	CHEVROLET Equinox 08~09 PONTIAC Torrent 08~09
27-1822-L			22711011;602221	CHEVROLET Malibu 09~12 PONTIAC G6 09~10 SATURN Aura 2009
27-1825		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	55077098AE;55077098AF; 55077098AL;68043386AA; 68043386AB;68043386AC; 602118AS;602130AS	DODGE Ram1500 Pickup 03~09; Ram2500 Pickup 03~10; Ram3500 Pickup 03~10; Ram4500HD Pickup 08~10; Ram5500HD Pickup 08~10
27-1825-L			55077098AE;55077098AF; 55077098AL;68043386AA; 68043386AB;68043386AC; 602118;602130	DODGE Ram1500 Pickup 03~09; Ram2500 Pickup 03~10; Ram3500 Pickup 03~10; Ram4500HD Pickup 08~10; Ram5500HD Pickup 08~10

27-1829C-D			12494825;602205	BUICK GL8(别克GL8) CHEVROLET Venture 97~05 OLDSMOBILE Silhouette 97~04 PONTIAC Montana 99~05; Trans Sport 97~98
27-1834A		V 12V W RPM.L RPM.R N.m	6I8Z17508b;ZC076601 ;602301AS	FORD Escape 01~06 MAZDA Tribute 01~06 MERCURY Mariner 05~06
27-1834A-L			6I8Z17508b;ZC076601; 602301AS	FORD Escape 01~06 MAZDA Tribute 01~06 MERCURY Mariner 05~06
27-1838		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30 Angle1 ± Angle2 ±	5S4Z17566A;7S4Z17566A ;602311AS;602317AS	FORD Focus 00~07
27-1838-L			5S4Z17566A;7S4Z17566A ;602311;602317	FORD Focus 00~07
27-1856C		V 12V W 40 RPM.L 42±7 RPM.R 62±7 N.m ≥30 Angle1 ± Angle2 ±	2L1Z17508AB;4L1Z17508 AA;6L1Z17508BA;8L1Z17 508A;602320AS	FORD Expedition 03~17 LINCOLN Navigator 03~08
27-1856C-L			2L1Z17508AB;4L1Z17508 AA;6L1Z17508BA;8L1Z17 508A;602320	FORD Expedition 03~17 LINCOLN Navigator 03~08
27-1861		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	BT4317500BB	FORD Edge 11~14 LINCOLN MKX 11~15
27-1867		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	9L1Z17500A;	FORD Expedition 09~14 LINCOLN Navigator 09~14

27-1867-2		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25	8S4Z17566AA;602316AS	FORD Focus 08~11
27-1867-2L			8S4Z17566AA;602316	FORD Focus 08~11
27-1867-L			9L1Z17500A;602563	FORD Expedition 09~14 LINCOLN Navigator 09~14
27-1891		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	7C1917504AB;W503924S427	FORD Transit(福特世代,江铃全顺V348) 06~13
27-1891A		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	4059963;YC1517K484BA;YC1517504BG;YC1517504BE;404520	FORD Transit 06~14
27-1891A-L			4059963;YC1517K484BA;YC1517504BG;YC1517504BE;404520	FORD Transit 06~14
27-1891-L			7C1917504AB;W503924S427	FORD Transit(福特世代,江铃全顺V348) 06~13
27-3029		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	5018657AA;5114534AA;403029L	CHRYSLER Town&Country 04~07; Voyager(克莱斯勒大捷龙) 04~07 DODGE Caravan 04~07; Grand Caravan 04~07
27-3049		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	5113043AA;5113043AB;	CHRYSLER Town&Country(克莱斯勒大捷龙) 08~16 DODGE Grand Caravan 08~16

27-3049-L			5113043AA;5113043AB; 602112	CHRYSLER Town&Country(克莱斯勒大捷龙) 08~16 DODGE Grand Caravan 08~16
27-3050		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	55372141AA;55372141AB; 55372141AC;55372141AD ;55372141AE;55372141AF ;55372141AG;55372141A H;55372141AI;55372141A J;55372141AK;55372141A L;	DODGE RAM1500 Pickup 09~10; RAM2500 Pickup 2010 RAM 1500 11~18; 1500 Classic 2019; 2500 11~19; 3500 11~19; 4000 11~19; 4500 11~19; 5500 11~19
27-3050-L			55372141AA;55372141AB; 55372141AC;55372141AD ;55372141AE;55372141AF ;55372141AG;55372141A H;55372141AI;55372141A J;55372141AK;55372141A L;602185	DODGE RAM1500 Pickup 09~10; RAM2500 Pickup 10~ RAM 1500 11~18; 1500 Classic 2019; 2500 11~19; 3500 11~19; 4000 11~19; 4500 11~19; 5500 11~19
27-3089		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	23328193;25923882;60223 0AS	CADILLAC Escalade(凯迪拉克凯雷德) 07~17 CHEVROLET Avalanche 07~13; Cheyenne 14~18 Silverado 1500 07~18; Silverado 2500 07~18; Silverado 3500 07~18; Suburban 1500 07~14; Suburban 2500 07~13; Tahoe 07~14 GMC Sierra 1500 07~18; Sierra 2500 08~18; Sierra 3500 08~18; Yukon 07~14; Yukon XL 1500 07~14; Yukon XL 2500 07~14

27-3089-L			23328193;25923882;602230	CADILLAC Escalade 08~14; Escalade ESV 07~14; Escalade EXT 07~13 For CHEVROLET Avalanche 1500 07~13; Silverado 1500 07~13; Silverado 2500 HD 08~15; Silverado 3500 HD 08~15; Suburban 1500 07~14; Suburban 2500 07~13; Tahoe 07~14 GMC Sierra 1500 07~13; Sierra 2500 HD 08~13; Sierra 3500 HD 09~13; Yukon 07~14; Yukon XL 1500 07~14; Yukon XL 2500 07~13
27-3113		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥25 Angle1 ± Angle2 ±	22820107;	BUICK Enclave(别克昂科雷) 13~17 CHEVROLET Traverse 13~17 GMC Acadia 13~16
27-3113-L			22820107;602066	BUICK Enclave 13~17 CHEVROLET Traverse 13~17 GMC Acadia 13~16
27-7915		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	19120755;	BUICK Allure 2005; Lacrosse 2005 PONTIAC Grand prix 04~05
27-7915-L			19120755;851053LK;602240	BUICK Allure 2005; Lacrosse 2005 PONTIAC Grand prix 04~05
27-8020B		V 12V W 40 RPM.L 40±7 RPM.R 60±7 N.m ≥20	600595600F;600595600G	TESLA(特斯拉) Model S 12~21
27-8020B-L			600595600F;600595600G	TESLA(特斯拉) Model S 12~21


29-1086		V 24V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30 Angle1 ± Angle2 ±		Left INDIA
29-1086A		V 12V W 50 RPM.L 42±7 RPM.R 62±7 N.m ≥30 Angle1 ± Angle2 ±		Left INDIA
29-1086-L				Left INDIA

Fan Motor



30-2016		V 12V A ≤ W 60 RPM D.R		URBAN Baby(都市贝贝)
30-2036		V 12V A ≤ W 40 RPM D.R		FAW XIALI(夏利三缸) DAIHATSU BLOWER
30-2359		V 12V A ≤ W 200 RPM 2900 D.R		JINBEI Hiace(金杯海狮)
30-2359A		V 12V A ≤ W 200 RPM 2900 D.R		ZOTYE(众泰) Z300
30-2360		V 12V A ≤ W 180 RPM 2700 D.R		JMC Kaiyun(江铃凯运); Shunda(顺达)
30-2362		V 12V A ≤ W RPM D.R		JMC Shunda(江铃顺达)
30-2362A		V 24V A ≤ W RPM D.R		VALIN(华菱)
30-2450		V 12V A ≤2 W 160 RPM 2800 D.R		CHANA Benni MINI(长安奔奔迷你)
30-2451		V 12V A ≤2 W 70 RPM 2400 D.R		CHANA Yuexiang 09~(长安悦翔副扇)
30-2452		V 12V A ≤2 W 70 RPM 2400 D.R		CHANA Yuexiang 09~(长安悦翔主扇)


32-2046		V 12V A ≤ W 50 RPM D.R	2538629000;TIY3391	HYUNDAI Elantra 96~00
32-2047		V 12V A ≤ W 40 RPM D.R	19189060;2538622020;2538622120;88918537;FS35328;PM3907;TIY3461	HYUNDAI Accent 1.5 RAD 95~99
32-2049		V 12V A ≤2.5 W 150 RPM ±2800 D.R	96144448;TIY3159	DAEWOO Matiz FTM
32-2049A		V 12V A ≤2.5 W 150 RPM ±2800 D.R	0K55215150;0K55215150A	KIA Carnival 01~06
32-2082		V 12V A ≤ W 70 RPM D.R	A005165;2838022000;9778622010	HYUNDAI Accent 95~99 KIA(起亚千里马) KK-2057 KK-2057A FAN ASSY
32-2082B		V 12V A ≤ W 70 RPM D.R	977863E900;A005317	KIA Sorento(起亚索兰托) 2.5 06~
32-2095		V 12V A ≤ W 100 RPM 3300 D.R	SM22T15150	KIA FTM TWO SPEED Pride
32-2100		V 12V A ≤2 W 100 RPM 2500 D.R	9778638000	HYUNDAI Sonata(现代索纳塔) 2.0 98~
32-2100-2		V 24V A ≤2 W 100 RPM 2500 D.R		HYUNDAI
32-2100A		V 12V A ≤2 W 100 RPM 3400 D.R	2539128050	HYUNDAI Elantra 90~95

32-2101		V 12V A ≤ W RPM D.R		DAEWOO Cielo
32-2101A		V 12V A ≤1 W 100 RPM ±2700 D.R	96395001	DAEWOO Matiz
32-2101B		V 12V A ≤ W RPM D.R		DAEWOO Cielo
32-2101C		V 12V A ≤ W RPM D.R		
32-2101D		V 24V A ≤ W RPM D.R		
32-2101E		V 24V A ≤ W RPM D.R		在2102D的基础上换插头，线长290mm
32-2101F		V 24V A ≤ W RPM D.R		在2102D的基础上不要插头，线长290mm
32-2102E		V 12V A ≤2 W 120 RPM 2700 D.R	253861G000;253861G050; A005211	KIA Rio(起亚锐欧) 05~20
32-2102H			253862B400;A005236	HYUNDAI SantaFe 07~09
32-2103		V 12V A ≤ W 130 RPM 3000 D.R	2538626200;TIY3562	HYUNDAI Soanta Fe(现代胜达,格越) L4&V6 RAD 01~05

32-2105		V 12V A ≤ W 110 RPM 3100 D.R	F00S3A2257	TATA INDIGO NEW MXI
32-2105A		V 12V A ≤ W 110 RPM 3300 D.R	2538605500	HYUNDAI Santro KK-2504B FAN ASSY
32-2105B		V 24V A ≤2 W 260 RPM ±3400 D.R		HYUNDAI
32-2106		V 12V A ≤2 W 140 RPM 2800 D.R	253862E250;253861F380	HYUNDAI Tucson 04~10
32-2106A		V 12V A ≤2 W 140 RPM 2500 D.R	253861F251;F00S3A2348	HYUNDAI Tucson 2.7-V6 04~10 KIA Sportage 04~10
32-2106B		V 12V A ≤2 W 120 RPM 2200 D.R	253861D101;F00S3A2392	KIA Carens(起亚佳乐) 07~12
32-2106C		V 12V A ≤2 W 220 RPM D.R	25386C5000;25386C5200; 25386C5250;A005505	KIA Sorento(起亚索兰托) 14~18
32-2106D		V 12V A W RPM D.R	A005510;25386C1200;	HYUNDAI Sonata(现代索纳塔) 15~18 KIA(起亚) K5 16~
32-2106E		V 12V A ≤ W RPM D.R		HYUNDAI Venue
32-2108		V 12V A ≤ W 70 RPM D.R	96144976;TIY3128	DAEWOO Cielo KK-2506 FAN MOTOR

32-2109		V 12V A ≤ 1.5 W 70 RPM ± 3100 D.R		CHEVROLET Optra 1.8
32-2109D		V 12V A $\leq$ W RPM D.R		DAEWOO Lacetti
32-2109E		V 12V A $\leq$ W RPM D.R		DAEWOO Lacetti
32-2110		V 12V A $\leq$ W RPM D.R		TOYOTA
32-2111		V 12V A ≤ 2 W 130 RPM ± 2300 D.R	2538607100;F00S3A2262	KIA Picanto 04~10
32-2111A		V 12V A $\leq 2A$ W 100 RPM ± 2400 D.R	253861E350;F00S3A2341	HYUNDAI Accent 06~10
32-2113			253862S500;F00S3A2476	HYUNDAI(现代) IX35 09~15; Tucson 09~15 KIASportage(起亚狮跑) 09~15
32-2115		V 12V A ≤ 2.5 W 120 RPM 2700 D.R	253861R140; A005416	DODGE Attitude 11~13 HYUNDAI Accent 12~13; Veloster 12~14 KIA(起亚) K2 14~15 Rio 12~17
32-2115C			25386B4100;A005459	HYUNDAI I10 13~20
32-2115E			A005502	HYUNDAI Mistra(现代名图) 13~17

32-2115F			253863R170;253863S280; 253863R200;253863R140; A005384	HYUNDAI(现代) I45 10~14; Sonata(索纳塔) 11~14; Azera(雅尊) 11~14 KIA (起亚) Cadenza(凯尊) 11~12; Carens(佳乐) 12~16; Optima 10~15
32-2115G		V 12V A ≤2.5 W 120 RPM 2700 D.R	25386M6140;A005595	HYUNDAI Avante; Elantra; Ioniq; i30 KIA Ceed
32-2116			25386C7160;A005489	HYUNDAI Veloster(现代飞思) 11~14 For KIA(起亚) K2 2015~
32-2144		V 12V A ≤1 W 120 RPM 2800 D.R	253861Y140;253861Y160; 3137230107	KIA Morning 10~14; Picato 11~14
32-2145A		V 12V A ≤ W 70 RPM 3500 D.R		SUZUKI Wagonr K10
32-2145B		V 12V A ≤ W 70 RPM 3500 D.R		SUZUKI Wagonr K10
32-2147		V 12V A ≤ W 70 RPM 3500 D.R	2538602000	DODGE Atos 00~04 HYUNDAI Atos 00~04
32-2147A		V 24V A ≤2 W 70 RPM 3500 D.R		HYUNDAI
32-2153		V 12V A ≤ W 120 RPM 2600 D.R	1711162D50000	DAEWOO RAD

32-2153A		V 12V A ≤ W 100 RPM 2800 D.R		FLYER South America
32-2153B		V 24V A ≤ W 100 RPM 2800 D.R		FLYER South America
32-2155A		V 12V A ≤ W 180 RPM 3300 D.R	22T15150	KIA FTM TWO SPEED Pride
32-2186		V 12V A ≤ W 70 RPM 3200 D.R		DAEWOO A / C
32-2186-2		V 24V A ≤ W 70 RPM 3200 D.R		DAEWOO A / C
32-2186A		V 12V A ≤ W 70 RPM 3200 D.R		DAEWOO Nubira 99~02
32-2283		V 12V A ≤ W 60 RPM 3100 D.R	2538624001;HA1283	HYUNDAI Elantra 1.8 98~; Excell
32-2708		V 12V A ≤ W RPM D.R	253861E200;	DODGE Attitude 06~10 HYUNDAI Accent 06~09 A / C
32-2709		V 12V A ≤ W 70 RPM 3500 D.R	253861E100	DODGE Atos 00~04 HYUNDAI Atos 00~04
32-3500		V 12V A ≤ W RPM D.R		Latin America

32-3616		V 12V A ≤ W RPM D.R	253862H050;	HYUNDAI Elantra 07~11
32-3618		V 12V A ≤ W RPM D.R	253861U100;25386C6000; 253862P500;3137230079; 3137230225	HYUNDAI Santa FE(现代胜 达) 09~12 KIA Sorento 16~18
32-3618A		V 12V A ≤ W RPM D.R	25386D3500	KAI(起亚) KX5 16~; Sportage 16~19
32-3619		V 12V A ≤ W RPM D.R	25386A6100;253863X000; 3137230306;3137230307	HYUNDAI Elantra(现代朗动) 12~17 KIA Forte 2014; Soul 12~19
32-3620		V 12V A ≤ W RPM D.R	253861Y120;3137230108; F00S342486	FORD KIA Picanto 2015~
32-3620A		V 12V A ≤ W 70 RPM 3500 D.R	253864H110;A005335	HYUNDAI H-1(现代辉翼) 07~11 Grand Starex 15~18
32-3621		V 12V A ≤ W 70 RPM 3500 D.R	253860X000;253860X150; 253800X050;253800X550	HYUNDAI I10 08~13
32-3700		V 12V A ≤ W RPM D.R	253862D500	HYUNDAI Elantra 01~03
32-3703A		V 12V A ≤ W RPM D.R	977864H000	HYUNDAI Starex 07~14
33-2001		V 12V A ≤ W 40 RPM 2300 D.R	FE6815150;TIY359	FORD Golden Lanser 1.6 90 ~ MAZDA 323 86~92

33-2002		V 12V A ≤ W 100 RPM 2500 D.R	MB37615150;F20215150A ;KRF0515150;TIY385	FORD Festiva 1.1,1.5 90~95 MAZDA 626 RAD 88~92 KIA Pride(起亚普莱特)
33-2003		V 12V A ≤ W 40 RPM 3000 D.R	Z50115035;Z50915035B;2 148785Y01;VDO.PM2513; TIY3087	MAZDA Protege 95~98 NISSAN BE3;Sentar 1.6 95~99
33-2004		V 12V A ≤ W RPM D.R	1712060B60;TIY3080	SUZUKI Swift 89~91(MT)
33-2005		V 12V A ≤ W RPM D.R	MB845116;TIY3047	MITSUBISHI Lancer 1.6 RAD 93~96
33-2006		V 12V A ≤ W 110 RPM 2600 D.R		SUZUKI Alto(铃木奥拓)
33-2006A		V 24V A ≤ W 110 RPM 2600 D.R	1625005592	SUZUKI 福將9T~17T
33-2007		V 12V A ≤ W 50 RPM 2700 D.R	MB845145;TIY3049	MITSUBISHI Lancer 1.6 RAD 93~96
33-2008		V 12V A ≤ W 80 RPM 2700 D.R	BPD715150;B6BG15150;T IY3040;M23830200RD;MZ 4383	MITSUBISHI Lancer 1.6 RAD 93~96
33-2010		V 12V A ≤ W 60 RPM 3000 D.R →	163630D011;163630H070; 163630H090;163630V130; 1636303100;1636328230;1 636374000;1636374360;16 36374370;TO3116107;TIY 3295;TIY3304	TOYOTA Camry(丰田凯美瑞) 00~17; Corolla 98~02; Solara 99~08; Venza 09~16

33-2010-1		V 12V A ≤ W 60 RPM 3000 D.R ←	2635005111;2635006330	TOYOTA Harrier 99~
33-2010A		V 12V A ≤ W 60 RPM 3000 D.R →	19030PNA003;19030PZA901;19030RAAA01;19030RZAA01;38616PSA003;75750;PM3946	ACURA RSX 02~06 HONDA(本田) Accord(雅阁) 03~07; Civic 03~05; CRV 02~09; Element 10~11
33-2010A-1		V 12V A ≤ W 60 RPM 3000 D.R ←	19030PAAA01;19030PAA02;19030PEJ003;19030PLC003;19030P8CA01;35006;35254;TIY3303	ACURA CL 01~03; TL 99~03 HONDA(本田) Accord(雅阁) 98~02; Civic 99~05; Odyssey(奥德赛) 95~98
33-2010B		V 12V A ≤ W 60 RPM 3000 D.R →	163630J010;163630H010;163630H050;1636323010;TIY3361;VDO.PM9266	SCION TC 05~10 For TOYOTA CAMRY 07~17; Venza(丰田威驰) 09~16; Yaris 00~04
33-2010B-1		V 12V A ≤ W 60 RPM 3000 D.R ←	1636374340;PE0115150A;2635005070;2635005241	DAIHATSU Mira 0.66 98~04; Yrv 1.0 00~02 LEXUS IS250 06~13 MAZDA(马自达) CX-5 15~ CX-8 19~ PROTON Waja PERODUA Kelisa Kenari
33-2010C		V 12V A ≤ W 60 RPM 3000 D.R ←	16363BZ020;1636331040;FM3236;2635005480;2635005730;2635006080	DAIHATSU Esse 0.66 05~; Mira 0.66 04~07 LEXUS IS250 06~13; IS350 06~12 PERODUA Myvi; Viva TOYOTA Avanza; Passo 1.0 04~10
33-2010C-1		V 12V A ≤ W 60 RPM 3000 D.R →	1636328020;2635005391	TOYOTA Estima Acr30; RAV4 06~13

33-2010D		V 12V A ≤ W 55 RPM D.R		mitsubishi Virage 1.6,1.8
33-2010E		V 12V A ≤ W 55 RPM 2850 D.R		HONDA
33-2010F		V 12V A ≤ W 55 RPM 2850 D.R →	163630A130;163630P030; 163630P220;1636320250; 1636320280;1636331270	LEXUS ES350 07~11; RX350 04~06; RX350 16~19 TOYOTA Avalon 05~18; Camry 07~17; Highlander 08~10; Venza 09~15
33-2010F-1		V 12V A ≤ W 55 RPM 2850 D.R ←	1636331010	LEXUS LS460 07~13
33-2010G		V 12V A ≤2 W 55 RPM 2850 D.R →	163630A120;163630P230; 1636331280	LEXUS ES350 07~11 TOYOTA Avalon 05~18; Camry 07~17; Highlander 08~10; Sienna 04~05; Venza 09~15
33-2010G-1		V 12V A ≤2 W 55 RPM 2850 D.R ←	163630P020;1636331020; 2635006220;2635005780	TOYOTA Crown(丰田皇冠) 03~12
33-2010H		V 12V A ≤ W 55 RPM 2850 D.R →	2635005700	PERODUA Kancil 660 Kancil 850
33-2010N		V 12V A ≤ W 60 RPM 3000 D.R ←	21487CY000;21487CY010 ; ASMO.8680000041;ASMO .8680000060	NISSAN Serena 07~
33-2012		V 12V A ≤ W RPM D.R	2148758Y00;TIY3045	MAZDA 626 00~02 NISSAN B13,B14 90~99; Sentra 90~99; Tsuru 93~99

33-2013		V 12V A ≤ W RPM D.R	19030P08014;19030PT00 04;19030P3F024;19030P M5A04;35288;PM3901	ACURA Integra 90~97; TL 95~98; Vigor 92~94 HONDA Accord 89~97; Civic 88~95; CR-X 88~91; CRV 97~01; Prelude 90~96
33-2013A		V 12V A ≤ W RPM D.R		HONDA
33-2014		V 12V A ≤ W RPM D.R		HONDA
33-2014A		V 12V A ≤ W RPM D.R	19030PFE014	HONDA Acty
33-2017		V 12V A ≤ W RPM D.R ←	1636303020;1636316010;1 636363030;1636364030;19 030PE0013;35407;35411; TIY335	GEO Prizm 89~92 HONDA TOYOTA Camry 87~91; Corolla 88~92
33-2019		V 12V A ≤ W RPM D.R ←	1636310010;1636316030; TIY387	TOYOTA Carina 88~92; Corolla 86~87
33-2019A		V 12V A ≤ W RPM D.R ←		TOYOTA Carina 88~97; Corolla 86~87
33-2019B		V 12V A ≤ W RPM D.R ←	19030PH4661;19030PH70 03;19030PH7013;19030PK 1671	ACURA Integra 90~93 HONDA Accord 86~89
33-2019C		V 24V A ≤ W RPM D.R ←	1625005590;1625005592	HINO 500 FC 96~02; 500 FD 96~02; 500 FG 96~02; 500 FM 97~98; 500 FT 97~02

33-2020		V 12V A ≤ W RPM D.R	1625004894;1625005822; TIY3335	DAIHATSU Classy(夏利四缸) PERODUA Kancil
33-2022		V 12V A ≤ W RPM D.R	0625004423;TIY3041	MITSUBISHI PROTON Saga 1.6 RAD 95~
33-2024		V 12V A ≤ W RPM D.R	1712071C10;51100044;QF Z1308	SUZUKI Lingyang RAD(长安 羚羊)
33-2025		V 12V A ≤ W RPM D.R	60600323;QOF21309;9532 060B50	SUZUKI Lingyang A / C(长安 羚羊)
33-2029		V 12V A ≤2 W 40 RPM D.R	MB845078;2625000111;TI Y3082	MITSUBISHI Lancer GL,XL 93~96(MT); MITSUBISHI PROTON Wira(S) 1.6 98~; Saga
33-2030A		V 12V A ≤ W RPM D.R	38616PT2J03;38616PT3A 02;38616PT3A03;75725;P M9106	ACURA CL 1997; Integra 94~01 HONDA Accord 90~97; CRV 97~99; Prelude 92~98
33-2030B		V 12V A ≤ W RPM D.R	19030RTA004;19030RME A51;38616PAAA01;38616 PLCJ01;38616PMMA01;38 616RCAA00;75734;PM911 0;PM9268	ACURA(讴歌) CL 98~99; MDX 01~06; TL 99~01 HONDA Accord(本田雅阁) 98~07; CRV 99~01; Civic 01~11; Fit 07~08; Odyssey 95~04; Pilot 03~08; Prelude 99~01
33-2030C		V 12V A ≤ W RPM D.R	38616P8CA01;38616P8FA 01;VDO.PM9153	ACURA MDX 01~02; TL 04~08 HONDA Accord 03~07; Odyssey 99~04; Pilot 03~08

33-2030		V A W RPM D.R	12V ≤	19030PT8013;19030PH74 661;80151SR3003;80151S R3013;75726;PM9108	HONDA Civic 92~98; Civic Del Sol 93~97
33-2030D		V A W RPM D.R	12V ≤		HONDA
33-2030E		V A W RPM D.R	12V ≤		DAEWOO(大宇)
33-2031		V A W RPM D.R	12V ≤	E30115150;E56315025;TI Y311	MAZDA 323
33-2032		V A W RPM D.R	12V ≤	F20115150;TIY3051	MAZDA 323 90~95; 626 88~92
33-2038		V A W RPM D.R	12V ≤		SUZUKI Alto BLOWER(铃木 奥拓暖风)
33-2040		V A W RPM D.R	12V ≤		Latin America
33-2041		V A W RPM D.R	12V ≤	1625003972;TIY3050	MITSUBISHI PROTON Wira; Saga(B)ND
33-2043		V A W RPM D.R	12V ≤	2635000101;TIY3083	MITSUBISHI PROTON Wira(B) 1.6 98~
33-2044		V A W RPM D.R	12V ≤ ←	19030P08003;19030P0801 3;19030PT0003;19030P1R 003	ACURA Integra 94~01 HONDA Accord 90~97; Civic 92~98; Prelude 92~98

33-2048		V 12V A ≤ W RPM D.R	1668087712;1668087722; TIY312;HC3009	FAW XIALI(夏利三缸) DAIHATSU Charade Skywing G11 1.0 85~90 BLOWER
33-2084		V 12V A ≤ W RPM D.R ←	1636310020;1636315020;1 636315120;1636374120;94 581024;2625000362;TIY38 6	DAEWOO Nubira 00~03 TOYOTA Tercel 90~96
33-2084A		V 12V A ≤ W RPM D.R ←	MI3116106;MR188156;ME 200195;VDO.PM2506;TIY 3132	MITSUBISHI Mirage 97~02; Montero V46 2.8 1993~
33-2051		V 12V A ≤ W RPM D.R	214871L000;214870Z800; 21487PA20A;92120EA200 ;92122VB000	INFINITI I30 96~99 NISSAN Cefiro 04~(尼桑风度A33); Frontier 05~06; Maxima 95~03; Pathfinder 05~06; Sentra 00~01; Patrol(途乐) Y61 97~09; Xterra 05~06
33-2051C		V 12V A ≤ W RPM D.R	1355A141;21481ET000;21 487AX000;21487AX00B;2 1487ED000;214875L705;2 14875Y720;214878H300;2 14878H30A;214878J000;2 14878J010;214878J01A;2 1487AD201;21487EQ30A; 21487ED80A;92122EE90A ;L32115150	INFINITI I35 02~04 MITSUBISHI Lancer(欧蓝德) 08~17 MAZDA 6 03~08 NISSAN(尼桑颐达, 骐达, 轩逸 骊威, 奇骏) Altima 02~06; Maxima 2002; Tiida 07~12; X-Trail 02~13
33-2051D		V 12V A ≤ W RPM D.R		NISSAN Maxima 01~; Sentra 1.8 01~; Xterra 03~09
33-2051E		V 12V A ≤ W RPM D.R	92122VK20B;92122VK60B ;92122VK60C;MR312898; MR993933	MITSUBISHI(三菱) ASX(劲炫) 11~12 Lancer 05~12; Outlander(欧蓝德) 08~13 NISSAN D22 05~; D22F 09~; D22FF 17~ D22SS 09~11 D22X 08~13; NP300 99~11

33-2051A		V A W RPM D.R	12V ≤	214875B600	NISSAN Altima(尼桑蓝鸟) 93~97
33-2051B		V A W RPM D.R	12V ≤	5037181650F;92122VW00 0;921223XA0A	NISSAN Genuine 01~07 NV350 12~17
33-2052		V A W RPM D.R	12V ≤	214870Z000;2148738U00; 214879E000;PM9114;7581 1	INFINITI I30 00~01 NISSAN Altima 98~01; Maxima 95~03; Sentra 00~01
33-2055		V A W RPM D.R	12V ≤	19188889;214875B401;88 999581;921205B401;3510 4;PM2507	INFINITI G20 91~95 MAZDA Protege 1996 NISSAN 200SX 95~98; Sentra 95~99; Tsuru 95~99
33-2055A		V A W RPM D.R	12V ≤	1355A084;TEMP.02016M0 64	NISSAN Tsuru GS MEXICO MITSUBISHI Minicab 07~12(U61T,U61TP,U61V,U 61W,U62T,U62TP,U62V,U62 W,U67V)
33-2060		V A W RPM D.R	12V ≤	VDO.PM1403;MITSUBA.M 3611	HONDA Civic 1.6 88~92
33-2060A		V A W RPM D.R	12V ≤		HONDA Fit
33-2060B		V A W RPM D.R	12V ≤	19030REAZ01;19030PWA J51	HONDA City(本田飞度) 04~07
33-2082A		V A W RPM D.R	12V ≤	0K2FA61F03;A005148	KIA Caren II 02~05; Xtrek 02~05
33-2085		V A W RPM D.R	12V ≤	MB845865;MB906422;MR 146417;VDO.PM9132;TIY 3292	CHRYSLER Sebring 95~99 DODGE Avenger 95~99 EAGLE Talon 95~98 MITSUBISHI Galant 94~98(AT); Eclipse 95~97

33-2085C		V A W RPM D.R	24V ≤	1680006570;1680006573	VDL MAGIQ E5
33-2087		V A W RPM D.R	12V ≤	PC140111	mitsubishi PROTON Saga 1.6 96~
33-2087A		V A W RPM D.R	12V ≤	FM3144XX	mitsubishi PROTON Saga
33-2088		V A W RPM D.R	12V ≤	PC140118;FM3049XX;TIY3402	TSURU III 93~03 mitsubishi PROTON Wira 00~
33-2088A		V A W RPM D.R	12V ≤	2148757A01;TIY3046	NISSAN BE2
33-2089		V A W RPM D.R	12V ≤ 80	2148285Y01;214875B401; 2148779Y00;TIY389	NISSAN BE3(MT) 90~94; Sentra 91~97
33-2090		V A W RPM D.R	12V ≤ 80	2148753J00;2148760Y00; B700286Y50;TIY390	INFINITI G20 91~96 NISSAN 200SX 95~98; BE3(AT) 90~99; Sentra 91~97
33-2097		V A W RPM D.R	12V ≤ ←	163610A010;163630A011; 1636311030;1636311080;1 636374030;1636374170;35 393;PM2805;TIY361	FORD Probe 89~97 TOYOTA Avalon 95~99; Camry 88~97; Exsior 93~96; RAV4 96~00; Tercel 95~98(AT)
33-2097A		V A W RPM D.R	12V ≤ ←	2624000512	TOYOTA Hiace; Regius
33-2097B		V A W RPM D.R	12V ≤ ←	2624000141	DAIHATSU G200 PROTON Perdana V6

33-2098		V 12V A ≤ W RPM D.R	163630A020;163630A030; 163630A040;TIY3403	LEXUS ES300 97~98 TOYOTA Avalon 95~99; Camry 97~98;
33-2102		V 12V A ≤2 W 120 RPM 2700 D.R	A005232	SUZUKI Swift Diesel K-Car
33-2102D		V 12V A ≤2 W 120 RPM 2700 D.R		SUZUKI Swift Diesel High Speed
33-2107		V 12V A ≤ W RPM D.R	MR315781;TIY3472	MITSUBISHI Galant 98~ PROTON Waja
33-2107A		V 12V A ≤ W RPM D.R	PW950174;PW950317	PROTON Waja; Exora; Persona 07~09
33-2109F		V 12V A ≤ W RPM D.R	214874LA1B;214874LA3A	NISSAN Datsun
33-2114		V 12V A ≤ W RPM D.R	1625005444	SUZUKI 6H
33-2114A		V 12V A ≤ W RPM D.R	96068060;TIY3336;TIY3454	SUZUKI Swift(AT) GM GEO Metro;Spint RAD 95~01
33-2145		V 12V A ≤ W RPM D.R	A005390	SUZUKI Alto; Alto 800; Alto K10; Wagonr K
33-2146		V 12V A ≤ W RPM D.R	TIY396	NISSAN BE2 MOTOR KK-2096 FAN ASSY

33-2148		V 12V A ≤ W RPM D.R	214875B600;TIY3084	NISSAN Altima 93~97; Maxima 95~99; Sentra(AT) 95~99
33-2149A		V 12V A ≤ W RPM D.R		Latin America
33-2182		V 12V A ≤ W RPM D.R	BE48285Y10;TIY3044	NISSAN Senter BE3 1.6 90~95
33-2183		V 12V A ≤ W RPM D.R ←	B6BF15150;B6DN15150;3 5321;PM2512;TIY3277	MAZDA Protege 95~98
33-2184		V 12V A ≤ W RPM D.R	2148785E10;2148785E11; 2148796E10;2148796E11; VDO.PM9113;TIY3279	NISSAN Altima 93~97; Maxima 89~93
33-2189		V 12V A ≤ W RPM D.R	21487EW00B;F00S3A235 7	NISSAN(尼桑骏逸,轩逸,骊威) Grand Livina Sylphy 06~12; Versa 07~11
33-2189A		V 12V A ≤ W RPM D.R	21487EW30B	NISSAN Tida 06~
33-2220		V 24V A ≤ W RPM CW D.R ←	884501040;2635001220	HINO Ranger; Dutro
33-2221		V 24V A ≤ W RPM CW D.R ←	1625005592	HINO Profia; Ranger MITSUBISHI Great TOYOTA Dyna
33-2242A		V 12V A ≤ W RPM D.R	1636320050;1636320060;3 5113;PM9074	TOYOTA Sienna 98~03

33-2242		V 12V A ≤ W RPM D.R →	1636320400;1636320390;1636331260;1636375030;CY0415150;CY0415150A;CY0415150B;CY0415150C;L33L15150;L33L15150A;L33L15150C;L33L15150D;L33M15150;L33M15150B;L33M15150C	LEXUS(雷克萨斯) RX350 10~13; RX400H 06~08; RX450H 10~13 MAZDA CX-7 07~09; CX-9 07~09 TOYOTA Hiace(丰田海狮) 04~; Highlander 06~11
33-2242B		V 12V A ≤ W RPM D.R ←	1712061J20;1680004840	SUZUKI Carry grand vitara 11~16
33-2242C		V 12V A ≤ W RPM D.R →	1636320150;1680003750	TOYOTA Estima 2000
33-2243		V 24V A ≤ W RPM D.R ←	1680003701	TOYOTA Dyna HINO Dutro
33-2243M-1		V 24V A ≤ W RPM D.R ←	1680004380	HINO 11~ TOYOTA Dyna 6.5T 08~
33-2243M-3		V 24V A ≤ W RPM D.R →	8855037120;1680004530	HINO 11~
33-2247A		V 12V A ≤2 W 100 RPM ±2000 D.R →	163630A110;163630A180;163630D050;163630D070;163630D110;163630J020;1636320210;1636323020;1636323030;35114;PM9267;TIY3380	LEXUS ES300 02~03 TOYOTA Camry 02~06; Corolla(丰田花冠) 2003; Echo 00~04; Matrix 03~08; RAV 4 01~03; Solara 04~08; Yaris 07~08
33-2248A		V 12V A ≤2 W 100 RPM ±2000 D.R ←	19030PGKA01;19030P8FA01;19030RCAA01VDO.PM9128;VDO.PM9263	ACURA MDX 01~06 HONDA Accord(本田雅阁) 03~07; Odyssey 99~04; Pilot 03~06

33-2248		V 12V A ≤2 W 100 RPM ±2000 D.R →	163630A050;163630A060; 163630A090;163630D020; 1636320030;1636320070;1636320170;1636320360;1636322010;35112;PM9073; PM9116;TIY3271;TIY3365	LEXUS ES300 99~01; RX300 01~03 TOYOTA Avalon 00~04; Camry 99~01; Corolla 98~99; Highlander(丰田汉兰达) 01~07; Solara 00~03
33-2248C		V 12V A ≤2 W 100 RPM ±2000 D.R →	163630A140	LEXUS ES350 07~11; RX350 07~09 TOYOTA Avalon 13~18; Camry 07~17; Sienna 04~10
33-2248D		V 12V A ≤2 W 100 RPM ±2000 D.R →	1712080G00;1680003740	SUZUKI Ignis 00~03
33-2249		V 12V A ≤2 W 40 RPM D.R	8855032050;8855033010;8855032070;8855006010	TOYOTA Camry 87~96
33-2250		V 12V A ≤ W RPM D.R ←	1636311020;1636311050;1636311070;1636374020;1636374200;1636374260;ZL0115150;TO3116105;2635000622;TIY388	MAZDA Protege 99~03 TOYOTA AE100; Camry 92~99; Celica 90~99; Corolla 93~97; MR2 91~95; Paseo 92~98; Solara 99~01; Tercel 91~98
33-2256		V 12V A ≤ W RPM D.R	1625001920	TOYOTA Unser Proton Tiara
33-2256A		V 12V A ≤ W RPM D.R	2825000101	TOYOTA Costar BLOWER
33-2256B		V 24V A ≤ W RPM D.R	8855036020;2825000112	TOYOTA Costar BLOWER

33-2324		V 12V A ≤ W RPM D.R	17100C81061	SUZUKI Alto(铃木奥拓王子)
33-2350		V 12V A ≤0.5 W RPM ±2600 D.R →	1712077J00;1680007881;1711163J00;1712063J00;1776063J00	SUZUKI Swift Vetis(铃木雨燕)
33-2350A		V 12V A ≤ W RPM D.R →	163630D040;163630D090;163630D100;163630H030;163630M010;1636321030;1636328200;1636328150	SCION XD 08~14 For TOYOTA(丰田) Altis 07~13; Corolla(花冠) 03~08; Matrix 03~08; Prius 04~09; Vios(威驰) 02~08; Yaris(雅力仕) 06~18
33-2350A-1		V 12V A ≤ W RPM D.R →	1636336100;2680005041	TOYOTA RAV4 13~16
33-2350A-2		V 12V A ≤ W RPM D.R ←	1636328240;1636336110;1636336160;1636364240;16363BZ040;17120M68K00;1680001030;1680007170;	PERODUA Alza Axia SUZUKI Alto 10~ TOYOTA(丰田) Agya; Ayla; Rav4 06~16; Prius 16~19
33-2350A-3		V 12V A ≤ W RPM D.R ←	PE0215150A;1680001341	MAZDA(马自达) CX-5 13~16 CX-8 19~ SUZUKI Jimny ABA-JB23W
33-2350A-7		V 24V A ≤ W RPM D.R ←	8980906840;8981570440;1680008210;1680008490	ISUZU NMR 10~; NPR 10~; NKR 10~ HINO ZM300 MEGA 700
33-2350A-8		V 24V A ≤ W RPM D.R ←	S884501120;1680008220	ISUZU ELF 3.5T 10~; NLR 3.5T 10~ HINO 500 FM 02~17
33-2350B		V 12V A ≤ W RPM D.R ←	17100M53M00;17120M76G00;SR1680004771	SUZUKI Alto 800 12~18 Wagon R Shroud KK-2556 FAN ASSY

33-2350B-1		V 12V A ≤ W RPM D.R ←	19030PVJA01;19030RMXA51;38616RFE003;1680007511	ACURA MDX 01~06 HONDA(本田) Accord 03~07; Civic(思域) 06~11; Life 2005; Pilot 03~08; Odyssey(奥德赛RBE) 05~08
33-2350B-2		V 12V A ≤ W RPM D.R ←	1636321040;1636326090;1636328370;1680001640	TOYOTA RAV4 02~12; Prius(丰田普锐斯,普瑞维亚) 04~09
33-2350B-3		V 12V A ≤ W 130 RPM D.R →	163630P110;163630T020;163630T030;163630T210;1636322120	SCION IM 2016 PONTIAC Vibe 09~10 TOYOTA C-HR 18~19; Corolla(丰田卡罗拉,花冠,雷凌) 09~19; Matrix 09~14; Sienna 07~10 SUZUKI Escudo 2.0
33-2350B-4		V 24V A ≤ W RPM D.R ←	168008810	ISUZU Giga
33-2350B-5		V 12V A ≤ W RPM D.R →	190305R1003;190305LAA01;19030R1AA01;19030R40A01;19030R60U01;19030R70A01;38616RB0003;38616R5AA01;386165R1003	ACURA(讴歌) RDX 13~15; TL 09~14; TSX 09~14 HONDA(本田) Accord(雅阁) 08~12; Accord Crosstour 10~11; Crosstour 12~15; CRV 10~16; FIT(飞度,锋范) 09~19
33-2350B-6		V 12V A ≤ W RPM D.R ←	19030RSJE01;3861651BH01;386165LAA01;386165MRA01;38616RV0A01;38616R40A01;38616R60A01;38616R60U01;38616R70A01	ACURA(讴歌) ILX 13~15; RDX 13~15; TSX 09~14 HONDA(本田) Accord(雅阁) 08~12; Accord Crosstour 10~11; Civic 12~15; Crosstour(歌诗图) 12~15; Odyssey 11~17 ; HR-V 16~20 Mobilio(思铂睿) 09~13; Vezel(缤智) 17~19; XR-V 15~20
33-2350B-7		V 12V A ≤ W RPM D.R →	19030RNAA01;19030RNAA51;38616RAAA01;38616RGLA01;PM9160	HONDA(本田) Accord(雅阁) 03~07; Civic(思域) 06~11; Odyssey 05~10

33-2350B-8		V 12V A ≤ W RPM D.R →	1636328270;1636330010;163630H140;1712065J00;1712065J10;1680007980	SUZUKI Grand Vitara 09~13 TOYOTA Corolla 01~ Camry 07~11; Highlander 04~07
33-2350C		V 12V A ≤ W RPM D.R →	1355A503;163630H110;163630M020;163630T040;1636320330;1636321050;1636328160;1680002680	LEXUS ES330 04~06 MITSUBISHI Xpander 17~ SCION XA 04~06, XB 04~06 TOYOTA(丰田) Altis 07~13; Camry 06~16; Corolla(花冠) 07~13; Echo(普瑞维亚) 00~05
33-2350C-1		V 12V A ≤ W RPM D.R →	1636328170	LEXUS ES330 04~06 TOYOTA(丰田) Alphard(埃尔法) 08~15; Camry 04~06; Previa(普瑞维亚) 00~06; RAV4 06~12
33-2350C-2		V 12V A ≤ W RPM D.R ←	1636328102;1636328290;16363BZ130;16363BZ160;1680002810	LEXUS IS350 06~12 TOYOTA Agya 19~ Calya 16~; RAV4 06~12; Siga 16~
33-2350C-3		V 12V A ≤ W RPM D.R ←	16363BZ100;1680002380;1680002410	TOYOTA Avanza 2011
33-2350D		V 12V A ≤ W RPM D.R →	1712061J10;1680009370	SUZUKI Apv Van 1.6i 05~
33-2350D-1		V 12V A ≤ W RPM D.R →	163630H120;1712066J00;1712066J10;1680009730	SUZUKI Grand Vitara 06~08 TOYOTA Camry 06~09
33-2350D-3		V 12V A ≤ W RPM D.R ←	1636328420;1680002670	TOYOTA(丰田) Alphard(埃尔法) 08~15; Previa(普瑞维亚) 06~ 12
33-2350E		V 24V A ≤ W RPM D.R ←		SUZUKI

33-2350F		V 12V A ≤ W RPM D.R →	CY0215150A;CY0215150B ;CY0215150C;163630D16 0;163630P180;163630P19 0;163630P240;163630T10 0;163630T140;163630V11 0;1636322100;1636331150 ;1636331200;1636331210; 1636331450	MAZDA CX-9 07~15 LEXUS RX350 10~15 TOYOTA(丰田) Altis 08~14; Highlander(汉兰达) 08~19; Sienna(威飒) 11~16
33-2350H		V 12V A ≤ W RPM D.R ←	163630A150;163630P280; 1636321110;1636331470	LEXUS RX350 07~09; RX350 16~19 TOYOTA(丰田) Avalon 13~18; Camry 07~17; PRIUS C 12~19; Sienna 04~10; Venza 09~11
33-2350H-1		V 12V A ≤ W RPM D.R →	163630P250;163630V120	LEXUS RX350 10~15 TOYOTA(丰田威飒) Sienna 11~16
33-2350H-3		V 12V A ≤ W RPM D.R →	16363B5020;1680001110	DAIHATSU Hijet 10~
33-2350I		V 12V A ≤ W RPM D.R →	1712080J00;17120M74L00 ;16800008310	MAZDA(马自达) 2 07~15 SUZUKI Swift(铃木雨燕) 10~20; SX4 07~13
33-2350I-1		V 12V A ≤ W RPM D.R ←	1355A279;1680007030	MITSUBISHI Mirage G4 12~19
33-2350J		V 12V A ≤ W RPM D.R ←	1636328210;1680001650	SCION TC 05~10 TOYOTA WISH ZGE20
33-2350J-1		V 12V A ≤ W RPM D.R →	1712060R00;1680001932	SUZUKI SX4 S-Cross 16~19; Vitara 15~19
33-2350K		V 12V A ≤ W RPM D.R ←	1636338080;1680002660	LEXUS GS 300 08~11; LS460 08~11

33-2350K-1		V 12V A ≤ W RPM D.R →	1636346170;CY0315150;CY0315150A;CY0315150B;1680002630	MAZDA CX-9 07~15 TOYOTA Estima 3.5 08~20; Highlander(丰田汉兰达) 08~10; Vellfire 3.5 08~14
33-2350L		V 12V A ≤ W RPM D.R →	17120M60M00;17120B77M00N000;1712077M01;1680009480;2680004060	MITSUBISHI Colt 08~ PROTON Ertiga SUZUKI Sx4 15~21; Vitara 15~21
33-2350L-1		V 12V A ≤ W RPM D.R →	1355A302;1680002460	MITSUBISHI Genuine
33-2350M		V 12V A ≤ W RPM D.R ←	MR360801;MR568284;168007710	MITSUBISHI Montero(三菱帕杰罗) 01~02
33-2350N		V 12V A ≤ W RPM D.R ←	19030RSRE01	HONDA Civic Type S 2.2L 07~11
33-2350P		V 12V A ≤ W RPM D.R ←	19030RN0A51;19030RN0A71	HONDA Pilot 09~15;Ridgeine 09~13
33-2360A		V 12V A ≤ W RPM D.R		Latin America
33-2383		V 12V A ≤ W RPM D.R	TJ1483;TH2383	TOYOTA Corolla 93~97; Ercel 95~98
33-2383A		V 12V A ≤ W RPM D.R	300044	HONDA
33-2400		V 12V A ≤ W RPM D.R		SUZUKI Maruti Steem FM35

33-2402		V 12V A ≤ W RPM D.R	TIY3124	HONDA Accord 90~; Civic 1.6 88~94
33-2411		V 12V A ≤ W 55 RPM D.R	214875L700;21487CX000; L32715150;L32815150;MR 314718	MAZDA Atenza 02~ MITSUBISHI Lancer 02~07 NISSAN Sentra 02~06; X-Trail(尼桑奇骏) 02~13
33-2411A		V 12V A ≤ W 55 RPM D.R	1355A087;1355A093;1355 A131;MI3115139	MITSUBISHI(三菱) ASX(劲炫) 08~16; Lancer 08~15
33-2604		V 24V A ≤ W RPM CW D.R	2635000833	ISUZU Giga Condenser 14.3 00~05
33-2613		V 12V A ≤ W RPM D.R		HINO 700(日野700)
33-2860		V 12V A ≤ W RPM CCW D.R	2825001000	TOYOTA Dyna; Toyoace
33-2860A		V 12V A ≤ W RPM CCW D.R		HINO BLOWER
33-2860B		V 24V A ≤ W RPM CW D.R	2825000131	HINO New Ranger 35T 03~ MITSUBISHI Fiter
33-2860C		V 24V A ≤ W RPM CW D.R	2825000212	MITSUBISHI Canter 6.5T 96~(RHD)
33-2871		V 24V A ≤ W RPM CCW D.R	1625005461	HINO Profia; Ranger TOYOTA Dyna; Toyoace

33-2871A		V 24V A ≤ W RPM CW D.R	2825000030	HINO Mfg 15T 90~
33-3001		V 12V A ≤ W RPM D.R	HR8102P620C	PERODUA Exora
33-3002		V 12V A ≤ W RPM D.R	TGA0033GC01;5Z10036; MR315449;MR315450;781 2A038	MITSUBISHI Montero Sport 97~07; Nativa Sport 97~11 PROTON Waja
33-3002B		V 12V A ≤ W RPM D.R	AJ5815150	MAZDA 6 03~08
33-3010A		V 12V A ≤ W RPM D.R	214871HC0A;214871HC0 B;214871HS0A;214871HS 0B	NISSAN(尼桑) March(玛驰)11~15; Almera(阳光)11~14
33-3010D		V 12V A ≤ W RPM D.R	214823AU1C	NISSAN Note 2018; Sunny 2013
33-3011		V 12V A ≤1.5 W 100 RPM ±2800 D.R	214871AA0A;214871AA0B ;214871AA0E;214871DAO A;214873GF1A;21487EB7 0C214874CE0B;21487ZX5 0A	NISSAN(尼桑) Livana(骊威) 13~15; Navara D40T 08~12; NV200 14~18; Teana(天籁) 08~12 Tiida(骐达) 14~16 Maxima(西玛) 16~ Sylphy(轩逸) 16~19
33-3011A		V 12V A ≤2 W 160 RPM ±2800 D.R	214871HS3C;214871HS3 D;214873LM0A21487JG30 A;21487JG30B;21487JG7 0B;21487JG70C;214873T A0A	NISSAN March 11~18; NV200 12~18; Rogue S35 10~; Sentra 13~19; Versa 15~18; X-trail T31 10~18
33-3012		V 12V A ≤1.5 W 100 RPM ±2800 D.R	214871KA0A;214871KA0B ;214871KA0E;214873RA1 A	NISSAN(尼桑) Altima(蓝鸟) 16~19 Sylphy(轩逸) 12~19 Versa 12~17

33-3012B		V 12V A ≤ W RPM D.R →	214871VM1A;21487JF00B	INFINITI Q50 16~; Q60 16~19; Q70 15~16 NISSAN(日产) New Xtrail T32, G-TR 09~20
33-3012C		V 12V A ≤ W RPM D.R →	21487JF01B	NISSAN(日产) G-TR 09~20
33-3013		V 12V A ≤1.5 W 100 RPM ±2800 D.R ←	1903055AZ01;190305A2A 01;19030RB0004;19030RL F901;19030R1AA02;38616 R1AA01;	ACURA ILX 13~15 HONDA(本田) Accord(雅阁) 13~17; City(锋范经典) 08~14 Civic(思域) 12~15; CRV 10~16; CR-Z 11~16; FIT(飞度) 09~14; Insight 10~14; Odyssey(奥德赛) 09~14 Spirior(思铂睿)13~17
33-3013A		V 12V A ≤1.5 W 100 RPM ±2800 D.R →	386165A2A01;38616RLF9 01	HONDA(本田) Accord(雅阁) 13~17; Odyssey(奥德赛) 09~14
33-3014		V 12V A ≤1.5 W 100 RPM ±2800 D.R ←	1355A262;1355A272;2148 7B212B	MITSUBISHI OutlanderIII 12~21
33-3014A		V 12V A ≤1.5 W 100 RPM ±2800 D.R →	1355A260;21487B212A;21 487W010P	MITSUBISHI OutlanderIII 12~21
33-3015		V 12V A ≤1.5 W 100 RPM ±2800 D.R	21487JN00A;21487JN01C	NISSAN(日产) Note 13~16
33-3228		V 12V A ≤ W RPM D.R	163630Y030;163630Y040; 163630Y050;2680006002; 2680008170	TOYOTA(丰田) Vios(威驰) 15~19; Yaris L(致炫) 14~20; Yaris L(致享) 17~18
33-3609		V 12V A ≤ W RPM D.R	7020018;9778625000;9778 625100	HYUNDAI Accent 00~05

33-3609A		V 24V A ≤ W RPM D.R		HYUNDAI
33-3703		V 12V A ≤ W RPM D.R		Latin America
35-2026		V 12V A ≤ W 70 RPM D.R	125474	CITROEN PEUGEOT 306 benzina; 306 2.0 TDS; 605 DS
35-2045		V 12V A ≤ W RPM D.R	PGK0B02APM	PEUGEOT 405 KK-2037 FAN ASSY
35-2050		V 12V A ≤3 W 190W RPM ±2100 D.R	MP8125TSC;5000114;464 30980;46539871;46550400 ;7787852;	TATA INDICA FIAT Bravo 1.4,1.6; Brava 1.4,1.6; Marea 1.6; MultiplaU 1.6,1.9JTD
35-2054		V 12V A ≤ W RPM D.R	9625461380;VDO.PM8120	PEUGEOT 405
35-2054A		V 12V A ≤ W RPM D.R	125315	PEUGEOT 405
35-2061		V 12V A ≤ W RPM D.R	6401016;50012120	SW 1600 MIKNATISLI CİFT DEVİRLİ BLOWER
35-2062		V 24V A ≤ W RPM D.R	6401005	OTOMARSAN 302 MB BLOWER
35-2063		V 24V A ≤ W RPM D.R	6401017;50012124	MIKNATISLI CİFT DEVİRLİ BLOWER

35-2066		V 24V A ≤ W RPM D.R	6401133	MB KAMYON BLOWER
35-2067		V 12V A ≤ W RPM D.R	69400104	PEUGEOT J9 BLOWER
35-2068		V 24V A ≤ W RPM D.R	BASKURT.50012222	FORD CARGO-YETSAN GENİS GOVDE ÇİFT DEVİR BLOWER
35-2069		V 12V A ≤ W RPM D.R	BASKURT.50012219	YETSAN HIZLI GENİS GOVDE ÇİFT DEVİRLİ BLOWER
35-2070		V 12V A ≤ W RPM D.R	BASKURT.50012122	CORUM TİPİ MİNİ MİKNATISLI BLOWER
35-2071		V 24V A ≤ W RPM D.R	BASKURT.50012123	CORUM TİPİ MİNİ MİKNATISLI BLOWER
35-2072		V 12V A ≤ W RPM D.R	BASKURT.50011118	FORD Transit(江铃全顺) 78~99 BLOWER
35-2072E		V 12V A ≤1.5 W 150 RPM ±3800 D.R		TURKEY BLOWER
35-2072F		V 24V A ≤ W RPM D.R		TURKEY BLOWER
35-2073		V 12V A ≤ W RPM D.R	BASKURT.50012167;BAS KURT.50011113	BMC LEYLAND TM 30 YENİ MODEL SACLİ BLOWER

35-2073A		V 12V A ≤ W RPM D.R	BASKURT.50012161	VOLVO BLOWER
35-2073B		V 24V A ≤ W RPM D.R	BASKURT.50012173;BASKURT.50013447	BMC BELDE OTOBUS ON KALOPIFER MOTORU BLOWER
35-2073C		V 12V A ≤ W RPM D.R	BASKURT.50012164	DEV FATİH SACLİ BLOWER
35-2074		V 24V A ≤ W RPM D.R	0130007043	VOLVO SCANIA 0302 WEBASTO BLOWER
35-2075		V 12V A ≤ W RPM D.R	0130007064	RENAULT Master 82~97 BLOWER
35-2076		V 12V A ≤ W RPM D.R	3137220291	AUDI VW TRANSPORTER BLOWER
35-2076A		V 24V A ≤ W RPM D.R	0130063042;17ABE2310	RUSSIA BLOWER
35-2076C		V 12V A ≤ W RPM D.R	7701203257;0130063071; SAMPLE.201322	RENAULT Clio 92~97; Kangoo 98~04 BLOWER
35-2076D		V 12V A ≤ W RPM D.R	0130063810	BLOWER
35-2143		V 24V A ≤ W RPM D.R	BASKURT.50021119	TURBO FAN MOTORU OTOMARSAN TURBO MOTORU BLOWER


35-2155		V 12V A ≤ 2.5 W 160W RPM ± 3200 D.R	125491;125473	CITROEN PEUGEOT 106;306;405 I ;405 II ;605
35-2155B		V 12V A $\leq$ W 250 RPM D.R	125467;125470;125490	CITROEN Xsara 97~05; XM 89~00; ZX 91~97 PEUGEOT 306 93~01; 405 I 87~92; 405 II 92~96; 605 89~99 KK-2837 FAN ASSY
35-2215		V 12V A $\leq$ W RPM D.R	BASKURT.50051222	TAKVIYE MOTORU BLOWER
35-2215-2		V 24V A $\leq$ W RPM D.R	BASKURT.50051225	TAKVIYE MOTORU BLOWER
35-2252		V 24V A $\leq$ W RPM D.R	67114327;	GS IRAN BLOWER
35-2253		V 12V A $\leq$ W RPM D.R	67113111	IRAN BLOWER
35-2253-2		V 24V A $\leq$ W RPM D.R	67113112	IRAN BLOWER
35-2254		V 24V A $\leq$ W RPM D.R	BASKURT.50014110	TURKEY BLOWER
35-2310		V 24V A $\leq$ W RPM D.R	BASKURT.50014213	OTOMARSAN DUZ BLOWER FAN MOTORU BLOWER

35-2311		V 24V A ≤ W RPM D.R	BASKURT.50043133	CİFT MİLLİ DÜZ BLOWER MOTORU BLOWER
35-2311A		V 24V A ≤ W RPM D.R	BASKURT.50043119	57-M RUSSIA 011-B40-22,011-B46-22
35-2312		V 24 A ≤ W RPM D.R	BASKURT.50014210	OTOMARSAN / MAN VİDALI VİDALI SALYANGOZ MOTOR BLOWER
35-2313		V 24V A ≤ W RPM D.R	BASKURT.50043113	KONVEKTA KUCUK KLİMA MOTORU BLOWER
35-2314		V 12V A ≤ W RPM D.R	BASKURT.50041156	LONG LIFE YENİ MODEL KLİMA MOTORU BLOWER
35-2314-2		V 24V A ≤ W RPM D.R	BASKURT.50041159	LONG LIFE YENİ MODEL KLİMA MOTORU BLOWER
35-2315		V 12V A ≤ W RPM D.R	BASKURT.50041113	SUTRAK KLİMA MOTORU CEMBERLİ BLOWER
35-2316		V 12V A ≤ W 60 RPM D.R	2016557702254844;64012 03	RENAULT R5 T.T.;R9 T.T.;R19 T.T.
35-2317		V 24V A ≤ W RPM D.R	BASKURT.50012138	OTOMARSAN CD 6mm VİDALI ON KALOPIFER BLOWER
35-2317A		V 12V A ≤ W RPM D.R	BASKURT.50012146	PEUGEOT J9 BLOWER

35-2318		V 12V A ≤3.5 W 180 RPM ±2800 D.R	125487	PEUGEOT 206 98~ KK-2568B FAN ASSY
35-2318A		V 12V A ≤ W 220 RPM D.R	8D0959455;8D0959455C;8D0959455Q;8D0959455P;8D0959455L	AUDI A4 95~99; 98~; A8 98~ VW PASSAT 96~00
35-2318B		V 12V A ≤ W 230 RPM D.R	1250G6;1250G7;1489767080;1494742080	CITROEN C8;N.jumpy(07) FIAT N.scudo(07); Nuovo(02); N.ulyse(02) LANCIA Phedra(01)
35-2318C		V 12V A ≤ W 250 RPM D.R		PEUGEOT 206 98~ KK-2568A FAN ASSY
35-2320		V 12V A ≤ W RPM D.R	06940110200099;7701038405;7700785115	RENAULT Clio 1.1,14; R9; R19; R21;
35-2326A		V 12V A ≤ W 110 RPM D.R	06940119600099;914866	RENAULT Clio Klimal
35-2328		V 12V A ≤ W RPM D.R	9010832;	FIAT Doblo 01~ KK-2535 FAN ASSY
35-2330		V 12V A ≤ W RPM D.R	235200066	OPEL Astra G 98~09; Zafira A 99~05 KK-2543 FAN ASSY
35-2332		V 12V A ≤ W RPM D.R	235200027	OPEL Astra G 98~09; Zafira A 99~05 KK-2525 FAN ASSY
35-2334		V 12V A ≤ W RPM D.R	235200031	OPEL Combo 01~; Corsa C 00~09; Tigra 04~ KK-2523 FAN ASSY

35-2336		V 12V A ≤ W RPM D.R	235200012	OPEL Combo 01~; Corsa C 00~09 KK-2531 FAN ASSY
35-2338		V 12V A ≤ W RPM D.R	235200136	OPEL Vectra B 95~03 KK-2527 FAN ASSY
35-2340		V 12V A ≤ W RPM D.R	A82700069	OPEL Vectra B 95~03 KK-2541 FAN ASSY
35-2342		V 12V A ≤ W RPM D.R	235200060	BUICK Sail(别克赛欧) OPEL Astra F 91~01; Calibra A 90~97; Combo 94~01; Corsa B 93~00; Tigra 94~00; Vectra A 88~95 KK-2537 FAN ASSY
35-2344		V 12V A ≤ W RPM D.R		FIAT Croma 86~96; Tempra 90~96; Tipo 87~95; Uno 85~93 LANCIA Dedra 89~99; Delta II 93~99 KK-2545 FAN ASSY
35-2344A		V 12V A ≤ W 90 RPM D.R	46744928;46515058;46514973;7762665	FIAT Brava 98~; Bravo 98~; Marea 99~; Multipla
35-2345		V 12V A ≤ W 50 RPM D.R	MQ0746;7704319;46400256	FIAT Palio 01~ Nuova Cinquecento 903-1.1 cc.; Nuova Seicento 1.1 903cc.-889
35-2345A		V 12V A ≤2 W 50 RPM D.R	7700653324	RENAULT Clio
35-2352		V 12V A ≤3 W 160 RPM ±3000 D.R	46538861;60809409	ALFA ROMEO 145,146 94~ FIAT Palio

35-2354		V 12V A ≤ 3.5 W 220 RPM ± 3200 D.R	46743392	ALFA ROMEO 147 1.9JTD 00~ FIAT Doblo 05~
35-2355		V 12V A $\leq$ W 380 RPM D.R	55700342;55703902	FIAT Bravo ~06; Grande Punto ~05
35-2356		V 12V A $\leq$ W RPM D.R		EUROPE
35-2357		V 12V A $\leq$ W 570 RPM D.R	46524608;46785741;46776540;46789115	FIAT NUOVA PUNTO 1.2 8V-16V CF2-CF3 AC(99-03); NUOVA PUNTO FL(03); IDEA(03)
35-2357A		V 12V A ≤ 2.5 W 170 RPM ± 3500 D.R		CITROEN Jumper 94~06 PEUGEOT Boxea 94~02 FIAT Ducato 94~06
35-2357B		V 12V A $\leq$ W 370 RPM D.R	90030452	FIAT
35-2358		V 12V A $\leq$ W RPM D.R	6Q0959455AE	VW Polo 4
35-2368		V 12V A $\leq$ W RPM D.R		RENAULT Twingo 93~
35-2405		V 12V A $\leq$ W RPM D.R	7700728083;7700828623; TIY334	RENAULT R5 72~96
35-2406		V 12V A $\leq$ W RPM D.R	856656GH;	RENAULT Kangoo I 98-03

35-2544		V 12V A ≤5 W 300 RPM ±3800 D.R		OPEL Astra H 04~; Zafira B 05~
35-2555-1		V 12V A ≤4 W 250 RPM ±3700 D.R	3N065407;5000918;5YY0548	RENAULT Duster; Dacia; Logan L90
35-2555-2		V 12V A ≤345 W RPM D.R		RENAULT
35-2576		V 12V A ≤ W RPM D.R	需要散热环	FIAT Viaggio(菲翔) 2012~
35-2800A		V 12V A ≤ W RPM D.R		FIAT 500 07~ FORD KA 08~
35-2803		V 12V A ≤ W RPM D.R	90570740;0130303246	OPEL Astra H 05~; Corsa D 06~; Zafira B 05~ OE.
35-2803A		V 12V A ≤ W RPM D.R		OPEL
35-2809A		V 12V A ≤ W 200 RPM D.R		SEAT Cordoba 93~02; Ibiza II 93~02; Inca 95~03; Toledo I 91~99 VW Caddy II 95~04; Derby 99~05 Polo 97~01
35-2857		V 12V A ≤ W RPM D.R	67113212	RUSSIA BLOWER

35-2857-2		V 24V A ≤ W RPM D.R	67113213	RUSSIA BLOWER
35-2988A		V 12V A ≤ W 150 RPM D.R	46524621	FIAT Nuova Punto 1.9DS,JTD 99~
35-3010		V 12V A ≤ W RPM D.R	21487JD20A;21487JE30A	NISSAN Qashqai(尼桑逍客) 08~14
37-2065		V 12V A ≤ W φ RPM D.R	6401065	FORD CARGO PERVANELI BLOWER
37-2065A		V 24V A ≤ W φ RPM D.R	6401070	FORD CARGO PERVANELI BLOWER
37-2083		V 12V A ≤ W RPM D.R	4644367;PM9070	CHRYSLER Caravar 93~95; Voyager 93~95
37-2086		V 12V A ≤ W RPM D.R	1680006430	HOLDEN Commodore VT VX VU
37-2086A		V 12V A ≤ W RPM D.R		CHRYSLER
37-2102A		V 12V A ≤ W RPM D.R		CHEVROLET NEW Epica;Optra
37-2102B		V 12V A ≤3 W 110 RPM ±2300 D.R	94511188	CHEVROLET Aveo DAEWOO Nexia

37-2102C		V 12V A ≤ W RPM D.R	92217925;A005359	CHEVROLET Lova;Kalos
37-2102F		V 12V A ≤3 W 110 RPM ±2300 D.R		CHEVROLET
37-2102G		V 12V A ≤3 W 110 RPM ±2300 D.R		CHEVROLET
37-2149		V 12V A ≤ W RPM D.R		CHEVROLET NEW Epica A / C ; Aveo
37-2160		V 12V A ≤ W RPM D.R	19189277;88918562;88999604;E3FZ8K621B;E3ZZ8K621A;E43Z8K621B;E5FZ8K621C;E6FZ8K621B;E6FZ8K621C;E6PZ8K621A;E6Z8K621A;E73Z8K621A;35653;35660;PM242E	FORD Escort 83-89; Exp 83-88; Mustang 83-93; Tempo 84-91; Thunderbird 85-88 MERCURY Capri 83-86; Cougar 84-86; Ln7 1983; Lynx 83-87; Topaz 84-91 OLDSMOBILE Cutlass calais 1989
37-2161		V 12V A ≤ W RPM D.R	19189043;19193486;4761509;4882800;75702;75711	CHRYSLER Cirrus 95~05 DODGE Stratus 95~06 PLYMOUTH Breeze 96~00
37-2162		V 12V A ≤3 W 100 RPM ±2700 D.R	19187870;52079786AA;55037659AA;55037659AB;75813	JEEP Liberty 02~05
37-2164		V 12V A ≤2.5 W 150 RPM ±3000 D.R	89023368;1580551;F00HX6B035;PM9327	CADILLAC Escalade 05~06 CHEVROLET Avalanche 07~13; Avalanche 1500 05~06; Silverado 1500 05~13; Suburban 1500 05~14; Tahoe 05~14 GMC Sierra 1500 05~13; Yukon 05~14; Yukon XL 1500 05~14

37-2162A		V 12V A ≤ W RPM D.R	19187866;5017407AA;5017407AB;75760;PM9145	CHRYSLER PT Cruiser 01~08
37-2163		V 12V A ≤3.5 W 160 RPM ±2700 D.R	19144545;19188934;52079860AA;52079528AC;52079528AD;35155;TIY3344	JEEP Grand Cherokee 99~03; Liberty 02~03
37-2163A		V 12V A ≤3 W 100 RPM ±2700 D.R	FA52079786AB;VDO.PM9265;TIY3452	JEEP Liberty 02~
37-2164A		V 12V A ≤ W RPM D.R		JEEP Grand Cherokee Liberty 3P
37-2164B		V 12V A ≤ W RPM D.R	15780796;1580881;F00HX6B068	CADILLAC Escalade 05~06 CHEVROLET Avalanche 07~13; Avalanche 1500 05~06; Silverado 1500 05~13; Suburban 1500 05~14; Tahoe 05~14 GMC Sierra 1500 05~13; Yukon 05~14; Yukon XL 1500 05~14
37-2165		V 12V A ≤2.5 W 110 RPM ±2300 D.R	19188930;4682517;88918523;35151;PM9046;TIY3289	CHRYSLER Grand Town&Country 96~00 DODGE Caravan 96~00; Grand Caravan 96~00 PLYMOUTH Grand Voyager 96~00; Voyager 96~00
37-2166		V 12V A ≤ W RPM D.R	JYCH1126M	CHRYSLER Sebring
37-2171		V 12V A ≤ W RPM D.R	2F1Z8C607AA;3F1Z8C607AA;3F1Z8C607GA;4F1Z8C607AA;5F1Z8C607A;5F1Z8C607B;D9ZZ8546D;F6DZ8C607A;FS.35125;VDO.PM9122;VDO.PM9123	FORD Sable 96~97; Taurus 96~99 MERCURY Sable 96~97

37-2167		V 12V A ≤ W RPM D.R	52028337;52028337AB;35160;PM9154;TIY3510	JEEP Cherokee 97~01; Comanche 91~92
37-2168		V 12V A ≤4 W 190 RPM ±3600 D.R	2L8Z8600FA;2L8Z8C607EA;2L8Z8C607FA;2L8Z8C607GA;YL8Z8600EA;YL8Z8600FB;YL8Z8C607GF;35187;PM9167	FORD Escape 01~04 MAZDA Tribute 01~05
37-2168A		V 12V A ≤2.5 W 100 RPM ±2600 D.R	19188866;05018380AA;5019290AA;35058;PM9264	CHRYSLER Sebring 01~06 DODGE Stratus 01~06
37-2169		V 12V A ≤ W RPM D.R	S2532A	CHRYSLER
37-2170		V 12V A ≤ W RPM D.R	F78Z8C607AA;XF2Z8C607AE;ZF2Z8C607AB;6U2Z8C607B;PM9127;35105;35136	FORD Windstar 95~98
37-2172		V 12V A ≤ W 120 RPM 2800 D.R	20903475;20903476;20903477;1581697;1581698;1581700	CADILLAC Escalade 10~14 CHEVROLET Avalanche 10~13; Silverado 1500 10~13; Suburban 1500 10~14; Suburban 2500 10~14; Tahoe 10~14 GMC Sierra 1500 10~13; Yukon 10~14; Yukon XL 1500 10~14; Yukon XL 2500 10~14
37-2172A		V 12V A ≤2.5 W 120 RPM ±2800 D.R	20903474;1581696	CADILLAC Escalade 10~14 CHEVROLET Avalanche 10~13; Silverado 1500 10~13; Suburban 1500 10~14; Suburban 2500 10~14; Tahoe 10~14 GMC Sierra 1500 10~13; Yukon 10~14; Yukon XL 1500 10~14; Yukon XL 2500 10~14
37-2178		V 12V A ≤ W 120 RPM 2800 D.R	1581679;25952813	CHEVROLET Equinox 10~17 GMC Terrain 10~17


37-2173		V 12V A ≤ W RPM D.R	5066162AA;24041451;24041228;PM9085;PM90885137714AA;A4267134938;A6131121128;A6344091841;M153950	CHEVROLET Venture 99~00 CHRYSLER 300 05~23 300M 99~04; Concorde 98~04; Intrepid 01~04; LHS 99~01 DODGE Challenger 08~23; Charger 11~23; Intrepid 98~04; Viper 08~17 OLDSMOBILE Silhouette 99~00 PONTIAC Montana 99~00
37-2200		V 12V A ≤ W RPM D.R	19189056;TIY3062	CHRYSLER LeBaron 1994; Voyager 84~88 DODGE Neon 95~99 PLYMOUTH Neon 95~99
37-2201		V 12V A ≤ W RPM D.R	19189144;19189235;4546538;4761510;88918554;FS.35459;FS.35575;VDO.PM3310;VDO.PM3321	CHRYSLER Cirrus 95~00; Imperial 91~93; Lebaron 91~94; New yorker 91~93; Stratus 96~97 DODGE Caravan 96~97; Daytona 91~93; Dynasty 91~93; Grand caravan 96~97; Shadow 91~94; Spirit 91~95; Stratus 95~00 PLYMOUTH Acclaim 91~95; Breeze 96~00; Grand voyager 96~97; Sundance 91~94; Voyager 96~97
37-2201A		V 12V A ≤ W RPM D.R	19189246;5211058;5211115;88918555;E0ZZ8K621A;VDO.PM3603;FS.35597	CHRYSLER E-Class 1983; LeBaron 82~83; New Yorker 1983 DODGE 400 82~83; 600 1983; Aries 82~83; Omni 78~82; Rampage ~82 FORD Fairmont 81~82; Granada 81~82; Mustang 80~82 MERCURY Capri 80~82 PLYMOUTH Caravelle 1983; Horizon 78~82; Reliant 82~83

37-2202		V 12V A ≤ W RPM D.R	19189283;88918564;FS.35662;VDO.PM3646	DODGE Caravan 88~89; Grand caravan 88~89; Mini ram 1988; Shadow 87~89 PLYMOUTH Grand voyager 88~89; Sundance 87~89; Voyager 88~89
37-2203		V 12V A ≤ W RPM D.R	19189275;4244246;4246494;433423;88918557;35651	CHRYSLER E class 83~84; Executive limousine 1985; Laser 84~86; Lebaron 83~89; New yorker 83~88 DODGE 400 82~83; 600 83~88; Aries 82~89; Charger 83~87; Dakota 87~97; Daytona 84~89; Lancer 85~89; Omni 83~89; Rampage 83~84; PLYMOUTH Caravelle 83~88; Horizon 83~89; Reliant 82~89; Turismo 83~87; RENAULT Alliance 86~87; Encore 1986;
37-2204		V 12V A ≤ W RPM D.R	19189133;4266689;4401002;88918548;FS.35444;VDO.PM3674	DODGE Caravan 1990; Grand caravan 1990; Mini ram 1990; Shadow 1990 PLYMOUTH Grand voyager 1990; Sundance 1990; Voyager 1990
37-2204A		V 12V A ≤ W RPM D.R	4240490;4240494;4266283;4266371;4419167;PM3643;31651	CHRYSLER LeBaron 84~90; New Yorker 84~90
37-2204B		V 12V A ≤ W RPM D.R	19189143;4401132;88918553;VDO.PM3657;FS.35457	CHRYSLER Daytona 1990; LeBaron 1990; Spirit 89~90

37-2204C		V 12V A ≤ W RPM D.R	4762347;VDO.PM3325;FS.35324	DOGDE Neon 95~99 MAZDA MPV 89~98 PLYMOUTH Neon 95~99 SUBARU Justy 87~94
37-2204D		V 12V A ≤ W RPM D.R	19030P5M004;19144473;19189055;VDO.PM3347;FS.35323	HONDA Accord 98~01; Civic 98~01; CRV 97~00
37-2205		V 12V A ≤ W RPM D.R	19189289;4266940;4364866;88918570;FS.35668;VDO.PM3627	CHRYSLER Laser 84-85; Lebaron 87-90; Tc maserati 89-90 DODGE Charger 84-87; Dakota 94-97; Daytona 84-92; Lancer 85-89; Omni 85-86; Shadow 87-90 PLYMOUTH Horizon 84-86; Sundance 87-88
37-2206		V 12V A ≤ W RPM D.R	19189285;4266858;4339461;88918566;FS.35664;VDO.PM3645	DODGE Dakota 87~92; Shadow 87~90; Omni 1990 PLYMOUTH Horizon 1990; Sundance 87~90
37-2206A		V 12V A ≤ W RPM D.R	19189141;4546232;4546233;5252800;5252801;FS.35455;VDO.PM3678	CHRYSLER Town & country 91~92 DODGE Caravan 91~92; Grand caravan 91~92 PLYMOUTH Grand voyager 91~92; Voyager 91~92
37-2206B		V 12V A ≤ W RPM D.R	19189009;214820C025;2148758Y01;2148785Y10;88918522;FS.35257;VDO.PM3915;VDO.PM3358	NISSAN 200SX 97~98; NX 91~93; Sentra 91~99; Tsuru II 95~97
37-2208		V 12V A ≤ W RPM CW D.R	4000504	AMERICA 6916-081

37-2213		V 12V A ≤ W RPM D.R ←	12362507;12362565;88986473;GM3116103;FS.35285;FS.35360;VDO.PM543;VDO.PM545	BUICK Century 1999; Regal 97~98 CHEVROLET Classic 04~05; Malibu 97~03; Vectra 03~05 OLDSMOBILE Alero 99~04; Cutlass 97~99; Intrigue 1998 PONTIAC Grand Am 99~05; Grand Prix 97~02
37-2213A		V 12V A ≤ W RPM D.R →	10427837;12362509;19189087;22088311;22088783;22088785;22119863;22120308;22120616;22134671;22136414;22136544;22136897;22137319;88890699;88890701;88918540;88957398;GM3116101;35292;35380;35389;PM538;PM540;PM541;PM542;PM544	BUICK Century 89~05; Lacrosse 2005; Lesabre 94~99; Park Avenue 95~96; Regal 90~04; Riviera 95~99; Rendezvous 02~07; Roadmaster 94~96; Skylark 89~95; Somerset 1986; Somerset Regal 1985 CADILLAC Deville 91~99; Eldorado 95~00; Fleetwood 94~96; Seville 88~00 CHEVROLET Beretta 94~96; Camaro 1995; Caprice 94~96; Cavalier 92~05; Corsica 94~96; Impala 95~96; Lumina 94~01; Lumina Apv 92~95;
37-2244		V 12V A ≤2A W 120 RPM ±2500 D.R	5014577AA;VDO.PM9119;TIY3248	CHRYSLER Neon 2.0 MT 00~03 DODGE Neon 2.0 MT 00~03
37-2244A		V 12V A ≤ W RPM D.R	5019212AA;TIY3567	DODGE Neon 2.0 AT 00~03
37-2348		V 12V A ≤2.5 W 180 RPM ±3100 D.R	S93BB8B605AA;5925475;5933628;5933631;7568372	FORD Ikon FIAT Ducato 90~

37-2246		V 12V A ≤ W RPM D.R	19188863;89001440;FS.35054;TIY3246	CHRYSLER Town&Country 93~95 DODGE Caravan 93~95; Grand Caravan 93~95 PLYMOUTH Grand Voyager 93~95; Voyager 93~95
37-2247B		V 12V A ≤ W RPM D.R →	163630A100;163630A170; 1636328030;5127521AA;5 127521AB;FS.75757;VDO. PM9259	DODGE Neon 04~05; SX 2.0 04~05 LEXUS ES300 02~03 TOYOTA Camry 02~06; RAV4 06~12; Solara 04~08
37-2248E		V 12V A ≤ W RPM D.R	MR355977; VDO.PM9255	CHRYSLER Sebring 98~00 DODGE Avenger 98~00
37-2251		V 12V A ≤ W RPM D.R	19188929;4682516;89001430;FS.35150;VDO.PM9044	CHRYSLER Grand Town&Country 96~00 DODGE Caravan 96~00; Grand Caravan 96~00 PLYMOUTH Grand Voyager 96~00; Voyager 96~00
37-2319		V 12V A W RPM D.R →	10427857;22040861;22040881;22040991;22048577;22049519;22049526;22049579;22051205;22062554;22067446;22073429;22073432;22074968;22074969;22081940;22082436;22088075;22088773;22088786;22136898;22137318;35656;PM517	BUICK Century 84~05; Clectra 85~90; Lesabre 85~97; Park avenue 91~05; Reatta 89~91; Regal 88~04; Riviera 86~99; Roadmaster 94~96; Skyhawk 84~87; Skylark 86~93; Somerset 86~87; Somerset regal 1985 CADILLAC 60 special 1993; Allante 87~92; Brougham 87~92; Cimarron 85~88; Commercial chassis 1992; Deville 85~95; Eldorado 86~93; Fleetwood 85~96; Seville 86~93 CHEVROLET Beretta 87~95; C

37-2353		V 12V A ≤3.2 W 180 RPM ±3000 D.R	XS6H8C607PCR	FORD Courier 2000; FiestaIV 95~00 MAZDA 121III 96~03 KK45-2353-BM FAN ASSY
37-2353A		V 12V A ≤ W RPM D.R	MP8125178PO	FORD Courier 2000; FiestaIV 95~00 MAZDA 121III 96~03
37-2361		V 12V A ≤4 W 150 RPM ±2900 D.R		FORD Transit V348(福特世 代,江铃全顺)
37-2361A		V 12V A ≤4 W 280 RPM ±3300 D.R		FORD Transit V348(福特世 代,江铃全顺)
37-2365		V 12V A ≤ W RPM D.R	69401399	FORD V184 TEK MOTOR PERVANESiZ KK-2309 FAN ASSY BLOWER
37-2366		V 12V A ≤4 W 300 RPM ±3400 D.R	5000474	CHEVROLET Cammaro; Sonic FORD Escape; Freestar;Transit 07~13
37-2366A		V 12V A ≤4 W 300 RPM ±3400 D.R	3L156410;5000483	FORD Transit 07~13
37-2366B		V 12V A ≤4 W 300 RPM ±3400 D.R	10792920;5000440;5YY01 14;3J364306;377X14D	FORD Freestar; Scape
37-2367		V 12V A ≤4.5 W 240 RPM ±3600 D.R	555836;4365502;864777A	FORD Courier 99~05; Fiesta 99~00; Ikon 95~; KA 00~09 KK-2573 FAN ASSY
37-2572		V 12V A ≤4 W 350 RPM ±3300 D.R	55555839;1ME036A;1ME0 37A	FORD Fiesta 05~09; EcoSport 03~09

37-2711		V 12V A ≤ 4 W 190 RPM ± 3300 D.R	8V618C607E	FORD Focus
37-2712		V 12V A ≤ 3 W 120 RPM ± 3200 D.R		FORD Fiesta
37-2713		V 12V A $\leq$ W RPM D.R	1095445	FORD Mondeo 97~00
37-2719		V 12V A ≤ 3 W 250 RPM ± 3500 D.R	8V518C607EJ	FORD B-MAX 12~; Eco Sport(翼博); Fiesta 09~; Fiesta VI 08~
37-2719C		V 12V A ≤ 3.5 W 170 RPM ± 3400 D.R	94509633;A10101358M	CHEVROLET Trax 14~16; Tracker
37-2723A		V 12V A $\leq$ W RPM D.R	1ME033C	CHEVROLET Chevy; Corsa Hatchback 97~02
37-2723B		V 12V A ≤ 2 W 40 RPM D.R		FORD B-MAX 12~; Fiesta 09~; Fiesta VI 08~
37-2914A		V 12V A ≤ 3 W 110 RPM 2300 D.R	A005381	CHEVROLET Spark 2010~
37-2915		V 12V A ≤ 2 W 50 RPM 2680 D.R		CHEVROLET Matiz 06~ DAEWOO Matiz 98~
37-2987		V 12V A ≤ 3 W 150 RPM ± 2800 D.R	MP8120VYV6S;M5000276	CHEVROLET STS-783

37-2988		V 12V A ≤4 W 170 RPM ±2600 D.R	MP8120VYV8M;5000256	CHEVROLET STS-777
37-2989		V 12V A ≤ W RPM D.R	MP8125VYV8M;5000257	CHEVROLET STS-778
37-2990		V 12V A ≤ W RPM D.R	MP8125VYV6SM;5000275	CHEVROLET STS-784
37-3010C		V 12V A ≤2.5 W 130 RPM ±2800 D.R	M157983;A10111384LC	NISSAN Altima; Juke; X-trail
37-3265		V 12 A ≤ W RPM D.R	19193525;5072181AA;5072181AB;VDO.PM9234;FS.75745	CHRYSLER 300E 99~04; Concorde 98~04; Intrepid 99~04; LHS 99~01 DODGE Intrepid 98~04
39-1900		V 12V A ≤ W RPM D.R	TY0022756004599	12V 12W AP11 3730 / P519 RUSSIA BLOWER
39-1900A		V 24V A ≤ W RPM D.R	4123730000	M3236 Kaluga
39-1900C		V 24V A ≤ W RPM D.R	24373000000	GAZ ,UAZ 21.3780
39-2015		V 12V A ≤ W RPM D.R ←	1636328060;1636346030;1636364080;1636374180;8855002020;8855012130;8855012150;8855012160;065002521;0650002060;065002061;0650002132;0650002442;0650002480;0650002860;0650007290;PM9115	LEXUS GS300 93~95 TOYOTA(丰田) Carina 92~98, Celica 93~99; Corolla 93~97; Crown 91~95; Paseo 96~98; Prado(普拉多) 04~16; Rav4 94~00; Tercel 95~98

39-2015A		V 12V A ≤ W RPM D.R ←	38616PWAA01;38616PW AJ01;38616REZA01;3861 6RNAA01;38616RZAA01;8 0151SAA003;0650002940; 0650003070;0650003250	HONDA(本田) CRV 09~11; Fit 03~08; Jazz 02~08
39-2015B		V 12V A ≤ W RPM D.R ←	38616P3G003;065000179 2;0650002571;0650002572	HONDA(本田) CRV 02~06; Element 03~06
39-2015C		V 12V A ≤ W RPM D.R ←	0650002271;TIY3355	HONDA Accord SV4 94~97 PROTON Perdana; Waja; Wira 1.5
39-2015D		V 12V A ≤ W RPM D.R ←	16363B2010;0650003231	HONDA Accord SV4 94~97 PROTON Perdana; Waja; Wira 1.5
39-2015E		V 12V A ≤ W RPM D.R ←	8855001020;8855012120;0 650001890;TIY3137	(需要确认风叶外观,副厂风叶 无法使用) GEO Prizm 89~92 TOYOTA Corolla 88~92
39-2015F		V 12V A ≤ W RPM D.R ←	0650003330;0650000911	PROTON Wira TOYOTA AE101 SUZUKI Jimmy; Katana; Twincam
39-2015G		V 12V A ≤ W RPM D.R ←	0650002492	SUZUKI Aerio Baleno
39-2015H		V 12V A ≤ W RPM D.R ←	0650002033	PROTON Wira 1.6
39-2015I		V 12V A ≤ W RPM D.R ←	1712050M00;0650003390; 0650003391	SUZUKI MR Wagon(MF33S) Wagon R(MH34S MH44S) Alto(HA35S) Spacia(MK32S)

39-2015J		V 12V A ≤ W RPM D.R ←	0650007351	SUZUKI SX4 13~22
39-2053		V 12V A ≤3.5 W 120 RPM ±2400 D.R		TATA INDICA BEHR SMALL PLUG
39-2053A		V 12V A ≤3 W 70 RPM ±3300 D.R		TATA INDICA BEHR BIG PLUG
39-2053B		V 12V A ≤ W RPM D.R		SAFARI DICOR 2.2 INDIA TATA
39-2059		V 12V A ≤ W RPM D.R		TATA Ace 09~10
39-2059A		V 12V A ≤ W RPM D.R		TATA Ace 11~12 KK-2907 FAN ASSY
39-2081A		V 12V A ≤ W 80 RPM D.R		UNIVERSAL KK-2150V KK-2152V FAN ASSY
39-2081A-2		V 24V A ≤ W 80 RPM D.R		UNIVERSAL KK-2150V KK-2152V FAN ASSY
39-2091		V 12V A ≤ W 50 RPM D.R		UNIVERSAL
39-2091-2		V 24V A ≤ W 50 RPM D.R		UNIVERSAL

39-2091A		V 12V A ≤ W 50 RPM D.R		UNIVERSAL(M6)
39-2091B		V 12V A ≤ W 50 RPM D.R		UNIVERSAL KIA Pride
39-2091C		V 12V A ≤ W 50 RPM D.R	FDMSF08135E	UNIVERSAL Latin America
39-2091T		V 12 A ≤ W 50 RPM D.R		UNIVERSAL 泰国New Star专用;线路相反
39-2091T-2		V 24V A ≤ W 50 RPM D.R		UNIVERSAL 泰国New Star专用;线路相反
39-2092		V 12V A ≤ W 50 RPM D.R		UNIVERSAL
39-2092-2		V 24V A ≤ W 50 RPM D.R		UNIVERSAL
39-2092A		V 12V A ≤ W 50 RPM D.R		UNIVERSAL KIA Pride
39-2092B		V 12V A ≤ W 50 RPM D.R		LADA UNIVERSAL
39-2092C		V 12V A ≤ W 50 RPM D.R	37406F510;7812A100	MITSUBISHI L200 05~15; Montero 05~15

39-2092C-2		V 24V A ≤ W 50 RPM D.R		mitsubishi
39-2099C		V 12V A ≤ W RPM D.R ←	0650001700;0650001701	TOYOTA
39-2104		V 12V A ≤2.5 W 170 RPM ±3200 D.R	B2134IFB;EO250100;	TATA INDICA BEHR
39-2363		V 12V A ≤ W RPM D.R	2109130800801	LADA Samara; Vega KK-2547-BM FAN ASSY
39-2401		V 12V A ≤ W RPM D.R ←	1636328050;0650007320; TIY3382	TOYOTA RAV4 01~ 05
39-2401A		V 12V A ≤ W RPM D.R ←	MB878162;0650007121	mitsubishi Pajero V32,V33
39-9005		V 12V A ≤ W RPM D.R	1YY0093;8N37421	MAHINDRA XUV500


Fan Assy



40-2496		V 12V A ≤ W φ 301 RPM W.D Pull	130801001	CHANA RAD(长安风扇)
42-1001		V 12V A ≤ W φ RPM W.D	55056948AB;55056948AC; 55056948AD;55056948AE; 55056948AG;55056948AH ;55056948AI;VDO.FA7082 3	DODGE RAM 1500 PICKUP 09~10 RAM 2500 PICKUP 09~10 RAM 3500 PICKUP 09~ RAM 1500 11~18 1500 CLASSIC 19~23 2500 11~18
42-1002		V 12V A ≤ W φ RPM W.D	55037992AD;55037992AC ;621498	DODGE DURANGO 11~20 JEEP GRAND CHEROKEE 11~21
42-1003		V 12V A ≤ W φ RPM W.D	5080646AA;5080647AB;50 93760AA;68004163AA;621 639	DODGE RAM 1500 PICKUP 02~08 RAM 2500 PICKUP 03~07 RAM 3500 PICKUP 04~07
42-1004		V 12V A ≤ W φ RPM W.D	68038241AA;68057238AA; 68102116AA;68102119AA; 68038247AA;68057237AA; 620036	DODGE JOURNEY 09~20
42-1005		V 12V A ≤ W φ RPM W.D	55038994AD;55038994AE; 55038994AF;55038994AG; 55038994AH;55038994AI; VDO.FA70980	DODGE DURANGO 11~ 2013 JEEP GRAND CHEROKEE 11~13
42-1006		V 12V W RPM.L RPM.R N.m	253801C360;253801C350	HYUNDAI Getz 02~09
42-1007		V 12V W RPM.L RPM.R N.m	253801M020;253801X000; 253801M000;253801M050	KIA (起亚) FORTE 09~

42-1008		V 12V W RPM.L RPM.R N.m	253801D100	KIA (起亚) 佳乐 07~13 RANDO 08~09
42-1009		V 12V W RPM.L RPM.R N.m	253802K000	KIA (起亚) SOUL 09~11
42-1010		V 12V W RPM.L RPM.R N.m	2538007550;2538007500	KIA (起亚) PICANTO 05~
42-1011		V 12V W RPM.L RPM.R N.m	2538007100;2538007200	KIA (起亚) PICANTO 04~07
42-1012		V 12V W RPM.L RPM.R N.m	0K2A161710A;0K2A161710;0K2A161710C	KIA (起亚) 佳乐 02~
42-1013		V 12V W RPM.L RPM.R N.m	0K2A115025A;0K2A115025B;0K2A115025C;0K2A115025D;0K2A115025E;0K2A115025F;0K2A115025	KIA (起亚) SHUMA 96~01
42-1014		V 12V W RPM.L RPM.R N.m	96181888;033811200;234052320;734012180;96181889;96184988	DAEWOO (大宇) LEGANZA 97~04 NUBIRA 97~03 旅行家 97~03
42-1015		V 12V W RPM.L RPM.R N.m	68189000AA;68189000AD;531851110;68188996AA;68188996AB;68189000AB;68189000AC;DG488004;621637	RAM PROMASTER 14~21

42-1016		V W RPM.L RPM.R N.m	12V	10431404;19130418;19130419;89022511	CHEVROLET Impala 00~03
42-1017		V W RPM.L RPM.R N.m	12V	2523138000;2535038000	HYUNDAI SONATA 99~05 XG300 01~ XG350 02~05 KIA OPTIMA 01~06
42-1019		V W RPM.L RPM.R N.m	12V	9773038000;9773138000;977353F000;9778638000;9773038001	HYUNDAI SONATA 99~05 XG300 01~ XG350 02~03 KIA OPTIMA 01~06
42-1020		V W RPM.L RPM.R N.m	12V	253804P550;25350C8050	HYUNDAI I20 15~21
42-1021		V W RPM.L RPM.R N.m	12V	977304H000;977304H500	HYUNDAI(现代)辉翼 08~10
42-1022		V W RPM.L RPM.R N.m	12V	25380F8500	HYUNDAI TUCSON 15~
42-1023		V W RPM.L RPM.R N.m	12V	2538022020;	HYUNDAI 现代 ACCENT I 94~00
42-1024		V W RPM.L RPM.R N.m	12V	977302D100;977302D000;977352D000;977862D000	HYUNDAI 现代 ELANTRA 00~06

42-1025		V 12V W RPM.L RPM.R N.m	2538017100;252312D000; 2535017000;2535017030;2 538017030;2538017130;25 38017800;2538617000;253 8617800	HYUNDAI 现代 美佳 01~10
42-1026		V 12V W RPM.L RPM.R N.m	9773017000;9773517000;9 773717000;9778617000	HYUNDAI 现代 美佳 01~10
42-1027		V 12V W RPM.L RPM.R N.m	2538025000;2535025000;2 538625001	HYUNDAI 现代 ACCENT II 00~05
42-1028		V 12V W RPM.L RPM.R N.m	9773025000;9773525000;9 773725000;9778625001	HYUNDAI 现代 ACCENT II 00~05
42-1029		V 12V W RPM.L RPM.R N.m	253801E100;	HYUNDAI 现代 雅绅特 05~10
42-1030		V 12V W RPM.L RPM.R N.m	977301E000;	HYUNDAI 现代 雅绅特 05~10
42-1031		V 12V W RPM.L RPM.R N.m	253802H020;253802H050	HYUNDAI 现代 ELANTRA 06~11 i30 07~11
42-1032		V 12V W RPM.L RPM.R N.m	253803X000;25380A6100; 25380A6200	HYUNDAI 现代 ELANTRA 11~15 i30 11~16

42-1033		V 12V W RPM.L RPM.R N.m	96182264;EU03005;EU50001	DAEWOO 大宇 LANOS 97~99
42-1034		V 12V W RPM.L RPM.R N.m	96183756;234052340;94581033;96181887;96351331	DAEWOO 大宇 LEGANZA 97~04 NUBIRA 97~02
42-1036		V 12V W RPM.L RPM.R N.m	OK30C61710;OK30C61710C;OK30C61710D	KIA 起亚 RIO 00~05
42-1037		V 12V W RPM.L RPM.R N.m	253801G050;	KIA 起亚 RIO II 05~
42-1038		V 12V W RPM.L RPM.R N.m	253802F000;	KIA 起亚 CERATO 04~09
42-1039		V 12V W RPM.L RPM.R N.m	977302F000;	KIA 起亚 CERATO Hatchback 04~07
42-1040		V 12V W RPM.L RPM.R N.m	OK2A115025;	KIA 起亚 SHUMA 97~01
42-1041		V 12V W RPM.L RPM.R N.m	OK2A161710A;	KIA SPECTRA 02~

42-1042		V 12V W RPM.L RPM.R N.m	25380F2000;	HYUNDAI 现代 ELANTRA 15~16
42-1043		V 12V W RPM.L RPM.R N.m	253803X500;	HYUNDAI 现代 ELANTRA 13~ KIA 起亚 CERATO 13~
42-1044		V 12V W RPM.L RPM.R N.m	95205516;95205515;DOR MAN.621556	CHEVROLET SPARK 13~15
42-1045		V 12V W RPM.L RPM.R N.m	96611266;96322939	DAEWOO 大宇 MATIZ 98~04
42-1046		V 12V W RPM.L RPM.R N.m	253801Y030;253801Y050; 253801Y000;253801Y090	KIA 起亚 PICANTO 11~
42-1047		V 12V W RPM.L RPM.R N.m	25380H9000;25380H9050; 25380H8450	KIA RIO 19~
42-1048		V 12V W RPM.L RPM.R N.m	253801U100;253801U200; 253801U201;VDO.FA7086 6;DORMAN.621493	HYUNDAI SANTA FE 10~12 KIA SORENTO 11~13
42-1049		V 12V W RPM.L RPM.R N.m	386155R1003;386165R10 03;VDO.FA70983;DORMA N.621375	HONDA FIT 15~20

42-1050		V 12V W RPM.L RPM.R N.m	253800A170;253803K210	HYUNDAI SONATA 09~10
42-2057		V 12V A ≤6 W 60 φ 312 RPM ±1800 W .D	2538022220; 2535022000; 9773722000; 620777	HYUNDAI Accent 95~99 RAD KIA(起亚千里马主扇)
42-2057A		V 12V A ≤6 W 60 φ 312 RPM ±1800 W .D	9773022010; 9773522000; 9773737100; 2538022000; 9778622010; 620715	HYUNDAI Accent 95~99 A / C KIA(起亚千里马副扇)
42-2504		V 12V A ≤7.5 W 90 φ 325 RPM ±2200 W .D	2538002000; 5083452AA;	DODGE Atos 00~04 HYUNDAI Atos(现代阿托兹) 00~04
42-2504A		V 12V A ≤5 W 90 φ 325 RPM ±2400 W .D		HYUNDAI Atos Prime 99~; Santro 05~
42-2504B		V 12V A ≤8 W φ 325 RPM ±2800 W .D	2538005500;	HYUNDAI Atos Prime 99~; Santro 05~
42-2505		V 12V A ≤ W φ RPM W .D	977304F100;977304F150	HYUNDAI PORTER 94~08
42-2505A		V 24V A ≤ W φ RPM W .D		HYUNDAI PORTER 94~08

42-2506		V 12V A ≤ W φ 298 RPM W .D	96353136; 96144965; 96144976	DAEWOO Cielo(大宇蓝天) 95~97; Nexia 95~97
42-2508		V 12V A ≤ W φ RPM W .D	253801E300;253801E350; 253801E450	HYUNDAI Accent 05~10
42-2509		V 12V A ≤ W φ RPM W .D	253801F250;253801F251; 253802E250;	HYUNDAI TUCSON 05~09 KIA SPORTAGE 05~09
42-2513		V 12V A ≤ W φ RPM W .D	253802Z000;253802Y100	HYUNDAI iX35 10~15
42-2616		V 12V A ≤ W φ RPM W .D	253800X000; 253800X050	HYUNDAI I10 08~13
42-2617		V 12V A ≤ W φ RPM W .D	253801R050; 253801W150; 253801W151; 253801W152; 252311R390;253501R050; 253501W050; 253804L050;253851M000; 253861R140;	DODGE Attitude 11~13 HYUNDAI Accent 12~13; Veloster 12~14 KIA Rio 12~17
43-1001		V 12V A ≤ W φ RPM W .D	214813AB3A;214819KK0A ;VDO.FA70910	NISSAN VERSA 12~19
43-1002		V 12V A ≤ W φ RPM W .D	214813SH5A;214819AM0 A;214819AP0A;VDO.FA70 921	NISSAN SENTRA 13~19

43-1003		V 12V A ≤ W φ RPM W .D	214811HS3A;FS.76359	NISSAN VERSA 12~19
43-1004		V 12V A ≤ W φ RPM W .D	38615R1AA01;38615R1AA02;621490	ACURA(讴歌) ILX 13~15 HONDA(本田思域) CIVIC 12~15
43-1005		V 12V A ≤ W φL φR W .D	19015RAAA01;VDO.FA70211	HONDA ACCORD(本田雅阁) 03~07
43-1006		V 12V A ≤ W φ RPM W .D	92120ZP50A;92120ZL00A	NISSAN FRONTIER 07~15 PATHFINDER 07~12 XTERRA 07~15
43-1007		V 12V A ≤ W φ RPM W .D	19015R1AA01;19015R1AA02;DORMAN.621480	ACURA(讴歌) ILX 13~15 HONDA(本田思域) CIVIC 12~15
43-1008		V 12V W RPM.L RPM.R N.m	MB66032C;1355A132;1355A141;1355A146	MITSUBISHI (三菱) LANCER VIII 08~10
43-1009		V 12V W RPM.L RPM.R N.m	MR497767	MITSUBISHI (三菱) LANCER VI 95~03
43-1010		V 12V W RPM.L RPM.R N.m	MR958398;MR568816;MR233814;MR568812;MN185142;CW740887	MITSUBISHI (三菱) LANCER VI 95~03

43-1011		V W RPM.L RPM.R N.m	12V	CW722119;MB845072;MR188156;CL4156A;MB188151	mitsubishi (三菱) LANCER VI 95~03
43-1012		V W RPM.L RPM.R N.m	12V	MR201374;MB877089;MR315271;MR460922;MR513229	mitsubishi (三菱) LANCER VI 95~03
43-1013				163600V340;1636025010;16360F0010;163600P170;2685002000;1636331490 (电机)	CAMRY 18~21 亚洲龙 19~22
43-1014				1636031510;1636331510 (电机)	CAMRY 18~21
43-1015				167110Y280;163610Y340 (扇叶);163610Y350 (扇叶);1636347060 (电机);1636347050 (电机)	TOYOTA 卡罗拉/雷凌 1.2T 19~
43-1016				16711F2030;1636347060 (电机);16361F2050 (风叶)	TOYOTA 奕泽 18~ C-HR 19~ 雷克萨斯 UX200 19~21
43-1017				16360F0090;16363F0080;1636025020;1636331500 (电机)	TOYOTA 威兰达 20~
43-1018				16360F2120;1636331500 (电机)	TOYOTA RAV4 19~

43-1019			1636025030	LEXUS NX350H 22~ TOYOTA RAV4 22~23 RAV4 PRIME 21~
43-1020			16360F0100	TOYOTA HIGHLANDER 20~22
43-1021		V 12V W 400 RPM.L RPM.R N.m	190305AAA01;190155AG H01;190155AAA01;19015 RAAA01ZP;190205AAA01	HONDA CIVIC 1.6
43-1022		V 12V W RPM.L RPM.R N.m	19015RZAA01;19020PNL G01;19030RZAA01;HO31 15139;19020PNA003;6202 12	HONDA CR-V 07~09
43-1023		V 12V W RPM.L RPM.R N.m	21481CD000;21481CF40B ;21483CD000;21486CA00 0;21486CD000;21487CD0 00;21487CD00A;21481CF 40A;FA70261;620429	INFINITI G35 03~07 350Z 03~07
43-1024		V 12V W RPM.L RPM.R N.m	MVATO00053	TOYOTA Avanza 07~15
43-1025		V 12V W RPM.L RPM.R N.m	214812L700;2148138U01; 2148138U00;2148338U10; 2148685;2148685E00;214 8685E10;2148738U00	INFINITI(英菲尼迪) J30 92~97
43-1026		V 12V W RPM.L RPM.R N.m	1710061M20;1710061M00	SUZUKI SX4 S-CROSS 13~21 VITARA 13~21

43-1027		V 12V W RPM.L RPM.R N.m	36811RR2H51	HONDA 锋范
43-1028		V 12V W RPM.L RPM.R N.m	1180008731;1680008701	HONDA City/Fit Radiator Fan Cooling Fan
43-1029		V 12V W RPM.L RPM.R N.m	Shroud:214811HS0D Blade&Motor:214821HS0D	Nissan Sunny Radiator
43-1030		V 12V W RPM.L RPM.R N.m	163610D150;163630D120; 167110D190	TOYOTA 丰田 VERSO 09~ 花冠 09~12
43-1031		V 12V W RPM.L RPM.R N.m	1636137110;1636137100;1 636337100;1636337110;16 71137180;TO3115212	TOYOTA PRIUS PRIME 17~22
43-1032		V 12V W RPM.L RPM.R N.m	1671147110	TOYOTA AURIS 18~
43-1033		V 12V W RPM.L RPM.R N.m	167110Y120	TOYOTA C-HR 16~
43-1034		V 12V W RPM.L RPM.R N.m	1636131410;1636138040;1 636331300;1636331400;16 71131610;DORMAN.6204 98	LEXUS IS300 16~23 IS350 14~23

43-2010A		V 12V A ≤ W φ RPM W .D	19015PNB003;19015PNL G01;19015PZDA01;VDO.F A70130;DORMAN.620232	HONDA(本田) CRV 02~06 ELEMENT 03~11
43-2010A- 1BM		V 12V A ≤ W φ 297 RPM W .D	19020PL6003	HONDA Fit 03~08
43-2010B		V 12V W RPM.L RPM.R N.m	1636103070;1636103071;1 636103081;1636122030;16 36128100;1636303100;163 630H010;1636374370;167 110H020;FA70106;620542	TOYOTA CAMRY 99~01 SOLARA 99~01
43-2030B		V 12V A ≤ W φ RPM W .D	38615PLCN01;38615PMM C00;FA70124	HONDA CIVIC(本田里程) 01~05
43-2051C		V 12V A ≤ W φ RPM W .D	21481ED50B;21481ED50 C	NISSAN(日产) 颐达 05~10 骊威 骏逸 L10Z 07~10 骐达 05~11
43-2096- BM		V 12V A ≤ W φ 248 RPM W .D	TIY396	NISSAN BE2
43-2242		V 12V A ≤ W φ 340(7L) φ 340(5R) RPM W .D	1671175230;	TOYOTA(丰田) Hiace 04~
43-2242- 1BM		V 12V A ≤ W φ 340(5R) RPM W .D	1636175030	TOYOTA Hiace 04~

43-2242-BM		V 12V A ≤ W φ 340(7L) RPM W .D	1636175040	TOYOTA Hiace 04~
43-2304		V 12V A ≤8 W 60 φ 300 RPM ±2200 W .D	9212051C28; 921205B401; 620407	NISSAN BE3(MT) 90~94; Sentra 91~97
43-2304A		V 12V A ≤ W 80 φ 300 RPM W .D	921204B901; 9212054J00; 9212060Y01; 620408	INFINITI G20 91~96 NISSAN 200SX 95~98; BE3(AT) 90~99; Sentra 91~97
43-2350B-5		V 12V A ≤ W φ RPM W .D	190155LAA01;19015R5AA 01;19015REZA01;VDO.FA 70941	HONDA(本田) CR-V 10~16
43-2350B-5BM		V 12V A ≤ W φ 300 RPM W .D	38611RBB003;38615RB00 03;	HONDA City 2009; Fit 2009
43-2350B-7		V 12V A ≤ W φ RPM W .D	38615RGLA01;VDO.FA70 290	HONDA ODYSSEY 05~10
43-2350I		V 12V A ≤ W φ 316 RPM W .D	ZJ3815025B; 76327; FA70896; 621412	MAZDA(马自达) 2 11~14
43-2371		V 12V A ≤ W φ 310 RPM W .D	MB66019A; MR312899; MR314718; MR464708; MR968365; MR993933; 76163; FA70237;	MITSUBISHI Lancer(三菱欧 蓝德) 02~07

43-2372		V 12V A ≤ W φ 367 RPM W .D		INFINITI(英菲尼迪) JX35 2013; QX60 14~20 NISSAN Pathfinder 13~20
43-2372-1		V 12V A ≤ W φL φR W .D	214813JA0A;214813JA0E; 214813JA2E;76333;FA717 50;621586	INFINITI(英菲尼迪) JX35 2013; QX60 14~20;NISSAN Pathfinder 13~20
43-2501		V 12V A ≤ W φ 302 RPM W .D	1711177A00; 1711076A00	HONDA SUZUKI
43-2526		V 12V A ≤ W φ RPM W .D	95950465;96808149;94567 001;FS.76240	CHEVROLET AVEO 09~15 PONTIAC G3 07~10 SUZUKI SWIFT 09~11
43-2551A		V 12V A ≤ W φ 300 RPM W .D	2148151C86; 214815B401; 21481F430A; 2148160Y00; 620405	NISSAN BE3(MT) 90~94; Sentra 91~97
43-2551B		V 12V A ≤ W φ 300 RPM W .D	2148160R01; 2148160Y01; 2148160Y10; 2148179R00; 620406	INFINITI G20 91~96 NISSAN 200SX 95~98; BE3(AT) 90~99; Sentra 91~97
43-2556		V 12V A ≤ W φ 300 RPM W .D	17100M79F03; SR1227509950; SR1680004771;	SUZUKI Wagon R Shroud
43-2601		V 12V A ≤ W φ 301 RPM W .D	16360B2010; 1668087402	DAIHATSU Mira 0.66 04~07 Sirion 2 1.0i TOYOTA Passo 1.0 04~10

43-2602		V 12V A ≤ W φ 301 RPM W .D	16360B2050	DAIHATSU Esse 0.66 05~; Mira 0.66 05~07
43-2603		V 12V A ≤ W φ 301 RPM W .D	1667097201	DAIHATSU Mira 0.66 98~04; Yrv 1.0 00~02
43-2604		V 24V A ≤ W φ 301 RPM W .D	227403632	ISUZU Giga Condenser 14.3 00~05
43-2605- BM		V 12V A ≤ W φ 320 RPM W .D	16360B2081	DAIHATSU Move 0.66 06~; Mira 0.66 06~
43-2606		V 12V A ≤ W 130 φ 355 RPM W .D	1671121110; 1671121030; 1671137050; 167110M040; 620549	TOYOTA Vios;Yaris(丰田威 驰,雅力仕) 06~13
43-2607		V 12V A ≤ W φ 297 RPM W .D	19015P08003; 19015P08013; 19020P08003;19020PD20 03;19020PH4661;19030P0 8003;19030P08013;9030P 1R003; 620217;620204	HONDA Civic 92~98
43-2607- BM		V 12V A ≤ W φ 297 RPM W .D	19020P08003;	HONDA Civic 92~95
43-2608A		V 12V A ≤ W 130 φ 360 RPM W .D	163610D090; 1636121060; 163630D040; 163630D100; 1636323020; 167110D070; 167110D071; 167110D072;	PONTIAC Vibe 03~08 TOYOTA Avensis 03~08; Corolla(丰田花冠) 03~08; Matrix 03~08

43-2609		V 12V A ≤2 W 130 φ 370 RPM W .D	167110T040; 167110T010; 621363	TOYOTA Corolla(丰田卡拉) 08~10
43-2609-BM		V 12V A ≤2 W 130 φ 370 RPM W .D	163610T040; BE63610T040	TOYOTA Corolla(丰田卡拉) 08~10
43-2610		V 12V A ≤ W 352 φ 7(L) φ 5(R) RPM W .D	167110H140; 167110H150; 163610H240; 163610H270	TOYOTA Camry(丰田凯美瑞) 2.0L 07~10
43-2611		V 12V A ≤ W 352 φ 7(L) φ 5(R) RPM W .D	1671131370; 76105; FA70724; 621175	TOYOTA Highlander(丰田汉兰达) 08~15
43-2612		V 12V A ≤ W φ RPM W .D	19005PAAA01; 19015PAAA01; 19020PAAA01; 19020PLC003; 19030PAAA01; 620227	HONDA Accord 98~02
43-2612A		V 12V A ≤ W φ RPM W .D	19015PLC003;19015PLC004;19015PMMA51;19000PLF513;19020PLC003;19030PAAA01;FA70118;620219	HONDA CIVIC(本田里程) 01~05
43-2614		V 12V A ≤ W φ RPM W .D	19015RCAA01; 19020RCAA01; 19030RCAA01; 620235; FA70207	HONDA Accord(本田雅阁) 03~07
43-2618		V 12V A ≤ W φ RPM W .D	214814BE0B; 214816MA0A; 214816MA0B; 214814EA0A; 214814EB0A; 214814BE0A; 214814EA0B; 21481DF30A;	NISSAN Qashqai J11(尼桑逍客) 15~22

43-2618-BM		V 12V A ≤ W φ RPM W .D		NISSAN Qashqai J11(尼桑逍客) 15~22
43-2639		V 12V A ≤ W φ RPM W .D	38615REZA01; 620938	HONDA(本田) CRV 10~14
43-2639A		V 12V A ≤ W φ RPM W .D	38615RZAA01;620245	HONDA(本田) CR-V 07~09
43-2640		V 12V A ≤ W φ RPM W .D	214816M100; 214836M100; 214869E000; 214869E010; 214870Z800; 214916M100	NISSAN Sentra 00~06
43-2903		V 12V A ≤5 W 50 φ 253 RPM ±2200 W .D		HONDA City A / C T1,T2
43-2904		V 12V A ≤ W φ 253 RPM W .D		MITSUBISHI Lancer A / C PETROL
43-2909		V 12V W 80 RPM.L RPM.R N.m	MN123607	MITSUBISHI (三菱) L 200 05~15
43-2910		V 12V A ≤ W φ RPM W .D	MB924137;MB906062;MB924138;VDO.FA70669	CHRYSLER Sebring 95~99 DODGE Avenger 95~99 EAGLE Talon 95~98 MITSUBISHI Eclipse 95~99

43-2912			19015RNAA01; 19020RCJA01; 19030RTA004; 38611RTA004	HONDA (本田) 思域 05~06
43-3010		V 12V A ≤18 W φ 382 RPM ±2000 D.R W .D	21481JD200; 21481JE30A; 21483JE20A; 21486JE20A	NISSAN Qashqai J10(尼桑逍 客) 08~14
43-3013		V 12V W RPM.L RPM.R N.m	190305A2A01;19020RWK J01;190155A2A01PFM;HO 3115162	HONDA (本田) ACCORD 13~17
45-1001		V 12V A ≤ W φL φR W .D	15788745;15254643;15236 647;22713868;VDO.FA702 71	CHEVROLET MALIBU 04~12 PONTIAC G6 05~10 SATURN AURA 07~09
45-1002		V 12V A ≤ W φL φR W .D	19129812;19129813;19129 814;19129815;19129816;1 9130231;19130401;191304 02;19130470;19130471;62 1052;FA70436	CHEVROLET EQUINOX 06~08 PONTIAC TORRENT 06~08
45-1003		V 12V A ≤ W φ RPM W .D	13267634;13289627;13360 890;DORMAN.620658	BUICK VERANO 12~17 CHEVROLET CRUZE 11~15 CRUZE LIMITED 16~ OPEL Astra(雅特) 11~15;
 Zafira(赛飞利);
45-1004		V 12V A ≤ W φ RPM W .D	15211556;15849635;19417 092;20824475;VDO.FA702 66	CHEVROLET COBALT 05~10 PONTIAC G5 07~10 PURSUIT 05
45-1005		V 12V A ≤ W φL φR W .D	13269460;13269461;13321 421;20970655;20970656;2 0970657;22747157;227471 58;22747159;23109120,D ORMAN.620971	BUICK REGAL 14~17 CHEVROLET IMPALA 14~19 MALIBU 13~15 MALIBU LIMITED 16~

45-1006		V 12V A ≤ W φ RPM W .D	15817306;22728111;25784660;VDO.FA70427	CHEVROLET HHR 06~11
45-1007		V 12V A ≤ W φ RPM W .D	95080113;95080114;95352378;95391500;95391501;95942905;620586	CHEVROLET SONIC 12~19
45-1008		V 12V A ≤ W φ RPM W .D	95392642;95465725;FA72240;621576	CHEVROLET TRAX 13~20
45-1010		V 12V A ≤ W φL φR W .D	1C0121206A;1C0121206B;1C0121207;1C0121207A;1C0121207B;1C0121207C;1C0121209;1C0121209A;FA70174;620773	SEAT CORDOBA 03~09 IBIZA 02~10 VW Beetle 98~06
45-1011		V 12V W 300 RPM.L RPM.R N.m	64506908024;64546921383;64548380776;6454839182;64546919053;64546921942;64548390968	BMW 740I 99~01 740IL 99~01 750IL 99~01
45-1012		V 12V W 300 RPM.L RPM.R N.m	64548380774;64548369070	BMW 740I 97~98 740IL 96~98 750IL 96~98
45-1013		V 12V W 400 RPM.L RPM.R N.m	64546921379;64547603657;64546946372	BMW 745I 03~05 745LI 03~05 750I 06~08 750LI 06~08 760I 04~06 760LI 03~08
45-1014		V 12V W 600 RPM.L RPM.R N.m	17417589028	BMW 5 系 10~17 7 系 08~15

45-1015		V 12V W 850 RPM.L RPM.R N.m	17427806017;1742850974 3	BMW 550I 11~16 550I GT 10~17 650I 12~18 750I 09~15 750LI 09~15 ALPINA B7 11~15 ALPINA B7L 11~13
45-1016		V 12V W 400 RPM.L RPM.R N.m	17428677741;1742793387 5;17427953569;174279534 01;17428619627;17428638 429	BMW 7系 16~23 5系 17~24 2.0T 6系 17~24
45-1017		V 12V W 600 RPM.L RPM.R N.m	17428677740;1742793387 4;17427953568;174286196 26;17427953400	BMW 7系 16~23 5系 17~24 2.0T 6系 17~24
45-1018		V 12V W 300 RPM.L RPM.R N.m	64548380780;6454837099 3;64546919057;645483807 82;64546913887;64548380 781;64548361935;6454837 1362	BMW 5系 95~03 2.5L
45-1019		V 12V W 300 RPM.L RPM.R N.m	64546921395;6454692194 6;64506908030	BMW 525I 01~03 528I 99~00 530I 01~03 540I 99~03 M5 00~03
45-1020		V 12V W 400 RPM.L RPM.R N.m	17427540681;1742760376 2;17427526824	BMW 5系 02~09 2.5L
45-1021		V 12V W 600 RPM.L RPM.R N.m	17427543282;1742751418 1;17427534912;174275248 81;17427534911	BMW 5系 02~09 3.0L
45-1022		V 12V W 400 RPM.L RPM.R N.m	17428508251	BMW 5系 02~09 2.5L

45-1023		V 12V W 600 RPM.L RPM.R N.m	17427801657	BMW 5系 02~09 3.0L
45-1024		V 12V W 400 RPM.L RPM.R N.m	17428509740;1741758903 1;17427633273	BMW 5系 10~16 2.0T
45-1025		V 12V W 600 RPM.L RPM.R N.m	17428509741;1742759949 3;17427802943;174275607 64	BMW 5系 10~16 3.0L
45-1026		V 12V W 400 RPM.L RPM.R N.m	17418642160;1741761878 6	BMW 5系 10~16 2.0T
45-1027		V 12V W 600 RPM.L RPM.R N.m	17418642161;1741864216 2;17418617103;174186191 43;17417618787	BMW 5系 10~16 3.0L
45-1028		V 12V W 850 RPM.L RPM.R N.m	17428509742;1742764765 2;17424582294;171176019 09	BMW 5系 10~16 3.0T
45-1029		V 12V W 300 RPM.L RPM.R N.m	17117561757;1711752550 8;17117510617;171177908 95;17117510085;17117510 086;17117801422	BMW 3系 98~06 2.0L
45-1030		V 12V W 850 RPM.L RPM.R N.m	17112283621	BMW 3系 08~13 3.0T

45-1031		V 12V W 400 RPM.L RPM.R N.m	17428506668;17427788906	BMW 3系 01~10 2.0L
45-1032		V 12V W 600 RPM.L RPM.R N.m	17427801647	BMW 3系 04~13 2.5L
45-1033		V 12V W 400 RPM.L RPM.R N.m	17427640509;17428641963	BMW 3系 15~18 1.6T
45-1034		V 12V W 600 RPM.L RPM.R N.m	17427640511;17428641964	BMW 3系 15~18 2.0T
45-1035		V 12V W 400 RPM.L RPM.R N.m	17428625439	BMW 3系 16~19 2.0T
45-1036		V 12V W 600 RPM.L RPM.R N.m	17428625440	BMW 3系 16~19 2.0T
45-1037		V 12V W 400 RPM.L RPM.R N.m	17428666815;17428477379	BMW 3系 18~ 2.0T
45-1038		V 12V W 400 RPM.L RPM.R N.m	17428591441	BMW 3系 18~ 2.0T

45-1039		V 12V W 400 RPM.L RPM.R N.m	64546921381;64546921940	BMW X5 99~06 4.4L
45-1040		V 12V W 400 RPM.L RPM.R N.m	17428618238;17427598738	BMW X5 06~13 3.0L BMW X5 14~20
45-1041		V 12V W 400 RPM.L RPM.R N.m	17428618239;17427634466	BMW X5 06~13 3.0L BMW X5 14~20
45-1042		V 12V W 600 RPM.L RPM.R N.m	17428618240;17427533558;17427598740	BMW X5 06~13 3.0T BMW X5 14~20
45-1043		V 12V W 600 RPM.L RPM.R N.m	17428618241;17427634467	BMW X5 06~13 3.0T BMW X5 14~20
45-1044		V 12V W 850 RPM.L RPM.R N.m	17428618243;17427647754;17427634472;17427576281	BMW X5 06~13 4.4T BMW X5 14~20
45-1045		V 12V W 850 RPM.L RPM.R N.m	17428618242;17427634471;17427616104;17427647753;17427795757;17428508177	BMW X5 06~13 4.4T BMW X5 14~20
45-1046		V 12V W 600 RPM.L RPM.R N.m	17428655761;17427953224 (风框)	BMW X5 20~ 3.0T

45-1047		V 12V W 400 RPM.L RPM.R N.m	17113452509;17113401056	BMW X3 03~09 2.0L
45-1048		V 12V W 600 RPM.L RPM.R N.m	17113442089;17423442096	BMW X3 04~10 2.0L
45-1049		V 12V W 400 RPM.L RPM.R N.m	17427601176	BMW X3 13~17 X4 15~18
45-1050		V 12V W 600 RPM.L RPM.R N.m	17427560877;17427593847	BMW X3 11~18 2.0T
45-1051		V 12V W 400 RPM.L RPM.R N.m	17118642749 17428487636	BMW X3 18~ 2.0T
45-1052		V 12V W 400 RPM.L RPM.R N.m	17428472314;17428487637	BMW X3 19~ 2.0T
45-1053		V 12V W 600 RPM.L RPM.R N.m	17427545366	BMW X1 09~16 2.0T
45-1054		V 12V W 300 RPM.L RPM.R N.m	17427617608;17428596236;17428596237;17428596238	BMW X1 16~ 1.5T X2 18~ 1.5T 1系2系 19~ 1.5T MINICOOPER 13~17 1.5T

45-1055		V 12V W 600 RPM.L RPM.R N.m	17427617610;17429425816	BMW X1 16~ 2.0T BMW X2 18~ 2.0T BMW 1系2系 19~ 2.0T
45-1056		V 12V W 300 RPM.L RPM.R N.m	17422754854	MINI 07~16 1.5T
45-1057		V 12V W 300 RPM.L RPM.R N.m	17422752632	MINI 07~16 1.5T
45-1058		V 12V W 300 RPM.L RPM.R N.m	17101475577;17117541092	MINI 02~08 1.5T
45-1059		V 12V W 600 RPM.L RPM.R N.m	A2205000193	MERCEDES S级 00~12 5.5L
45-1060		V 12V W 600 RPM.L RPM.R N.m	A2205000093	MERCEDES S级 00~12 5.5L
45-1061		V 12V W 850 RPM.L RPM.R N.m	A2205000293	MERCEDES S级 03~05 5.5T MERCEDES SL级 05~11 5.5T
45-1062		V 12V W 600 RPM.L RPM.R N.m	A2215000493;A2215000993;A2215001193;A2215000793;A2219066500;A2215050155	MERCEDES S级 05~13 5.5L

45-1063		V 12V W 600 RPM.L RPM.R N.m	A0999065501	MERCEDES S级W222 13~20 5.5L S级C217 14~20 S级X222 14~20
45-1064		V 12V W 850 RPM.L RPM.R N.m	A0999060612	MERCEDES S级W222 13~20 5.5T S级C217 14~20 S级X222 14~20
45-1065		V 12V W 600 RPM.L RPM.R N.m	A2115001693;A211505055 5;A2115000593;A0999069 000	MERCEDES E级 02~09 2.5L CLS 03~11 2.5L
45-1066		V 12V W 850 RPM.L RPM.R N.m	A2115001893;A211500229 3	MERCEDES E级 05-20 3.5L C级 07-20 3.5L S级 08~13 3.5L
45-1067		V 12V W 850 RPM.L RPM.R N.m	A2129061002;2125000493	MERCEDES C级 07~20 3.0L E级 12~20 3.0L S级 13~16 3.0L
45-1068		V 12V W 600 RPM.L RPM.R N.m	A0999063902;A099906560 1;A0999061301;A0995050 000	MERCEDES E级 16~19 2.0T GLC 17~19 2.0T
45-1069		V 12V W 850 RPM.L RPM.R N.m	A0999063802;A099906140 1	MERCEDES E级 16~19 2.0T GLC 17~19 2.0T
45-1070		V 12V W 600 RPM.L RPM.R N.m	A2035001693;A203500049 3;A2035000293;A2035000 093;A2035050255;A20354 00788	MERCEDES C级 00~07 2.5L CLK350 03~09 3.0L

45-1071		V 12V W 400 RPM.L RPM.R N.m	A2045000193;A2049064702	MERCEDES C级 08~15 1.6T E级 09~16 1.6T GLK 09~15 1.6T
45-1072		V 12V W 600 RPM.L RPM.R N.m	A2045000293;A204906680 2	MERCEDES C级 08~15 1.8T E级 09~16 1.8T GLK 09~15 1.8T
45-1073		V 12V W 400 RPM.L RPM.R N.m	A2045000393;A204906210 2	MERCEDES C级 08~15 1.6T E级 09~16 1.6T GLK 09~15 1.6T
45-1074		V 12V W 600 RPM.L RPM.R N.m	A2045000493;A204906140 3	MERCEDES C级 08~15 1.8T E级 09~16 1.8T GLK 09~15 1.8T
45-1075		V 12V W 600 RPM.L RPM.R N.m	A0999061100;A099906100 0;A0999061200;A0999061 400;0999061800	MERCEDES C级 14~21 2.0T
45-1076		V 12V W 850 RPM.L RPM.R N.m	A1635000293;A163500039 3	MERCEDES M级 98~05 5.5L
45-1077		V 12V W 600 RPM.L RPM.R N.m	A1645000493;A164500019 3;A1645000593	MERCEDES ML350 05~11 3.7L
45-1078		V 12V W 850 RPM.L RPM.R N.m	A1645000093;A164500039 3	MERCEDES ML350 05~11 5.0L

45-1079		V 12V W 600 RPM.L RPM.R N.m	A0999060900;A0999062500;A0999062400;A0999060700	MERCEDES ML350 11~15 3.5L GLE 15~ 3.0T GL 12~20 3.0T
45-1080		V 12V W 850 RPM.L RPM.R N.m	A0999060800;A0999064000;A0999066200;A0999067100	MERCEDES ML350 15~16 3.0T G 13~16 3.0T
45-1081		V 12V W 600 RPM.L RPM.R N.m	A1679061704	MERCEDES GLE350 2.0L GLE450 3.0L 19~
45-1082		V 12V W 850 RPM.L RPM.R N.m	A1679061804	MERCEDES GLE350 2.0L GLE450 3.0L 19~
45-1083		V 12V W 400 RPM.L RPM.R N.m	A1698203542	MERCEDES A级 04~12 1.6L B级 05~11 2.0L
45-1084		V 12V W 400 RPM.L RPM.R N.m	A2465000093	MERCEDES GLA 13~20 1.6T A级 04~12 1.5L B级 05~11 2.0L
45-1085		V 12V W 400 RPM.L RPM.R N.m	A2465000064	MERCEDES GLA 13~20 1.6T A级 04~12 1.5L B级 05~11 2.0L
45-1086		V 12V W 600 RPM.L RPM.R N.m	A2479060100	MERCEDES A CLASS 18~21 B CLASS 18~21 CLA 19~21

45-1087		V 12V W 850 RPM.L RPM.R N.m	A4635000293	MERCEDES G500 99~15 G63 AMG 14~16 G65 AMG 14~16
45-1088		V 12V W 600 RPM.L RPM.R N.m	A4479060412;A447906440 0;A4475000478;A4479060 212 (鼓风机)	MERCEDES 威霆 16~19 2.0T
45-1089		V 12V W 300 RPM.L RPM.R N.m	A0002009323	MERCEDES smart 07~14 1.0T
45-1090		V 12V W 300 RPM.L RPM.R N.m	A4539064300	MERCEDES smart 15~18 1.0T
45-1091			LR045248;LR024292;LR09 4390;LR100364;LR011905 ;LR002660	LAND ROVER 揽胜 05~13 2.0T
45-1092			LR044833;LR100366;LR03 2047	LAND ROVER 极光 14~17 2.0T
45-1093			LR026078	LAND ROVER 神行者2 08~12 3.2L
45-1094		V 12V W 600 RPM.L RPM.R N.m	LR084438(短 线) ;LR036523;LR069901;LR0 81688 (长 线);LR125203;LR146883	LAND ROVER 揽胜行政版 14~ 3.0T

45-1095		V W RPM.L RPM.R N.m	12V 600	LR099669	LAND ROVER 发现神行 18~3.0T
45-1096				LR072552;LR062329;LR082548;LR084439;LR125197;CPLA8C607BF	五代LAND ROVER 发现 16~21 2.0T LAND ROVER揽胜运动 14~21 4.4/3.0T
45-1097				LR072553;LR048175;CPLA8C607AF	LAND ROVER 揽胜 Vogue 17~ 3.0T
45-1098				LR082549;LR125198;LR072554;LR146154;HPLA8C607DB	五代LAND ROVER 发现 16~21 2.0T LAND ROVER揽胜运动 19~3.0T
45-1099				LR012644;LR112860	Radiator Viscous Fan Cooling LAND ROVER 揽胜运动13 14~17
45-1100				LR012645;LR095536;LR112861	Radiator Viscous Fan Cooling 10~13
45-1101				LR025965;LR025965G;PGG500370;PGG500270;PGB500030;PGG500170;PGG500271;5H228600JC	Radiator Viscous Fan Cooling 04~18
45-1102				LR023392;LR013695;LR021990;LR023392GEN	Radiator Viscous Fan Cooling 09~18

45-1103				LR025966;PGG500350	VEMO V48-04-0007 Embrague- ventilador del radiador 05~09
45-1104				LR025234;PGG500360;P GG500260	Land Rover RANGE ROVER SPORT L320 05~09
45-1105				LR022732	New Land Rover 4.4 V8 Diesel Radiator Cooling Fan Coupling全新LAND ROVER4.4 V8柴油散热器冷 却风扇联轴器 02~12
45-1106				LR025955;PGG500380;P GG500280;LR025955GEN	LAND ROVER RANGE ROVER L322 ENGINE DIFFUSER FAN 06~09
45-1107		V W RPM.L RPM.R N.m	12V 600	97010606106	PORSCHE PANAMERA 09~16 3.6L
45-1108		V W RPM.L RPM.R N.m	12V 600	9A712120312	PORSCHE PANAMERA 17~19 2.9T
45-1109		V W RPM.L RPM.R N.m	12V 600	95810606112;9581060613 1 (混 动) ;95810606120;7P0121203 H;7P0121203D;7P012120 3K;7P0121203A	PORSCHE CAYENNE 11~18 3.6L 大众 途锐 11~17 3.6L
45-1110		V W RPM.L RPM.R N.m	12V 600	95B121003A;4H0121207B	PORSCHE MACAN 14~20 3.0T

45-1111		V 12V W 600 RPM.L RPM.R N.m	PAB95945520;PAB95945530;PAB959455B	PORSCHE CAYENNE 18~3.0T 大众 途锐 18~ 3.0T
45-1112		V 12V W 400 RPM.L RPM.R N.m	99162493901;99162493902	PORSCHE 981 12~15 3.8L
45-1113		V 12V W 400 RPM.L RPM.R N.m	9P1959455BY	PORSCHE 982 17~19 3.8T 718 17~19 2.0T
45-1114		V 12V W 300 RPM.L RPM.R N.m	99762412802;99762413202	PORSCHE 997/911 BOXSTER 987 CAYMAN
45-1115			8K0959455G;8K0959455K	AUDI A6 12~16 2.0T A7 14~16 2.0T A4 08~15 2.5L A5 08~15 2.5L Q5 09~15 2.5L Q3 15~17 2.0L
45-1116			8K0959455F;8K0959455M	AUDI A6 12~16 2.0T A7 14~16 2.0T A4 08~15 2.5L A5 08~15 2.5L Q5 09~15 2.5L Q3 15~17 2.0L
45-1119			7L0959455G;7L0959455D	AUDI Q7 07~11 3.0T 保时捷 卡宴 08~11 3.0T VW 途锐 09~11 3.0T
45-1120			7L0959455F;7L0959455C	AUDI Q7 07~11 3.0T PORSCHE CAYENNE 08~11 3.0T VW 途锐 09~11 3.0T

45-1121			4H0959455AB	AUDI A8 10~17 3.0T
45-1122			4H0959455AC	AUDI A8 10~17 3.0T
45-1123		V 12V W 400 RPM.L RPM.R N.m	4H0959455AD	AUDI A7 12~18 2.0T VW 辉昂 16~21 2.0T
45-1124		V 12V W 400 RPM.L RPM.R N.m	4H0959455AE	AUDI A7 12~18 2.0T VW 辉昂 16~21 2.0T
45-1128			5Q0121203CD;5Q0121203AA;5Q0121203AB;5Q0121203BB;5Q0121203BK;5Q0121203CC;5Q0121203CN;5Q0121203CP;5Q0121203CT;5Q0121203DA;5Q0121203EA;5Q0959455AF;5Q0959455AG;5Q0959455BI	GOLF 7 14~17 1.4T
45-1129			5Q0121205D;5Q0121207AM;5Q0121207K;5Q0959455AN	GOLF 7 14~17 1.6L
45-1130		V 12V W 850 RPM.L RPM.R N.m	7E0121205B (850W) ;7E0121205J;7E0121205A (600W)	VW 迈特威
45-1131		V 12V W 600 RPM.L RPM.R N.m	31657360;31657361	VOLVO XC60 18~ 2.0T V90 17~19 2.0T V60 19~ 2.0T S90 17~19 2.0T

45-1132		V 12V W 920 RPM.L RPM.R N.m	31439756;31657772	VOLVO XC90 16~ 3.0T
45-1133			31686808;30668629;32339742;31338823	VOLVO XC60 08~16 2.0T
45-1134			31686806	VOLVO S60 12~18 S80 15~16 V60 15~18 V70 10~ XC60 10~17 XC70 09~16
45-1135			214811275R;214102845R;921001397R;214109155R	RENAULT KANGOO III 21~
45-1136		V 12V W 400 RPM.L RPM.R N.m	992959447B;992959447D	PORSCHE 911 19~ 3.0T
45-1137			95562413500	PORSCHE Cayenne
45-1138			95510625810	PORSCHE Cayenne
45-1139			PAB12120700;PAB12120710;PAB12120720;PAB12120730	PORSCHE Cayenne

45-1140		V 12V W 450 RPM.L RPM.R N.m	5QD121203;5Q0121205A D;5Q0121203CL;5Q01212 03CB;5Q0959455AR;5Q01 21203B;4QD959455B;2Q0 121203H;5Q0121203T;5W A121203H;5Q0959455J;5 Q0121203CE;5Q0121203 BG	AUDI A3 15~20 TT 18~21 VOLKSWAGEN E-GOLF 15~19 GOLF 15~21 GTI 15~20
45-1141			6R0959455D	SEAT CORDOBA 02~09 IBIZA 02~15 TOLEDO 12~15 SKODA FABIA 99~14 RAPID 12~15 ROOMSTER 06~15
45-1142			3QG121207;3QG959455C ;3QF959455BC;3QF12120 7;3QG959455B	VW Teramont/Atlas
45-1143		V 12V W 600 RPM.L RPM.R N.m	4H0121207C;4HO959455 AF;4H0959455AG	AUDI S6 13~18
45-1144		V 12V W 300+400 RPM.L RPM.R N.m	7N0121207;7N0121207E	VW Sharan SEAT Atlas
45-1145		V 12V W 400 RPM.L RPM.R N.m	8W0121207A;8W0959455 A;8W0959455B	AUDI A6 18~23 A7 17~23 Q8 18~23 VW Touareg 19~23
45-1146		V 12V W 400 RPM.L RPM.R N.m	5Q0121205AF;5Q0121205 BB;5Q0121207AF;5Q0121 203DQ;5Q0121203DR;	AUDI A3/Q2 17~ Skoda Karoq 18~ Kodiah 17~ Superb 15~ VW Arteon 17~ Golf 13~
45-1147		V 12V W 400 RPM.L RPM.R N.m	8W0121003H;8W0959455 K;8W0959455L	AUDI RS5/S4/S5


45-1148			180121205;5QD959455G	上汽大众 朗逸 15~
45-1149		V 12V W 600 RPM.L RPM.R N.m	8W0121207C	VW Touareg 18~ AUDI A6/A7 19~ A8/S8 18~ Q7 16~ Q8 19~ RS6/RS7/RSQ8 20~
45-1150		V 12V W 450 RPM.L RPM.R N.m	1C0959455F;1C0121205A; 1C0121207G	VW Beetle 06~10
45-1151		V 12V W 600 RPM.L RPM.R N.m	8K0959455H	AUDI A4 08~12 A4AR 10~16 A4Q 08~12 A5CA 10~11 A5C0 08~11 A5 09~12 RS5 10~16
45-1152		V 12V W 400 RPM.L RPM.R N.m	4S0121203A;4S0121203B; 4S0121203C	AUDI R8 13~15
45-1153		V 12V W 600 RPM.L RPM.R N.m	8E0959455J	AUDI A4 05~08 A4Q 05~08 AA4C 07~09
45-1154		V 12V W 450 RPM.L RPM.R N.m	1ED121203A;1EA121203C ;1EA121203;1ED121205;1 EA121203E;1EA121203B; 1EA121203A;1EA121203D	VW ID4 ID6
45-1155			7N0121207A	VW Sharan 11~16 SEAT:Alhambra 11~15

45-1156		V 12V W 400 RPM.L RPM.R N.m	8W0121003G;8W0959455 J;8W0959455AC;8W0121 207	AUDI A4/A4Q 16~23 A5/Q5 17~23 A6/A6Q/A7 19~23
45-1158		V 12V W 600 RPM.L RPM.R N.m	17427646410	BMW F45 Active Tourer 14~18 F45 Active Tourer LCI 17~19 MINI Countryman F60 15~19
45-1159		V 12V W 400 RPM.L RPM.R N.m	64546988913;6454690507 6	BMW 3er E46
45-1161		V 12V W 600 RPM.L RPM.R N.m	17428666817	BMW 3er G20 Z4 G29
45-1163		V 12V W 500 RPM.L RPM.R N.m	17428591442	BMW 3er G20 Z4 G29
45-1164		V 12V W 600 RPM.L RPM.R N.m	17428472321;1742857814 7	BMW X3 G01/X4 G02
45-1165		V 12V W 600 RPM.L RPM.R N.m	17428742612;1742847226 8	BMW 5er G38 LCI 20~
45-1166		V 12V W 400 RPM.L RPM.R N.m	17428472266	BMW 5er G30/G31 6er G32 GT

45-1167		V 12V W 600 RPM.L RPM.R N.m	17428590051;17428576513	BMW 5er G30/G31 6er G32 GT 7er G11/G12 8er G14/G15?
45-1168			23497174;84448451;84221606;84448452;502083505	CHEVROLET equinox 18~20 GMC Terrain 18~20
45-1169		V 12V W 600 RPM.L RPM.R N.m	84355900	CHEVROLET MALIBU XL19 (上汽通用)
45-1170			23123633;23123634;23123635;23390829	CHEVROLET Silverado 1500/Suburban/Tahoe GMC SIERRA 1500/YUKON/YUKON XL Cadillac ESCALADE 20162017
45-1171			500072908	LANDROVER Discovery Sport 18~Diesel 2.0
45-1172			8240327	LANDROVER Freelander 2.0 01~06
45-1175		V 12V W RPM.L RPM.R N.m	95301358;1341108;1341103;95026332	CHEVROLET 雪佛兰 TRAX 12~13 OPEL 欧宝 MOKKA 12~13
45-1176		V 12V W RPM.L RPM.R N.m	95421534;1341123;94537576;1341127;42607459;42441968	OPEL Vauxhall Mokka MK1 12~19

45-1177		V W RPM.L RPM.R N.m	12V	1253H0;1253H5;1253P9;1253Q0	CITRO?N 雪铁龙 C2 03~05 C3 02~16 C4 CACTUS 14~ DS 09~15
45-1178		V W RPM.L RPM.R N.m	12V	1253A9;1250G1;1250G2;1250G4;1253K1;1253Q8;1400821280;1401312280;9635494380	CITRO?N 雪铁龙 BERLINGO 96~11 C4 04~15 C5 01~04 DS 谛艾仕 DS 4 15~ FIAT 菲亚特 SCUDO 07~11 ULYSSE 02~11
45-1179		V W RPM.L RPM.R N.m	12V	8200765566;6001548527;6001550562	DACIA 达契亚 LOGAN 06~10 SANDERO 08~11 RENAULT 雷诺 LOGAN I 07~15
45-1181		V W RPM.L RPM.R N.m	12V	10385464	MG ZS Excite 17~19
45-1182		V W RPM.L RPM.R N.m	12V	10276698	MG GS Radiator Cooling 16~18
45-1183		V W RPM.L RPM.R N.m	12V	10512973;10701192;10130506	ROEWE I5 I6
45-1184		V W RPM.L RPM.R N.m	12V	42349019;42426778;42333850;DORMAN.621558	CHEVROLET SPARK 16~22
45-1185		V W RPM.L RPM.R N.m	12V	5Q0121205R;5Q0959455A E;5Q0959455L	VW GOLF 7 GTI/R 13~20

45-1186		V 12V W RPM.L RPM.R N.m	2H0121203L	VW AMAROK 10~
45-1188		V 12V W RPM.L RPM.R N.m	19258431;89018691;89018693;89018695;89018696;89018697;VDO.FA70322;DORMAN.620974	BUICK LACROSSE 08~09 CHEVROLET IMPALA 06~13 IMPALA LIMITED 14~16 MONTE CARLO 06~07 PONTIAC GRAND PRIX 05~08
45-2037		V 12V A ≤ W 120 φ 315 RPM W .D	TIY371; 125378	PEUGEOT 405 1.9 86~95; 106 96~
45-2301		V 12V A ≤15 W 170 φ 301 RPM ±2200 W .D	06940225800099	FIAT TOFAS YENİ MODEL KOMPLE MAKÖ: CİTASİZ
45-2306		V 12V A ≤ W 200 φ 301 RPM W .D	1308CF; 1305197080	CITROEN Jumper 94~02 FIAT Ducato 94~02 PEUGEOT Boxea 94~02
45-2306A		V 12V A ≤ W 200 φ 301 RPM W .D	1308CF; 1305197080	CITROEN Jumper 94~02 FIAT Ducato 94~02 PEUGEOT Boxea 94~02
45-2306-BM		V 12V A ≤ W 200 φ 301 RPM W .D	125339; 1253C1; 1253F1; 1325269080	CITROEN Jumper 94~02 FIAT Ducato 94~02 PEUGEOT Boxea 94~02
45-2307		V 12V A ≤9.5 W 170W φ 302 RPM ±2500 W .D	85013265;7857126;06940229500099	TOFAS SLX YM(KABLOLU) FIAT SLX N.M. FAN-WITH CABLE

45-2308		V 12V A ≤ W φ 302 RPM W .D	85055159;0694022940009 9	TOFAS SLX YM(SOKETLi) FIAT Slx N.M. FAN-WITH SOCKET
45-2321		V 12V W RPM.L RPM.R N.m	9806313580;9836638080;1 7308075	CITRO?N (雪铁龙) BERLINGO 08~16 DS (谛艾仕) DS 7 Crossback 17~18 PEUGEOT (标致) 3008 SUV 16~ 308 SW II 14~18
45-2347- BM		V 12V A ≤ W φ RPM W .D	191959455T; 1H0959455; 1H0959455P; 3A0959455J;	VW Cabrio 95~98; GolfIII 93~99; Jetta 93~98; Passat 88~97
45-2355A		V 12V A ≤ W 200 φ 405 RPM W .D	51820792;55700342;55703 902;069422238010	FIAT Grande Punto 05~
45-2368A		V 12V A ≤ W φ 385 RPM ±2000 W .D	214753416R; 214814116R; 214816703R; 214816812R; 214818009R	DACIA Dokker 12~ Duster 10~ Lodgy 12~ logan 12~ Sander 12~; NISSAN Micra 16~ RENAULT
45-2500A- BM		V 12V A ≤ W φ 301 RPM W .D	1341219; 22061171;	OPEL Combo 94~01; Corsa B 93~00
45-2500- BM		V 12V A ≤ W 140 φ 280 RPM W .D	1341244; 22061461; 93230490; 9130451171	CHEVROLET Chevy 96~12; Chevy Pickup 99~03; Corsa 2002 OPEL Astra F 91~01; Corsa A 88~93; Corsa B 93~00;
45-2507		V 12V A ≤ W 200 φ 308 RPM W .D	5490624; 90510209; 90469600; 92099808	BUICK Sail(别克赛欧)

45-2510-BM		V 12V A ≤ W 306 φ 306 RPM W .D	7519723; 9117716; 93294288; 0130303244; 9130451046	FIAT Uno; Duna; Fiorino GM OPEL Corsa 96~03 Tigra 98~
45-2512		V 12V A ≤ W 270(L) W 200(R) φ 277 W .D	46524624; 46849148; 51738691; 51753624	FIAT Punto 99~; Punto Van 00~09
45-2521		V 12V A ≤ W 270(L) W 200(R) φ 277 W .D	46821264; 51718489; 51753828	FIAT Doblo 01~; Doblo Carqo 01~05
45-2521-1		V 12V A ≤ W 270 φ 277 RPM W .D	46821266; 51718487; 51738799	FIAT Doblo 01~; Doblo Carqo 01~05
45-2521A		V 12V A ≤ W 270(L) W 200(R) φ 277 W .D	51755591	FIAT Doblo 05~; Doblo Carqo 05~10
45-2521A-1		V 12V A ≤ W 270 φ 277 RPM W .D	51755589	FIAT Doblo 05~; Doblo Carqo 05~10
45-2521-BML		V 12V A ≤ W 270 φ 277 RPM W .D		FIAT Doblo 01~; Doblo Carqo 01~05
45-2521-BMR		V 12V A ≤ W 200 φ 277 RPM W .D		FIAT Doblo 01~; Doblo Carqo 01~05

45-2522A-BM		V 12V A ≤16 W 210 φ 320 RPM ±2700 W .D	46449102; 46449130; 46764671; 46782466; 46782468; 46815898; 46815901; 46832896;	FIAT Fiorino 01~07; Idea 01~07 Palio 01~07; Siena 01~07; Strada 01~07 Uno 01~07
45-2523		V 12V A ≤ W 250 φ 389 RPM W .D	1314442; 24445175; 621902	GM CHEVROLET Corsa 02~08; Tornado 04~12 OPEL Combo 01~; Corsa C 00~09; Tigra 04~
45-2523A		V 12V A ≤ W 250 φ 389 RPM W .D	1314443; 24445183; 696382	OPEL Combo 01~; Corsa C 00~09; Tigra 04~
45-2523A-BM		V 12V A ≤ W 250 φ 389 RPM W .D	1341337; 24402524;	OPEL Combo 01~; Corsa C 00~09; Tigra 04~
45-2523B		V 12V A ≤ W 250 φ 389 RPM W .D	1314445; 24421234; 696369	OPEL Combo 04~; Corsa C 00~09; Tigra 04~
45-2523B-BM		V 12V A ≤ W 250 φ 389 RPM W .D	1341354; 24445184;	OPEL Combo 04~; Corsa C 00~09; Tigra 04~
45-2523-BM		V 12V A ≤ W 250 φ 389 RPM W .D	1341331;1341351;46779423;	CHEVROLET Corsa 02~08; Tornado 04~12 OPEL Combo 01~; Corsa C 00~09; Tigra 04~
45-2524		V 12V A ≤10 W 200 φ 385 RPM ±2000 W .D	1314447;	OPEL Combo 1.7 01~; Corsa C 1.7 00~09

45-2524A		V 12V A ≤ W 200 φ 385 RPM W .D	蔡敏专用	OPEL Astra H 1.3 05~; Corsa C 1.3,1.7 03~09
45-2524B		V 12V A ≤ W 200 φ 385 RPM W .D	1314313; 1314473; 1314558;	OPEL Astra H 1.3 05~; Corsa C 1.3,1.7 03~09
45-2524B-BM		V 12V A ≤ W 200 φ 385 RPM W .D	1341388 13208239	OPEL Combo 1.7 01~; Corsa C 1.7 00~09
45-2524-BM		V 12V A ≤ W 200 φ 385 RPM W .D	1341334; 9129965	OPEL Combo 1.7 01~; Corsa C 1.7 00~09
45-2525		V 12V A ≤11 W 280 φ 389 RPM ±2200 W .D	1314453;1314542;1314543 ;24431825;24456281;9057 0736;90570739;90572581; 90572582;93277989;93277 994;93315725;93937994	OPEL Astra G 98~09; Zafira A 99~05
45-2525A		V 12V A ≤ W 280 φ 389 RPM W .D	1314539; 1314552;	OPEL Astra G 98~09; Zafira A 99~05
45-2525A-BM		V 12V A ≤ W 280 φ 389 RPM W .D	1341299;1341300;1341344 ;1341346;24431828;90570 740;93335423;0130303246 ;F006KM0601;F006KM060 4;696280	OPEL Astra G 98~05; Zafira A 99~05
45-2525B		V 12V A ≤11 W 280 φ 389 RPM ±2200 W .D	6341178; 13207167	OPEL Astra H 06~14

45-2527		V 12V A ≤8 W 170 φ 311 RPM ±2200 W .D	1341155;	OPEL Vectra B 95~03
45-2527-BM		V 12V A ≤ W 200 φ 311 RPM W .D	1341155; 1341258; 1341262; 52464704; 52464739	OPEL Vectra B 95~03
45-2531		V 12V A ≤15 W 200 φ 315 RPM ±2600 W .D	13114008; 24445191; 24445192; 6341151; 6341164;	OPEL Combo 01~; Corsa C 00~09
45-2531-BM		V 12V A ≤ W 200 φ 315 RPM W .D	1341332; 9158008	OPEL Combo 01~; Corsa C 00~09
45-2533		V 12V A ≤11 W 200 φ 282 RPM ±2600 W .D	701959455A; 701959455AC; 701959455AD; 701959455AE; 701959455AM; 701959455C; 701959455D; 701959455E;	VW TRANSPORTER IV 90~03
45-2533A		V 12V A ≤12 W 200 φ 282 RPM ±2500 W .D	4A0959455C; 893959455F; 893959455G; 4A0959455A; 696036	AUDI 100 92~94; 80 90~96; A6 94~97; COUPE 91~96
45-2535		V 12V A ≤ W 250 φ 389 RPM W .D	46737733;46759753;46786099;51738798;069422025010	FIAT Doblo 01~
45-2535A		V 12V A ≤10 W 140 φ 383 RPM ±2100 W .D	51768022; 51774951	FIAT Doblo 05~

45-2535B		V 12V A ≤ W 300 φ 383 RPM W .D	51758856	FIAT Doblo 05~
45-2537		V 12V A ≤ W 70 φ 293 RPM W .D	1341200;1341360;1845042; 1845043;90504897;90511 262;9128850;0130701238	BUICK Sail(别克赛欧) OPEL Astra F 91~01; Calibra A 90~97; Combo 94~01; Corsa B 93~00; Tigra 94~00; Vectra A 88~95
45-2538		V 12V A ≤25 W 280 φ 292 RPM ±3300 W .D	13114009; 1341195; 1341338; 1850087; 24426581; 6341163;	OPEL Combo 01~; Corsa C 00~09; Tigra 04~
45-2538A		V 12V A ≤25 W 280 φ 292 RPM ±3300 W .D	1341196;	OPEL Combo 01~; Corsa C 03~09; Tigra 04~
45-2538- BM		V 12V A ≤ W 260 φ 292 RPM W .D	09129966; 1341338	OPEL Combo 01~; Corsa C 00~09; Tigra 04~
45-2539		V 12V A ≤13.5 W 120 φ 348 RPM ±2300 W .D	1J0959455; 1J0959455D; 1J0959455E; 1J0959455F; 6E0959455A; 6H0959455B; 6N0959455F; 6N0959455G;	AUDI A3 96~03; TT 98~06 SEAT Arosa 98~04; IbizaIV 02~09; Leon 99~06; Toledo II 99~06
45-2539A		V 12V A ≤ W 348 φ 348 RPM W .D	6X0959455; 6X0959455C; 6N0959455L	SEAT Arosa 97~04; Cordoba 02~09 SKODA Fabia 99~08 VW Bora 98~05; GolfIV 98~06; Lupo 98~05;
45-2540A		V 12V A ≤ W 220 φ 280 RPM W .D	4B0959455; 4B3959455A; 8D0959455; 8D0959455C; 8D0959455D; 8D0959455Q; 97VW15150DA; 620800	AUDI A4 94~01; A6 94~05; A8 94~02 FORD Galaxy 95~06 SEAT Alhambra 96~10 VW(大众) Passat 95~05;

45-2540B		V 12V A ≤ W 220 φ 280 RPM W .D	8D0959455J; 8D0959455N; 8D0959455P; 8D0959455R	AUDI A4 94~01; A6 97~05; A8 94~02 SKODA Superb 01~08 VW(大众) Passat 00~05
45-2541		V 12V A ≤15 W 130 φ 391 RPM ±1600 W .D	1341159; 52464741	OPEL Vectra B 95~03
45-2541A		V 12V A ≤15 W 130 φ 391 RPM ±1600 W .D	52464380; 0130303872; F006SA0305; 696009R	CHEVROLET OPEL Vectra 97~05
45-2541A-BM		V 12V A ≤ W 250 φ 391 RPM W .D	52478169;	CHEVROLET OPEL Vectra 97~05
45-2541-BM		V 12V A ≤ W 250 φ 391 RPM W .D	1341159; 52464705	OPEL Vectra B 95~03
45-2542		V 12V A ≤16.5 W 190 φ 390 RPM ±2300 W .D	1314963; 24424392; 0130303298; 0986338039	OPEL Astra G 00~09
45-2542A		V 12V A ≤16.5 W 190 φ 391 RPM ±2300 W .D	1314556; 6341171	OPEL Astra H 04~; Zafira B 05~
45-2542A-BM		V 12V A ≤ W 250 φ 391 RPM W .D	13147274; 13205947; 1341386	OPEL Astra H 04~; Zafira B 05~

45-2542-BM		V 12V A ≤ W 250 φ 391 RPM W .D	1341372; 13128687; 6341168;	OPEL Astra G 00~09
45-2543		V 12V A ≤22 W 200 φ 311 RPM ±2900 W .D	1341176;	OPEL Astra G 98~09; Zafira A 99~05
45-2543B-BM		V 12V A ≤16.5 W 320 φ 311 RPM ±2800 W .D	1341178;1341182;1341297; 1341324;1341347;1341348; 1341377;1341378; 1314727924431829;24431830; 09129011;09132916;90570745; 6341172;0130303302; 0130303275;	OPEL Astra G 98~05; Zafira A 99~05
45-2543C		V 12V A ≤ W 160 φ 311 RPM W .D	1341321; 1341345 24431281; 24431827; 90570741; 90570744; 9133342; 9133061;	OPEL Astra G 98~05; Zafira A 99~05
45-2544		V 12V A ≤20.5 W 300 φ 311 RPM ±3000 W .D	13126384; 13130010; 13132559; 1314554; 1314555	OPEL Astra H 04~; Zafira B 05~
45-2545		V 12V A ≤ W 100 φ 302 RPM W .D	7650190;7650192;7608426; 46461607;46517602;46524328; 46749590;069402249	FIAT Croma 86~96; Tempra 90~96; Tipo 87~95; Uno 85~93 LANCIA Dedra 89~99; Delta II 93~99
45-2546		V 12V A ≤ W 200 φ 311 RPM W .D	1314559	OPEL Astra H 04~
45-2555A		V 12V A ≤10 W 140 φ 382 RPM ±2100 W .D	6001546844;6001550769;7701048284; 8200702959	DACIA Logan 04~12 Sandero 08~12 RENAULT Clio I 90~98; Clio II 99~05; Logan I 04~07 Sandero 07~10

45-2555A-BM		V 12V A ≤ W 250 φ 382 RPM W .D	7701059544; 9212000Q0GHQ	NISSAN Platina 02~10 RENAULT Clio 02~10
45-2557		V 12V A ≤18.5 W 150 φ 383 RPM ±2100 W .D	6341153; 6341185; 24410992	OPEL Signum 03~05; Vectra C 02~ SAAB 9-3 02~
45-2557-BM		V 12V A ≤ W 230 φ 383 RPM W .D	1341362; 24410988;	OPEL Signum 03~05; Vectra C 02~ SAAB 9-3 02~
45-2559		V 12V A ≤ W φ 420(L) φ 292(R) W .D	7H0121201CN; 7H0121201BQ; 7H0121201CJ; 7H0959455H	VW Caravelle 05~; Multivan T5 03~09; Shuttle 07~ Transporter T5 03~09;
45-2559-BML		V 12V A ≤24.5 W 330 φ 420 RPM ±2900 W .D	7H0959455A; 0130303290	VW Caravelle 05~; Multivan T5 03~09; Shuttle 07~ Transporter T5 03~09;
45-2559-BMR		V 12V A ≤22.5 W 210 φ 292 RPM ±2900 W .D	7H0959455D; 0130303306	VW Caravelle 05~; Multivan T5 03~09; Shuttle 07~ Transporter T5 03~09;
45-2563		V 12V A ≤12 W 220 φ 335 RPM ±2700 W .D	46826688; 46848916	FIAT Palio 01~
45-2563A		V 12V A ≤12 W 220 φ 335 RPM ±2700 W .D		FIAT ZOTYE(众泰) Z200

45-2564-BM		V 12V A ≤17 W 200 φ 385 RPM ±2100 W .D	46799284; 51797700	FIAT Doblo 01~; Palio 01~
45-2565		V 12V A ≤ W 270 φ 385 RPM W .D	125394; 1253P3; 1253Q9; 1253R3; 51780703	CITROEN Nemo 08~ FIAT Fiorino 07~; Qubo 08~ PEUGEOT Bipper 08~
45-2566		V 12V A ≤ W 160 φ 385 RPM W .D	1253P2; 1253P5; 51780660	CITROEN Nemo 08~ FIAT Fiorino 07~; Qubo 08~ PEUGEOT Bipper 08~
45-2567		V 12V A ≤ W φ 385 RPM W .D	1341135; 13490890; 51797135; 51831825; 51878036; 55701410	FIAT Grande Punto 05~11 OPEL Corsa D 06~14
45-2567A-BM		V 12V A ≤ W φ RPM W .D	46816876;46816877;46816879;9158007	FIAT Palio 02~; Siena 02~; Strada 02~ GM CHEVROLET Corsa 00~04
45-2567-BM		V 12V A ≤ W φ 385 RPM W .D	1341390; 1341394; 1341395; 1341397; 1341682; 13263552; 55702179; 55704031	FIAT Punto 05~ OPEL Corsa D 06~
45-2568		V 12V A ≤ W 250 φ RPM W .D	125391; 125392; 1253C7; 696070; 696074	PEUGEOT 206 98~
45-2568A		V 12V A ≤ W 250 φ 393 RPM W .D	1253C9; 9643386780; 696071; 696073	PEUGEOT 206 98~

45-2568B		V 12V A ≤ W 250 φ 393 RPM W .D	1253C5; 696069	PEUGEOT 206 98~
45-2569		V A ≤ W φ 335 RPM W .D	1250G6; 1250G7; 1253P7; 1253Q7; 1401312180; 1489767080; 1494742080	CITROEN C8 02~; Jumpy 07~ FIAT Scudo 00~06; Ulysse 99~11 LANCIA Phedra 02~10 PEUGEOT
45-2571		V 12V A ≤ W 250 φ 382 RPM W .D	7701051495;7701054967;7701070315;7701071862	RENAULT Megane II 02~; Scenic II 03~
45-2571-BM		V 12V A ≤ W 250 φ 382 RPM W .D	6025371190;6025313368;6025371390;7701044183;7701044185;7701045816;7701054966;7701057254;7701070217;214814567RBC	RENAULT Clio II 98~09; Kangoo 97~; Megane 96~99; Megane I 99~03; Megane II 02~; Scenic I 99~03; Scenic II 03~
45-2574		V 12V A ≤ W φ RPM W .D	1250E9;125364;125474;1308R9;069422286010;MTC286AX	CITROEN Berlingo 96~; Xsara 97~05 PEUGEOT 306 98~02; 406 95~04; Partner 96~
45-2575		V 12V A ≤19 W φ 385 RPM ±2400 W .D	1250H9; 1342690080; 1347697080; 1358010080; 1358012080; 1358062080; 1362916080; 1635087980;1635088080;1	FIAT öVRIGT; DUCATO 07~ PEUGEOT Boxer 08~
45-2575-BM		V 12V A ≤ W φ 385 RPM W .D	878419R	FIAT öVRIGT; DUCATO 07~ PEUGEOT Boxer 08~
45-2578		V 12V A ≤ W φ RPM W .D	46799410; 51848272	FIAT Panda 00~

45-2578A-BM		V 12V A ≤ W φ 335 RPM W .D	51822633; 46816880; 24445171; 24445190	FIAT Idea 10~11; Palio 01~; Strada 20~; Uno 01~ Siena EL 13~ GM Corsa 00~08
45-2578-BM		V 12V A ≤ W φ RPM W .D		FIAT Panda 00~
45-2579		V 12V A ≤ W 30±5 φ 300 RPM 2200 W .D	7700785115;7700828623;7700828624;7701041302	RENAULT R19 88~92; R21 86~94; Clio I 90~98; Rapid 85~98
45-2579A-BM		V 12V A ≤ W φ RPM W .D	7701045216; 7701046627; 7701050678; 7701051484; 7701051492; 7701051494; 7701051490; 7701051499;	DACIA Logan 04~ NISSAN Kubistar 03~; Platina 02~10 RENAULT Clio II 98~10; Kangoo 97~
45-2579-BM		V 12V A ≤ W φ RPM W .D		RENAULT R19 88~92; R21 86~94; Clio I 90~98; Rapid 85~98
45-2590		V 12V A ≤ W 200 φ 405 RPM W .D	51965900; 51966714	FIAT 500X 2014~ JEEP Renegade 2014~
45-2591		V 12V A ≤17 W 200 φ RPM ±2500 W .D	1253H6; 1253P8; 9675280980; 9653804080	CITROEN C3 06~10 PEUGEOT 207 06~11
45-2592		V 12V A ≤17 W 200 φ RPM ±2500 W .D	21481AY610; 7701059785; 7701059786; 7701063956	NISSAN Micra 03~10; Note 06~12 RENAULT Clio 05~10; Modus 04~10; Twingo 07~10

45-2593		V 12V A ≤ W 250 φ 393 RPM W .D	1250F8; 125397; 1253C8; 1253E4; 1253E6; 1253C2; 542959455B; 696137	CITROEN Berlingo 96~; Jumpy 99~97; Xsara Picasso 99~ PEUGEOT 406 99~04; 607 00~; 807 02~;
45-2593B		V 12V A ≤ W 250 φ 393 RPM W .D	1253A6; 1253F0; 1253F8; 1253G7; 1253K2; 1253K4; 1253K7; 696091	CITROEN C4 04~13; Jumpy 07~ Xsara Picasso 07~13 PEUGEOT 3008 09~; 5008 09~; 307 00~13;
45-2594		V 12V A ≤ W φ RPM W .D	9802840680;1253T1;1107 2803	Peugeot 508 11~15 CITROEN C5 14~17 C6 16~
45-2595		V 12V A ≤ W 600 φ RPM W .D	8W0959455F;8W0959455 C;8W0121003B;L80D1210 03;8W0959455T;8W09594 55M;8W0121207B	AUDI A4 17~21 A5 18~21 A6 19~23 A7 19~21 E-TRON 19~21 S4 18~21 S5 18~21
45-2618A		V 12V A ≤15 W 220 φ 440 RPM ±2000 D.R W .D	214814354R; 214819674R; 214813939R; 214818467R; 214819007R; 696881; 696882	RENAULT Grand ScenicIV 16~17 Megane 15~18 ScenicIV 16~18 Talisman 16~
45-2619		V 12V A ≤ W φ RPM W .D	214814297R; 214813179R	RENAULT Kwid 18~
45-2620		V 12V A ≤13.5 W 50 φ 395 RPM ±1600 W .D	6Q0959455D; 696375	SEAT Cordoba 02~09; ibizaIV 02~09; ibiza V 08~ KODA Fabia 03~08; Roomster 06~10 VW
45-2620A		V 12V A ≤ W φ 395 RPM W .D	6Q0959455N	SEAT Cordoba 02~09; Ibiza 02~09 SKODA Fabia 03~08; Roomster 06~10 VW Fox 05~;


45-2621-BMR		V 12V A ≤ W φ 385 RPM ±2400 W .D	4F0121003ACS1; 4F0959455D; 0130303312	AUDI A6 04~11
45-2622-BM		V 12V A ≤ W 200 φ 311 RPM W .D	6K0959455L	SEAT Cordoba 99~02; Ibiza 99~02; Inca 96~03 VW Caddy 96~03; Polo Classic 00~05
45-2625-BM		V 12V A ≤ W 200 φ 311 RPM W .D	1341301; 1341313; 52479024; 52479136; 90573554	OPEL Astra G CC 99~05; Vectra B 97~02; Vectra B CC 97~032
45-2627-BM		V 12V A ≤ W φ 382 RPM ±2100 W .D	46743390; 46743391; 51702461	ALFA ROMEO 147 01~07
45-2628			8K0121207A;8K0121003P	AUDI A4 07~15; A5 07~17; Q5 08~17;
45-2628-BML		V 12V A ≤19 W 180 φ 380 RPM ±2100 W .D	8K0959455G;8K0959455K; 8K0959455T	AUDI(奥迪) A4 07~16; A5 08~17; Q5 09~17; S4 13~15; S5 10~16
45-2628-BMR		V 12V A ≤12 W 180 φ 335 RPM ±2500 W .D	8K0959455F;8K0959455;8 K0959455R;8K0959455C	AUDI(奥迪) A4 07~16; A5 08~17; Q5 09~17; S4 13~15; S5 10~16
45-2636-BM		V 12V A ≤ W φ 345 RPM ±2600 W .D	701959455AB; 7D0959455; 7D0959455A; 7D0959455E; 7D0959455F; 7D0959455H; 7D0959455J; 7D0959455M	VW Caravelle 90~03; Eurovan 90~03

45-2638		V 12 A ≤ W 200 φ 405 RPM W .D	1341398; 1341421; 55702058; 55703929	OPEL Corsa D 06~14
45-2642		V 12V W RPM.L RPM.R N.m	214754524R;921205226R; 921209221R	RENAULT (雷诺) MASTER III 10~16
45-2643		V 12V A ≤ W φ RPM W .D	253803R170;253803R470; 253803Q170;620795	HYUNDAI SONATA 11~13 KIA OPTIMA 11~14
45-2662		V 12 A ≤ W φ 390 RPM W .D	6Q0959455AE;6R0121207 ;6Q0959455AD;6R095945 5C;DORMAN.621938;6R0 121207Q	AUDI A1 10~ SEAT IBIZA 09~17 TOLEDO 13~17 VW Polo 09~
45-2706		V 12V A ≤18.5 W 220 φ 370 RPM ±2600 W .D	93382154;	GM CHEVROLET OPEL Corsa 06~09; Tornado 06~12
45-2706-BM		V 12V A ≤18.5 W 220 φ 370 RPM ±2600 W .D	93343243; 93382155; F006D10017	GM CHEVROLET OPEL Corsa 06~09; Tornado 06~12
45-2707		V 12V A ≤ W φ 370 RPM W .D	93382149; 93378665; F006D10018	GM CHEVROLET OPEL Corsa 06~09; Tornado 06~12
45-2707A-BM		V 12V A ≤ W φ 370 RPM W .D	93382150; F006BE0096	GM CHEVROLET OPEL Corsa 06~09; Tornado 06~12

45-2800		V 12V A ≤ 16 W 170 ϕ 405 RPM ± 2200 W .D	51787116; 51887780; 1560758; 9S518C607BA	FIAT 500 07~ FORD KA 08~
45-2800-BM		V 12V A ≤ 16 W 170 ϕ 405 RPM ± 2200 W .D		FIAT 500 07~ FORD KA 08~
45-2803		V 12V A $\leq$ W 290 ϕ 335 RPM 2900 W .D	24467444; 0130303304	OPEL Astra H 05~; Zafira B 05~
45-2803-FA		V 12V A $\leq$ W 290 ϕ 335 RPM ± 2900 W .D	1314212; 1314553;	OPEL Astra H 05~; Corsa D 06~; Zafira B 05~
45-2804-BM		V 12V A $\leq$ W 200 ϕ 311 RPM W .D	7M0121209B	FORD Galaxy 96~00
45-2805		V 12V A ≤ 14 W 160 ϕ 363 RPM ± 2400 W .D	1341271; 1341242; 90512980; 90442046	OPEL Astra F 91~98; Calibra A 90~97; Vectra A 88~95
45-2807		V 12V A $\leq$ W 80 ϕ 292 RPM W .D	1J0959455K; 1J0959455L; 330959455A	AUDI A3 98~05 SKODA Fabia 99~08 VW(大众桑塔纳) Bora 98~05; GolfIV 97~06; Passat00~05
45-2807A		V 12V A ≤ 6.5 W 90 ϕ 292 RPM ± 1800 W .D	1C0959455C; 1J0959455M; 6Q0959455L	AUDI A3 98~03 SEAT Cordoba 02~09; IbizaIV 02~09; Leon 99~06; Toledo II 99~06 SKODA Fabia 99~08;

45-2807B		V 12V A W φ RPM W .D	6QD959455B; 6Q0959455J	SEAT Cordoba 02~09; IbizaIV 02~09; SKODA Fabia 99~08; VW FOX 05~09 Polo 02~12
45-2809B		V 12V A ≤ W 200 φ 300 RPM W .D	6K0959455B	SEAT Cordoba 96~02; IbizaIII 99~02; Inca 95~03; Toledo I 91~99 VW Caddy II 95~04; Derby 99~05;
45-2811		V 12V A ≤18 W φ 320 RPM ±3200 W .D	377959455; 377959455H; 547959455E; 9130451086; 9130451122; 9130451165	FORD Escort 92~96; Verona 92~96 VW GOL 94~10; Parati 95~12; Saveiro 97~09
45-2817		V 12V A ≤ W φ 380 RPM W .D	4F0959455; 8E0959455; 8E0959455A; 8E0959455K; 8E0959455L; 696017; 698609; 698610;	AUDI(奥迪) A4 00~09; A6 01~11
45-2818		V 12V A ≤13.5 W φ 280 RPM ±2800 W .D	4F0959455A; 8E0959455B; 8E0959455C; 8E0959455M; 8E0959455N; 696018; 698611; 698612	AUDI(奥迪) A4 00~09; A6 01~11
45-2822		V 12V A ≤ W φ 280 RPM W .D	BAU100209; 9130081058	FIAT Uno Mille
45-2826		V 12V A ≤ W φ 398 RPM W .D	6R0959455C; 6Q0959455AD; 6Q0959455AE	SEAT Cordoba 02~09; IbizaIV 02~09; Ibiza V 08~ SKODA Fabia 99~ VW(大众桑塔纳,捷达,波罗) Fox 05~; Polo 01~
45-2826B		V 12V A ≤19.5 W 210 φ 398 RPM ±2400 W .D	5U0121253E	VW Fox 03~14; Gol 08~16; Golf 08~14; Polo 12~15; Saveiro 10~13; Spacefox 06~14; Voyage 08~09~16

45-2826B-BM		V 12V A ≤19.5 W 210 φ 398 RPM ±2400 W .D	5U0959455B; 5U0959455C	VW Fox 03~14; Gol 08~16; Golf 08~14; Polo 12~15; Saveiro 10~13; Spacefox 06~14; Voyage 08~09~16
45-2837		V 12V A ≤12 W 170 φ 315 RPM ±2300 W .D	125333; 125352; 125366; 125374; 125381; 125467; 125470; 125490;	CITROEN Xsara 97~05; XM 89~00; ZX 91~97 PEUGEOT 306 93~01; 405 I 87~92; 405 II 92~96;
45-2901		V 12V A ≤ W 120 φ 282 RPM W .D	51718772	FIAT Albea 1.3; Strada 05~
45-2901-BM		V 12V A ≤ W 120 φ 282 RPM W .D		FIAT Albea; Strada 05~
45-2902		V A ≤ W φ RPM W .D	17117801423; 17117786009; 17117790896; 7786009; 7790896; 7801423	BMW 3-Series 00~06
45-2906		V 12V A ≤ W 400 φ RPM W .D	17427617609;	BMW(宝马) X1 16~21 X2 18~19 MINI COOPER 14~19 COOPER CLUBMAN 16~21 COOPER COUNTRYMAN
45-2906A		V 12V A ≤ W 600 φ RPM W .D	17427617610;	BMW(宝马) X1 16~21 X2 18~19 MINI COOPER 14~19 COOPER CLUBMAN 16~21 COOPER COUNTRYMAN
45-2906B		V 12V A ≤ W 850 φ RPM W .D	17427617611;	BMW(宝马) X1 16~21 X2 18~19 MINI COOPER 14~19 COOPER CLUBMAN 16~21 COOPER COUNTRYMAN

45-2911		V 12V A ≤ W φ RPM W .D	17427562080;17425A3F106;17427522055	BMW(宝马) 128I 08~13 325I 06~ 325XI 06~ 328I 07~13 328XI 07~08 330I 06~ 330XI 06~
45-2922		V 12V A ≤ W φ RPM W .D	17427563259;17427523258	BMW(宝马)X1 09~16
45-2923		V 12V W RPM.L RPM.R N.m	17117590699; 17427523259; 621195	BMW (宝马) 1 系 03~11 3 系 04~12
45-3973		V 12V A ≤ W φ 405 RPM W .D Pull	51833973;55213077;069422472010;MTC472AX	FIAT Doblo 10~
45-3973A		V 12V A ≤ W φ 405 RPM W .D	51821155;52052605;069422454010;MTC454AX	FIAT Doblo 01~
45-3973-BM		V 12V A ≤ W φ 405 RPM W .D Pull	1341399; 55702236	OPEL Corsa D 06~17; Corsa MKIII 06~14; Corsavan MKIII 06~12
45-5226		V 12V A ≤ W φ 405 RPM W .D	51785226	FIAT Linea 07~
47-1002		V 12V A ≤ W φL φR W .D	4677695AB;4677695AA;4677695AC;VDO.FA70318	CHRYSLER TOWN & COUNTRY 05~07 DODGE CARAVAN 05~07 GRAND CARAVAN 05~07

47-1003		V 12V A ≤ W φL φR W .D	5072330AB;5137713AA;5137714AA;68050294AC;620039XD;FA72137	CHRYSLER 300 05~14 DODGE CHALLENGER 08~21 CHARGER 06~21 MAGNUM 05~08
47-1004		V 12V A ≤ W φL φR W .D	5159099AA;5191253AA;68002051AA;68004051AA;621029;FA70557	CHRYSLER 200 11~14 SEBRING 07~10 DODGE AVENGER 08~14 CALIBER 07~12 JEEP COMPASS 07~17
47-1005		V 12V A ≤ W φ RPM W .D	5174136AA;55037692AA;55037692AB;55037692AC;620475	JEEP LIBERTY 04~05
47-1006		V 12V A ≤ W φ RPM W .D	68050129AA;621526XD	CHRYSLER 300 09~21 DODGE CHALLENGER 09~21 CHARGER 09~21
47-1007		V 12V A ≤ W φ RPM W .D	52002591;52005748;52005748AB;52079444AB;83503411; 83503412; 83503582; 83503583;VDO.FA70115	JEEP CHEROKEE 87~01 COMANCHE 87~92 WAGONEER 87~90
47-1008		V 12V A ≤ W φ RPM W .D	55056642AC;55056642AD;68039593AA;68039594AA;68039595AA;VDO.FA70437	JEEP WRANGLER 07~11
47-1009		V 12V A ≤ W φ RPM W .D	BR3Z8C607A;DR3Z8C607B;DR3Z8C607D;FS.75646	FORD MUSTANG 05~14
47-1010		V 12V A ≤ W φ RPM W .D	5005144AK;5005144AN;5058674AA;5058674ACI;5058674AD;FA70554;621028	CHRYSLER TOWN & COUNTRY 08~16 DODGE GRAND CARAVAN 08~20 RAM C/V 12~15 VW ROUTAN 09~14

47-1011		V 12V A ≤ W φ RPM W .D	8S4Z8C607A;FS.76200	FORD FOCUS 08~11
47-1012		V 12V A ≤ W φL φR W .D	AL3Z8C607A;AL3Z8C607B;BL3Z8C607A;BL3Z8C607B;FS.76158	FORD EXPEDITION 10~17 F-150 10~14 LINCOLN NAVIGATOR 10~17
47-1013		V 12V A ≤ W φL φR W .D	LF8B15025C;LF8B15025H;R2AH15025B;VDO.FA70824	MAZDA 3 10~13
47-1014		V 12V A ≤ W φL φR W .D	3F2Z8C607AE;4F2Z8C607AB;5F2Z8C607AA;5F2Z8C607AB;5F2Z8C607CA;5F2Z8C607CB;FS.75629	FORD FREESTAR 04~07 MERCURY MONTEREY 04~07
47-1015		V 12V A ≤ W φ RPM W .D	7E5Z8C607A	FORD FUSION 06~-2009 LINCOLN ZEPHYR 06~ MERCURY MILAN 06~09
47-1016		V 12V W RPM.L RPM.R N.m	EJ7Z8C607G;EJ7Z8C607A;EJ7Z8C607C;EJ7Z8C607E	FORD ESCAPE 13~19 LINCOLN MKC 15~19
47-1017		V 12V W 400 RPM.L RPM.R N.m	T2H20465;T2H45980	JAGUAR XE 17~ 2.0T
47-1018		V 12V W 600 RPM.L RPM.R N.m	T2H20467	JAGUAR XE 17~ 2.0T

47-1019		V 12V W 400 RPM.L RPM.R N.m	C2D24142;C2D21511;C2D42525;C2D52869	JAGUAR XF 10~15 2.OT XJ 10~15 2.OT XJR 14~15 2.OT XK 10~15 2.OT XKR 10~15 2.OT
47-1020		V 12V W 600 RPM.L RPM.R N.m	C2D38738;C2D38736;C2Z10955;C2D24125	JAGUAR XF 09~15 2.OT
47-1021		V 12V W 600 RPM.L RPM.R N.m	C2D24144;C2P17030;C2P25886;T2R25161;C2D38737;C2P17120	JAGUAR XF 10~15 3.0T XJ 10~15 3.0T XJR 14~15 3.0T XK 10~15 3.0T XKR 10~15 3.0T
47-1022		V 12V W 600 RPM.L RPM.R N.m	C2Z13765;C2P9525;C2P16825;C2D18413	JAGUAR XF 10~15 3.0L XJ 10~15 3.0L XJR 14~15 3.0L XK 10~15 3.0L XKR 10~15 3.0L
47-1023		V 12V W 300 RPM.L RPM.R N.m	107708400E;107708400D	TESLA model 3 17~21
47-1024		V 12V W 300 RPM.L RPM.R N.m	149399500B	TESLA model Y 20~
47-1025		V 12V W 400 RPM.L RPM.R N.m	HL3Z8C607D;HL3Z8C607C;HL348C607AB;HL348C607AC	FORD Expedition 18~ Lincoln Navigator 18~ FORD F150 15~
47-1026		V 12V W 400 RPM.L RPM.R N.m	26686973;26686974	BUICK GL8

47-1027		V 12V W 400 RPM.L RPM.R N.m	84020224	BUICK Regal/LaCrosse OPEL Z18 INSIGNIA-B 18~19 CHEVROLET CRUZE
47-1028			84297662;84000785;2812035;84297679	BUICK Regal/LaCrosse OPEL Z18 INSIGNIA-B 18~19 CHEVROLET Malibu NEW MODEL
47-1029		V 12V W 450 RPM.L RPM.R N.m	84268014;22942915	BUICK Envision
47-1030		V 12V W 500 RPM.L RPM.R N.m	13356630;39052896;39013323;39013322	BUICK Regal/LaCrosse CHEVROLET CRUZE
47-1031			13453909;39030262	BUICK Regal/LaCrosse CHEVROLET CRUZE
47-1032		V 12V W 400 RPM.L RPM.R N.m	39009028;39013321;39009026	BUICK Verano CHEVROLET CRUZE
47-1033			13356648;39009027	BUICK Verano CHEVROLET CRUZE
47-1034			670003403;500017502;670102597;940012202;5020694	MASERATI Giboli/Quattroporte/Levante

47-1035			670107328;670038839;5020861	MASERATI Ghibli 17~
47-1036			670106014	MASERATI Ghibli Quatt 14~21
47-1037		V 12V W RPM.L RPM.R N.m	68143894AA;68143894AB; 621601;FA90112	JEEP WRANGLER 12~17 WRANGLER JK 18~
47-1038		V 12V W RPM.L RPM.R N.m	4596212;620160	CHRYSLER CONCORDE 93~97 LHS 94~97 NEW YORKER 94~96 DODGE INTREPID 93~97 EAGLE VISION 93~97
47-1039		V 12V W RPM.L RPM.R N.m	DG9Z8C607D	FOD MONDEO 13~16
47-1040		V 12V W RPM.L RPM.R N.m	96395500	CHEVROLET 雪佛兰 MATIZ 05~13 SPARK 05~10
47-1041		V 12V W RPM.L RPM.R N.m	13267630;13267633;13267640;13267641;13335181	CHEVROLET 雪佛兰 科鲁兹 11~13
47-1042		V 12V W RPM.L RPM.R N.m	RF272;8W1Z8C607A;RF234;RF243;RF258	FORD CROWN VICTORIA 06~11 LINCOLN TOWN CAR 06~11 MERCURY GRAND MARQUIS 06~11

47-1043		V 12V W RPM.L RPM.R N.m	51965898	JEEP RENEGADE 15~
47-1044		V 12V W RPM.L RPM.R N.m	DG1Z8C607A;DG1Z8C607D;DG1Z8C607E;DG1Z8C607F;FO3115210	FORD EXPLORER 16~19 POLICE INTERCEPTOR 13~19 TAURUS 13~19
47-1045		V 12V W RPM.L RPM.R N.m	BA5Z8C607D;	FORD TAURUS 10~12 LINCOLN MKS 10~12
47-2009		V 12V A ≤ W φ RPM W .D	T111308130;T111308030	CHERY(奇瑞) TIGGO 06~
47-2162A		V 12V A ≤18.5 W 170 φ 470 RPM ±2300 W .D	52079528AD; 620041	JEEP Grand Cherokee 2004
47-2162A-1		V 12V A ≤ W φ RPM W .D	5017407AB;VDO.FA70136	CHRYSLER PT CRUISER 01~05
47-2162A-BM		V A ≤ W φ 470 RPM W .D		JEEP Grand Cherokee 2004
47-2163		V 12V A ≤13.5 W 160 φ 470 RPM ±1900 W .D	52079528AB; 620010	JEEP Grand Cherokee 99~03; Liberty 02~03

47-2164B		V 12V A ≤ W φ 405 RPM W .D	15780789; 15780793; 15780794; 15780796; 76016; FA70618;FA70620; 620654	CADILLAC Escalade 07~14 CHEVROLET Avalanche 07~13; Silverado 1500 07~13; Suburban 1500 07~14; Suburban 2500 07~13; Tahoe 07~14; GMC
47-2165-BM		V 12V A ≤7.5 W 110 φ 325 RPM ±2000 W .D	4364910; 4682593; 4682624; 4682636; 4682624AB; 4682624AC;	CHRYSLER Grand Voyager 96~00; Town&Country 99~00; Voyager 96~00 For DODGE Caravan 96~00; Grand Caravan 96~00 PLYMOUTH
47-2178		V 12V A ≤ W φ 405 RPM W .D	20879994; 25952782; 25952785; 621456	CHEVROLET Equinox 10~17 GMC Terrain 10~17
47-2353-BM		V 12V A ≤ W 360 φ RPM W .D	96FB8C607DH; XS6H8C607CB; 1020253; 1020914; 1112868	FORD Courier 2000; FiestaIV 95~00 MAZDA 121III 96~03
47-2498-BM		V 12V A ≤ W 300 φ RPM W .D		FORD Transit(江铃全顺)
47-2572		V 12V A ≤16.5 W φ 345 RPM ±2500 W .D	2S658C607EA;2S658C607EABC;2565BK620DA;698672R;698673R	FORD Ecosport 03~09; Fiesta 01~10
47-2572-BM		V 12V A ≤ W 345 φ RPM W .D	698678R	FORD Ecosport 03~09; Fiesta 01~10
47-2573		V 12V A ≤ W 345 φ RPM W .D	X1S658C607BA; 4EV012A; 4EV012B	FORD Courier 99~07 Fiesta 99~04;

47-2573A		V 12V A ≤ W φ 345 RPM W .D	1206273; XS5H8C607KC; XS5H8C607LC	FORD
47-2573-BM		V 12V A ≤ W φ 345 RPM W .D		FORD Courier 99~07 Fiesta 99~04;
47-2703		V 12V A ≤ W φ 394 RPM W .D	3N218C607AD	FORD Fiesta 99~01
47-2710		V 12V A ≤ W φ 386 RPM W .D	1690949; 1740023; 8V618C607FB; 8V618C607FC; BV618C607KC; BV6Z8C607K; CV618C607BA; X60115025B	FORD C-Max 10~17; Focus(福特福克斯) 10~17
47-2712		V 12V A ≤15.5 W 120 φ 347 RPM ±2500 W .D	ZJ3615025	FORD Fiesta
47-2712-BM		V 12V A ≤15.5 W 120 φ 347 RPM ±2500 W .D		FORD Fiesta
47-2715		V 12V A ≤15.5 W φ 383 RPM ±2400 W .D	6G918C607GH	FORD Mondeo(福特蒙迪欧) 06~10
47-2715A		V 12V A ≤ W (L) φ (R) RPM W .D		FORD Mondeo 06~10

47-2716		V 12V A ≤ W φ 360 RPM W .D	1141511; 1319972; 1337584; 1366100; 1475302; 1495676; 2S6H8C607EA; 2S6H8C607EC;	FORD Fiesta V 01~08; Fusion 02~12
47-2717		V 12V A ≤ W φ 300 RPM W .D	1061258; 1069390; 1072555; 1073160; 1075126; 1075130; 1107126; 1318692;	FORD Focus 98~04; Focus C-MAX 04~07; Focus II 04~
47-2717-BML		V 12V A ≤ W φ 300 RPM ± W .D		FORD Focus 98~04; Focus C-MAX 04~07; Focus II 04~
47-2717-BMR		V 12V A ≤ W φ 300 RPM ± W .D		FORD Focus 98~04; Focus C-MAX 04~07; Focus II 04~
47-2718		V 12V A ≤ W φ 393 RPM W .D	3M5H8C607RJ; Z60115025E; Z60115025H9A; 3M5H8C607VE; Z60215025B; Z60215025C; Z60215025D; Z60215025E;	FORD Focus C-MAX 04~07; Focus II (福克斯) 04~ MAZDA M3 04~09
47-2718-BM		V 12V A ≤ W φ RPM W .D	5M5H8C607AD	FORD Focus C-MAX 04~07; Focus II 04~ MAZDA M3 04~09
47-2719		V 12V A ≤17 W 250 φ 347 RPM ±2500 W .D	1525897; 1541278; 1557573; 1771265; 1819248; 1820863; 1836293; 1843124;	FORD B-MAX 12~; Eco Sport(福特翼博); Fiesta 09~; Fiesta VI 08~
47-2719A		V 12V A ≤17 W 250 φ 347 RPM ±2500 W .D		FORD B-MAX 12~; Fiesta 08~

47-2719B		V 12V A ≤17 W 250 φ 347 RPM ±2500 W .D	1525891; 1541276; 1557572; 1843120; 1933768; 2145093; 8V518C607AD; 8V518C607AE;	Ford Fiesta 11~17 Ikon 11~15
47-2719C		V 12V A ≤ W φ 405 RPM W .D Pull	52096869; 94509632; 94733314; 95018602; 95080111; 95352366; 94560893; 95352379;	CHEVROLET Sonic 12~17
47-2719C-BM		V 12V A ≤ W φ 405 RPM W .D Pull	52096865; 95018153;	CHEVROLET Sonic 12~17
47-2719D		V 12V A ≤17 W 250 φ 347 RPM ±2500 W .D		同47-2719,不要电阻总成
47-2721		V 12V A ≤ W φ 393 RPM W .D	1852732;1858189;8V618C607EB;8V618C607EC;8V618C607ED;DV618C607AD; DV618C607AB	FORD Focus C-MAX 11~14
47-2722		V 12V A ≤30 W 340 φ 382(L) RPM ±2400(L) φ 280(R) RPM	1451529; 1490302; 5041292; 7T168C607MB; 7T168C607NA; 7T168C607NB	FORD Touneo Connect 02~; Transit Connect 02~
47-2722A		V 12V A ≤16 W 200 φ 382 RPM ±2400 W .D	1439619; 1451528; 4371783; 4371786; 4391617; 4391619; 4521760; 4540015;	FORD Touneo 02~; Transit 02~
47-2723A-BM		V 12V A ≤ W φ 282 RPM W .D	698637R	CHEVROLET Chevy 91~02

47-2723-BM		V 12V A ≤ W φ 282 RPM W .D	698670R	FORD Ecosport 03~09; Fiesta 01~09
47-2723C-BM		V 12V A ≤ W φ 282 RPM W .D	46815900; 93396847; 93337577; 696054R; 698600R	CHEVROLET Celta 01~16; Prisma 07~12 FIAT Fiorino
47-2725-BML		V 12V A ≤ W φ RPM W .D	BK318C607CC	FORD Transit V363 14~
47-2725-BMR		V 12V A ≤ W φ RPM W .D	BK318C607CC	FORD Transit V363 14~
47-2727		V 12V A ≤ W φ 314 RPM W .D	4809170AC; 4809170AD; 4809170AE; 4809170AF; 620017	CHRYSLER Town&Country; Voyager 01~05 DODGE Caravan 01~05; Grand Caravan 01~05
47-2728		V 12V A ≤ W φ 314 RPM W .D	4809171AC; 4809171AD; 4809171AE; 4809171AF; 4809171AG; 620018	CHRYSLER Town&Country; Voyager 01~05 DODGE Caravan 01~05; Grand Caravan 01~05
47-2729		V 12V A ≤ W φ RPM W .D	1S4Z8C607AA;1S4Z8C607AC;1S4Z8C607AD;1S4Z8C607CA;1S4Z8C607CC; 620126	FORD Focus 00~04
47-2729-BML		V 12V A ≤ W φ RPM W .D		FORD Focus 00~04

47-2741-BM		V 12V A ≤ 16 W ϕ 363 RPM ± 2500 W .D	52409926; 93341072; 93341928; 93341929	CHEVROLET Meriva 04~08
47-2742		V 12V A $\leq$ W ϕ 335 RPM W .D	8L8Z8C607A; ZZC315025; 76229; FA70513; 621395	FORD Escape 09~12 MAZDA Tribute 09~11 MERCURY Mariner 09~11
47-2742A		V 12V A $\leq$ W ϕ 405 RPM W .D	8L8Z8C607B; ZZC415025; 76150; FA70593; 621038	FORD Escape 09~12 MAZDA Tribute 09~11 MERCURY Mariner 09~11
47-2743		V 12V A $\leq$ W ϕ RPM W .D	52028337AB;52028337AC; 52028339AB;52028337;19 144546;19188940	JEEP Cherokee 95~01
47-2745		V 12V A $\leq$ W ϕ RPM W .D	26203418; CO4364400	CHEVROLET New sail 3 18~22
47-2746		V 12V A $\leq$ W ϕ RPM W .D	93740672; 93742533; 96536666	CHEVROLET Aveo 05~08 PONTIAC G3 07~08 Wave 05~08 SUZUKI Swift 07~08
47-2801		V 12V A ≤ 11.5 W 90 ϕ 290 RPM ± 2400 W .D	87FB8K620BA; 89FB8B605BA; 89FB8K620AA; 6401205	FORD Escort 90~94; Escort V 90~92; Escort VI 92~94; Fiesta II 86~89; Fiesta III 89~95
47-2802		V 12V A $\leq$ W 80 ϕ 280 RPM W .D	87AB8B605A1A; 96FB8K620DA	FORD Fiesta III 89~85


47-2808		V 12V A ≤ W φ RPM W .D	MVW21;377121207G;547 959455F;913045114;9130 451141	VW(大众) GOL 10~13 PARATI 10~
47-2914		V 12V A ≤13.5 W 130 φ 383 RPM ±2100 W .D	95978939; 95978940	CHEVROLET Spark M300
47-2920		V 12V A ≤ W φ RPM W .D	1580747; 1580754; 93740543; 93740674; 96536520; 620646	CHEVROLET Aveo 04~; Lova(雪佛兰乐风,乐驰); Kalos 05~ DAEWOO Kalos 02~
47-2921		V 12V A ≤8.5 W φ RPM ±1700 W .D	1580762; 96536522; 96536521; 621053	CHEVROLET Aveo 04~; Lova(雪佛兰乐风,乐驰); Kalos 05~ DAEWOO Kalos 02~
47-2941		V 12V A ≤ W φ RPM W .D	96553241; 96553377	CHEVROLET Optra 1.6,1.8 04~ DAEWOO Excelle 1.6,1.8(别克凯越 1.6,1.8)
47-2942		V 12V A ≤8.5 W φ RPM ±1700 W .D	96553242	CHEVROLET Optra 1.8 04~ DAEWOO Excelle 1.8(别克凯越 1.8)
47-2964		V 12V A ≤ W φ RPM W .D	96553364	CHEVROLET Optra 1.6 04~ DAEWOO Excelle 1.6(别克凯越 1.6)
47-2969		V 12V A ≤ W φ RPM W .D	10313769	GM BUICK Regal 99~(别克世纪君威, GL8, 皇朝)

47-2987-BM		V 12V A ≤9 W 150 φ 280 RPM ±2300 W .D	MP8120VYV6SM 5000276 92145783	CHEVROLET STS-783 376.00.5210
47-2988-BM		V 12V A ≤ W φ RPM W .D	MP8120VYV8M 5000256 92145777;92147982	CHEVROLET STS-777 378.01.5210
47-2989-BM		V 12V A ≤ W φ RPM W .D	MP8125VYV8M 5000257 92145778	CHEVROLET STS-778 378.01.5310
47-2990-BM		V 12V A ≤ W φ 393 RPM W .D	MP8125VYV6SM 5000275 92145784	CHEVROLET STS-784 376.00.5310
47-2991		V 12V A ≤ W φ RPM W .D	7T4Z8C607B; 7T4Z8C607A; CT4Z8C607B; 622030	FORD Edge 07~09 LINCOLN MKX 07~09
47-2993		V 12V A ≤ W φ RPM W .D	2041816;2192892;BK218C 607DA	FORD Transit Custom 15~23
49-2015A		V 12V A ≤ W φ RPM W .D	38611RNAA01;38615RNA A01;38616RNAA01;62101 1	HONDA CIVIC 06~11
49-2015B		V 12V A ≤4.5 W φ 294 RPM W .D	38615PNB003; 38615PNLG01; 38615PNLG02; 38615PPAA01; 38615PZDA01; 620233; FA70161	HONDA CRV 02~06; Element 03~06

49-2018		V 12V A ≤ W 40 φ 188 RPM W .D	TIY358	UNIVERSAL Fan in the car
49-2018A		V 24V A ≤ W 40 φ 188 RPM W .D		UNIVERSAL Fan in the car
49-2104		V 12V A ≤ W φ 365 RPM W .D		TATA INDICA BEHR
49-2150A		V 12V A ≤5.5 W 50 φ 255X284 RPM ±2300 W .D		10"UNIVERSAL
49-2150A-2		V 24V A ≤5.5 W 50 φ RPM ±2300 W .D		10"UNIVERSAL
49-2150B		V 12V A ≤ W 50 φ 255*284 RPM W .D		10"UNIVERSAL
49-2150B-2		V 24V A ≤ W 50 φ 255*284 RPM W .D		10"UNIVERSAL
49-2150C		V 12V A ≤5.5 W 50 φ RPM ±2300 W .D		10"UNIVERSAL 配套专用

49-2150M		V 12V A ≤5.5 W 50 φ RPM ±2300 W .D		10"UNIVERSAL 墨西哥APYMSA专用,线路不变,风叶相反
49-2150T		V 12V A ≤5.5 W 50 φ RPM ±2300 W .D		10"UNIVERSAL 泰国New Star专用,线路相反,风叶相反
49-2150T-2		V 24V A ≤5.5 W 50 φ RPM ±2300 W .D		10"UNIVERSAL 泰国New Star专用,线路相反,风叶相反
49-2150V		V 12V A ≤4.5 W 50 φ 255*284 RPM ±2800 W .D		10"UNIVERSAL 中电机
49-2152A		V 12V A ≤6.5 W 70 φ 307*338 RPM ±2300 W .D		13"UNIVERSAL TATA BEHR 中电机
49-2152A-2		V 24V A ≤6.5 W 70 φ 307*338 RPM ±2300 W .D		13"UNIVERSAL TATA BEHR 中电机
49-2152B		V 12V A ≤ W 50 φ 288*325 RPM W .D		12"UNIVERSAL
49-2152B-2		V 24V A ≤ W 50 φ 288*325 RPM W .D		12"UNIVERSAL

49-2152C		V 12V A ≤ 7 W 50 ϕ 280*310 RPM ± 2000 W.D		12"UNIVERSAL
49-2152C-2		V 24V A ≤ 7 W 50 ϕ 280*310 RPM ± 2000 W.D		12"UNIVERSAL
49-2152D		V 12V A ≤ 7 W 50 ϕ 280*310 RPM ± 2000 W.D		12"UNIVERSAL LADA 2170,2171,2172 Priora
49-2152E		V 12V A $\leq$ W 90 ϕ 282*307 RPM W.D	21103F811200620	12"UNIVERSAL LADA 2170,2171,2172 Priora
49-2152M		V 12V A ≤ 7 W 50 ϕ 280*310 RPM ± 2000 W.D		12"UNIVERSAL 墨西哥APYMSA专用,线路不变,风叶相反
49-2152T		V 12V A ≤ 7 W 50 ϕ 280*310 RPM ± 2000 W.D		12"UNIVERSAL 泰国New Star专用,线路相反,风叶相反
49-2152T-2		V 24V A ≤ 7 W 50 ϕ 280*310 RPM ± 2000 W.D		12"UNIVERSAL 泰国New Star专用,线路相反,风叶相反
49-2152V		V 12V A $\leq$ W 80 ϕ 288*325 RPM W.D		12"UNIVERSAL 中电机

49-2154A		V 12V A ≤ 8 W 100 ϕ 339*375 RPM ± 2200 V 12 A ≤ 14.5 W 70		14"UNIVERSAL TATA BEHR 中电机
49-2154A-2		V 24V A ≤ 8 W 100 ϕ 339*375 RPM ± 2200 V 12 A ≤ 14.5 W 70		14"UNIVERSAL TATA BEHR 中电机
49-2154C		V 12V A ≤ 10 W 120 ϕ 355*384 RPM ± 1900 W .D		15"UNIVERSAL TATA BEHR 大电机
49-2154C-2		V 24V A ≤ 10 W 120 ϕ 355*384 RPM ± 1900 W .D		15"UNIVERSAL TATA BEHR 大电机
49-2154T		V 12V A $\leq$ W 50 ϕ 330*375 RPM W .D		14"UNIVERSAL 泰国New Star专用,线路相反, 风叶相反
49-2156A		V 12V A $\leq$ W 80 ϕ 391*428 RPM W .D		16"UNIVERSAL TATA BEHR 中电机
49-2156A-2		V 24V A $\leq$ W 80 ϕ 391*428 RPM W .D		16"UNIVERSAL TATA BEHR 中电机
49-2157T		V 12V A ≤ 4.5 W ϕ 189*210 RPM ± 3100 W .D		7.5"UNIVERSAL 泰国New Star专用,线路相反, 风叶相反

49-2157T-2		V 12V A ≤ 4.5 W ϕ 189*210 RPM ± 3100 W .D		7.5"UNIVERSAL 泰国New Star专用,线路相反, 风叶相反
49-2159T		V 12V A ≤ 4.5 W 50 ϕ 227*248 RPM ± 2700 W .D		9"UNIVERSAL 泰国New Star专用,线路相反, 风叶相反
49-2297		V 24V A $\leq$ W 180 ϕ 391*428 RPM W .D		16" UNIVERSAL(挖机装载机 车,冷藏车,叉车) 大电机
49-2298B		V 24V A $\leq$ W ϕ 305 RPM W .D		UNIVERSAL
49-2298C		V 12V A $\leq$ W ϕ 305 RPM W .D		UNIVERSAL
49-2300B		V 24V A ≤ 12.5 W 230 ϕ 300 RPM ± 2500 W .D		UNIVERSAL
49-2300C		V 12V A ≤ 12.5 W 230 ϕ 300 RPM ± 2500 W .D		UNIVERSAL
49-2303		V 24V A ≤ 12 W ϕ 296 RPM ± 2500 W .D	75416502	MB Prat MOTOR ISUZU ASSY MOTOR UNIVERSAL

49-2303A		V 12V A ≤ 12 W ϕ 296 RPM ± 2500 W .D	35022047	MB Prat MOTOR ISUZU ASSY MOTOR UNIVERSAL
49-2303B		V 24V A $\leq$ W ϕ 296 RPM W .D Pull		MB Prat MOTOR ISUZU ASSY MOTOR UNIVERSAL
49-2303C		V 12V A $\leq$ W ϕ 296 RPM W .D Pull		MB Prat MOTOR ISUZU ASSY MOTOR UNIVERSAL
49-2547-BM		V 12V A ≤ 11 W 80 ϕ 282 RPM ± 2400 W .D	2109130800801	LADA Samara; Vega
49-2580		V 12V A ≤ 36 W 470 ϕ 383(L) RPM ± 2500 (L) ϕ 315(R) RPM		TATA WINGER (TAXI, BIG VAN)
49-2581		V 12V A $\leq$ W ϕ RPM W .D		TATA INDIA VISTA QUATERJET
49-2581-BM		V 12V A $\leq$ W ϕ RPM W .D		TATA INDIA VISTA QUATERJET
49-2582		V 12V A $\leq$ W ϕ RPM W .D		INDIA TATA VISTA TDI

49-2853-1		V 12V A ≤6 W 80 φ 281 RPM ±2100 W .D	2103130800801; 2103130801010; ty3745912791	LADA Samara
49-2853-3		V 12V A ≤7 W 120 φ 280 RPM ±2400 W .D	21100130800800	LADA 2108
49-2907		V 12V A ≤ W φ 301 RPM W .D		TATA Ace 11~12

BLOWER



50-5001		V 12V A ≤ W φ RPM D.R	128410358	BAIC(北汽) 北京E系列 12~13; Senova(绅宝) D20 2015
52-1001		V 12V A ≤ W φ RPM W .D	971132E800;971132E900	HYUNDAI Tucson(现代途胜) 04~10 KIA Sportage(起亚狮跑) 05~10
52-1002		V 12V A ≤ W φ RPM W .D	0K08A61B10;0K55261R07; 0K60A61B10;K08A61B10; K60A61B10;FS.35086	KIA SPORTAGE 94~04
52-1003		V 12V A ≤ W φ RPM W .D	971132Y500	HYUNDAI ix35 10~ KIA Sportage 10~14
52-1004		V 12V A ≤ W φ RPM W .D	971093E060;	KIA Sorento I 02~11
52-1005		V 12V A ≤ W φ RPM W .D	971093D000;9710938000; 972303A010;VDO.PM9220	HYUNDAI SANTA FE 01~06 SONATA 99~05 XG300 01~ XG350 02~05 KIA OPTIMA 01~06
52-1006		V 12V A ≤ W φ RPM W .D	700259;971132Y000;9711 33X000;971134R000;HY3 126111;HY3126113;VDO. PM9383	HYUNDAI AZERA 12~17 ELANTRA 11~17 EQUUS 14~16 SONATA 11~15 KIA CADENZA 14~16 FORTE 14~18 OPTIMA 12~16
52-1007		V 12V A ≤ W φ RPM W .D	971111W100;VDO.PM412 6	KIA RIO 12~17

52-1008		V 12V A ≤ W φ RPM W .D	971132P700	KIA Sportage 10~ Sorento 09~15
52-1009		V 12V A ≤ W φ RPM W .D	971131H000;971132L000; VALEO.715089	HYUNDAI i30 07~12 KIA CEED 06~12 PRO 08~12
52-1010		V 12V A ≤ W φ RPM W .D	971132H000;971132B000; 971133M000;VDO.PM937 2;VALEO.715083	HYUNDAI ELANTRA 07~09 EQUUS 11~13 GENESIS 10~13 SANTA FE 07~09 VERACRUZ 07~12
52-1011		V 12V A ≤ W φ RPM W .D	97113B4000	HYUNDAI i10 MK2 13~18
52-1012		V 12V A ≤ W φ RPM W .D	97126C8000;BOSCH.F00 S3B2542;	HYUNDAI i20 Active 15~
52-1013		V 12V W RPM.L RPM.R N.m	4885669AA;4885669AB;48 85669AC;4885669AD;501 5865AA;VDO.PM9200	DODGE DAKOTA 00~04 DURANGO 01~03
52-5203		V 12V A ≤ W φ RPM D.R	971121C000;715261; 75805; PM9247	HYUNDAI Accent(现代御翔) 03~07
53-1002		V 12V A ≤ W φ RPM W .D	79310T0TH01;79310T2JH 01	Honda(本田) CR-V IV 12~23;杰 德 13~20;奥德赛 15~18;艾力绅 16~;雅阁 14~16;思铂睿 15~17;
53-1003		V 12V A ≤ W φ RPM W .D	7425065D00;7425065D01; 8710302080;8710302070;8 710302370	TOYOTA AVENSIS 03~08 COROLLA Verso 04~09

53-1004		V 12V A ≤ W φ RPM W .D	27220VB000;27220VB001; 27220VB002;	NISSAN Patrol 97~00
53-1005		V 12V A ≤ W φ RPM W .D	8710302120;8710302130;8710302140;8710302150;8710302160;8710302310;8710302460;8710302470;8710306090;;871030E050;871030K200;871030R010	TOYOTA VERSO 09~17 COROLLA 13~19 AURIS 07~13
53-1006		V 12V A ≤ W φ RPM W .D	8980474510	ISUZU NPR NQR 98~22
53-1007		V 12V A ≤ W φ RPM W .D	272264BA0A;272264BC0A; 272264BG0B;272264EM0A	NISSAN QASHQAI II 15~ X-TRAIL 14~15
53-1008		V 12V A ≤ W φ RPM W .D	7801A502	MITSUBISHI Pajero(三菱帕杰罗) 06~16
53-1009		V 12V A ≤ W φ RPM W .D	272261HB0A	KIA Niro 16~22 NISSAN Micra 15~23
53-1010		V 12V A ≤ W φ RPM W .D	8710347010	TOYOTA Prius Liftback 00~09
53-1011		V 12V A ≤ W φ RPM W .D	7425054J10;7802A105;VA LEO.815225	SUZUKI GRAND VITARA 03~05 VITARA 04~ XL-7 02~06
53-1012		V 12V A ≤ W φ RPM W .D	7415062JA0	KIA CeeD SW 07~12 Suzuki SX4 06~23

53-1013		V 12V A ≤ W φ RPM W .D	8710347020;8710347050; VDO.PM9249	TOYOTA PRIUS 01~09
53-1014		V 12V A ≤ W φ RPM W .D	272205M000;272208B410; 72240FA020	NISSAN FRONTIER 98~04 SENTRA 95~06 XTERRA 00~04 SUBARU FORESTER 98~99 IMPREZA 97~01
53-1015		V 12V A ≤ W φ RPM W .D	MR568593	MITSUBISHI LANCER 02~07 OUTLANDER 03~06
53-1016		V 12V A ≤ W φ RPM W .D	8710342060;72223AG01A; 79220SHJA01;79220SHJA 02;	HONDA ODYSSEY 05~10 TOYOTA RAV4 04~05 SUBARU LEGACY 05~09 OUTBACK 05~09
53-1017		V 12V A ≤ W φ RPM W .D	8981394270	NISSAN TITAN 16~19
53-1018		V 12V A ≤ W φ RPM W .D	8710335040;8710335041;8 710335060;8710335070;F S.75737	LEXUS GX470 03~07 TOYOTA 4RUNNER 03~09;PRADO(丰田普拉多) 02~09
53-1019		V 12V A ≤ W φ RPM W .D	72223AN00A;72223FL00A ;72223FL00B;72223FL500 ;72223FL501;79310T21A4 1;79310THRA41;79310TL AA51;VDO.PM4818	ACURA INTEGRA 23~ CIVIC 22~23 CR-V 17~23 HR-V 23~ ODYSSEY 18~23 SUBARU CROSSTREK 18~23 IMPREZA 17~22 LEGACY 20~22 OUTBACK 20~22
53-1020		V 12V A ≤ W φ RPM W .D	7425064J10;7425064J11;7 425064J12;7425076K10;7 425076K11;7425076K12	SUZUKI GRAND VITARA 06~08

53-1021		V 12V A ≤ W φ RPM W .D	2720500QAL;4415548;770 1057556;93181460	NISSAN INTERSTAR 03~06 OPEL MOVANO 01~06 RENAULT MASTER 00~06 VAUXHALL MOVANO 00~10
53-1022		V 12V A ≤ W φ RPM W .D	7802A310	MITSUBISHI TRITON MQ 15~19
53-1023		V 12V A ≤ W φ RPM W .D	79307S6MA42;VDO.PM93 89	ACURA RSX 02~06 CIVIC 02~05
53-1025		V 12V A ≤ W φ RPM W .D	27225EN000;27225EN00B ;27225EN00C;27225ET00 A;27225ET00B;27225ET1 0A;27225ET10B;27225JD 00A;	NISSAN QASHQAI 07~13
53-1026		V 12V A ≤ W φ RPM W .D	7415080J10;VDO.PM4070	SUZUKI SX4 07~13
53-1027		V 12V A ≤ W φ RPM W .D	27226EA010;27226EA000	NISSAN FRONTIER 05~21 PATHFINDER 05~12 XTERRA 05~15
53-1028		V 12V A ≤ W φ RPM W .D	2720500QAK;4415547;770 1057555;93181459;	NISSAN INTERSTAR 02~06 OPEL MOVANO 98~06
53-1029		V 12V A ≤ W φ RPM W .D	79310SMGG41	HONDA CIVIC 05~12
53-1030		V 12V A ≤ W φ RPM W .D	8710342101;8710347041	TOYOTA COROLLA IM 17~18 PRIUS 10~15 TPRIUS PLUG-IN 13~14 PRIUS V 12~13 RAV4 06~18

53-1031		V 12V A ≤ W φ RPM W.D	79310SMGE41	HONDA CIVIC 5D MK8 06~12
53-1034		V 12V W RPM.L RPM.R N.m	871030K400	TOYOTA Hilux 15~20
53-1035		V 12V W RPM.L RPM.R N.m	700193;27200JA000;2722 53TA1A;27225AM611;272 25JK60B;27225JK60E;272 25JK61A;IN3126100	INFINITI EX35 08~12 EX37 13~ FX35 09~12 FX37 13 FX50 09~13 G25 11~12 G35 07~08 G37 08~13 JX35 13~ M35 06~ M45 06~ Q50 14~22 Q60 14~15 QX60 14~ QX70 14~17 NISSAN ALTIMA 07~14 GT-R 09~21 MAXIMA 09~14 MURANO 04~14 PATHFINDER 13~14 QUEST 11~17
53-1036		V 12V W RPM.L RPM.R N.m	700188;8710304043;87103 04044;TO3126117	TOYOTA TACOMA 05~15
53-2856		V 12V A ≤ W φ 118*73.5 RPM D.R	1163403391;DEONSO.272 5000413	SUZUKI Wagon R 0.66 98~00 DAIHATSU Mira 0.66 98~02 BLOWER
53-2858		V 12V A ≤ W φ 147*60 RPM D.R	89721195305	ISUZU NKR BLOWER

53-2858A		V 24V A ≤ W φ 147*60 RPM D.R	8972119540	ISUZU CHAMRION BLOWER
53-2858B		V 24V A ≤ W φ 147*65 RPM D.R	5027250586	ISUZU Elf MAZDA Titan BLOWER
53-2861		V 12V A ≤ W φ 150*75 RPM D.R	2825001470;S871041120; 871041120	HINO BLOWER
53-2861A		V 24V A ≤ W φ RPM D.R	1163406181	HINO Profia;Ranger BLOWER
53-2868		V 12V A ≤ W φ 148*66 RPM D.R	8710352020	TOYOTA AE100; Yaris 99~ BLOWER
53-2870		V 12V A ≤ W φ 130*70 RPM D.R	1163406883	HONDA Life SUZUKI Wagon R BLOWER
53-2873		V 12V A ≤ W φ 150*75 RPM D.R	79310TF0003;871030K140 ;2727000101;2727000770	HONDA CRZ 10~15; Fit 09~14; Jazz 13~14 TOYOTA Hilux Vigo 06~15
53-5301		V 12V A ≤ W φ 150*75 RPM D.R	8710306021;871030 6031;8710308050;8710308051;8710308070;871030C022 ;871030E010;GD7A61B10;VDO.P M9199	LEXUS RX330 04~06 MAZDA 626 98~02 TOYOTA(丰田) Avalon 00~04; Camry(佳美) 97~06; Sequoia 01~07; Sienna 04~10; Solara 99~08; Tundra 00~06

53-5303		V 12V A ≤ W φ 165*70 RPM D.R	8710307040;871030C040; 871030E040;8710330450; 8710330451;8710348080;8 710360400;VDO.PM9351	LEXUS ES300H 13~14; ES350 07~16; GS300 98~06; GS350 07~11; GS430 06~07; GS450H 07~11; GS460 08~11; GX460 10~19; IS F 08~14; IS250 06~13; IS350 06~13; RX350 10~13; RX450H 10~13 TOYOTA(丰田) 4Runner 10~19; Avalon 05~18; Camry(凯美瑞) 07~17; Highlander 08~19; Tundra 07~19; Venza 09~16
53-5304		V 12V A ≤17 W φ 155*70 RPM ±2800 D.R	8710302200;VDO.PM9368	PONTIAC Vibe 09~10 SCION TC 11~16; XB 08~15 TOYOTA Corolla(丰田花冠) 09~19; Matrix 09~14; RAV4 06~18
53-5305		V 12V A ≤17 W φ 155*70 RPM ±2800 D.R	8710352140;8710352141; VDO.PM9366	SCION XD 08~14 TOYOTA Yaris 07~11
53-5321		V 12V A ≤ W φ 155*70 RPM D.R	79310SAA305;
79310 SAAG01;
F006B1002 0;
700238;
PM9363	HONDA Fit(本田飞度) 07~08
53-5321A		V 12V A ≤ W φ 155*70 RPM D.R	8710312040	TOYOTA Corolla(丰田威驰) 93~97
53-5322		V 12V A ≤ W φ 155*70 RPM D.R	79310SDAA01;79310SDC A01;79310SDRA01;79310 SHJA01;79310SJAA01;79 310SJAA02;79310SJCA01 ;79310SJCA02;79310SJC A03; FS.75735; VDO.PM9175	ACURA RL 05~12; TSX 04~08 HONDA(本田) Accord(雅阁) 03~07; Odyssey 05~10; Ridgeline 06~14

53-5323		V 12V A ≤15.5 W φ RPM ±2500 D.R	68004195AA;79310SNAA01;79310SNAA02;F006BE0111;PM9317	JEEP Wrangler 07~10 HONDA Civic(本田思域) 06~11
53-5324		V 12V A ≤17.5 W φ 165*70 RPM ±2500 D.R	272201MA0A;79310T0AA01;79310T2FA01;79310TR6A71;79311TR6A71;VDO.PM4038	ACURA(讴歌) ILX 16~17; RDX 15~18 HONDA Accord 13~17; Civic 14~15 INFINTI(英菲尼迪) M35 2010; M35H 12~13; M37 11~13; M56 11~13; Q70 12~19
53-5325		V 12V A ≤17.5 W φ 165*70 RPM ±2500 D.R	25770668;5191345AA;68048903AA;68048903AB;68048905AB;68089118AA;79310STKA41;79310STXA01;79310TA0A01;79310TK4A41;7L4Z19805A;7T4Z19805A;8710335100;8710360330;VDO.PM9313	ACURA(讴歌) MDX 07~13; RDX 07~12; TL 09~14; TLX 15~20; TSX 09~14; Lucerne 06~11 CADILLAC DTS 06~11; 200 11~14; Sebring 07~10 CHRYSLER Sebring(克莱斯勒铂锐) 07~09 DODGE(道奇) Avenger 08~14; Caliber 07~12; Journey 09~11; Ram 1500 Pickup 09~10; Ram 2500 Pickup 2010; Ram 3500 Pickup 2010 FORD Edge(福特锐界) 07~19; Fusion 13~19 HONDA Accord 08~12; CRV 07~11; Odyssey 11~17; Pilot 09~15 JEEP Com
53-5326		V 12V A ≤15 W φ 155*70 RPM ±2700 D.R	79310TF0G01;VDO.PM9387	HONDA Fit;Jazz(本田飞度) 08~14
53-5328		V 12V A ≤14.5 W φ 155*70 RPM ±2600 D.R	871030K060;871030K091;871030K092;8710326111	HONDA Fit(本田飞度) 15~ TOYOTA Innova 04~16; Fortuner 05~12; Hiace 05~14; Hilux 04~12

53-5329		V 12V A ≤14.5 W φ 155*70 RPM ±2600 D.R	79310S5DA01;79310S7AG12;79310SCVA01;79310S5JM01;FS.75736;VDO.PM9177	HONDA(本田) Civic(里程) 01~06; CRV 02~06; Element 03~11; Odyssey(奥德赛) 04~; Stream(时韵) 03~; MITSUBISHI Endeavor 04~05; Galant 04~05; SUZUKI Aerio 02~07
53-5342		V 12V A ≤14.5 W φ 148*85 RPM ±3100 D.R	27226EE91A;27226EE91B;27226EE91C;VDO.PM9376	NISSAN(尼桑) 骏逸, 骊威, NV200) Tiida 07~17 Versa 07~12
53-5343		V 12V A ≤11 W φ 130*103 RPM ±3000 D.R	272261HM0A;272261HK0A;272263AN0A;272269ME1A;FS.75013;VDO.PM4060	NISSAN March(玛驰) 11~15; Sunny(阳光) 11~14; Versa 13~19
53-5343A		V 12V A ≤11 W φ 130*103 RPM ±3000 D.R	272261HA0A	NISSAN March 11~15(RHD)
53-5344		V 12V A ≤15 W φ 136*86 RPM ±3000 D.R	272263SG0A;VDO.PM4054;FS.76986	NISSAN Sentra 13~17; Tiida(骊达) 18~
53-5345		V 12V A ≤10.5 W φ 110*79 RPM ±3800 D.R	1940008032	TOYOTA(中国) VIOS(威驰) 14~18; YARIS X(致炫) 14~18; YARIS L(致享) 14~18
53-5346		V 12V A ≤ W φ RPM D.R	27226JS60B	NISSAN NP300 Navara 2.3 08~
53-5347		V 12V A ≤ W φ 122*115 RPM 3000 D.R	272263SB0A	NISSAN Bluebird 12~; Sylphy 12~ QASHQAI II 13~15 X-TRAIL 14~15

53-5351		V 12V A ≤ W φ RPM D.R	7802A217;7802A277;VDO. PM9362;FS.75848	MITSUBISHI Lancer 08~17; Outlander 08~18;
53-5360		V 12V A ≤ W φ RPM D.R	DD2F61B10;GHP96 1B10;KD4561B10; VDO.PM4106	MAZDA 3 14~18; 6 14~19; CX-3 16~19; CX-5 13~19
55-1001		V 12V A ≤ W φ RPM W .D	3D0959101;17264769;MF0 160700551;0130111045	Bentley Continental Gt 05~
55-1002		V 12V A ≤ W φ RPM W .D	2308200214;A2308200214	MERCEDES SL500 03~06 SL55 AMG 03~07 SL550 07~ SL600 04~07 SL65 AMG 05~07 SLR MCLAREN 05~09
55-1003		V 12V A ≤ W φ RPM W .D	1613566380;6441X7	CITROEN JUMPY 07~11 PEUGEOT EXPERT Tepee 07~11
55-1004		V 12V A ≤ W φ RPM W .D	31390437;30661644;30676 613;31332747;313327470; 313904370	VOLVO C30 08~13 C70 06~13 S40 04~11 V50 05~11
55-1005		V 12V A ≤ W φ RPM W .D	7701067950	RENAULT TWINGO II 07~11
55-1006		V 12V A ≤ W φ RPM W .D	1609690280	CITROEN C4 13~16
55-1007		V 12V A ≤ W φ RPM W .D	42562718;500326592;5040 88153	Iveco Daily IV Kasten 01~11

55-1008		V 12V A ≤ W φ RPM W .D	2119062400;2118300508;2118301008;A2118300508;A2118301008;A2119062400	MERCEDES E320 05~09 E350 06~09 E500 03~06 E55 AMG 03~06 E550 07~09 E63 AMG 07~09
55-1009		V 12V A ≤ W φ RPM W .D	5Q1819021H;3QF819021;5Q1819021B;5Q1819021E;5QD819021B;5QD819021D	AUDI A3 15~20 Q3 19~21 RS3 17~22 S3 15~20 VW ATLAS 18~23 E-GOLF 15~19 GOLF 15~21 GTI 15~20 JETTA 19~23 TAOS 22~23 TIGUAN 18~23
55-1010		V 12V A ≤ W φ RPM W .D	13276230;1845105	OPEL ASTRA TURBO 09~15
55-1011		V 12V A ≤ W φ RPM W .D	2209060000;2208203542;A2208203542;A2209060000	MERCEDE S-Class 98~06
55-1012		V 12V A ≤ W φ RPM W .D	64119242608;64119194590;64119200935;9200935;9242608	BMW(宝马) 5-Series 09~17 7-Series 08~15
55-1013		V 12V A ≤ W φ RPM W .D	272102988R	RENAULT DOKKER 13~ DACIA DOKKER 12~15 LODGY 12~15
55-1014		V 12V A ≤ W φ RPM W .D	1608174880;871030H010;871030H011;1608175580;871030H020;871030H021;6441V16441V0	CITROEN C1 05~14 PEUGEOT 107 05~14 TOYOTA AYGO 05~10
55-1015		V 12V A ≤ W φ RPM W .D	71743151;7415063J00	FIAT SEDICI 06~14 SUZUKI SX4 06~15 Swift 05~12

55-1016		V 12V A ≤ W φ RPM W .D	8T2820021	AUDI(奥迪) A4 Allroad 08~15 A5 Sportback 07~17 PORSCHE(保时捷) Macan 14~
55-1017		V 12V A ≤ W φ RPM W .D	2108203842;A2108203842	MERCEDES E-Class 95~03
55-1018		V 12V A ≤ W φ RPM W .D	6441V5;6441V6;6441V7	PEUGEOT 207 07~13
55-1019		V 12V A ≤ W φ RPM W .D	4B1820021	AUDI A6 99~04 ALLROAD 01~05 RS6 03~04 S6 02~03
55-1020		V 12V A ≤ W φ RPM W .D	6441F3	CITROEN XM 89~00 PEUGEOT 605 89~99
55-1021		V 12V A ≤ W φ RPM W .D	13293624;55702444;77364 953;77366026;13392209;7 7365038;1845114	FIAT GRANDE PUNTO 05~15 PUNTO EVO 08~12 OPEL CORSA 06~14
55-1022		V 12V A ≤ W φ RPM W .D	1610497180;DB271001	Peugeot 308 14~21
55-1023		V 12V A ≤ W φ RPM W .D	77362775	FIAT IDEA 04~09 LANCIA MUSA 04~12
55-1024		V 12V A ≤ W φ RPM W .D	6441N76441N6	CITROEN C5 01~04

55-1025		V 12V A ≤ W φ RPM W .D	1808067;90228667	OPEL VECTRA 88~95 VAUXHALL CAVALIER Mk III 88~95
55-1026		V 12V A ≤ W φ RPM W .D	7701056964	RENAULT MEGANE II 03~09
55-1027		V 12V A ≤ W φ RPM W .D	6441CZ	CITROEN C4 II 09~15 DS4 11~15 PEUGEOT 308 09~14 RCZ 10~15
55-1028		V 12V A ≤ W φ RPM W .D	6441AS	CITROEN BERLINGO 08~14 C4 06~13 PEUGEOT PARTNER 08~16
55-1029		V 12V A ≤ W φ RPM W .D	0008352385;0018305808;0 5133436AA;2D2959101;2 D2959101B;A0008352385; A0018305808;	MERCEDES SPRINTER 96~00 T1 88~96
55-1030		V 12V A ≤ W φ RPM W .D	0008304901;A0008304901	MERCEDES(奔驰)METRIS 16~21
55-1031		V 12V A ≤ W φ RPM W .D	64111373766;6411138615 4;1373766;1386154	BMW(宝马) 3 82~94 Z1 88~91 Z3 95~03
55-1032		V 12V A ≤ W φ RPM W .D	6441Q6;6441R0	CITROEN C2 03~06 C3 02~10 PEUGEOT 1007 05~07 206 02~07
55-1033		V 12V A ≤ W φ RPM W .D	1608182080	PEUGEOT 2008 13~15 208 12~15

55-1034		V 12V A ≤ W φ RPM W .D	1609170880;1609170780;1610705080	CITROEN C-ELYSEE 12~14 PEUGEOT 301 12~
55-1035		V 12V A ≤ W φ RPM W .D	27226JY10A	RENAULT Koleos(科雷傲) 17~
55-1036		V 12V A ≤ W φ RPM W .D	7802A237;CSA431D227;1607025680;7415076K10;7415076K10000;7415076K11;7415076K11000;7415076K12;7415076K12000;7425076K12000;6441CC;6441Z3;6441Z4	CITROEN C-CROSSER 07~10 C4 AIRCROSS 12~ MITSUBISHI(三菱) ASX Van 10~ 劲炫 10~15 欧蓝德 06~12 PEUGEOT 4008 12~
55-1037		V 12V A ≤ W φ RPM W .D	4518301600;4518300108;4518350007	SMART FORTWO 08~17
55-1038		V 12V A ≤ W φ RPM W .D	2Q1819021	VW POLO VI 17~23
55-1039		V 12V A ≤ W φ RPM W .D	46723715	FIAT DOBLO 01~ PUNTO 99~12
55-1040		V 12V A ≤ W φ RPM W .D	0008304701	MERCEDES METRIS 16~22
55-1041		V 12V A ≤ W φ RPM W .D	31320392;30715483;8665191;9171719	VOLVO S80 02~
55-1042		V 12V A ≤ W φ RPM W .D	2108205242;2108203442;2108206842;2109060200	MERCEDES E300 95~99 E320 96~03 E420 97~98 E430 98~02 E55 AMG 99~02

55-1043		V 12V A ≤ W φ RPM W .D	7H1819021B;7E1819021A; 7E1819021C;7E1820021;7 E5820021;7H1819021A;7 H1819021D;7H1820021B; 7H1820021D	VW MULTIVAN 15~ TRANSPORTER 03~15
55-1044		V 12V A ≤ W φ RPM W .D	52466654;1808082	VAUXHALL TIGRA Mk I 94~00 OPEL CORSA B 93~00 TIGRA 94~00
55-1045		V 12V A ≤ W φ RPM W .D	7701056598	RENAULT Scenic 04~08
55-1046		V 12V A ≤ W φ RPM W .D	77365569	ALFA ROMEO GIULIETTA 10~
55-1047		V 12V A ≤ W φ RPM W .D	272106020R;6001547487	DACIA DUSTER 10~15 LOGAN 04~10 SANDERO 08~11 LADA LARGUS 12~16 RENAULT DUSTER 11~15 LOGAN 04~11 SANDERO/STEPWAY I 07~10
55-1048		V 12V A ≤ W φ RPM W .D	46723714;46722948;46770 835	FIAT DOBLO 01~10 PUNTO Van 00~09
55-1049		V 12V A ≤ W φ RPM W .D	1845202;90535114	OPEL Corsa 00~09 TIGRA 04~10
55-1052		V 12V A ≤ W φ RPM W .D	64119297752;6411929775 1	MINI COOPER 15~23 BMW(宝马) 228I 20~23 I3 14~21 I3S 18~21 M235I 20~23 X1 16~22 X2 18~23

55-1050		V 12V A ≤ W φ RPM W .D	7701068976	RENAULT KANGOO 08~12 MASTER III 10~11
55-1051		V 12V A ≤ W φ RPM W .D	64118372183;6411839085 1	BMW 5-Series 95~03 7-Series 95~01
55-1053		V 12V A ≤ W φ RPM W .D	64118391809	BMW(宝马) 740I 95~01
55-1054		V 12V A ≤ W φ RPM W .D	6441N4;6441E1;6441J5;64 41K5;6441J0;95666814	CITROEN BERLINGO 96~11 EVASION 95~02 JUMPY 95~06 XSARA 97~05 ZX 91~97
55-1055		V 12V A ≤ W φ RPM W .D	6441CG;6431Q1	CITROEN BERLINGO 08~16
55-1056		V 12V A ≤ W φ RPM W .D	8D1820021B;8D1820021	AUDI A4 00~02 VW PASSAT 98~05
55-1057		V 12V A ≤ W φ RPM W .D	64113422644;6411342264 6;64119266899;700265	MINI(迷你) COOPER 07~15
55-1058		V 12V A ≤ W φ RPM W .D	64113422645	MINI CLUBMAN 07~15 COUNTRYMAN 10~16 MINI CLUBVAN 12~14 PACEMAN 12~16
55-1059		V 12V A ≤ W φ RPM W .D	1H1819021	VW CABRIO 95~98 GOLF 93~98 JETTA 93~99

55-1060		V 12V A ≤ W φ RPM W .D	6441S0	CITROEN BERLINGO 96~11 JUMPY 98~06 PARTNER 01~13
55-1061		V 12V A ≤ W φ RPM W .D	1718350004;A1718350004	MERCEDES SLK280 06~08 SLK300 09~11 SLK350 05~11 SLK55 AMG 05~10
55-1062		V 12V A ≤ W φ RPM W .D	1608175880;871030H030; 871030H031;6441V2	CITROEN C1 05~14 107 05~14 TOYOTA AYGO 05~10
55-1063		V 12V A ≤ W φ RPM W .D	2209060100;2208203142	MERCEDES CL500 00~06 CL55 AMG 01~06 CL600 01~06 CL65 AMG 05~06 S350 06~ S430 00~06 S500 00~06 S55 AM 01~06 S600 01~06 S65 AMG 05~06
55-1064		V 12V A ≤ W φ RPM W .D	2038202614;A2038202614	MERCEDES C240 01~02
55-1065		V 12V A ≤ W φ RPM W .D	64119350396;6411923755 9	BMW 1-SERIES F20 F21 11~
55-1066		V 12V A ≤ W φ RPM W .D	7701206251;7701041792	RENAULT MEGANE 97~99 Scenic 99~03
55-1067		V 12V A ≤ W φ RPM W .D	13214734;1845107	OPEL ZAFIRA B Van 05~15

55-1068		V 12V A ≤ W φ RPM W .D	1648350007;1648350307;1648350507;A1648350007;A1648350307;A1648350507	MERCEDES GL320 07~09 GL350 10~12 GL450 07~12 GL500 08~12 GL550 08~12 ML320 07~09 ML350 06~11 ML450 10~11 ML500 06~07 ML550 08~11 ML63 AMG 07~11 R320 07~09 R350 06~13 R500 06~08 R550 08~ R63 AMG 07~
55-1069		V 12V A ≤ W φ RPM W .D	4635462;5047527;5049085;5331236;5333539	SAAB 9-5 99~09
55-1070		V 12V A ≤ W φ RPM W .D	0008358304;A0008358304	MERCEDES(奔驰) 唯雅诺 03~10 威霆 03~12
55-1071		V 12V A ≤ W φ RPM W .D	4F0820020A;4F0820020	AUDI(奥迪) A6 05~11 R8 08~15 S6 07~11
55-1072		V 12V A ≤ W φ RPM W .D	7E2819021C;7E2819021A;7H2819021A;7H2819021B;7H2819021D	VW TRANSPORTER 03~15
55-1073		V 12V A ≤ W φ RPM W .D	13250117;12799558;698807	SAAB 9-3 03~06
55-1074		V 12V A ≤ W φ RPM W .D	6441A2	PEUGEOT 306 94~02

55-1075		V 12V A ≤ W φ RPM W .D	0008357904;8357904;A00 08357904	MERCEDES(奔驰) 唯雅诺 03~10 威霆 03~10
55-1076		V 12V A ≤ W φ RPM W .D	701819021B;357819021;7 03820022;191820121;8A1 820021	AUDI 80 88~92 90 88~95 A4 96~ CABRIOLET 94~98 COUPE 90~91 VW CORRADO 90~94 EUROVAN 92~03 GOLF 85~92 JETTA 84~92 PASSAT 90~97
55-1077		V 12V A ≤ W φ RPM W .D	71734232;46722702;6441 S4	CITROEN JUMPER 94~06 FIAT DUCATO 94~02 PEUGEOT BOXER 94~06
55-1078		V 12V A ≤ W φ RPM W .D	7701208225;7701050309;9 1158686;93161216;440944 7;4413391	OPEL VIVARO 01~06 RENAULT TRAFIC 01~08 VAUXHALL VIVARO 01~14
55-1079		V 12V A ≤ W φ RPM W .D	13250115;13221349;30592 634;32101262;9228317;69 8806	SAAB 9-3 03~11 SAAB 9-3X 10~11
55-1080		V 12V A ≤ W φ RPM W .D	7701045892;7701206250	RENAULT MEGANE 96~99 Scenic 99~03
55-1081		V 12V A ≤ W φ RPM W .D	8710360180	LAND ROVER DISCOVERY 99~ TOYOTA LAND CRUISER 95~
55-1082		V 12V A ≤ W φ RPM W .D	7701048752;7701048753;4 6799643;77364449	ALFA ROMEO 147 01~10 156 97~06 RENAULT LAGUNA II 01~07

55-1083		V 12V A ≤ W φ RPM W .D	0008358004;A0008358004	MERCEDES(奔驰) 唯雅诺 03~07 威霆 03~07
55-1084		V 12V A ≤ W φ RPM W .D	7701046058	RENAULT MEGANE I 96~03
55-1085		V 12V A ≤ W φ RPM W .D	2108200042	MERCEDES E-Class 95~02
55-1086		V 12V A ≤ W φ RPM W .D	0008309308;81619300036; 1294099	MERCEDES(奔驰) VARIO 96~13
55-1087		V 12V A ≤ W φ RPM W .D	272108241R;272100042R; 272104937R	RENAULT Megane 08~13
55-1088		V 12V A ≤ W φ RPM W .D	2028209342;A2028209342	MERCEDES C220 96~97 C230 96~00 C280 96~00 C36 AMG 96~97 C43 AMG 98~00 CLK320 98~03 CLK430 99~03 CLK55 AMG 01~03 SLK230 98~04 SLK32 AMG 02~04 SLK320 01~04
55-1089		V 12V A ≤ W φ RPM W .D	2048200008;2048200208; A2048200008;A204820020 8	MERCEDES-BENZ C230 08~09 C250 10~11 C300 08~14 C350 08~10 C63 AMG 08~09 E300 12~ E350 10~11 E550 10~ E63 AMG 10~ GLK250 13~15 GLK350 10~ SLS AMG 11~15

55-1090		V 12V A ≤ W φ RPM W .D	64119204154;6411837279 7	BMW 318TI 99~ 320I 01~05 323CI 00~ 323I 98~00 325CI 01~06 325I 01~05 325XI 01~05 328CI 00~ 328I 97~00 330CI 01~06 330I 01~06 330XI 01~06 M3 01~06 X3 04~10
55-1091		V 12V A ≤ W φ RPM W .D	7701048754	RENAULT LAGUNA II 01~07
55-1092		V 12V A ≤ W φ RPM W .D	6441N3;6441K4	CITROEN XSARA 07~05 ZX 91~97
55-1093		V 12V A ≤ W φ RPM W .D	1K2820015;1K2820015G;1 K2820015H;3C0907521C; 3C2820015;3C2820015D;3 C2820015E;3C2820015F	VW TIGUAN 12~14
55-1094		V 12V A ≤ W φ RPM W .D	71736002;46723511;77363 823	FIAT STILO 02~06
55-1095		V 12V A ≤ W φ RPM W .D	1408301208;1408300508; A1408300508;A140830120 8	MERCEDES 300SD 92~93 300SE 92~93 400SE 92~ 400SEL 93~ 500SEC 93~ 500SEL 92~93 600SEC 93~ 600SEL 92~93 CL500 98~99 CL600 98~99 S320 94~99 S350 94~95 S420 94~99 S500 94~99 S600 94~99

55-1096		V 12V A ≤ W φ RPM W .D	6441E0;9464242580	CITROEN EVASION MPV 95~02 JUMPY 95~06 FIAT(菲亚特)SCUDO 96~06 PEUGEOT 806 94~02 EXPERT 96~06
55-1097		V 12V A ≤ W φ RPM W .D	272101005R	RENAULT CLIO IV 12~16
55-1098		V 12V A ≤ W φ RPM W .D	64118390208;6411146845 3	BMW 318I 92~99 318IS 92~99 320I 92~95 323I 98~99 323IS 98~99 325I 92~95 325IS 92~95 328I 96~99 328IS 96~99 M3 94~99
55-1099		V 12V A ≤ W φ RPM W .D	7082382;7078734	FIAT PALIO 97~04 SIENA 00~12
55-1100		V 12V A ≤ W φ RPM W .D	1318888080;1307829080;0 001307829080	FIAT DUCATO 94~02
55-1101		V 12V A ≤ W φ RPM W .D	46721251;46721160;46722 218	FIAT PUNTO 93~00 BARCETTA 95~05 LANCIA Y 95~03
55-1102		V 12V A ≤ W φ RPM W .D	6Q1820015G;6Q1820015; 6Q1820015B;6Q1820015C ;6Q1820015E;6Q1820015 H	AUDI A1 10~18 A2 00~05 SEAT CORDOBA 02~09 IBIZA 99~15 TOLEDO 12~15
55-1103		V 12V A ≤ W φ RPM W .D	6441S6;6441Y7	CITROEN C4 04~13 PEUGEOT 307 00~09

55-1104		V 12V A ≤ W φ RPM W .D	8T1820021;PAB820021C	AUDI(奥迪) A4 13~16 A5 12~17 ALLROAD 13~16 Q5 13~17 RS5 13~15 S4 13~16 S5 12~17 SQ5 14~17 PORSCHE(保时捷) MACAN 15~23
55-1105		V 12V A ≤ W φ RPM W .D	71735484;46722956	FIAT DOBLO 01~10 PUNTO Van 00~09
55-1106		V 12V A ≤ W φ RPM W .D	6Q1819015B;6Q1819015; 6Q1819015C;6Q1819015E ;6Q1819015G;6Q1819015 H;6Q1819015J;6R1819015	AUDI A1 10~18 A2 00~05 SEAT CORDOBA 02~09 IBIZA 02~15 TOLEDO 12~13 SKODA FABIA 99~14 RAPID 12~13 ROOMSTER 06~15 VW FOX 03~14 POLO 02~14
55-1107		V 12V A ≤ W φ RPM W .D	46722992;46722759	FIAT DUCATO 94~02
55-1108		V 12V A ≤ W φ RPM W .D	6441R4;644195;E165017; E165114;95658442	CITROEN BERLINGO 96~11 ZX 91~97
55-1109		V 12V A ≤ W φ RPM W .D	0008356107;00083561076 4;MB3126115	MERCEDES SPRINTER 10~18
55-1110		V 12V A ≤ W φ RPM W .D	1557646;77364884;9S511 8527AA	FIAT 500 07~10 PANDA 03~09

55-1111		V 12V A ≤ W φ RPM W .D	1698200642;715051	MERCEDES B200 06~11
55-1112		V 12V A ≤ W φ RPM W .D	357820021;176820021;701820021;893820021;698157	AUDI 80 90~92 90 90~91 VW CORRADO 90~94 EUROVAN 93~03 GOLF 90~92 JETTA 90~93 PASSAT 90~97
55-1113		V 12V A ≤ W φ RPM W .D	6441T8	PEUGEOT 307 00~08
55-1114		V 12V A ≤ W φ RPM W .D	30858848	VOLVO S40 00~04 V40 00~04
55-1115		V 12V A ≤ W φ RPM W .D	31291516;30767008;31267505;8623276	VOLVO S60 11~18 S80 07~16 V60 15~18 V70 08~10 XC60 10~17 XC70 08~16
55-1116		V 12V A ≤ W φ RPM W .D	1845055;90568692	OPEL VECTRA B 95~03
55-1117		V 12V A ≤ W φ RPM W .D	7E0819021A	AUDI Q7 07~15 VW(大众) TOUAREG 04~10
55-1118		V 12V A ≤ W φ RPM W .D	9119001;1845062	OPEL ZAFIRA A MPV 99~05

55-1119		V 12V A ≤ W φ RPM W .D	6441R5;6441E3	CITROEN BERLINGO 96~11 EVASION MPV 94~02 JUMPY 95~06 PEUGEOT 806 95~02 EXPERT 96~06 PARTNER 96~15
55-1120		V 12V A ≤ W φ RPM W .D	6441A0	PEUGEOT 306 94~01
55-1121		V 12V A ≤ W φ RPM W .D	6441L3	CITROEN BERLINGO 96~08 ZX 91~97 PEUGEOT PARTNER 96~15
55-1122		V 12V A ≤ W φ RPM W .D	7P0820021B;7P0820021;7P0820021D;7P0820021F;95857234200;95857234201;95857234202	PORSCHE(保时捷) CAYENNE 11~18 VW(大众) TOUAREG 11~17
55-1123		V 12V A ≤ W φ RPM W .D	64118382305	BMW(宝马) 525I 01~03 X5 01~04
55-1124		V 12V A ≤ W φ RPM W .D	77366917;77366208	FIAT 500 07~13 PANDA 12~15
55-1125		V 12V A ≤ W φ RPM W .D	272104377R	RENAULT Fluence 10~14
55-1126		V 12V A ≤ W φ RPM W .D	6441Y1;77364090	CITROEN JUMPER 06~11 FIAT DUCATO 06~11 PEUGEOT BOXER 06~11
55-1127		V 12V A ≤ W φ RPM W .D	6441P1	PEUGEOT 307 00~09

55-1128		V 12V A ≤ W φ RPM W .D	7701051271	RENAULT CLIO II 98~09 THALIA 98~08
55-1129		V 12V A ≤ W φ RPM W .D	6441G3;644194	PEUGEOT 405 87~99 406 95~04
55-1130		V 12V A ≤ W φ RPM W .D	6441G6;644171	CITROEN AX 86~98 SAXO 96~04 PEUGEOT 106 91~04 405 87~97
55-1132		V 12V A ≤ W φ RPM W .D	6441K0;6441N9;6441W5	CITROEN Senna 99~11 PEUGEOT 206 99~13
55-1134		V 12V A ≤ W φ RPM W .D	3506530;6820812;6820815; 6849031;6849562	VOLVO 850 93~97
55-1135		V 12V A ≤ W φ RPM W .D	8K2820021B;8K2820021A; 8K2820021C	AUDI A5 08~10
55-1136		V 12V A ≤ W φ RPM W .D	8D2819021B	AUDI A4 94~00
55-1137		V 12V A ≤ W φ RPM W .D	7701067032	Renault Clio 11~23
55-1138		V 12V A ≤ W φ RPM W .D	9119002;1845070;1845071; 9119003	OPEL ASTRA 99~05 VAUXHALL ASTRA Mk 98~05

55-1139		V 12V A ≤ W φ RPM W .D	13214733;13333050;1845106;1845134;39090004	OPEL ZAFIRA B Van 05~15 VAUXHALL INSIGNIA Mk 05~17
55-1140		V 12V A ≤ W φ RPM W .D	13250116;13221348;1845088;1845109;1845122;9180222	OPEL SIGNUM Hatchback 03~08 VECTRA C Estate 03~08 VECTRA C GTS 03~08 SAAB 9-3 02~15
55-1141		V 12V A ≤ W φ RPM W .D	4H1820021B;4H1820021C	AUDI(奥迪) A6 12~18 A7 12~18 A8 11~18 RS7 14~18 S6 13~18 S7 13~18 S8 13~18
55-1142		V 12V A ≤ W φ RPM W .D	6441CP	CITROEN DS5 11~15 PEUGEOT 3008 09~16 5008 09~15
55-1143		V 12V A ≤ W φ RPM W .D	0028301608;0038300308; A0028301608;A0038300308;	MERCEDES SPRINTER 95~06
55-1144		V 12V W RPM.L RPM.R N.m	52400424;52484829;89019321;GM3126102	CADILLAC ESCALADE 02~06 CHEVROLET SILVERADO 1500 99~02 SILVERADO 2500 99~02 SILVERADO 3500 01~02 TAHOE 00~06 GMC SIERRA 1500 99~02 SIERRA 2500 99~02 SIERRA 3500 01~02 YUKON 00~06
55-1145		V 12V W RPM.L RPM.R N.m	15850268;19153333;22754990;22792042;GM3126119	BUICK ALLURE 05~09 LACROSSE 05~09 CHEVROLET IMPALA 04~13 IMPALA LIMITED 14~16 MONTE CARLO 04~07 PONTIAC GRAND PRIX 04~08

55-1146		V 12V W RPM.L RPM.R N.m	A0999062003	MERCEDES CLC 15~ LHD C180L/C200L/C300/C260/E2 00/E260/GLC260 ENZ C400.C-KLASS W205 BENZ W205, 213, 238, 257 15-
55-1147		V 12V W RPM.L RPM.R N.m	1248200142;1248203342	MERCEDES (奔驰) CABRIOLET 92~93 COUPE 87~93 E-CLASS 93~96 KOMBI 85~93
55-2064		V 24V A ≤ W φ 190 RPM D.R	6401138	IVECO PERVANELİ BLOWER
55-2065B		V 24V A ≤ W φ 106*89 RPM D.R	6402025;6145167	BMC PROFESYONEL BLOWER
55-2302		V 12V A ≤ W φ 195 RPM D.R	7702252844;7701027046;6 401125	RENAULT R9 81~88; Rapid 85~98 BLOWER
55-2322		V 12V A ≤ W φ 128*100 RPM D.R	1808068;1845021;1845035 ;1845038;1845057;904495 76;90450963;90450980;90 504705;90506193;9058951 1;4366746;4366944;47588 19;VDO.7733006075V	OPEL Astra F 91~01; Calibra A 90~97; Vectra A 88~95 SAAB 900 I 85~94; 900 II 93~98 BLOWER
55-2852		V 12V A ≤ W φ 135*81 RPM D.R	2012071401;990773002;53 99861040	BLOWER
55-2854		V 24V A ≤ W φ 174 RPM D.R	6401149	MB KAMYON PERVANELİ BLOWER
55-2859		V 24V A ≤ W φ 134*95 RPM D.R	06940139500099	BMC PROFESSIONAL TRUCK BLOWER

55-2864		V 12V A ≤11.5 W φ 130.5*84 RPM ±3500 D.R	77366404;1940008011	FIAT Viaggio(菲亚特菲翔) 12~
55-2865		V 12V A ≤ W φ 151*60 RPM D.R	5920012	FIAT Ducato T.T. BLOWER
55-2866		V 24V A ≤ W φ 149*77 RPM D.R	0038300108;A0038300108	MB Axor II -Atego II -III
55-2875		V 12V A ≤ W φ 168 RPM D.R		ALFA ROMEO Spider Veloce 84~
55-2876		V 12V A ≤ W φ 170 RPM D.R		ALFA ROMEO Spider Veloce 69~
55-2890		V 12V A ≤ W φ 205 RPM D.R	69401290	TOFAS Dogan SLX FIAT Dogan SLX
55-2890A		V 12V A ≤ W φ 205 RPM D.R	69401287	TOFAS Dogan; Kartal; Sahin FIAT Dogan; Kartal; Sahin
55-5502		V 12V A ≤15 W φ 146*71 RPM ±3300 D.R	6441K9;2761400QAC;440 9448;91158687;770103589 2;7701050310;698059;698 447;715059	NISSAN Primastar 01~19 OPEL Vivaro A 01~19 PEUGEOT 406 95~04; 607 00~08 RENAULT Trafic II 99~13; Master 98~10; Master I 80~98; Safrane 92~00; Trafic 01~19

55-5516		V 12V A ≤11 W φ 138*76 RPM ±2800 D.R	7701057683;7701059205	RENAULT ClioIII 05~18; Kangoo 97~18
55-5517		V 12V A ≤14 W φ 147*70 RPM ±2900 D.R	272269U01A;27226AX105; 27226AX205;6001547691; 7701060014;7701060015;7 701062225;7701062226;77 01067982;7701209802;698 755;715056;715057;71507 1	DACIA Logan 04~16; Sandero 08~16 NISSAN MicraIII 03~10; Note 06~12 For RENAULT ClioIII 08~12; Logan I 04~12; Modus 04~18; Twingo II 07~14; Wind 10~13
55-5518		V 12V A ≤ W φ 147*70 RPM D.R	272100975R;715251	DACIA Logan 12~13; Sandero 12~15; RENAULT Logan 08~13; Sandero 13~
55-5520		V 12V W RPM.L RPM.R N.m	885001314;885001315;524 88121	RENAULT Laguna 01~06
55-5521		V 12V A ≤13.5 W φ RPM ±3100 D.R	1845003;1845065;1845101 ;1845119;9117606;919293 5;93181057;93191901	OPEL Astra G 98~10; Astra H 04~14
55-5524		V 12V A ≤16 W φ 141*71 RPM ±3100 D.R	6441BE;6441BF;6441CH;6 441CL;6441CN;1845115;1 845116;1845132;13335074 ;55702446;55702447;7736 4827;77364952;77364955	CITROEN Nemo 08~19 FIAT Fiorino 07~19; Punto 05~19; Qubo 08~19 OPEL Adam 12~19; Corsa D 06~14; Corsa E 15~; Corsavan 06~14 PEUGEOT Bipper
55-5525		V 12V A ≤10.5 W φ 134*63 RPM ±3400 D.R	1845222;24436989;698563	OPEL Combo 01~16; Corsa C 00~16; Tigra Twintop 04~09

55-5531		V 12V A ≤17 W φ 138*76 RPM ±3100 D.R	1845112;1845113;1845133 ;13335075;55702442;5570 2443;55802442;77364826; 77364828;77364951;77364 956;715268	FIAT Grande Punto 05~12; Linea 07~
55-5533		V 12V A ≤13 W φ 135*83 RPM ±3100 D.R	77362537;77362538;77364 885;1557648;9S5118527B A	FIAT 500C 07~19; Panda 03~16 FORD KA 09~
55-5534		V 12V A ≤ W φ 138*76 RPM D.R	6441y8;77364234	CITROEN Relay 06~19 FIAT Ducato 06~19 PEUGEOT Boxer 06~19
55-5535A		V 12V A ≤ W φ 138*76 RPM D.R	5N8522100;51836347;518 36362;98619154;98619172 ;98619201	FIAT 500 07~16 Palio 12~17 Panda 03~06 Fiorino 11~ Grand Siena 12~ Uno 11~16 For FORD KA 08~
55-5537		V 12V A ≤ W φ 138*76 RPM D.R	5A373030AM;7088614;708 8222;7082288	FIAT Idea 11~16; Palio 96~17; Siena 04~13; Strada 01~13
55-5538		V 12V A ≤ W φ 138*76 RPM D.R	7077161;9130451074	FIAT UNO 90~13; UNO Mille 84~13; Fiorino 83~13; Siena 96~01; Strada 96~01
55-5559		V 12V A ≤ W φ 138*76 RPM D.R	2118300908;2118300408; A2118300408;A211830090 8;	MERCEDES(奔驰) CLS500 06~ CLS63 AMG 07~ E320 03~06 E350 06~09 E500 03~06 E63 AMG 07~
55-5560		V 12V A ≤19 W φ 133*66 RPM ±3800 D.R	2128200708;A2128200708 ;VDO.PM4111;FS.75028	MB(奔驰 W212) AMG GT 16~18; C-CLASS 10~15; CLS-CLASS 12~18; E-CLASS 12~17; GLK-CLASS 11~15; SL-CLASS 15~18

55-5562		V 12V A ≤ W φ RPM ± D.R	2218200514;2218202714; A2218200514;A221820271 4;VDO.PM4795	MB(奔驰 W221) CL-CLASS 07~14; S-CLASS 12~13
55-5563		V 24V A ≤ W φ 138*76 RPM D.R	9130451222	MB 1620 96~
55-5563A		V 24V A ≤ W φ 138*76 RPM D.R	0008200908;A0008200908 ;9130451223	MB 1621,1938,2423,2428,2638 96~05
55-5572		V 12V A ≤ W φ RPM ± D.R	64116933401;6411039479 1;64116913401;6913401;0 394791;69334013401	BMW(宝马) 7-Serises 02~08
55-5574		V 12V A ≤14.5 W φ 146*71 RPM ±2500 D.R	64116971108;6411922965 8;64119245849;VDO.PM4 065; FS.75052	BMW(宝马 E70,E71) X5 07~18; X6 08~19
55-5577		V 12V A ≤14.5 W φ 146*71 RPM ±2500 D.R	64116933663;6411914420 0;6411922767;715048;PM 9354; 75896	BMW(宝马 E90) 1-SERIES 08~13; 323I 06~13; M3 08~13; X1 12~15; X3 11~17; X4 15~18; Z4 09~16
55-5578		V 12V A ≤22 W φ 147*70 RPM ±3500 D.R	64119200936;6411920448 5;64119242607;641192439 50;64119248171;FS.75027	BMW(宝马 F10,F18,F01,F02) 5-Serises 11~17; 6-Serises 12~18; 7-Serises 10~15; ACTIVEHYBRID 5 12~16; ACTIVEHYBRID 7 13~15; ALPINA B6 15~18; ALPINA B7 11~15; M5 12~16; M6 12~17
55-5584		V 12V A ≤ W φ 138*76 RPM D.R	5U0820021B;996014W;70 0886	VW Gol Saveiro 08~19 Spacefox 10~19 Voyage 09~19 Saveiro 09~19

55-5579		V 12V A ≤14.5 W φ 146*71 RPM ±2500 D.R	64119237557;6411935039 5; VDO.PM5127; FS.75064	BMW(宝马) F20.F21.F22.F33.F35) 2-Series 14~20; 3-Series 13~19; 4-Series 14~20; Activehybrid 3 13~15; M2 16~20; M235i 14~16; M240i 17~19; M3 15~18; M4 15~20
55-5585		V 24V A ≤ W φ 138*76 RPM D.R	2R2819015;812313C	VW Constellation 05~02
55-5586			1J1819021;1J1819021A;1J1819021B;1J1819021C;99657290300;99657290302;99662410701;V150318791;698262	AUDI TT 00~06 VOLKSWAGEN Beetle 98~10 Golf 99~06 Jetta 99~05
55-5587			1K1819015;1K1819015C;1K1819015D;1K1819015E;1K1820015;1K1820015A;1K1820015C;1K1820015D;1K1820015E;1K1820015F;1K1820015G;1K1820015J;1K1820015L;1K1820015P;1K1820015Q;1KD8200	AUDI A3 06~13 Q3 15~19 TT 08~15 VOLKSWAGEN CC 15~17 Eos 09~16 Golf 06~14 Gti 06~14 Jetta 05~18 Rabbit 06~09 Tiguan 12~17 TIGUAN LIMITED 18~
55-5588			8K1820021A;8K1820021B;8K1820021C;351040251	AUDI A4 09~12 A5 08~11 Q5 09~12 S4 09~12 S5 08~11
55-5591		V 24V A ≤13 W φ 129*60 RPM ±3400 D.R	1271194;1357713;1401436;1495692;0130111184	SCANIA(斯堪尼亚) 4-Series 114
55-5593		V 24V A ≤12 W φ 129*60 RPM ±3300 D.R	81619300055;0018300308;A0018300308;3090909	MAN(欧曼), MB(奔驰), VOLVO(沃尔沃)

55-5594			351040651;64116933910;693391	BMW 525I 04~07 525XI 06~07 528I 08~10 528XI 08~ 530I 05~07 530XI 06~07 535I 08~11 535XI 08~ 550I 06~10 645CI 04~05 650CI 06~11 650I 06~09 M5 06~10 M6 06~10
57-1001		V 12V A ≤ W φ RPM W .D	68038826AB;68003996AA; 68038826AA;68038827AA	DODGE NITRO 07~11 JEEP LIBERTY 08~12
57-1002		V 12V A ≤ W φ RPM W .D	22954786;23253380	BUICK VERANO 12~17 CADILLAC ELR 14~16 CHEVROLET ORLANDO 12~14 VOLT 11~15
57-1003		V 12V A ≤ W φ RPM W .D	6M3418527DA;UR8361B1 0;1505611	FORD RANGER 06~12 MAZDA BT-50 06~15
57-1004		V 12V A ≤ W φ RPM W .D	NA1P61B10	MAZDA(马自达) MX-5 MIATA 16~22
57-1005		V 12V A ≤ W φ RPM W .D	79310SNB013;AV2700538 1;C2Z6520	JAGUAR XF 09~15 XJ 11~19
57-1007		V 12V A ≤ W φ RPM W .D	XS8H18456AA;93BW1845 6AC;97BW18456AA;1027 751;1027753;1085691;688 2135	FORD COUGAR 98~01 MONDEO 93~00
57-1008		V 12V A ≤ W φ RPM W .D	5201308;DG9H19846AB	FORD(福特) Edge(锐界) 14~18 GALAX(金牛座) 14~18 S-MAX 15~18

57-1006		V 12V A ≤ W φ RPM W .D	68029719AA;68029719AB; 68037308AA;68044151AB; 68079477AA;68079477AB; 68224166AA;68224166AB; 68238029AA;7B0820021	CHRYSLER 300 08~23 TOWN & COUNTRY 08~16 DODGE CHALLENGER 08~23 CHARGER 08~23 DURANGO 11~23 GRAND CARAVAN 08~20 MAGNUM 08~ JEEP GRAND CHEROKEE(吉普大切诺基) 11~22 RAM C/V 12~15 VW ROUTAN 09~14
57-1009		V 12V A ≤ W φ RPM W .D	AV1119846BB;AV1119846 BA;1752046;1804473	FORD(福特) B-MAX 12~15 ECOSPORT(翼搏) 13~16 KA+ 16~18 TOURNEO 13~17
57-1010		V 12V A ≤ W φ RPM W .D	BJ0E61B10;CB0761B10A	MAZDA PROTEGE 99~03
57-1011		V 12V A ≤ W φ RPM W .D	5075553;1811783;AE8319 846AB;AV1119846AB	FORD(福特) B-MAX 12~15 ECOSPORT(翼搏) 12~17 TOURNEO COURIER 14~15
57-1012		V 12V A ≤ W φ RPM W .D	13263279;13369460	BUICK LACROSSE 10~16 REGAL 11~17 CHEVROLET CRUZE 11~16 MALIBU 13~16
57-1013		V 12V A ≤ W φ RPM W .D	4885475AC;4885475AB	CHRYSLER(克莱斯勒) PACIFICA 04~08 TOWN & COUNTRY 01~07 VOYAGER(大捷龙) 01~03 DODGE(道奇) CARAVAN(凯领) 01~07 GRAND CARAVAN 01~08
57-1015		V 12V A ≤ W φ RPM W .D	5073486AA;19193524;507 3968AA;5096255AA;50962 56AA;68031462AA;	DODGE RAM 1500 PICKUP 02~08 RAM 2500 PICKUP 02~09 RAM 3500 PICKUP 02~09 RAM 4000 02~10 RAM 4500 08~10 RAM 5500 08~10 JEEP GRAND CHEROKEE(吉普大切诺基) 02~04

57-1014		V 12V A ≤ W φ RPM W .D	1E0361B10A;1E0361B10C ;96FW18565AF;1003943;1 021296;1055062	FORD FIESTA 95~03 KA 96~08 STREET KA 03~05 MAZDA 121 III 96~03
57-1016		V 12V A ≤ W φ RPM W .D	1038587;1101897;1109798 ;7204771;7367246;95NW1 8456AA;95NW18456AB;9 5NW18456AC;95NW1845 6AD;XM2H18456AA;7M18 19021;7M1819021A;7M18 19021B;7M1819021D	FORD GALAXY 95~06 SEAT ALHAMBRA 96~10 VW Sharan 95~10
57-1017		V 12V A ≤ W φ RPM W .D	4886150AA	JEEP CHEROKEE 97~01 WRANGLER 97~01
57-1019		V 12V A ≤ W φ RPM W .D	2S6H18456AD;2S6H1845 6AC;1206930;1252926	FORD FIESTA 02~08 FUSION 02~12
57-1020		V 12V A ≤ W φ RPM W .D	4S7H19D859AA;1327522	FORD FOCUS 98~04 MONDEO III 00~07
57-1021		V 12V A ≤ W φ RPM W .D	1151989;1062248;1092817 ;1116783;2T1H18456BA;X S418456BA;XS418456BC; XS418456BD;XS4H18456 BB;XS4H18456BC;XS4H1 8456BD	FORD FOCUS 98~04 MONDEO III 00~07 TOURNEO 02~13
57-1022		V 12V A ≤ W φ RPM W .D	BP4K61B10	MAZDA(马自达) 3 04~09 5 06~10
57-1023		V 12V A ≤ W φ RPM W .D	95978693;96539656	PONTIAC G3 09~10 CHEVROLET AVEO 04~11

57-1024		V 12V A ≤ W φ RPM W .D	0018305708;0008356207	DODGE SPRINTER 03~09 MERCEDES SPRINTER 10~18
57-1025		V 12V A ≤ W φ RPM W .D	5017666AA;5017666AB;5017666AC	CHRYSLER PT CRUISER 01~05
57-1026		V 12V A ≤ W φ RPM W .D	6813021030;6921008A20	CHEVROLET CAPTIVA 09~ SSANGYONG REXTON II 06~
57-1027		V 12V A ≤ W φ RPM W .D	42424010;96327369;96423425;96440877;96629612;4803882	CHEVROLET EVANDA 05~ DAEWOO MAGNUS 03~04 WINSTORM 07~11
57-1028		V 12V A ≤ W φ RPM W .D	95AG18565BA;95AG1556BA5;1015486;6684269	FORD ESCORT 90~99 ORION 90~93
57-1030		V 12V A ≤ W φ RPM W .D	3M5H18456BD;3M5H18456BB;3M5H18456BC;1253202;1326643;1362641	FORD C-MAX 07~10 FOCUS 03~12 GALAXY 06~15 MONDEO 07~15
57-1034		V 12V W RPM.L RPM.R N.m	700274;76967;CG1Z19805B;CG1Z19805C;CG1Z19805D;DG1Z19805D;VDO.PM9393	FORD EXPLORER 12~19 FLEX 13~19 POLICE INTERCEPTOR SEDAN 13~19 POLICE INTERCEPTOR UTILITY 13~19 SPECIAL SERVICE POLICE SEDAN 14~18 TAURUS 12~19 LINCOLN MKS 12~16 MKT 12~19
57-1035		V 12V W RPM.L RPM.R N.m	6L1Z19805A	FORD EXPEDITION 03~17 LINCOLN NAVIGATOR 03~17

57-1036		V 12V W RPM.L RPM.R N.m	6L1Z19805B;MM930;MM938	FORD EXPEDITION 03~06 F-150 04~08 LINCOLN MARK LT 06~08 NAVIGATOR 03~06
57-1037		V 12V W RPM.L RPM.R N.m	89019301;88986838;89019320;GM3126130	CADILLAC ESCALADE 03~06 CHEVROLET AVALANCHE 03~06 SILVERADO 07~ GMC SIERRA 1500 03~06 SIERRA 1500 CLASSIC 07~ SIERRA 2500 03~06 SIERRA 2500 CLASSIC 07~ SIERRA 3500 03~06 SIERRA 3500 CLASSIC 07~
57-1038		V 12V W RPM.L RPM.R N.m	CL1Z19805B;MM1029;MM1030;MM1094	FORD EXPEDITION 09~17 F-150 09~14 LINCOLN NAVIGATOR 09~17
57-2065		V 12V A ≤ W φ 106*89 RPM D.R	6401065	FORD CARGO PERVANELI BLOWER
57-2065A		V 24V A ≤ W φ 106*89 RPM D.R	6401070	FORD CARGO PERVANELI BLOWER
57-2065C		V 12V A ≤ W φ 106*89 RPM D.R		FORD CARGO Wire(1020mm) BLOWER
57-2309		V 12V A ≤ W φ 131*75.5 RPM D.R	7188531;7188532;95VW18456BB;95VW18456CB;Y C1A18456CB;6C1H18456CA;069401399000	FORD Transit(江铃全顺) 86~13 BLOWER
57-2851		V 12V A ≤ W φ 151*60 RPM D.R	6401131;7337972	FORD Taurus PERVANELI BLOWER

57-2855		V 12V A ≤ W φ 123*94 RPM D.R	91VT18565AA;92VT18565AA;E3RF18527AA;E4RF18527AB;E6RF18527AA;6401044;50011118	FORD Transit 78~99 BLOWER
57-2867		V 12V A ≤ W φ 155 RPM D.R	1062247;1092286;1111936;1151988;2T1H18456AA;2T1Z18568A;XS4H18456AA;XS4H18456AB;XS4H18456AC;XS4H18456AD;YS4Z19805AA;YS4Z19805AB;FS.75754	FORD Focus 00~07; Transit 2010; Transit Connect 10~13; JAGUAR X-TYPE 01~08
57-2869		V 12V A ≤ W φ 143*75 RPM D.R	7C1918456BC	FORD Transit V348(江铃全顺)
57-5701		V 12V A ≤18 W φ 149*71 RPM ±3200 D.R	1538009;1791860;8E2H18456BA;8E2H18456BB;8V5118456BA;8V5118456BB	FORD Fiesta 08~17
57-5702		V 12V A ≤15 W φ 157*70 RPM ±3000 D.R	1253201;1253205;1326642;1326646;1379568;1696006;1696010;3M5H18456AB;3M5H18456AC;3M5H18456AD;3M5H18456EA;3M5H18456EB;3M5H18456EC;AV6N18456AA;AV6N18456CA	FORD(福特) C-MAX 07~19; Escape 13~; Escort(福睿斯) 15~19; Focus(福克斯) 10~19; Kuga 13~19; Tourneo Connect 13~19; Transit 13~
57-5703		V 12V A ≤25 W φ 164*70 RPM ±2650 D.R	5305136;DS7H19846AA	FORD Galaxy 15~19; Mondeo V 12~19; S-MAX 15~19
57-5704		V 12V A ≤15.5 W φ 146*71 RPM ±3100 D.R	BK2T18456AA;BK2T18456AC;BK2Z19805A;BK2Z19805B;BK2Z19805C;BK2Z19805HPM4063;PM9380;75051;0130115572	FORD Transit 17~19; Transit 150 15~19; Transit 250 15~19; Transit 350 15~19; Transit Custom 15~19

57-5704A		V 12V A ≤15.5 W φ 146*71 RPM ±3100 D.R	BK2T18456BA;BK2T18456BC;0130115573	FORD Transit 17~19
57-5705		V 12V A ≤13.5 W φ 142*72 RPM ±3100 D.R	19153680;20760617;20760618;20828731;20828732;20883397;20883404;22741027;25809974;25837290;25860467;25860468;52400050;52400177;52400425;52473336;52487717	CADILLAC Escalade 03~09 CHEVROLET Avalanche 07~09; Avalanche 1500 03~06; Avalanche 2500 03~06; Cheyenne 07~09; Silverado 1500 03~09; Silverado 1500 Classic 2007; Silverado 2500 03~09; Silverado 2500 Classic 2007; Silverado 3500 03~09; Silverado 3500 Classic 2007; Suburban 1500 03~09; Suburban 2500 03~09; Tahoe 03~09 GMC Sierra 1500 03~09; Sierra 1500 Classic 2007; Sierra 2500 03~09;
57-5712		V 12V A ≤13.5 W φ 142*72 RPM ±3100 D.R	1581685;20907444;22810567;22961461 1581786 VDO.PM9365	BUICK Enclave(昂科雷) 08~11 CHEVROLET Traverse 09~11 GMC Acadia 07~11 SATURN Outlook 07~10
57-5715		V 12V A ≤17 W φ 149*76 RPM ±2900 D.R	19130001;72223AJ01A;8710308080;8710308090;8710348060;FS.75809;VDO.PM9382	CADILLAC(凯迪拉克) Cts 08~15; Srx 07~09; Sts 07~11 LEXUS Rx330 2006; Rx350 07~09; Rx400H 2008 SUBARU Legacy 10~19; Outback 10~19 TOYOTA(丰田) Sienna 07~10
57-5719		V 12V A ≤17 W φ RPM ±3000 D.R	95472959;95920122;95920148;700309;42777757;FS.76932; GM3126150;VDO.PM4073	BUICK Encore(昂科拉) 13~20 CHEVROLET Sonic 12~18; Trax(创酷) 13~20

57-5719A		V 12V A ≤ 17 W ϕ RPM ± 3000 D.R	26669003	BUICK Excelle(英朗) 15~18
57-5720		V 12V A ≤ 14.5 W ϕ 146*71 RPM ± 2500 D.R	9030701	BUICK Excelle(凯越) 08~12
57-5721		V 12V A ≤ 17 W ϕ 159.5*80 RPM ± 2600 D.R	1581763;15781505;228964 30;25952810;VDO.PM932 4	CHEVROLET Captiva Sport 12~15; Equinox 06~17 GMC Terrain 10~17 PONTIAC Torrent 06~09 SATURN VUE 08~10 SUZUKI XL-7 07~09
57-5722		V 12V A ≤ 17 W ϕ 159.5*80 RPM ± 2600 D.R	AL1Z19805A;AL1Z19805B ;CL1Z19805A;VDO.PM936 4	FORD Expedition 09~14; F-150 09~14 LINCOLN Navigator 09~14
57-5724			8710333050;8710333081;8 710348040;VDO.PM9180; FS.75880	LAND ROVER Discovery 95~99 LEXUS ES300 02~03; ES330 04~06; RX330 04~06; RX400H 06~07;
57-5732		V 12V A $\leq$ W ϕ RPM D.R	1C3H19805AA;5C4Z19805 AA;5C4Z19850A;F81Z198 05BA;XC3Z19805CA;FS.7 6900;VDO.PM9216	FORD Excursion 00~05; F-250 Super Duty 99~07; F-350 Super Duty 99~07; F-450 Super Duty 99~07; F-550 Super Duty 99~07; F-650 00~07; F-750 00~07; Freestar 04~07; Windstar 97~03 MERCURY Monterey 04~07
57-5761		V 24V A $\leq$ W ϕ RPM D.R	81619306079;8161930608 3;81619306086;816193060 89;81619306098	Man TGE 17~22

OTHER

60-1001		V 12V A ≤ W 50 RPM 48±3 N.m ≥24		播种仓播种电机
60-1002		V 12V A ≤ W 50 RPM 48±3 N.m ≥24		播种仓播种电机
60-1005		V 48 A ≤ W RPM N.m ≥	8Nm	Garage Door Motor
60-1006		V 36 A ≤ W 40 RPM 58±7 N.m ≥20		58RPM 20N.m
60-1007		V 24V A ≤ W 40 RPM N.m ≥20		
60-1009		V 24V A ≤ W 40 RPM 23 N.m ≥27	塑料齿轮	Garage Door Motor
60-1009A		V 24V A ≤ W 40 RPM 23 N.m ≥27	铜齿轮	Garage Door Motor
60-1125I		V 12V A ≤ W 30 RPM.L 42±7 RPM.R 62±7 N.m ≥25		Garage Door Motor
60-1294		V 24V A ≤ W RPM 210 N.m ≥		电动清洁车左边刷电机
60-1295		V 24V A ≤ W RPM 210 N.m ≥		电动清洁车右边刷电机

60-1800B		V 24V A ≤ W RPM N.m ≥		DC Motor
60-1855		V 24V A ≤ W 60 RPM 60±5 N.m ≥25		Garage Door Motor
60-1855A		V 12V A ≤ W 50 RPM 50±5 N.m ≥23	POM齿轮	DC Motor
60-1855B-1		V 12V A ≤ W 60 RPM 60±5 N.m ≥30	金属齿轮	DC Motor
60-1855B-2		V 12V A ≤ W 60 RPM 60±5 N.m ≥30	胶木齿轮	DC Motor
60-1855C		V 12V A ≤ W 50 RPM 50±5 N.m ≥23	POM齿轮	Shift Motor
60-1855D		V 12V A ≤ W 50 RPM 50±5 N.m ≥23	POM齿轮	Shift Motor
60-1855E		V 12V A ≤ W 50 RPM 32±2 N.m ≥23 FN.m ≥20	POM齿轮	家用按摩椅升降电机
60-1855G		V 24V A ≤ W 60 RPM 60±3 N.m ≥25 FN.m ≥20	POM齿轮	家用车库门电机
60-1855H		V 18V A ≤ W 60 RPM 60±3 N.m ≥25 FN.m ≥20	POM齿轮	家用车库门电机

60-1856		V 24V A ≤ W 60 RPM 60±5 N.m ≥25		Garage Door Motor
60-1858		V 24V A ≤ W 20 RPM 80±5 N.m ≥10	404603	Seat Motor
60-1858A		V 12V A ≤ W 20 RPM 140±10 N.m ≥10		DC Motor
60-1858B		V 12V A ≤ W 20 RPM 80±5 N.m ≥10		DC Motor
60-1858G		V 24V A ≤ W 20 RPM 400±20 N.m ≥10		DC Motor
60-1860		V 24V A ≤ W 80 RPM 55 N.m ≥50		Garage Door Motor
60-2488		V 12V A ≤3.5 W 350 RPM 2700 N.m ≥	7700420305A; 7700421259; 7701470783	NISSAN Almera II 03~; Kubistar 03~09 RENAULT Clio II 98~05; Kangoo 97~; Rapid 94~98; Thalia, Kubistar, Meriva B
60-3005-LM		V 12V A ≤ W RPM 12 N.m ≥50		通用2线176/43
60-3005-RM		V 12V A ≤ W RPM 12 N.m ≥50		通用2线176/43

60-3501-AB		V A ≤ W RPM N.m ≥	单个价格	汽车电动踏板被动支架(铰链、连动杆)左右通用
60-3501-FB		V A ≤ W RPM N.m ≥	单个价格	汽车电动踏板主动支架(铰链、连动杆)左右通用
60-3501-LM		V 12V A ≤ W RPM 12 N.m ≥50	VPLGP0153	LAND ROVER Range Rover 13~16 通用5线166/43 汽车电动踏板左电机
60-3501-LMB		V A ≤ W RPM N.m ≥	单个价格	汽车电动踏板左主动总成 无前后之分
60-3501-P		V A ≤ W RPM N.m ≥	单个价格	汽车电动踏板面板总成左右通用（视需求如1.8米、2米、2.2米,编为P180、P200、P220）
60-3501-RM		V 12V A ≤ W RPM 12 N.m ≥50	VPLGP0136	LAND ROVER Range Rover 13~16 通用5线166/43 汽车电动踏板右电机
60-3501-RMB		V A ≤ W RPM N.m ≥	单个价格	汽车电动踏板右主动总成 无前后之分
60-3501-W		V A ≤ W RPM N.m ≥		汽车电动踏板线束总成（视车型车型需求如TOYOTA,编为WT1、WT2、WT3）
60-3502-LM		V 12V A ≤ W RPM 12 N.m ≥50		
60-3502-RM		V 12V A ≤ W RPM 12 N.m ≥50		

60-3701-LM		V 12V A ≤ W RPM 12 N.m ≥50	11570192; 11570193; 19303235; 747951	CADILLAC Escalade(凯迪拉克凯雷德) 07~14 CHEVROLET Avalanche 07~13; Silverado 1500 07~13; Silverado 2500 07~14; Silverado 3500 08~14; Suburban 14; Suburban 1500 07~14; Suburban 2500 07~13; Tahoe 07~14 GMC Sierra 1500 07~13; Sierra 2500 14; Sierra 3500 14; Sierra Denali 10; Yukon 07~14; Yukon XI 1500 07~14; Yukon XI 2500 07~13
60-3701-RM		V 12V A ≤ W RPM 12 N.m ≥50	11570192; 11570193; 19303236; 747952	CADILLAC Escalade(凯迪拉克凯雷德) 07~14 CHEVROLET Avalanche 07~13; Silverado 1500 07~13; Silverado 2500 07~14; Silverado 3500 08~14; Suburban 14; Suburban 1500 07~14; Suburban 2500 07~13; Tahoe 07~14 GMC Sierra 1500 07~13; Sierra 2500 14; Sierra 3500 14; Sierra Denali 10; Yukon 07~14; Yukon XI 1500 07~14; Yukon XI 2500 07~13
60-3702-LM		V 12V A ≤ W RPM 12 N.m ≥50	9L7Z16A507A; 747953	FORD Expedition 07~14 LINCOLN Navigator 07~14 通用5线176/43
60-3702-RM		V 12V A ≤ W RPM 12 N.m ≥50	9L7Z16A506A; 747954	FORD Expedition 07~14 LINCOLN Navigator 07~14 通用5线176/43
60-3703-LM		V 12V A ≤ W RPM 12 N.m ≥50	AL3Z16A506A; FL7Z16A507A; FL7Z16A507B	FORD F-150 07~14 RH

60-3703-RM		V 12V A ≤ W RPM 12 N.m ≥50	AL3Z16A507A; FL7Z16A506A; FL7Z16A506B	FORD F-150 07~14 LH
70-0001		V 12V A ≤2 W RPM 9800 N.m ≥		民用电机
70-1001		V 24V A W RPM 55 N.m ≥20		网拍穿拉线电机
70-1002		V 24V A W RPM 55 N.m ≥23		网拍穿拉线电机
70-1003		V 24V A W RPM 90 N.m ≥30		电器驱动电机
70-1005		V 48V A W RPM 80 N.m ≥	塑料齿轮	搅拌电机
70-1005A		V 48V A W RPM 80 N.m ≥	铜齿轮	搅拌电机
70-1006		V 36V A W RPM 60 N.m ≥	塑料齿轮	搅拌电机
70-1006A		V 36V A W RPM 60 N.m ≥	铜齿轮	搅拌电机
70-1009		V 24V A W RPM 60 N.m ≥	0390257694; F006B20099	回收饮料瓶设备电机

70-1013		V 24V W RPM.L 40±7 RPM.R 48±7 N.m ≥30		
70-1101		V 12V		2020年长安CS75PLUS电踏 安装说明
73-3101		V 12V		2017 Toyota Highlander(XU50) Running Board
75-5101		V 12V		2017年奥迪Q5L(B8,8R)电踏 安装说明
75-5301		V 12V		2019年荣威RX5 MAX电动登 车踏板
80-1000		V 12V A W RPM 24000 N.m		电器驱动电机
80-1001		V 24V A W RPM 24000 N.m		电器驱动电机
91-1066		V W RPM.L RPM.R N.m		三轮雨刷臂片
91-5V07			A1J6955707A; BEJ6955427	VW Golf(高尔夫) 99~06; Jetta(捷达) 01~05