

Salt Spray Report

Applicant: Shenzhen Cansheng Industry Development Co., Ltd.

Address: No. 20 JianLong Street, JianLong Village, HengGang Town, LongGang District,

ShenZhen City, China.

Manufacturer: Shenzhen Cansheng Industry Development Co., Ltd.

Address: No. 20 JianLong Street, JianLong Village, HengGang Town, LongGang District,

ShenZhen City, China.

Test sample **LED Strip**

Model of the sample C-SF2J

Sample received date Sep. 27, 2017

Test completed date Oct. 12, 2017

Test Standard ANSI/SCTE 143 2013

In case of 96 hours standby Test method

Please refer to next page. Test result



Manager Oct. 12, 2017

Report No.: BEL20170000101058

This Test Report is issued by the Company subject to its General Conditions of Service printed overleaf. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This Test Report cannot be reproduced, except in full, without prior written permission of the Company.

Page 1 of 4 Salt Spray Report

Report No.: BEL20170000101058



Salt Spray Report

Equipment:TMJ-9702 salt spray equipment		
Test Conditions		
Conditions	Setting	Actual record
Concentration of salt solution	5%NaCL	5%
Test room Temperature	35%C±1℃	35℃
Saturated air barrel temperature	47%C ±1℃	47 ℃
Test room relative humidity	More than 84%	90%RH
Pressure of compressed air	1±0.1KG/CM ²	0.9KG/CM ²
Collected volume of salt spray	1-2ML/CM ² /H	1.8ML/CM ² /H
PH of salt solution	7±0.5	7
Test duration:96 hours	Time in	8:30AM,2017.10.07
	Time out	10:00AM,2017.10.11
The appearance after testing: OK		
Acceptable Criteria: 1.Corrosion		area based on the test standard \leq 0.005% (\checkmark)
2.According		to the customer requirement:()
3.According		to the other method: ()
Judgement: (√) Accepted () Rejected () Other option		

Salt Spray Report Page 2 of 4



PHOTOGRAPHS OF TEST SAMPLE

Before test







Salt Spray Report Page 3 of 4



After test



*** END OF REPORT ****

Salt Spray Report Page 4 of 4